




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|-------------------------------------|--|--------------------------------|---|
| MSIG INSURANCE (SINGAPORE) PTE LTD | | | Ref : CS3/MSG19008628/Gsd3e2-2 | |
| 16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581 | | | Date : 13-09-2019 |  |
| | | | Code : MSG | |
| 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION) | | | | |
| | Insured Veh. | FBC 1357A | Veh. Inspected | SLB 6685G |
| | Policy No. | MSD/VMT/18-389692-CA | Coverage (\$) | 0.00 |
| | Claim No. | MSC/V/19-000561 | Excess (\$) | 0.00 |
| | Assign From | CHRISTINA WONG | Assign Date | 03/09/2019 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | HONDA VEZEL | c.c | 1496 |
| | Engine No. | HIDDEN | Year of Reg. | 2016 |
| | Chassis No. | RU11113153 | Colour | SILVER |
| | Odometer | 46477 | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm |
| | L/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm |
| | R/H Rear Tyre | 215/60 R16 | DUNLOP | 6 mm |
| | L/H Rear Tyre | 215/60 R16 | DUNLOP | 6 mm |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| | Accident Date | 11/05/2019 | Inspection Date | 11/09/2019 |
| | Survey held at | SAU HOCK MOTOR SERVICES BLK 10 ANG MO KIO INDUSTRIAL PARK 2A (AVE 5) #02-14 AMK AUTOPOINT SINGAPORE 568047. | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 5 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 6685G

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|--------------------------------|---------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER | REPLACED | 762.70 | 762.70 |
| 2 | REAR BUMPER RH / LH | SERVICEABLE | 390.00 | - |
| 2 | REAR BUMPER REFLECTOR RH / LH | N/S REPLACED / O/S SERVICEABLE | 282.20 | 141.10 |
| 2 | REAR BUMPER SIDE RETAINER RH / LH | SERVICEABLE | 44.00 | - |
| 1 | REAR END PANEL | REPAIRED SEE LABOUR | 415.60 | - |
| 1 | REAR END PANEL INNER TAILGATE ANTENNA SENSOR | SERVICEABLE | 85.00 | - |
| 1 | REAR END PANEL LOWER UNDER COVER | SERVICEABLE | 190.00 | - |
| 1 | REAR END PANEL OUTER BUZZER | SERVICEABLE | 80.00 | - |
| 1 | TAILGATE | REPLACED | 953.30 | 953.30 |
| 1 | TAILGATE LOGO "HONDA" | SERVICEABLE | 25.00 | - |
| 1 | TAILGATE EMBLEM "VEZEL" | REPLACED | 56.20 | 56.20 |
| 1 | TAILGATE MECHANISM LOCK | REPLACED | 157.50 | 157.50 |
| 2 | REAR NUMBER PLATE LAMP RH / LH | SERVICEABLE | 77.00 | - |
| 1 | TAILGATE OUTER GARNISH | SERVICEABLE | 220.00 | - |
| 11 | SET TAILGATE OUTER GARNISH CLIP | SERVICEABLE | 71.50 | - |
| 1 | TAILGATE OUTER LOCK HANDLE SWITCH | SERVICEABLE | 175.50 | - |
| 2 | TAILGATE REFLECTOR LAMP BACK RUBBER GASKET RH / LH | SERVICEABLE | 37.00 | - |
| 6 | TAILGATE REFLECTOR LAMP CLIP RH / LH | REPLACED | 39.00 | 26.00 |
| 2 | TAILGATE REFLECTOR LAMP RH / LH | REPLACED | 826.40 | 326.20 |
| 2 | TAILGATE RUBBER GUIDE STOPPER RH / LH | SERVICEABLE | 25.00 | - |
| 1 | TAILGATE WEATHERSTRIP | REPLACED | 96.80 | 96.80 |
| 1 | TAILGATE WINDSCREEN MOULDING | REPLACED | 120.00 | 67.90 |
| 2 | REAR TAIL LAMP BACK RUBBER GASKET RH / LH | SERVICEABLE | 130.60 | - |
| 8 | REAR TAIL LAMP CLIP RH / LH | SERVICEABLE | 52.00 | - |
| 2 | REAR TAIL LAMP INNER PANEL RH / LH | REPAIRED SEE LABOUR | 270.00 | - |
| 2 | REAR TAIL LAMP RH / LH | SERVICEABLE | 949.20 | - |
| | LESS 20% DISCOUNT | | - | -517.54 |
| | | | 6,531.50 | 2,070.16 |

Report Ref No. CS3/MSG19008628/Gsd3e2-2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|-------------|---------------------------|-------------------|
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | SET REAR BUMPER CLIP (SN) | REPLACED | 30.00 | 30.00 |
| 1 | REAR BUMPER REVERSE SENSOR (SN) | REPLACED | 350.00 | 200.00 |
| 1 | TAILGATE REVERSE CAMERA (SN) | SERVICEABLE | 550.00 | - |
| 1 | SET TAILGATE INNER TRIM BOARD CLIP (SN) | REPLACED | 30.00 | 30.00 |
| 1 | REAR NUMBER PLATE C/W HOLDER (SN) | SERVICEABLE | 50.00 | - |
| 1 | TAILGATE WINDSCREEN SEALANT (SN) | REPLACED | 100.00 | 60.00 |
| | | | 1,110.00 | 320.00 |
| | <u>LABOUR</u> | | | |
| | TO STRAIGHTEN AND PANEL BEATING REAR FENDER RH / LH, REAR BOOT FLOOR PANEL AND REAR FRAME MEMBERS. TO CUT AND WELD REAR END PANEL. TO REMOVE AND REFIT ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR TAIL LAMP INNER PANEL RH / LH. | | 1,600.00 | 600.00 |
| | TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREA. | | 1,500.00 | 600.00 |
| | TO CHECK AND RECTIFY WIRING SYSTEM. | | 80.00 | 30.00 |
| | TO REMOVE AND REFIT REAR WINDSCREEN. | | 150.00 | 100.00 |
| | TO RUST PROOF AFFECTED AREAS. | | 120.00 | 60.00 |
| | | | 3,450.00 | 1,390.00 |
| | GRAND TOTAL | | 11,091.50 | 3,780.16 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 3,000.00 |

Report Ref No. CS3/MSG19008628/Gsd3e2-2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.