

ASS. REC. BY:

REF:

TMI/CC3/TMI 19015615 / KLF3A2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

03

Res.: Yes or No

Lum Sum: _____

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SHD 5470 C Yr Regn: 01.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toy Prius

c.c

1788

Colour _____

M White / R

A/C:

Insured / Std / NI / NA

Sp. Reading _____

48430

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JTDKB31U60.3079168

Gen. Cond: _____

Good / Fair / Poor / Burnt

Steering: _____

In order / Jammed / Leaked / Burnt or

Brake: _____

In order / Jammed / Leaked / Burnt or

Modl: _____

NII / S/Rim / STD / Rim or

Tyre Size: _____

F: _____

195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

Rear

R/Bal. _____

9

mm

R/Bal. _____

9

mm

L/Bal. _____

9

mm

L/Bal. _____

9

mm

D.O.A. _____

1/9/19

D.O.I. _____

3/9/19

Survey held at _____

Des. of Damages: _____

Frt / Rear / O/S / N/S / UIC / Rooftop or

C/S R

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

SHD 5470 C - CS/FCI 300500 / UVU 2

YL 9389K - CC3/AIG 12020062 / H/A2131

D.O.A. 20/01/2016

D.O.A. 15/10/2012

4/9 @ 11:44am - Revised via email to Tokyo GIA & estimate

25/9 83450.65 Sumit. Cred: 27662.23: 33%

RECEIVED 26 SEP 2019

Date/Time, File Pass to?

25/9 Typist

Date/Time, File Return to?



Prell. Report



Final Report

Days Of Repair: _____

3

Resurvey No. of Trip: _____

1

Survey Fee:

Transportation

S + RS SI

Fees

Others

Add Fee: _____



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

250

11

261

Report Format: _____

Tp

Lump Sum / I.B.I. (\$

3450.65



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 4/9/2019

Our Ref: CC3/TMI19015615/Ktf3

The Motor Claims Department
TOKIO MARINE INSURANCE SINGAPORE LTD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SHD 5470C

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 03/09/2019 at the premises of M/s TRANSCAB and have the following to report: -

| | |
|--------------------------|-----------------|
| Workshop Estimate Amount | : S\$ 31,112.88 |
| Revised Estimate Amount | : S\$ 3,450.65 |
| "Check" Items Amount | : S\$ 2,333.02 |
| Market Value | : S\$ |
| LTA Reimbursement Value | : S\$ - |
| Nett Value | : S\$ - |

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Repair days: 3

Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth Kong
Automotive Assessor

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 4 September 2019 11:44 AM
To: 'Motor Claims'
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 1/9/2019, SHD 5470C (TP VEHICLE), YL 9389K (OI VEHICLE)
Attachments: ESTIMATE.pdf; SHD 5470C GIA REPORT.pdf; PRELI ADVISED OF SHD 5470C.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 5470C at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 3/9/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Friday, 20 September 2019 5:11 PM
To: Denise Tay (LKKAUTO)
Subject: FW: SHD 5470C / TP / TOKIO MARINE / DOA: 01/09/2019 -- AAD1909-001
Attachments: ESTIMATE.pdf

Hi Denise

We submit \$ 3,450.65 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Wednesday, 18 September, 2019 9:36 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: SHD 5470C / TP / TOKIO MARINE / DOA: 01/09/2019

Dear Wai Yin,

Can finalize?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID: | 878K |

Vehicle No: SHD5470C

Vehicle No.: SHD5470C

Vehicle to be Exported: Yes

Intended Deregistration Date: 02 Sep 2019

Vehicle Make: **TOYOTA**

Vehicle Make: **TOYOTA**
Vehicle Model: **PRIUS 5DR HATCHBACK (AUTO)**

Vehicle Model: PRIUS SDR HATCHBACK (45115)

Primary Colour: Red
0010

Manufacturing Year: 2018

Engine No.: 2ZR2B98684

Chassis No. JTDKB3FU603079168

| | |
|-----------------------|-------------------|
| Maximum Power Output: | 90.0 kW (120 bhp) |
|-----------------------|-------------------|

| | |
|-----------------------|-------------|
| Maximum Power Output: | |
| Open Market Value: | \$26,605.00 |

| | |
|--------------------|--------------|
| Open Market Value: | \$28,000,000 |
| As of: | 25 Jan 2019 |

| | |
|-----------------------------|-------------|
| Original Registration Date: | 25 Jan 2019 |
| | 25 Jan 2019 |

First Registration Date: 25 Jan 2019

Transfer Count: 0

| | |
|------------------|-------------|
| Actual ARF Paid: | \$14,247.00 |
|------------------|-------------|

| | |
|-------------------|-----|
| PARF Eligibility: | Yes |
|-------------------|-----|

PARE Eligibility Expiry Date: 24 Jan 2027

| | |
|---------------------|-------------|
| PARE Rebate Amount: | \$10,685.00 |
|---------------------|-------------|

Intended COE Rebate Details

COE Expiry Date: 24 Jan 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

| | |
|-----------|-------------|
| PQP Paid: | \$20,838.00 |
|-----------|-------------|

COE Rebate Amount: \$16,670.00

| | |
|----------------------|-------------|
| Total Rebate Amount: | \$27,355.00 |
|----------------------|-------------|

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Sep 2019

| | |
|---|-------------------------------------|
| Address | BLK 642 YISHUN STREET 61 #09-250 |
| Postcode | 760642 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - HIRER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |

General Information of the Accident

| | |
|--------------------|------------|
| Type Of Accident | SIDE SWIPE |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

ON 01/09/2019 AT ABOUT 0715HRS, MY TAXI WAS STATIONARY IN THE PARKING LOT ALONG GEYLANG LORONG 17. I WAS IN MY TAXI TALKING ON THE PHONE AND SUDDENLY I FELT AN IMPACT ON THE RIGHT SIDE PORTION OF MY TAXI. VEHICLE B(YL9389K) HAS COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

Attachment(s)


| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|--------------------|
| Vehicle Registration Number | YL9389K |
| Vehicle Make/Model/Colour | LORRY |
| Details Of Properties | |
| Vehicle Category | COMMERCIAL VEHICLE |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5470C*Not Authored
Resurvey B&Paint***AAD1909-001**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

02 SEP 2019

~~30 AUG 2019~~**SHD 5470C**

JTDKB3FU603079168

TOYOTA

PRIUS

1.9.19

TOKIO MARINE

25/1/2019

| | | PART | | LIST |
|----|---|---|----|----------------------|
| 1 | 1 | PANEL SUB-ASSY, FRONT DOOR, RH | \$ | <i>By</i> 1,264.00 ✓ |
| 2 | 1 | WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH | \$ | <i>By</i> 316.90 X |
| 3 | 1 | CHECK ASSY, FRONT DOOR | \$ | <i>Dir</i> 156.60 ✓ |
| 4 | 1 | WEATHERSTRIP, FRONT DOOR FIX WINDOW, RH | \$ | <i>By</i> 75.50 X |
| 5 | 1 | RUN, FRONT DOOR GLASS, RH | \$ | <i>Sn</i> X 151.20 X |
| 6 | 1 | WEATHERSTRIP, FRONT DOOR, RH | \$ | <i>By</i> 228.10 ✓ |
| 7 | 1 | LOCK ASSY, FRONT DOOR W/MOTOR, RH | \$ | <i>By</i> 592.70 ✓ |
| 8 | 1 | HANDLE ASSY, FRONT DOOR, OUTSIDE RH | \$ | <i>Sn</i> X 385.60 X |
| 9 | 1 | FRONT DOOR OUTER MOULDING RH | \$ | <i>Dir</i> 188.60 ✓ |
| 10 | 1 | MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH | \$ | <i>By</i> 38.10 X |
| 11 | 1 | HINGE ASSY, FRONT DOOR, LOWER RH | \$ | <i>Dir</i> 94.10 ✓ |
| 12 | 1 | HINGE ASSY, FRONT DOOR, UPPER RH | \$ | <i>Dir</i> 83.40 ✓ |
| 13 | 1 | MOTOR ASSY, POWER WINDOW REGULATOR, RH | \$ | <i>Sn</i> X 791.50 X |
| 14 | 1 | REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH | \$ | <i>Sn</i> X 235.10 X |
| 15 | 1 | MOULDING ASSY, BODY ROCKER PANEL, RH | \$ | <i>By</i> 583.30 |
| 16 | 1 | REINFORCE SUB-ASSY, ROCKER, OUTER RH | \$ | <i>By</i> 572.10 |
| 17 | 1 | REINFORCEMENT SUB-ASSY, ROCKER PANEL, RH | \$ | <i>By</i> 336.60 |
| 18 | 1 | RIGHT SIDE VIEW MIRROR | \$ | <i>Sn</i> 1,275.52 |
| 19 | 1 | WIRE, FRONT DOOR, RH | \$ | <i>By</i> 454.10 } X |
| 20 | 1 | MOULDING, FRONT DOOR WINDOW FRAME, UPPER RH | \$ | <i>Sn</i> 90.50 |
| 21 | 1 | FRAME SUB-ASSY, FRONT DOOR, FRONT LOWER RH | \$ | <i>Sn</i> 142.90 |
| 22 | 1 | MOULDING, FRONT DOOR WINDOW FRAME, REAR RH | \$ | <i>Sn</i> 55.80 |
| 23 | 1 | FRAME SUB-ASSY, FRONT DOOR, REAR LOWER RH | \$ | <i>Sn</i> 87.60 |
| 24 | 1 | COVER, FRONT DOOR SERVICE HOLE, RH | \$ | <i>Sn</i> 185.70 |
| 25 | 1 | TAPE, BLACK OUT, NO.1 RH | \$ | <i>By</i> 13.10 ✓ |
| 26 | 1 | TAPE, BLACK OUT, NO.2 RH | \$ | <i>By</i> 42.90 ✓ |
| 27 | 1 | TAPE, BLACK OUT, NO.3 RH | \$ | <i>By</i> 25.90 ✓ |
| 28 | 1 | GLASS SUB-ASSY, FRONT DOOR, RH | \$ | <i>Sn</i> 514.80 X |
| 29 | 1 | WEATHERSTRIP, FRONT DOOR GLASS, INNER RH | \$ | <i>Sn</i> 136.30 X |

Trans-cab Auto Services Pte Ltd

AAD1909-001

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5470C

| | | | | |
|--------------|---|--|-----------|------------------------------------|
| 30 | 1 | BOARD SUB-ASSY, FRONT DOOR TRIM, RH | \$ | <i>Sm</i> 737.90 <i>X</i> |
| 31 | 1 | COVER, FRONT DOOR OUTSIDE HANDLE, RH | \$ | <i>Sm</i> 17.60 <i>X</i> |
| 32 | 1 | FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH | \$ | <i>Sm</i> 191.10 <i>X</i> |
| 33 | 1 | HANDLE SUB-ASSY, FRONT DOOR INSIDE, RH | \$ | <i>Sm</i> 95.30 <i>X</i> |
| 34 | 1 | MASTER SWITCH ASSY, MULTIPLEX NETWORK | \$ | <i>Sm</i> <i>X</i> 809.40 <i>X</i> |
| 35 | 1 | ARMREST ASSY, FRONT, RH | \$ | <i>Sm</i> 141.70 <i>X</i> |
| 36 | 1 | CABLE, FRONT DOOR INSIDE LOCKING, RH(FOR LOCK / UNLOCK KNOB) | \$ | <i>Sm</i> 42.50 <i>X</i> |
| 37 | 1 | CYLINDER SET, LOCK | \$ | <i>Sm</i> 245.20 <i>X</i> |
| 38 | 1 | KEY, BLANK | \$ | <i>Sm</i> 86.60 <i>X</i> |
| 39 | 1 | KEY, CUT | \$ | <i>Sm</i> 195.20 <i>X</i> |
| 40 | 1 | FRONT FENDER RH | \$ | <i>R</i> 963.80 <i>X</i> |
| 41 | 1 | EXTENSION, FRONT FENDER, RH | \$ | <i>Sm</i> 48.80 <i>X</i> |
| 42 | 1 | COVER SUB-ASSY, FRONT PILLAR, UPR RH | \$ | <i>Mr</i> 98.30 ✓ |
| 43 | 1 | LINER, FRONT FENDER, RH | \$ | <i>Sm</i> 200.70 <i>X</i> |
| 44 | 1 | FRONT FENDER EMBLEM RH | \$ | <i>R</i> 86.50 ✓ |
| 45 | 1 | SEAL, FENDER APRON MUDGUARD, RH | \$ | <i>Sm</i> 50.90 |
| 46 | 1 | PROTECTOR, FRONT FENDER SIDE PANEL, RH | \$ | <i>Sm</i> 92.30 |
| 47 | 1 | FRONT LED LAMP (LOWER) RH | \$ | <i>Sm</i> 907.75 |
| 48 | 1 | FRONT HEADLAMP RH | \$ | <i>Sm</i> 2,909.04 |
| 49 | 1 | COMPUTER SUB-ASSY, HEADLAMP, RH NO.1 | \$ | <i>Sm</i> 492.30 <i>X</i> |
| 50 | 1 | MOTOR, HEADLAMP LEVELING, RH | \$ | <i>Sm</i> 413.10 |
| 51 | 1 | FRONT BUMPER | \$ | <i>Sm</i> 509.10 |
| 52 | 1 | FRONT BUMPER SIDE RETAINER RH | \$ | <i>Sm</i> 112.70 |
| TOTAL | | | \$ | 18,566.31 |
| 25% | | | \$ | 4,641.58 |
| | | | \$ | 13,924.73 |

Special Nett

| | | | | |
|--------------|---|------------------------------------|-----------|--------------------|
| 1 | 1 | FRONT DOOR STICKER "TRANS-CAB" | \$ | <i>Mr</i> 60.00 |
| 2 | 1 | FRONT DOOR STICKER "CLASSIC" | \$ | <i>Mr</i> 15.00 |
| 3 | 1 | FRONT WHEEL RIM | \$ | <i>Sm</i> 1,570.55 |
| 4 | 1 | FRONT WHEEL RIM COVER | \$ | <i>Sm</i> 175.80 |
| 5 | 1 | CLIP, FRONT FENDER LINER | \$ | <i>Mr</i> 22.00 |
| 6 | 1 | BUMPER CLIP FRT | \$ | <i>Mr</i> 66.00 |
| 7 | 1 | WINDSCREEN SEALANT | \$ | <i>Mr</i> 253.80 |
| 8 | 1 | FRONT WINDSCREEN MOULDING | \$ | <i>Mr</i> 120.00 |
| 9 | 1 | FRONT WINDSCREEN INNER SPONGE SEAL | \$ | <i>Mr</i> 100.00 |
| TOTAL | | | \$ | 2,468.15 |

Trans-cab Auto Services Pte Ltd

AAD1909-001

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5470C

TOTAL PARTS \$ 16,392.88**LABOUR**

Putty And Spray Painting Of The Affected Portion.

\$ 6601 6,000.00

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 4001 6,000.00

To Rust-Proofing Of The Affected Areas.

\$ 301 170.00

To apply paint protection system (PPS) maintain and enhancement

\$ 22 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 22 380.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 22 380.00 X

To transfer of front door fittings, attachment and perform water seepage test.

\$ 601 170.00

To Check Electrical Lighting Concerned.

\$ 201 170.00

Towing Fees

\$ 501 170.00

To transfer of Fender fittings, attachments and perform water seepage test.

\$ 22 170.00

To transfer of Front Bumper fittings, attachments and perform water seepage test.

\$ 22 170.00 X

To transfer of tire, rim and on wheel balancing.

\$ 22 170.00 X

To check steering geometry and computer wheel alignment

\$ 22 220.00 X

To transfer of front windscreen glass to facilitate bodywork repair.

\$ 22 170.00 X

TOTAL \$ 14,720.00**Over All Total \$ 31,112.88****(PART-BY-PART) Repair Days**

20 days

3 days

the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be reviewed and is subject to final approval from

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19015615/KTF3N2

Date: 03/10/2019

REFERENCE

| | | | |
|-----------------------|--------------------------------------|----------------------|----------|
| Handling Insurer: | Tokio Marine Insurance Singapore Ltd | Policy No: | MS002475 |
| Claimant Vehicle No : | SHD5470C | Insured Vehicle No : | YL9389K |
| Date of Loss: | 01/09/2019 | Nature of Claim: | TP |
| | | Claim No: | M1906843 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|----------------------------------|-------------|-------------------|
| Reg No: | SHD5470C | Engine No: | 2ZR2B98684 |
| Make & Model: | TOYOTA PRIUS, 1.8 HYBRID CVT (A) | Chassis No: | JTDKB3FU603079168 |
| Reg. Date: | 25/01/2019 (Man. Year: 2018) | Odometer: | 48430 km |
| Colour: | Metallic White/Red | | |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-----------|------------------|-----------|
| Front Tyre Size: | 195/65R15 | Rear Tyre Size: | 195/65R15 |
| Front Left Side: | Giti 9 mm | Rear Left Side: | Giti 9 mm |
| Front Right Side: | Giti 9 mm | Rear Right Side: | Giti 9 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------------|-----------------|------------------|--------------|
| Parts | 16,392.88 | 2,230.65 | 14,162.23 | 86.39 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 14,720.00 | 1,220.00 | 13,500.00 | 91.71 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 31,112.88 | 3,450.65 | 27,662.23 | 88.91 |
| + GST 7.00/7.00% (S\$) | 2,177.90 | 241.55 | 1,936.35 | 88.91 |
| Nett Amount (S\$) | 33,290.78 | 3,692.20 | 29,598.58 | 88.91 |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 12/09/2019 | |
| Date Inspected: | 03/09/2019 Inspected At: | Trans-cab Auto Services Pte Ltd (Ang Mo Kio) |
| | | 2, Ang Mo Kio Street 63 |
| | | Singapore 569111 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 02 Oct 2019) |
| Parts: | 144 | TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SHD5470C) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|-------------|-------------|--------------|
| 1 | 1 | | *PANEL SUB-ASSY,FRONT DOOR,RH | Bent | 1,264.00 FL | *1,264.00 FL |
| 2 | 1 | | *WEATHERSTRIP,FRONT DOOR OPENING TRIM,RH | Serviceable | 316.90 FL | *- FL |
| 3 | 1 | | *CHECK ASSY,FRONT DOOR | Distorted | 156.60 FL | *156.60 FL |
| 4 | 1 | | *WEATHERSTRIP,FRONT DOOR FIX WINDOW,RH | Serviceable | 75.50 FL | *- FL |
| 5 | 1 | | *RUN,FRONT DOOR GLASS,RH | Serviceable | 151.20 FL | *- FL |
| 6 | 1 | | *WEATHERSTRIP,FRONT DOOR,RH | Cut | 228.10 FL | *228.10 FL |
| 7 | 1 | | *LOCK ASSY,FRONT DOOR W/MOTOR,RH | Bent | 592.70 FL | *592.70 FL |
| 8 | 1 | | *HANDLE ASSY,FRONT DOOR,OUTSIDE RH | Serviceable | 385.60 FL | *- FL |
| 9 | 1 | | *FRONT DOOR OUTER MOULDING RH | Distorted | 188.60 FL | *188.60 FL |
| 10 | 1 | | *MOULDING,FRONT DOOR WINDOW FRAME,FRONT RH | Serviceable | 38.10 FL | *- FL |
| 11 | 1 | | *HINGE ASSY,FRONT DOOR,LOWER RH | Distorted | 94.10 FL | *94.10 FL |
| 12 | 1 | | *HINGE ASSY,FRONT DOOR,UPPER RH | Distorted | 83.40 FL | *83.40 FL |
| 13 | 1 | | *MOTOR ASSY,POWER WINDOW REGULATOR,RH | Serviceable | 791.50 FL | *- FL |
| 14 | 1 | | *REGULATOR SUB-ASSY,FRONT DOOR WINDOW,RH | Serviceable | 235.10 FL | *- FL |
| 15 | 1 | | *MOULDING ASSY,BODY ROCKER PANEL,RH | Serviceable | 583.30 FL | *- FL |
| 16 | 1 | | *REINFORCE SUB-ASSY,ROCKER,OUTER RH | Repair | 572.10 FL | *- FL |
| 17 | 1 | | *REINFORCEMENT SUB-ASSY,ROCKER PANEL,RH | Repair | 336.60 FL | *- FL |
| 18 | 1 | | *RIGHT SIDE VIEW MIRROR | Serviceable | 1,275.52 FL | *- FL |
| 19 | 1 | | *WIRE,FRONT DOOR,RH | Serviceable | 454.10 FL | *- FL |
| 20 | 1 | | *MOULDING,FRONT DOOR WINDOW FRAME,UPPER RH | Serviceable | 90.50 FL | *- FL |
| 21 | 1 | | *FRAME SUB-ASSY,FRONT DOOR,FRONT LOWER RH | Serviceable | 142.90 FL | *- FL |
| 22 | 1 | | *MOULDING,FRONT DOOR WINDOW FRAME,REAR RH | Serviceable | 55.80 FL | *- FL |
| 23 | 1 | | *FRAME SUB-ASSY,FRONT DOOR,REAR LOWER RH | Serviceable | 87.60 FL | *- FL |
| 24 | 1 | | *COVER,FRONT DOOR SERVICE HOLE,RH | Serviceable | 185.70 FL | *- FL |
| 25 | 1 | | *TAPE BLACK OUT,NO 1 RH | Necessary | 13.10 FL | *13.10 FL |
| 26 | 1 | | *TAPE BLACK OUT,NO 2 RH | Necessary | 42.90 FL | *42.90 FL |
| 27 | 1 | | *TAPE BLACK OUT,NO 3 RH | Necessary | 25.90 FL | *25.90 FL |
| 28 | 1 | | *GLASS SUB-ASSY,FRONT DOOR,RH | Serviceable | 514.80 FL | *- FL |
| 29 | 1 | | *WEATHERSTRIP,FRONT DOOR GLASS,INNER RH | Serviceable | 136.30 FL | *- FL |
| 30 | 1 | | *BOARD SUB-ASSY,FRONT DOOR TRIM,RH | Serviceable | 737.90 FL | *- FL |
| 31 | 1 | | *COVER,FRONT DOOR OUTSIDE HANDLE,RH | Serviceable | 17.60 FL | *- FL |
| 32 | 1 | | *FRAME SUB-ASSY,FRONT DOOR OUTSIDE HANDLE,RH | Serviceable | 191.10 FL | *- FL |
| 33 | 1 | | *HANDLE SUB-ASSY,FRONT DOOR INSIDE,RH | Serviceable | 95.30 FL | *- FL |
| 34 | 1 | | *MASTER SWITCH ASSY,MULTIPLEX NETWORK | Serviceable | 809.40 FL | *- FL |
| 35 | 1 | | *ARMREST ASSY,FRONT RH | Serviceable | 141.70 FL | *- FL |
| 36 | 1 | | *CABLE,FRONT DOOR INSIDE LOCKING RH (FOR LOCK/UNLOCK KNOB) | Serviceable | 42.50 FL | *- FL |
| 37 | 1 | | *CYLINDER SET,LOCK | Serviceable | 245.20 FL | *- FL |
| 38 | 1 | | *KEY,BLANK | Serviceable | 86.60 FL | *- FL |
| 39 | 1 | | *KEY,CUT | Serviceable | 195.20 FL | *- FL |
| 40 | 1 | | *FRONT FENDER RH | Repair | 963.80 FL | *- FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|---------------|-------------|-----------|
| 41 | 1 | | *EXTENSION,FRONT FENDER,RH | Serviceable | 48.80 FL | *-FL |
| 42 | 1 | | *COVER SUB-ASSY,FRONT PILLAR,UPR RH | Missing | 98.30 FL | *98.30 FL |
| 43 | 1 | | *LINER,FRONT FENDER,RH | Serviceable | 200.70 FL | *-FL |
| 44 | 1 | | *FRONT FENDER EMBLEM RH | Necessary | 86.50 FL | *86.50 FL |
| 45 | 1 | | *SEAL,FENDER APRON MUDGUARD,RH | Serviceable | 50.90 FL | *-FL |
| 46 | 1 | | *PROTECTOR,FRONT FENDER SIDE PANEL,RH | Serviceable | 92.30 FL | *-FL |
| 47 | 1 | | *FRONT LED LAMP (LOWER) RH | Serviceable | 907.75 FL | *-FL |
| 48 | 1 | | *FRONT HEADLAMP RH | Serviceable | 2,909.04 FL | *-FL |
| 49 | 1 | | *COMPUTER SUB-ASSY,HEADLAMP,RH NO.1 | Serviceable | 492.30 FL | *-FL |
| 50 | 1 | | *MOTOR HEADLAMP LEVELING,RH | Serviceable | 413.10 FL | *-FL |
| 51 | 1 | | *FRONT BUMPER | Serviceable | 509.10 FL | *-FL |
| 52 | 1 | | *FRONT BUMPER SIDE RETAINER RH | Serviceable | 112.70 FL | *-FL |
| 53 | 1 | | *FRONT DOOR STICKER TRANS-CAB | Necessary | 80.00 FS | *60.00 FS |
| 54 | 1 | | *FRONT DOOR STICKER CLASSIC | Necessary | 80.00 FS | *15.00 FS |
| 55 | 1 | | *FRONT WHEEL RIM | Serviceable | 1,570.55 FS | *-FS |
| 56 | 1 | | *FRONT WHEEL RIM COVER | Serviceable | 175.80 FS | *-FS |
| 57 | 1 | | *CLIP,FRONT FENDER LINER | Not Necessary | 22.00 FS | *-FS |
| 58 | 1 | | *BUMPER CLIP FRT | Not Necessary | 66.00 FS | *-FS |
| 59 | 1 | | *WINDSCREEN SEALANT | Not Necessary | 253.80 FS | *-FS |
| 60 | 1 | | *FRONT WINDSCREEN MOULDING | Not Necessary | 120.00 FS | *-FS |
| 61 | 1 | | *FRONT WINDSCREEN INNER SPONGE SEAL | Not Necessary | 100.00 FS | *-FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 21,034.46 | 2,949.20 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 4,641.58 | 718.55 |
| Total Parts (\$\$) | 16,392.88 | 2,230.65 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|------------------|-----------------|
| Labour Items | | | | |
| 1 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 6,000.00 | 660.00 |
| 2 | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME | New | 6,000.00 | 400.00 |
| 3 | TO RUST-PROOFING OF THE AFFECTED AREAS | New | 170.00 | 30.00 |
| 4 | TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT | New | 380.00 | 0.00 |
| 5 | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR | New | 380.00 | 0.00 |
| 6 | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR | New | 380.00 | 0.00 |
| 7 | TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 60.00 |
| 8 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | 20.00 |
| 9 | TOWING FEES | New | 170.00 | 50.00 |
| 10 | TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 11 | TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 12 | TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING | New | 170.00 | 0.00 |
| 13 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 0.00 |
| 14 | TO TRANSFER OF FRONT WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR | New | 170.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 14,720.00 | 1,220.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >