

ASS. REC. BY:

REF: CS/FCI 19015633/04f3n2

Special Instruction:

Surveyor: MarcusASSIGNMENT (Office)From (Person): Hunny Kaoof FCIDate/Time: 4.9.19 10.49a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

MCP 8100

Insured:

SHA 0988A

at Workshop m/s

Fastech Auto

Tel:

67465405of 1 Kaki Bukit Ave 6 #01-46/48

Policy No:

Claim No:

D19065652 MFS4

Sum Insured:

Excess:

Make of Veh:

D.O.A. 30.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4.9.19 11.35a.m

Person Contacted:

NancyVehicle IN OUT

Date/Time

Action/Instruction (☒) EstimateMCP 8100 -xSHA 0988A -x5/9@11:08am:- Sent email pending estimate

(08/11/13) wef

REF:

ASS. REC. BY: *Marcus*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *MCP 8100*at Workshop m/s *Rp.*of *SHIA 988A*

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *RM 46*

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: *✓*

Consistent? : Yes or No

Est. Repairs: *10*

days

Res.: Yes or No

Lum Sum: *2*

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: *15/k*

Vehicle: IN / OUT

Date / Time

Action / Instruction

Sum insured 48/k

Veh No: *MCP 8100* Yr Regn: *10/14*
 Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: *Honda Jazz* C.O. *1497*
 Colour: *Blue* A/C: Insured / Std / NI / NA
 Sp. Reading: *93127* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *PMH GK 5890 F D 50 2061*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: *195/50 R16*
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *ZATken*Front: *6*Rear: *6*

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. *30/8/19*D.O.I. *4/9/19*

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Lf.

The U/C / Chassis frame / Body Structure affected due to collision.

16/9/19 1/5 & 15.000 confirmed with Alen. (Red: 23333.10 6596)

RECEIVED 16 SEP 2019

Date/Time, File Pass to?

☐

Preli. Report

1) *16/9 Typst.*☒

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: *10*Resurvey No. of Trip: *2*

Survey Fee: _____

Transportation: _____

Add Fee: ☐

Site Insp (\$ _____)

\$ + R\$ \$

☐

Interview (\$ _____)

Photo: *SA*☐

Tech. Invs (\$ _____)

Other: *SA*☐

Weekend (\$ _____)

TOTAL: *16/9/19*

Report Format:

Lump Sum / I.B.I. (\$ *15,000*)*33x15: 495**170+495**50**50+50**253**1068*

MOTOR SURVEY ASSIGNMENT

Date	02-09-2019	Our Ref No. D19005652MFSH
Accident Date	30-08-2019	Claim Type. Third Party
Insured Vehicle	SHA0988A	Third Party Vehicle. MCP8100
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
Contact Person.	NANCY LAM	
Contact No.	67465405/ 0	Fax No. 67458520
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FASTECH AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 5 September 2019 11:08 AM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments; SUR
Cc: 'Henry Kao'
Subject: RE: SURVEY ASSESSMENT - D19005652MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle MCP 8100 on 2/9/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 4 September 2019 1:46 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19005652MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Wednesday, 4 September, 2019 10:49 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005652MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

POLICY ENQUIRY DETAILS

POLICY DETAILS	
Policy No.	: W2209541
SST Reference No.	: SST-12-18-00710638
Cover Note No.	: JVD-6320495
Vehicle No. / Trailer No.	: MCP8100 / -
Issued Date	: 15-12-2018
Period of Cover	: From : 06-12-2018 To : 05-12-2019
Cover Note Status	: -
Submission No.	: -
JPJ Status	: -
JPJ Message	: -
Cover Note Type	: -
Agent Code / User ID	: P01100-00
Replaced by Cover Note No.	: -
Replacement of Cover Note No	: -
INSURED DETAILS	
Insured Name	: NORAZLAN BIN ABDULLAH
Insured Address	:
Post Code / Desc.	: - / -
New IC No. / Old IC No.	: 810425105671
D.O.B / Driver Age	: 25-04-1981 / 37
Occupation	: ADJUSTER
Business Reg. No.	: -
Nationality	:
GST Registered (Y/N)	: N
GST Registration No.	:
VEHICLE DETAILS	
Vehicle Type	: PRIVATE CAR EX GOODS
Coverage Type	: COMPREHENSIVE
Financial Type	: -
Loan Company	: -
Model	: HONDA JAZZ S
Variant-Series-Transmission	: S FACELIFT 5 SP AUTOMATIC
NVIC code	: I7P14A
BDM	:
BTM	:
Cubic Capacity	: 1497.00 CC
Body	: 4D HATCHBACK
Seating Capacity	: 5
Year Make	: 2014
Engine/Motor No.	: L15Z25902090
Chassis No.	: PMHKGK5890FD5020G1
Log Book No.	: -
Geographical Location	: MELAKA
Vehicle for Business use	: N

VEHICLE SCHEDULE

Vehicle Market Valuation : RM 48,000.00
 Sum Insured : RM 10,000.00
 Trailer Sum Insured : RM 0.00
 Basic Premium : RM 566.48
 Trailer Premium : RM 0.00
 All Rider : RM 0.00
 Total Basic : RM 566.48

NCD From : ETIQA TAKAFUL BHD (FORMERLY KNOWN AS TAKAFUL NASIONAL) - HQ

NCD Vehicle No : MCP8100
 NCD Policy No : -
 NCD Policy Effective Date : 08-12-2016
 NCD Policy Expiry Date : 07-12-2017
 Current NCD 55% : RM 311.56
 NCD Effective Date : 06-12-2018
 Endorsement Clause : 2

Total Extra Coverage : RM 0.00
 Gross Premium : RM 254.92
 Service Tax 6% : RM 15.30

Stamp Duty : RM 10.00
 Excess : RM 0.00

Total Payable (incl. tax) : RM 280.22
 Total Due (OTC & incl. tax) : RM 280.22

NAMED DRIVERS

No.	Name	New IC.No	Old IC.No	Age	Experience
1	THE POLICYHOLDER	810425105671	-	37	0

OPTIONAL COVER

No.	OptionalCover Details	Sum Insured	Premium
1	-	0.00	0.00

ENDORSEMENT DETAILS

No.	Type of Endorsement	Endorsement Effective Date	Additional Premium if any
1	-		-



KERAJAAN MALAYSIA
JABATAN PENGANGKUTAN JALAN MALAYSIA

No. Resit : 010401119B76147

Tarikh : 20/06/2019

Masa : 12:09:20 PM

RESIT RASMI

ASAL

Nama : NORAZLAN BIN ABDULLAH
No. Kad Pengenalan/No. Daftar Perniagaan : 810425105671
No. Pendaftaran Kenderaan : MCP8100
Alamat : BATU 27 1/2, KAMPUNG PERMATANG
KUALA SUNGAI BARU
78200 MELAKA
MELAKA MALAYSIA
Agensi : JABATAN PENGANGKUTAN JALAN MALAYSIA
Cawangan : 0104011 - JPJ NEGERI MELAKA
No. BSN : 19062001040110038204
Jenis Transaksi : SALINAN PERAKUAN PENDAFTARAN KENDERAAN

Bil.	Kod Terimaan	Kod Terimaan JPJ	No. Rujukan	Keterangan	Dari	Hingga	Amaun (RM)
1.	72404	2153050	MCP8100 (No Sekuriti: 0Gt1b6hb)	SALINAN P/PENDAF.MKR DLL	-	-	50.00
Jumlah							50.00

Bil.	Cara Bayaran	Bank	No. Transaksi
1.	TUNAI	-	-

Ringgit Malaysia : Lima Puluh Sahaja
Catatan : 0104011 N LUDDIN 0



SIJIL PEMILIKAN KENDERAAN
JABATAN PENGANGKUTAN JALAN

0GT1B6HB

No. Pendaftaran : MCP8100
No. ID : 810425105671
Nama Pemunya Berdaftar : NORAZLAN BIN ABDULLAH
Alamat : BATU 27 1/2, KAMPUNG PERMATANG KUALA SUNGAI BARU
78200 MELAKA MELAKA
No. Chasis/No. Enjin : PMHGK5890FD502061 / L15Z25902090
Buatan>Nama Model : HONDA / JAZZ 1.5L V
Keupayaan Enjin : 1497
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : PERSENDIRIAN-MOTOKAR INDIVIDU
Jenis Badan/Tahun Dibuat : MOTOKAR / 2014
Tarikh Pendaftaran : 09/10/2014
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -

[Home](#) / [Used Cars](#) / [Honda](#) / [Jazz](#) / [i-VTEC](#)

Updated on: September 01, 2019

2014 Honda Jazz 1.5 i-VTEC Hatchback

Updated on: September 01, 2019

 Dealer  Johor » Johor Bahru »

RM 603/month

RM 46,500

Seller Information

 Dealer  Johor » Johor Bahru

Key details

 Car type
Used Car Make Honda Model Jazz Variant i-VTEC Year 2014 Engine Capacity
1497 cc Transmission
Automatic Seat Capacity 5 Mileage
50000 - 55000k Colour Brown[View All 38 Cars From This](#)

Seller's comments

[Home](#) / [Used Cars](#) / [Honda](#) / [Jazz](#) / [Hybrid](#)

Updated on: August 31, 2019

RM 622/month


RM 48,000

2014 Honda Jazz 1.3 Hybrid Hatchback -- BEST DEAL --

Updated on: August 31, 2019

Dealer

Johor » Johor Bahru »



Seller Information

Dealer

Johor » Johor
Bahru

Key details

Car type	Used Car
Make	Honda
Model	Jazz
Variant	Hybrid
Year	2014
Engine Capacity	1339 cc
Transmission	Automatic
Seat Capacity	5
Mileage	50 - 55K
Colour	White

[View All 41 Cars From This](#)

ADVERTISING

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

Not Authorized
Make
4/5 @ 15,000
10 dr.

VEHICLE NO: MCP 8100

QTY	PARTICULAR	
1 PCS	REAR WINDSCREEN MOULDING	121.10
1 PCS	TAILGATE	845.50
1 PCS	TAILGATE 'H' LOGO	
1 PCS	TAILGATE 'JAZZ' EMBLEM	
1 PCS	TAILGATE 'RS' EMBLEM	
1 PCS	TAILGATE 'IVTEC' EMBLEM	
2 PCS	TAILGATE REFLECTORS @\$488.10	195.00 x 2 = 390
1 PCS	TAILGATE OUTER GARNISH	
1 PCS	TAILGATE INNER LOCK	178.20
1 PCS	TAILGATE LOCK SENSOR	
1 PCS	TAILGATE LOCK BUZZER	
1 PCS	TAILGATE INNER TRIM BORAD	450.50
1 SET	TAILGATE INNER TRIM BORAD CLIPS	
1 PCS	TAILGATE WEATHERSTRIP	
1 PCS	TAILGATE REAR WIPER MOTOR	
1 PCS	REAR BUMPER	521.30
2 PCS	REAR BUMPER SIDE RETAINERS @\$45.00	
1 SET	REAR BUMPER CLIPS	
1 PCS	REAR BUMPER lower skirting	
1 PCS	REAR BUMPER lower skirting lamp	205.00
2 PCS	REAR BUMPER REFLECTORS @\$45.00	
2 PCS	REAR BUMPER SIDE GRILLES @\$85.00	
1 PCS	REAR END PANEL	366.50
1 PCS	REAR END PANEL TOP GARNISH	158.20
1 PCS	REAR EXHAUST	
2 PCS	REAR EXHAUST MOUNTINGS @\$45.00	
2 PCS	REAR FENDERS @\$1105.10	865.30
2 PCS	REAR FENDER INNER BOARDS @\$485.0	
1 PCS	REAR FLOOR PANEL	911.40
1 PCS	REAR FLOOR PANEL TOP BOARD	520.30
2 PCS	TAILLAMPS @\$680.10	385.50 x 2 = 771
2 PCS	TAILLAMP HOUSING PANELS @\$255.00	
1 PCS	REAR SPARE TYRE [Tools sponge	
2 PCS	REAR FENDER INNER TOP SIDE GARNISH @\$145.00	
1 PCS	BONNET	665.30
1 PCS	BONNET RUBBER	
2 PCS	BONNET HINGES @\$105.00	
1 PCS	BONNET INSULATOR	
1 PCS	BONNET INSULATOR CLIPS	
1 PCS	BONNET LOCK	
1 PCS	FRONT BUMPER	566.60
2 PCS	FRONT BUMPER SIDE RETAINERS @\$45.00	
1 SET	FRONT BUMPER CLIPS	
1 PCS	FRONT BUMPER LOWER CENTRE GRILLE	
2 PCS	FRONT BUMPER FOG LAMPS @\$650.00	380 x 2 = 760

per	\$161.10	✓
body	\$1,266.30	✓
an	\$45.80	✓
an	\$48.80	✓
an	\$45.00	✓
an	\$48.50	✓
an	\$976.20	✓
an	\$385.40	✓
an	\$266.20	✓
an	\$285.50	✓
an	\$208.30	✓
an	\$650.10	✓
an	\$50.00	✓
an	\$188.20	✓
an	\$825.00	✓
an	\$845.10	✓
an	\$90.00	✓
an	\$45.00	✓
an	\$611.20	✓
an	\$288.50	✓
an	\$90.00	✓
an	\$170.00	✓
an	\$611.20	✓
an	\$298.30	✓
an	\$688.50	✓
an	\$90.00	✓
an	\$2,210.20	✓
an	\$970.00	✓
an	\$1,120.10	✓
an	\$660.50	✓
an	\$1,360.20	✓
an	\$510.00	✓
an	\$322.20	✓
an	\$290.00	✓
an	\$866.20	✓
an	\$85.00	✓
an	\$210.00	✓
an	\$245.50	✓
an	\$45.00	✓
an	\$165.00	✓
an	\$745.30	✓
an	\$90.00	✓
an	\$45.00	✓
an	\$211.20	✓
an	\$1,300.00	✓

20729.6

2072

2 PCS	FRONT BUMPER FOG LAMP COVERS @\$150.00	85 x 2 = 170
1 PCS	FRONT BUMPER REINFORCEMENT	295.30
1 PCS	FRONT GRILLE	
1 PCS	FRONT GRILLE OUTER	Garnish
1 PCS	FRONT GRILLE 'H' LOGO	
1 PCS	FRONT GRILLE CHROME MOULDING::	115.00
1 PCS	FRONT SUPPORT PANEL	664.30
1 PCS	FRONT SUPPORT PANEL TOP GARNISH	
2 PCS	HEADLAMPS \$1450.00	845.20 x 2 = 1690.40
1 PCS	AIR CON CONDENSER	866.20
1 PCS	RADIATOR	1415.30
1 PCS	RADIATOR FAN MOTOR	
1 PCS	RADIATOR FAN COWLING	
1 PCS	RADIATOR FAN BLADE	
2 PCS	FRONT FENDERS @\$611.00	
2 PCS	FRONT FENDER INNERSHIELDS @\$165.00	
1 SET	FRONT FENDER INNERSHIELD CLIPS	
1 PCS	ALTERNATOR	
1 PCS	AIR CON COMPRESSOR	
1 PCS	AIR CON SUCTION HOSE	
1 PCS	AIR CON DISCHARGE HOES	
1 PCS	AIR CON PIPE	

Del/cur	\$300.00	✓
Del	\$315.20	✓
CNE	\$385.40	✓
CNE	\$311.50	✓
net	\$38.50	✓
Sen/Net	\$220.00	✓
net	\$754.50	✓
net	\$288.20	X
CNE	\$2,900.00	✓
Sen/cur	\$1,100.20	✓
Del/cur	\$1,866.20	✓
17	\$395.00	X
17	\$145.00	X
17	\$152.00	X
17	\$1,222.00	X
17	\$330.00	X
17	\$50.00	X
17	\$1,205.00	X
17	\$1,866.10	X
17	\$325.30	X
17	\$388.20	X
17	\$195.20	X
	\$35,183.10	

1 SET	REAR BUMPER REVERSE SENSOR
1 PCS	REAR WINDSCREEN SEALANT
1 PCS	REAR END PANEL SEALANT
1 SET	REAR FLOOR PANEL INSULATOR
1 SET	REAR REVERSE CAMERA
1 PCS	REAR LICENCE PLATE W/HOLDER
1 PCS	FRONT LICENCE PLATE W/HOLDER
1 BOL	RADIATOR COOLANT

14733.5
35483.1
34871.9

should	\$280.00	200
net	\$50.00	40
net	\$50.00	✓
net	\$180.00	X
net	\$380.00	X
net	\$50.00	15
net	\$50.00	30
net	\$50.00	30

LABOUR CHARGES:

TO CHECK WIRING	\$80.00	30
TO DISMANTLE & REPLACING REVERSE SENOR	\$80.00	40
TO TRANSFER TAILGATE MECHANISM	\$120.00	60
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	60
TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY	\$150.00	80
TO MOUNT VEHICLE ON CAR-OLINER	\$380.00	X
TO REFILL AIR CON GAS	\$150.00	100
TO SPRAY RUST PROOFING	\$150.00	120
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$3,200.00	2400
TO PUTTY & SPRAY PAINTING	\$2,500.00	1900

TO \$43,333.10

43633.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

17503.2
14002.56
19287.56
4430



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19015633/Uif3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 988A	Veh. Inspected	MCP 8100	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005652MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	04/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	PMHGK5890FD502061	Colour	BLUE	
Odometer	93127	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	FALKEN	6 mm	
L/H Front Tyre	195/50 R16	FALKEN	6 mm	
R/H Rear Tyre	195/50 R16	FALKEN	6 mm	
L/H Rear Tyre	195/50 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/08/2019	Inspection Date	04/09/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. MCP 8100

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NECESSARY	161.10	121.10
1	TAILGATE	BADLY DENTED	1,266.30	845.50
1	TAILGATE "H" LOGO	NOT NECESSARY	45.80	-
1	TAILGATE "JAZZ" EMBLEM	NECESSARY	48.80	48.80
1	TAILGATE "RS" EMBLEM	NOT FITTED	45.00	-
1	TAILGATE "IVTEC" EMBLEM	NECESSARY	48.50	48.50
2	TAILGATE REFLECTORS @\$488.10	CRACKED	976.20	390.00
1	TAILGATE OUTER GARNISH	NOT NECESSARY	385.40	-
1	TAILGATE INNER LOCK	TWISTED	266.20	178.20
1	TAILGATE LOCK SENSOR	NOT NECESSARY	285.50	-
1	TAILGATE LOCK BUZZER	NOT NECESSARY	208.30	-
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	650.10	450.50
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
1	TAILGATE WEATHERSTRIP	TWISTED	188.20	188.20
1	TAILGATE REAR WIPER MOTOR	NOT NECESSARY	825.00	-
1	REAR BUMPER	DISTORTED	845.10	521.30
2	REAR BUMPER SIDE RETAINERS @\$45.00	BENT	90.00	90.00
1	SET REAR BUMPER CLIPS	NECESSARY	45.00	45.00
1	REAR BUMPER LOWER SKIRTING	DISTORTED	611.20	611.20
1	REAR BUMPER LOWER SKIRTING LAMP	CRACKED	288.50	205.00
2	REAR BUMPER REFLECTORS @\$45.00	NOT NECESSARY	90.00	-
2	REAR BUMPER SIDE GRILLES @\$85.00	NOT NECESSARY	170.00	-
1	REAR END PANEL	BADLY DENTED	611.20	366.50
1	REAR END PANEL TOP GARNISH	TWISTED	298.30	188.20
1	REAR EXHAUST	TO REPAIR SEE LABOUR	688.50	-
2	REAR EXHAUST MOUNTINGS @\$45.00	NOT NECESSARY	90.00	-
2	REAR FENDERS @\$1105.10	O/S BENT / BUCKLED / N/S TO REPAIR SEE LABOUR	2,210.20	865.30



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNER BOARDS @\$485.00	DISTORTED / CRACKED	970.00	970.00
1	REAR FLOOR PANEL	CRUMPLED / BUCKLED	1,120.10	911.40
1	REAR FLOOR PANEL TOP BOARD	TORN	660.50	520.30
2	TAILLAMPS @\$680.10	CRACKED	1,360.20	771.00
2	TAILLAMP HOUSING PANELS @\$255.00	O/S BENT	510.00	255.00
1	REAR SPARE TYRE TOOLS SPONGE	DISTORTED	322.20	322.20
2	REAR FENDER INNER TOP SIDE GARNISH @\$145.00	NOT NECESSARY	290.00	-
1	BONNET	BENT / BUCKLED	866.20	665.30
1	BONNET RUBBER	NECESSARY	85.00	85.00
2	BONNET HINGES @\$105.00	NOT NECESSARY	210.00	-
1	BONNET INSULATOR	NOT NECESSARY	245.50	-
1	BONNET INSULATOR CLIPS	NOT NECESSARY	45.00	-
1	BONNET LOCK	TWISTED	165.00	165.00
1	FRONT BUMPER	DENTED / DEFORMED	745.30	566.60
2	FRONT BUMPER SIDE RETAINERS @\$45.00	NECESSARY	90.00	90.00
1	SET FRONT BUMPER CLIPS	NECESSARY	45.00	45.00
1	FRONT BUMPER LOWER CENTRE GRILLE	TORN	211.20	211.20
2	FRONT BUMPER FOG LAMPS @\$650.00	CRACKED	1,300.00	760.00
2	FRONT BUMPER FOG LAMP COVERS @\$150.00	DEFORMED / TWISTED	300.00	170.00
1	FRONT BUMPER REINFORCEMENT	BENT	315.20	295.30
1	FRONT GRILLE	CRACKED	385.40	385.40
1	FRONT GRILLE OUTER GARNISH	CRACKED	311.50	311.50
1	FRONT GRILLE "H" LOGO	NECESSARY	38.50	38.50
1	FRONT GRILLE CHROME MOULDINGS	SCRATCHED / NECESSARY	220.00	115.00
1	FRONT SUPPORT PANEL	BENT	754.50	664.30
1	FRONT SUPPORT PANEL TOP GARNISH	NOT FITTED	288.20	-
2	HEADLAMPS @\$1450.00	CRACKED	2,900.00	1,690.40
1	AIR CON CONDENSER	BENT / PUNCTURE	1,100.20	866.20
1	RADIATOR	BENT / PUNCTURE	1,866.20	1,415.30
1	RADIATOR FAN MOTOR	NOT NECESSARY	395.00	-

Report Ref No. CS/FCI19015633/Utf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR FAN COWLING	NOT NECESSARY	145.00	-
1	RADIATOR FAN BLADE	NOT NECESSARY	152.00	-
2	FRONT FENDERS @\$611.00	TO REPAIR SEE LABOUR	1,222.00	-
2	FRONT FENDER INNERSHIELDS @\$165.00	NOT NECESSARY	330.00	-
1	SET FRONT FENDER INNERSHIELD CLIPS	NOT NECESSARY	50.00	-
1	ALTERNATOR	NOT NECESSARY	1,205.00	-
1	AIR CON COMPRESSOR	NOT NECESSARY	1,866.10	-
1	AIR CON SUCTION HOSE	NOT NECESSARY	325.30	-
1	AIR CON DISCHARGE HOES	NOT NECESSARY	388.20	-
1	AIR CON PIPE	NOT NECESSARY	195.20	-
	LESS 20% DISCOUNT		-	-3,500.64
			35,483.10	14,002.56
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT FITTED	180.00	-
1	SET REAR REVERSE CAMERA (SN)	NOT FITTED	380.00	-
1	REAR LICENCE PLATE W/HOLDER (SN)	NECESSARY	50.00	15.00
1	FRONT LICENCE PLATE W/HOLDER (SN)	BENT	50.00	30.00
1	BOL RADIATOR COOLANT (SN)	NECESSARY	50.00	30.00
			1,090.00	365.00
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO TRANSFER TAILGATE MECHANISM.		120.00	60.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX REAR EXHAUST.		100.00	60.00
	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY.		150.00	80.00
	TO MOUNT VEHICLE ON CAR-O-LINER.	NOT NECESSARY	380.00	-
	TO REFILL AIR CON GAS.		150.00	100.00
	TO SPRAY RUST PROOFING.		150.00	120.00

Report Ref No. CS/FC119015633/Utf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST,N/S REAR FENDER AND FRONT FENDERS. TO PUTTY & SPRAY PAINTING.		3,200.00	2,400.00
			2,500.00	1,900.00
			7,060.00	4,920.00
GRAND TOTAL			43,633.10	19,287.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,000.00

Report Ref No. CS/FCI19015633/Utf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.