

Your Ref : DHOM110096520909

Date: 03<sup>rd</sup> October 2019

Our Ref : CS/UOI19015641/Nvd3s2

**M/s United Overseas Insurance Ltd**

3 Anson Road #28-01

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBB 6579Z  
ACCIDENT ON 02/09/2019**

Instruction was received to inspect the vehicle Reg. No. GBB 6579Z. The inspection was conducted on 05/09/2019 at the premises of Chan Ah Sun Car Service, No. 10, Admiralty Street #01-26 North Link Building Singapore 757695.

The following vehicle information was recorded:

Registration Number	: GBB 6579Z
Make/Model	: Nissan Cabstar
Year of Registration	: 2009
Body Colour	: White
Chassis Number	: JN1SC2F24Z0801134
Engine Capacity	: 2953 cc
Speedometer Reading	: Not Available (Wiring Affected)

The vehicle sustained damages at the front portion. Engine burnt. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$ 3,000.00(est)
Less: LTA Reimbursement Value (RV)	(S\$ 272.00)
Nett Liability	<u>S\$ 2,728.00</u>

Vehicle Inspected By:



MUHD NAZRIL (NAZ)

Technical Investigator

LL.B. (Hons) London



K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.