

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Dec 2019 Edit Reg		03 Sep 2019 00:00 Edit Adj Rpt	S\$63,912.83 Edit Estimates	S\$63,912.83 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R									
Main Claimant: CHIN JIA YANG KENNETH , ID: S8609554H									
Vehicle Reg. No.:	SKE5505X	Date of Loss:	28/08/2019 19:00 - :59 [6 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19080749	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHD3661G	Policy No. (Claimant):	PNPV2019-00003385						
		Excess:							
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 13/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (27/12/2019): Alert - Adj Mandate Approved (S\$71596.73) - SKE5505X - Claim Handler: Zuhaidah B... - III_SG (06/09/2019): Alert - Adj Mandate Approved (S\$0.00) - SKE5505X - Claim Handler: Zuhaidah Bte S...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKE5505X (MCT19080749)**
[SHD3661G]
TP
CHIN JIA YANG KENNETH
Aug 28 2019 7:00PM
[COMFORT TRANSPORTATION PTE LTD]
Cycle & Carriage Industries Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images					
3 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/12/19 17:33	Chassis Number		Load JPG	
2	05/12/19 17:33	General View		Load JPG	
3	05/12/19 17:33	General View		Load JPG	
4	05/12/19 17:33	General View		Load JPG	
5	05/12/19 17:33	General View		Load JPG	
6	05/12/19 17:33	General View		Load JPG	
7	05/12/19 17:33	General View		Load JPG	
8	05/12/19 17:33	General View		Load JPG	
9	05/12/19 17:33	General View		Load JPG	
10	05/12/19 17:33	General View		Load JPG	
11	05/12/19 17:33	General View		Load JPG	
12	05/12/19 17:33	General View		Load JPG	
13	05/12/19 17:33	General View		Load JPG	
14	05/12/19 17:33	General View		Load JPG	
15	05/12/19 17:33	General View		Load JPG	
16	05/12/19 17:33	General View		Load JPG	
17	05/12/19 17:33	General View		Load JPG	
18	05/12/19 17:33	General View		Load JPG	
19	05/12/19 17:33	General View		Load JPG	
20	05/12/19 17:33	General View		Load JPG	
21	05/12/19 17:33	General View		Load JPG	
22	05/12/19 17:33	General View		Load JPG	
23	05/12/19 17:33	General View		Load JPG	
24	05/12/19 17:33	General View		Load JPG	
25	05/12/19 17:33	General View		Load JPG	
26	05/12/19 17:33	General View		Load JPG	
27	05/12/19 17:33	General View		Load JPG	
28	05/12/19 17:33	General View		Load JPG	
29	05/12/19 17:33	General View		Load JPG	
30	05/12/19 17:33	General View		Load JPG	
31	05/12/19 17:33	General View		Load JPG	
32	05/12/19 17:33	General View		Load JPG	
33	05/12/19 17:33	General View		Load JPG	
34	05/12/19 17:33	General View		Load JPG	
35	05/12/19 17:33	General View		Load JPG	
36	05/12/19 17:33	General View		Load JPG	
37	05/12/19 17:33	General View		Load JPG	
38	05/12/19 17:33	General View		Load JPG	
39	05/12/19 17:33	General View		Load JPG	
40	05/12/19 17:33	General View		Load JPG	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
41	05/12/19 17:33	General View		Load JPG	☒
42	05/12/19 17:33	General View		Load JPG	☒
43	05/12/19 17:33	General View		Load JPG	☒
44	05/12/19 17:33	General View		Load JPG	☒
45	05/12/19 17:33	General View		Load JPG	☒
46	05/12/19 17:33	General View		Load JPG	☒
47	05/12/19 17:33	General View		Load JPG	☒
48	05/12/19 17:33	General View		Load JPG	☒
49	05/12/19 17:33	General View		Load JPG	☒
50	05/12/19 17:33	General View		Load JPG	☒
51	05/12/19 17:33	General View		Load JPG	☒
52	05/12/19 17:33	General View		Load JPG	☒
53	05/12/19 17:33	General View		Load JPG	☒
54	05/12/19 17:33	General View		Load JPG	☒
55	05/12/19 17:33	General View		Load JPG	☒
56	05/12/19 17:33	General View		Load JPG	☒
57	05/12/19 17:33	General View		Load JPG	☒
58	05/12/19 17:33	General View		Load JPG	☒
59	05/12/19 17:33	General View		Load JPG	☒
60	05/12/19 17:33	General View		Load JPG	☒
61	05/12/19 17:33	General View		Load JPG	☒
62	05/12/19 17:33	General View		Load JPG	☒
63	05/12/19 17:33	General View		Load JPG	☒
64	05/12/19 17:33	General View		Load JPG	☒
65	05/12/19 17:33	General View		Load JPG	☒
66	05/12/19 17:33	General View		Load JPG	☒
67	05/12/19 17:33	General View		Load JPG	☒
68	05/12/19 17:33	General View		Load JPG	☒
69	05/12/19 17:33	General View		Load JPG	☒
70	05/12/19 17:33	General View		Load JPG	☒
71	05/12/19 17:33	General View		Load JPG	☒
72	05/12/19 17:33	General View		Load JPG	☒
73	05/12/19 17:33	General View		Load JPG	☒
74	05/12/19 17:33	General View		Load JPG	☒
75	05/12/19 17:33	General View		Load JPG	☒
76	05/12/19 17:33	General View		Load JPG	☒
77	05/12/19 17:33	General View		Load JPG	☒
78	05/12/19 17:33	General View		Load JPG	☒
79	05/12/19 17:33	General View		Load JPG	☒
80	05/12/19 17:33	General View		Load JPG	☒
81	05/12/19 17:33	General View		Load JPG	☒
82	05/12/19 17:33	General View		Load JPG	☒
83	05/12/19 17:33	General View		Load JPG	☒
84	05/12/19 17:33	General View		Load JPG	☒
85	05/12/19 17:33	General View		Load JPG	☒
86	05/12/19 17:33	General View		Load JPG	☒
87	05/12/19 17:33	General View		Load JPG	☒
88	05/12/19 17:33	General View		Load JPG	☒
89	05/12/19 17:33	General View		Load JPG	☒
90	05/12/19 17:33	General View		Load JPG	☒
91	05/12/19 17:33	General View		Load JPG	☒
92	05/12/19 17:33	General View		Load JPG	☒
93	05/12/19 17:33	General View		Load JPG	☒

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
94	05/12/19 17:33	General View		Load JPG	☒
95	05/12/19 17:33	General View		Load JPG	☒
96	05/12/19 17:33	General View		Load JPG	☒
97	05/12/19 17:33	General View		Load JPG	☒
98	05/12/19 17:33	General View		Load JPG	☒
99	05/12/19 17:33	General View		Load JPG	☒
100	05/12/19 17:33	General View		Load JPG	☒
101	05/12/19 17:33	General View		Load JPG	☒
102	05/12/19 17:33	General View		Load JPG	☒
103	05/12/19 17:33	General View		Load JPG	☒
104	05/12/19 17:33	General View		Load JPG	☒
105	05/12/19 17:33	General View		Load JPG	☒
106	05/12/19 17:33	General View		Load JPG	☒
107	05/12/19 17:33	General View		Load JPG	☒
108	05/12/19 17:33	General View		Load JPG	☒
109	05/12/19 17:33	General View		Load JPG	☒
110	05/12/19 17:33	General View		Load JPG	☒
111	05/12/19 17:33	General View		Load JPG	☒
112	05/12/19 17:33	General View		Load JPG	☒
113	05/12/19 17:33	General View		Load JPG	☒
114	05/12/19 17:33	General View		Load JPG	☒
115	05/12/19 17:33	General View		Load JPG	☒
116	05/12/19 17:33	General View		Load JPG	☒
117	05/12/19 17:33	General View		Load JPG	☒
118	05/12/19 17:33	General View		Load JPG	☒
119	05/12/19 17:33	General View		Load JPG	☒
120	05/12/19 17:33	General View		Load JPG	☒
121	05/12/19 17:33	General View		Load JPG	☒
122	05/12/19 17:33	General View		Load JPG	☒
123	05/12/19 17:33	General View		Load JPG	☒
124	05/12/19 17:33	General View		Load JPG	☒
125	05/12/19 17:33	General View		Load JPG	☒
126	05/12/19 17:33	General View		Load JPG	☒
127	05/12/19 17:33	General View		Load JPG	☒
128	05/12/19 17:33	General View		Load JPG	☒
129	05/12/19 17:33	General View		Load JPG	☒
130	05/12/19 17:34	Reinspection Photo		Load JPG	☒
131	05/12/19 17:34	Reinspection Photo		Load JPG	☒
132	05/12/19 17:34	Reinspection Photo		Load JPG	☒
133	05/12/19 17:34	Reinspection Photo		Load JPG	☒
134	05/12/19 17:34	Reinspection Photo		Load JPG	☒
135	05/12/19 17:34	Reinspection Photo		Load JPG	☒
136	05/12/19 17:34	Reinspection Photo		Load JPG	☒
137	05/12/19 17:34	Reinspection Photo		Load JPG	☒
138	05/12/19 17:34	Reinspection Photo		Load JPG	☒
139	05/12/19 17:34	Reinspection Photo		Load JPG	☒
140	05/12/19 17:34	Reinspection Photo		Load JPG	☒
141	05/12/19 17:34	Reinspection Photo		Load JPG	☒
142	05/12/19 17:34	Reinspection Photo		Load JPG	☒
143	05/12/19 17:34	Reinspection Photo		Load JPG	☒
144	05/12/19 17:34	Reinspection Photo		Load JPG	☒
145	05/12/19 17:34	Reinspection Photo		Load JPG	☒
146	05/12/19 17:34	Reinspection Photo		Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
147	05/12/19 17:34	Reinspection Photo	 Load JPG	☒
148	05/12/19 17:34	Reinspection Photo	 Load JPG	☒
149	05/12/19 17:34	Reinspection Photo	 Load JPG	☒
150	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
151	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
152	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
153	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
154	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
155	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
156	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
157	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
158	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
159	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
160	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
161	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
162	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
163	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
164	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
165	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
166	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
167	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
168	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
169	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
170	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
171	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
172	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
173	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
174	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
175	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
176	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
177	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
178	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
179	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
180	05/12/19 17:35	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/19 14:46	EMAIL DD 03092019	 Load PDF	
2	04/09/19 17:37	TP ESTIMATE- MARKED	 Load PDF	
3	04/09/19 17:37	TP GIA REPORT	 Load PDF	
4	05/12/19 17:01	LOD	 Load PDF	
5	05/12/19 17:01	RENTAL RECEIPT	 Load PDF	
6	05/12/19 17:40	PARF_COE REBATE	 Load PDF	
7	15/06/20 09:51	Authorisation to Act	 Load PDF	
8	15/06/20 09:51	DISCHARGE VOUCHER	 Load PDF	
9	15/06/20 10:08	WORKSHOP INVOICE (1)	 Load PDF	
10	15/06/20 10:08	WORKSHOP INVOICE (2)	 Load PDF	
11	15/06/20 10:08	WORKSHOP INVOICE (3)	 Load PDF	
12	15/06/20 10:09	WORKSHOP INVOICE (4)	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/09/19 09:18	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III19015642/T1PS3S2**Date:** 16/06/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SKE5505X	Insured Vehicle No :	SHD3661G
Date of Loss:	28/08/2019	Nature of Claim:	TP
		Claim No:	MCT19080749

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE5505X		
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Engine No:	27491031605743
Reg. Date:	13/02/2019 (Man. Year: 2018)	Chassis No:	WDD2050402R457056
Colour:	Grey	Odometer:	0 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	47,435.58	36,952.83	10,482.75	22.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	31,540.00	26,960.00	4,580.00	14.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	78,975.58	63,912.83	15,062.75	19.07
+ GST 7.00/7.00% (S\$)	5,528.29	4,473.90	1,054.39	19.07
Nett Amount (S\$)	84,503.87	68,386.73	16,117.14	19.07
+ Car Rental (30.0 x S\$100.00/day + 7.00% GST) (S\$)		3,210.00		
Nett Liability (S\$)		71,596.73		

INSPECTION

Date of Assignment:	03/09/2019	
Date Inspected:	03/09/2019 Inspected At:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	24.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

SPECIAL REMARKS

Market Value: \$175,000.00 (est) less LTA Rebate: \$62,340.00 (est) = Nett Value :\$112,660.00 (est)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Jun 2020)

Parts: 143 MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKE5505X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH/F HEADLAMP	Cracked	3,231.97 FS	*3,231.97 FS
2	1		*LH/F HEADLAMP CONTROL UNIT	Distorted	646.66 FS	*646.66 FS
3	1		*RADIATOR GRILLE SUPPORT	Cracked	134.39 FS	*134.39 FS
4	1		*RADIATOR GRILLE GARNISH SUPPORT	Not Necessary	174.16 FS	*- FS
5	1		*RADIATOR GRILLE TOP LEFT GARNISH	Cracked	65.91 FS	*65.91 FS
6	1		*RADIATOR GRILLE TOP RIGHT GARNISH	Not Necessary	65.91 FS	*- FS
7	1		*RADIATOR GRILLE BOTTOM LEFT GARNISH	Not Necessary	81.43 FS	*- FS
8	1		*RADIATOR GRILLE BOTTOM RIGHT GARNISH	Not Necessary	81.43 FS	*- FS
9	1		*BONNET	Bent	2,083.09 FS	*2,083.09 FS
10	1		*BONNET INSULATION	Deformed	238.78 FS	*238.78 FS
11	1		*BONNET LEFT HINGE	Not Necessary	189.58 FS	*- FS
12	1		*BONNET RIGHT HINGE	Not Necessary	189.58 FS	*- FS
13	2		*BONNET ACTUATOR	Not Necessary	378.42 FS	*- FS
14	2		*BONNET SPRING ELEMENT	Bent	66.04 FS	*66.04 FS
15	1		*BONNET UPPER CATCH	Bent	34.18 FS	*34.18 FS
16	1		*BONNET LOWER CATCH	Bent	68.26 FS	*68.26 FS
17	1		*LH/F FENDER	Bent	909.44 FS	*909.44 FS
18	1		*RH/F FENDER	Repair	909.44 FS	*- FS
19	1		*LH/F WHEEL ARCH	Torn	124.78 FS	*124.78 FS
20	1		*FRT BUMPER	Dented	1,557.32 FS	*1,557.32 FS
21	1		*LH/F BUMPER BRACKET	Deformed	12.19 FS	*12.19 FS
22	1		*LH/F BOTTOM GRILLE	Deformed	64.78 FS	*64.78 FS
23	1		*FRT BUMPER TOP SEAL	Necessary	27.55 FS	*27.55 FS
24	1		*CT/F BOTTOM GARNISH	Not Necessary	172.46 FS	*- FS
25	2		*LH/F PARKING SENSOR	Not Necessary	352.22 FS	*- FS
26	2		*LH/F PARKING SENSOR SEAL	Not Necessary	12.70 FS	*- FS
27	1		*LH/F BASIC CARRIER FRO BUMPER	Deformed	97.04 FS	*97.04 FS
28	1		*FRT BOTTOM BASIC CARRIER FOR BUMPER	Not Necessary	190.78 FS	*- FS
29	1		*FRT TP BASIC MOUNTING FOR BUMPER	Deformed	86.01 FS	*86.01 FS
30	1		*FRT IMPACT ABSORBER	Deformed	159.17 FS	*159.17 FS
31	1		*FRT PARKING SENSOR WIRING HARNESS	Not Necessary	151.64 FS	*- FS
32	1		*FRT PRESSURE SENSOR	Not Necessary	117.30 FS	*- FS
33	1		*LH/F BASIC CARRIER FOR BUMPER	Not Necessary	97.04 FS	*- FS
34	1		*LH/F SEAT BELT	Not Necessary	689.16 FS	*- FS
35	1		*RH/F SEAT BELT	Cut	689.16 FS	*689.16 FS
36	1		*LH/F SEAT BELT LOCK	Not Necessary	137.81 FS	*- FS
37	1		*RH/F SEAT BELT LOCK	Not Necessary	137.81 FS	*- FS
38	1		*LH/F SEAT BELT HEIGHT ADJUSTMENT	Not Necessary	107.15 FS	*- FS
39	1		*RH/F SEAT BELT HEIGHT ADJUSTMENT	Not Necessary	107.15 FS	*- FS
40	1		*LH/R SEAT BELT	Activated	413.57 FS	*413.57 FS
41	1		*RH/R SEAT BELT	Activated	413.57 FS	*413.57 FS
42	1		*REAR WINDSHIELD	Necessary	1,094.09 FS	*1,094.09 FS
43	4		*REAR WINDSHIELD PAD	Not Necessary	10.04 FS	*- FS
44	1		*GLAZING REPAIR KIT 5pcs	Necessary 1pc Only	784.15 FS	*156.83 FS
45	1		*ADHESIVE SEALANT 3pcs	Necessary 2pcs Only	2,330.43 FS	*1,553.62 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*SRS CONTROL UNIT	Necessary	933.06 FS	*933.06 FS
47	2		*SRS ACCELERATION SENSOR	Distorted	273.56 FS	*273.56 FS
48	1		*LH/R EXHAUST MUFFLER	Not Necessary	1,379.92 FS	*- FS
49	1		*RH/R EXHAUST MUFFLER	Not Necessary	1,180.45 FS	*- FS
50	1		*LH/R EXHAUST MUFFLER BRACKET	Not Necessary	119.37 FS	*- FS
51	1		*LH/R EXHAUST MUFFLER INNER SHIELDING	Bent	167.85 FS	*167.85 FS
52	1		*LH/R EXHAUST MUFFLER OUTER SHIELDING	Not Necessary	77.97 FS	*- FS
53	1		*LH/R TAIL LAMP	Cut	702.52 FS	*702.52 FS
54	1		*RH/R TAIL LAMP	Cracked	702.52 FS	*702.52 FS
55	2		*REAR LICENCE PLATE LAMP	Not Necessary	57.68 FS	*- FS
56	1		*REAR BUMPER	Deformed	1,635.44 FS	*1,635.44 FS
57	1		*REAR BOTTOM PANEL	Deformed	258.66 FS	*258.66 FS
58	1		*REAR BOTTOM PANEL GARNISH	Cracked	291.84 FS	*291.84 FS
59	1		*LH/R BOTTOM BRACKET	Deformed	33.30 FS	*33.30 FS
60	1		*RH/R BOTTOM BRACKET	Deformed	33.96 FS	*33.96 FS
61	4		*REAR PARKING SENSOR	Not Working	704.44 FS	*704.44 FS
62	4		*REAR PARKING SENSOR SEAL	Necessary	25.40 FS	*25.40 FS
63	1		*REAR BOTTOM HANDFREE ASSIST BRACKET	Distorted	39.80 FS	*39.80 FS
64	1		*REAR BOTTOM HANDFREE ASSIST COVER	Cracked	104.89 FS	*104.89 FS
65	1		*REAR BOTTOM HANDFREE ASSIST SENSOR	Distorted	133.40 FS	*133.40 FS
66	1		*REAR HANDFREE ASSIST CODE A WIRE	Distorted	122.99 FS	*122.99 FS
67	1		*REAR HANDFREE ASSIST CODE B WIRE	Distorted	122.99 FS	*122.99 FS
68	1		*REAR PARKING SENSOR WIRING HARNESS	Not Necessary	130.18 FS	*- FS
69	1		*CT/R BASIC MOUNTING FOR BUMPER	Deformed	91.92 FS	*91.92 FS
70	1		*LH/R BASIC MOUNTING FOR BUMPER	Necessary	56.64 FS	*56.64 FS
71	1		*RH/R BASIC MOUNTING FOR BUMPER	Necessary	56.64 FS	*56.64 FS
72	1		*LH/R TOP BASIC MOUNTING FOR BUMPER	Distorted	32.64 FS	*32.64 FS
73	1		*RH/R TOP BASIC MOUNTING FOR BUMPER	Distorted	32.14 FS	*32.14 FS
74	1		*LH/R BUMPER SIDE BRACKET	Necessary	55.82 FS	*55.82 FS
75	1		*RH/R BUMPER SIDE STABILITY	Necessary	56.01 FS	*56.01 FS
76	1		*REAR BOOT LID	Bent	2,127.67 FS	*2,127.67 FS
77	1		*REAR BOOT LID SEAL	Deformed	195.71 FS	*195.71 FS
78	1		*REAR BOOT LID INNER TRIM	Deformed	231.33 FS	*231.33 FS
79	1		*REAR BOOT LID CLOSING ASSIST DRIVE UNIT	Not Necessary	940.97 FS	*- FS
80	1		*LH/R BOOT LID HINGE LEVER	Bent	249.05 FS	*249.05 FS
81	1		*RH/R BOOT LID HINGE LEVER	Bent	249.05 FS	*249.05 FS
82	1		*LH/R BOOT LID DRIVE UNIT BRACKET	Not Necessary	81.77 FS	*- FS
83	1		*REAR BOOT LID GARNISH	Deformed	132.35 FS	*132.35 FS
84	1		*C180 EMBLEM	Necessary	89.09 FS	*89.09 FS
85	1		*REAR STAR EMBLEM	Necessary	47.69 FS	*47.69 FS
86	3		*GROMMET	Necessary	6.60 FS	*6.60 FS
87	1		*REAR BOOT LID HANDLE MOLDING	Deformed	208.53 FS	*208.53 FS
88	1		*REAR BOOT LID LOCK	Bent	287.44 FS	*287.44 FS
89	1		*REAR BOOT LID U-SHAPED STRIKER	Bent	465.12 FS	*465.12 FS
90	1		*REAR BOOT LID U-SHAPED STRIKER DRIVE	Not Necessary	173.56 FS	*- FS
91	1		*REAR CROSS MEMBER	Bent	651.93 FS	*651.93 FS
92	1		*REAR SPARE WHEEL WELL	Cracked	538.00 FS	*538.00 FS
93	1		*REAR SPARE WHEEL WELL BOTTOM COVER	Cracked	41.34 FS	*41.34 FS
94	1		*LOADING EDGE PANEL	Deformed	131.12 FS	*131.12 FS
95	1		*LH/R BOOT LID COMPARTMENT SIDE TRIM	Deformed	48.94 FS	*48.94 FS
96	1		*RH/R BOOT LID COMPARTMENT SIDE TRIM	Deformed	48.94 FS	*48.94 FS
97	1		*REAR BOOT LID COMPARTMENT FLOOR BOARD	Deformed	366.82 FS	*151.64 FS
98	1		*REAR END PANEL	Bent	1,414.23 FS	*1,414.23 FS
99	1		*LH/R FENDER	Bent	2,196.72 FS	*2,196.72 FS
100	1		*RH/R FENDER	Bent	2,196.72 FS	*2,196.72 FS
101	2		*REAR FENDER INSULATION	Necessary	118.68 FS	*118.68 FS
102	2		*REAR FENDER AIR FLAP	Necessary	51.58 FS	*51.58 FS
103	1		*LH/R WHEEL ARCH	Not Necessary	184.18 FS	*- FS
104	1		*RH/R WHEEL ARCH	Not Necessary	184.18 FS	*- FS
105	1		*REAR WINDSHIELD SOLAR FILM	Necessary	300.00 FS	*300.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
106	1	*REG. PLATE WITH HOUSING	Bent	60.00 FS	*60.00 FS
107	1	*FRT CROSS MEMEBER	Bent	423.49 FS	*423.49 FS
108	1	*LH/F CROSS MEMBER BRACKET	Bent	73.35 FS	*73.35 FS
109	1	*FRT END SUPPORT MEMBER	Bent	718.12 FS	*718.12 FS
110	1	*LH/F CROSS MEMBER ABSORBER	Deformed	202.53 FS	*202.53 FS
111	1	*FRT CONSOLE	Distorted	209.91 FS	*209.91 FS
112	1	*FRT CROSS MEMBER STRUT	Bent	46.46 FS	*46.46 FS
113	1	*BONNET LATCH SWITCH	Distorted	42.00 FS	*42.00 FS
114	4	*NUT	Necessary	21.48 F	*21.48 F
115	1	*FRT AIR DUCT	Deformed	127.48 F	*127.48 F
116	1	*LEFT ROOF MOULDING	Deformed	177.11 F	*177.11 F
117	1	*LH/R EXHAUST TAIL PIPE BRACKET	Bent	97.89 F	*97.89 F
118	2	*PLUG	Necessary	10.12 F	*10.12 F
119	1	*REAR BOOT COMPARTMENT END FLOOR HOLDER	Deformed	104.77 F	*104.77 F
120	1	*RH/R WHEEL HOUSE STRUT	Bent	113.03 F	*113.03 F
121	1	*REAR END FLOOR SUPPORT PANEL	Buckled	696.83 F	*696.83 F
122	1	*RH/R WHEEL HOUSE STRIKER PLATE	Bent	275.00 F	*275.00 F
123	2	*TWO-COMPONENT ADHESIVE	Necessary	204.00 F	*204.00 F
124	2	*SEAM SEAL	Necessary	209.98 F	*209.98 F
125	12	*BLIND RIVET	Necessary	15.48 F	*15.48 F
126	4	*BLIND RIVET W CSK. HEAD	Necessary	7.52 F	*7.52 F
127	15	*RIVET	Necessary	85.35 F	*85.35 F
128	7	*RIVET	Necessary	31.01 F	*31.01 F
129	5	*HEXAGON NUT W COLLAR	Necessary	12.55 F	*12.55 F
130	2	*PIN	Necessary	2.46 F	*2.46 F
131	2	*RUBBER PLUG	Necessary	23.06 F	*23.06 F
132	2	*RETAINER WEDGE	Necessary	21.18 F	*21.18 F
133	1	*SCREW	Necessary	2.51 F	*2.51 F
134	3	*SEAL RING	Necessary	7.53 F	*7.53 F
135	1	*REAR BOOT COMPARTMENT FLOOR INSULATION	Necessary	108.00 FS	*108.00 FS
136	1	*RELAY FUSE	Necessary	36.85 FS	*36.85 FS
137	2	*CLIP	Necessary	9.48 FS	*9.48 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 47,435.58 36,952.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.	New	380.00	380.00
2	CHECK HEADLAMP WITH FOCUS ADJUSTMENT.	New	120.00	120.00
3	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.	New	120.00	120.00
4	REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR REPL.	New	300.00	240.00
5	REMOVE & REPLACE EXHAUST SYSTEM MUFFLER.	New	300.00	240.00
6	RENEW REAR WINDSHIELD.	New	560.00	560.00
7	REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR.	New	1,440.00	960.00
8	TO SEAL PANEL JOINTS WITH SEALANT.	New	120.00	120.00
9	REMOVE & REPLACE DRIVER AND PASSENGER AIRBAG AND SAFETY BELT, RESET WITH PROGRAMMING.	New	2,400.00	1,920.00
10	REMOVE & INSTALL REAR SUSPENSION & WHEEL BASE.	New	2,400.00	1,920.00
11	PLACE VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS & STRUCTURE ALIGNMENT.	New	1,000.00	1,000.00
12	INSPECT & CONDUCT WHEEL ALIGNMENT.	New	540.00	540.00
13	REMOVE & REPLACE FRONT BUMPER, FRONT BONNET, FRONT LEFT FENDER, REAR BUMPER, REAR BOOT LID, REAR LEFT FENDER, REAR RIGHT FENDER, REAR END PANEL & REAR FRONT AND REAR SUPPORT ASSY COMPONENTS & REFINISH.	New	15,360.00	13,440.00
14	RESPRAY BUMPER, FRONT BONNET, FRONT LEFT FENDER, FRONT RIGHT FENDER, FRONT LEFT DOOR, REAR BUMPER, REAR BOOT LID, REAR LEFT FENDER, REAR RIGHT FENDER & REAR END PANEL.	New	6,500.00	5,400.00
Gross Labour Cost (\$)			31,540.00	26,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >