

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT 64 CECIL STREET #04/#05 IOB BUILDING SINGAPORE 049711 63476100

Industries Pte Limited **Authorised Dealer** Company No. 196400367W GST Reg No. MR-8500111-X Vehicle & Document Information

WIP No 36672

305 / Alan Quek Ai Lun

PHOTO BEFORE PAINT

Reg No/Reg Date

SKE5505X / 13/02/2019

Date In/Mileage Chassis No

0

MDD2050402R4570561 27491031605743

Engine No Make/Model Colour/Trim

MB/MB C 180 AVANTGARDE/AVANTGARDE 029 992 Selenite Gr/ 041 138 ARTICO Magm

Cycle & Carriage

Account No Terms Date/Time Printed CSE Operator WI000576 02/09/2019/ 23:04

Description of Goods / Services

AQ

Qty

QC

PB

Unit Price Disc%

0.10

0.07

Sale

Amount

380.00

120.00 a

120.00

560.00

120.00

60.00

240 300.00

240 300.00

new 300.00

1440.00

M_BPNSUN C TOTACO DATE : PEO19 0003380 PC -0 CO FEET CLA DATE IN/DATE SURVEY:

BY/AUTHRIZED ON A BPILAB

Credit

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS NETT

A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT. NETT

A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY

A BPILAB REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR REPL

REMOVE & REPLACE EXHAUST

A BPILAB RENEW REAR WINDSHIELD

S BPNSUB SUPPLY 1PC REAR WINDSHIELD SOLAR FILM PURCHASE ORDER NO:

A BPILAB REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR BPILAB

TO SEAL PANEL JOINTS WITH SEALENT

SUPPLY 1 PC REG. PLATE WITH HOUSING. NETT PURCHASE ORDER NO:

A BPILAB REMOVE & REPLACE DRIVER AND PASSENGER AIRBAG AND SAFETY BELT , RESET WITH REPROGRAMMING.

A BPILAB

2400.00 41 0 2400.00

Confirmed & accepted by


Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer 9

o signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally wors or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur,

we would advise you. Please be infermed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or chaque. You must also agree to pay full amount for renewal of the windscreen in the ovent of inadvertent breakage in the course of renewing the rubber seal or other requiring the removal of the windscreen. Pandan Loop Service Center

188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT 64 CECIL STREET #04/#05 IOB BUILDING SINGAPORE 049711 63476100

Vehicle & Document Information

36672

/ 13/02/2019 Reg No/Reg Date SKE5505X

Date In/Mileage

WIP No

Chassis No WDD2050402R4570561 27491031605743

Engine No

MB/MB C 180 AVANTGARDE/AVANTGARDE 029 992 Selenite Gr/ 041 138 ARTICO Magm

Unit Price

Disc%

0.00

3231.97 00.00

909.44 00.00

909.44 00.00

Amount

12440 15360.00

400/

dv 5 (2) 3231.97

540.00

6500.00

of the transfer of the transfe

Make/Model

Colour/Trim

Date/Time Printed CSE Operator

WI000576 Credit 02/09/2019/ 23:04 AO 305 / Alan Quek Ai Lun

Description of Goods / Services Qty REMOVE & INSTALL REAR SUSPENSION & WHEEL BASE TAXIN PLACE VEHT

A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT A BPILAB

REMOVE & REPLACE FRONT BUMPER, FRONT BONNET, FRONT LEFT FENDER, REAR BUMPER, REAR BOOT LID, REAR LEFT FENDER, REAR RIGHT FENDER, REAR END PANEL & REAR FRONT AND REAR SUPPORT ASSY COMPONENTS & REFINISH.

A BPIRES

Terms

Account No

RESPRAYFRONT BUMPER, FRONT BONNET, FRONT LEFT FENDE FRONT RIGHT FENDER, FRONT LEFT DOOR, REAR BUMPE REAR BOOT LID, REAR LEFT FENDER, REAR RIGHT FENDER & REAR END PANEL

LH/F HEADLAMP M LH/F HEADLAMP CONTROL UNI RADIATOR GRILLE SUPPORT RADIATOR GRILLE GARNISH SURPORT RADIATOR GRILLE TOP LEFT GARNESE RADIATOR GRILLE TOP RIGHT GARNISH M

RADIATOR GRILLE BOTTOM LEFT GARNISH RADIATOR GRILLE BOTTOM RIGHT GARNISH BONNET BONNET INSULATION

BONNET LEFT HINGE BONNET RIGHT HINGE BONNET ACTUATOR M BONNET SPRING ELEMENT

BONNET UPPER CATCH BONNET LOWER CATCH LH/F FENDER

1.00 646.66 00.00 1.00 134.39 00.00 174.16 00.00 1.00 65.91 1.00 00.00 65.91 00.00 1.00 81.43 00.00 1.00 81.43 00.00 1.00 2083.09 00.00 1.00 238.78 00.00 1.00 189.58 00.00 1.00 189.58 00.00 1.00 2.00 189.21 00.00 33.02 00.00 2.00 1.00 34.18 00.00 1.00 68.26 00.00

1.00

1.00

1.00

3231.97 645.66.66 6134.39 174.16 65.91 65.91 181.43 17.81.43 17.81.43 238.78 ? 189.58 189.58 X 378.42 -66.04 34.18 68.26 909.44 -909.44 X R


Confirmed & accepted by

RH/F FENDER

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mantion that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worm or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or me. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111 X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT 64 CECIL STREET #04/#05 IOB BUILDING SINGAPORE 049711 63476100

Terms

Account No

Date/Time Printed

WIP No

Reg No/Reg Date Date In/Mileage

Chassis No

Make/Model

Engine No

Colour/Trim

CSE

Operator

Vehicle & Document Information

36672

SKE5505X / 13/02/2019

WDD2050402R457056

27491031605743

MB/MB C 180 AVANTGARDE/AVANTGARDE 029 992 Selenite Gr/ 041 138 ARTICO Magm

| WI000576 | Credit | 02/09/2019/ 23: | 04 AQ | 305 | / Alan Quek | Ai Lun | | | |
|----------------------|------------------------------|------------------|-------------|----------------|-------------|--------------|------------------|-------|--------------|
| | | Description of | Goods / Sen | vices | | Qty | Unit Price | Disc% | Amount |
| M_LH/E W | EEL ARCH | | A 10 11 | | | 1.00 | 124.78 | 00.00 | 124.78 |
| M FRI BU | PER I | NOT | AN | | | 1.00 | 12.19 | 00.00 | 133 |
| ME DH/FE B | MPER BRANKE | | | | 51 -65 10 M | 1.00 | 64.78 | 00.00 | 64.78 |
| | TTOM GRILLE | | | | | 1.00 | | 00.00 | ne 27.55 |
| | PER TOP SEA | | | | | 1.00 | 172.46 | | × 172.46 |
| | TTOM GARNIS | | | | | 1300 | 176.11 | | 7 352 22 |
| | ARKING SENSO ARKING SENSO | | | | | 12.00 | | 00.00 | 12.70 |
| | SIC CARRIER | | | | ~ | 1.00 | 97.04 | 00.00 | 4 97.04 |
| | | ARRIER FOR BUMPE | P | | 111 | 1100 | 190.78 | 00.00 | 7 190.78⊀ |
| | | TING FOR BUMPER | | | U 117 | 100 | | 00.00 | de 2 86.01 |
| *** (DISTRICT OF TAX | ACT ABSORBE | | | 7 | INI | 1.00 | 159.17 | 00.00 | all 159.17 |
| | | WIRING HARNESS | | 21111 | 11/11/ | 1.00 | 151.64 | 00.00 | 7 151.64 |
| | SSURE SENSO | | | C 1111 | 610- | 1.00 | 117.30 | | 117.30 |
| | SIC CARRIER | | | $A = H \cup H$ | | 1.00 | | 00.00 | 97.04 |
| | AT BELT | 1 | | 11 0. | | 1.00 | 689.16 | | 689.16 3 |
| | AT BELT | | | U | | 1.00 | 689.16 | | cut 689.16 |
| | AT BELT LOC | x ID | الب | | | 1.00 | 137.81 | | 137.81 |
| | AT BELT LOC | | | | | 1.00 | 137.81 | | 7 137.81 |
| M LH/F S | AT BELT HEI | GHT ADJUSTMENT | | | | 1.00 | 107.15 | | 107.15 |
| M RH/F S | AT BELT HEI | GHT ADJUSTMENT | | | | 1.00 | 107.15 | | 107.15 |
| M LH/R S | AT BELT | | | | | 1.00 | 413.57 | 00.00 | 413.57 |
| M RH/R S | AT BELT | | | | | 1.00 | 413.57 | 00.00 | 413.57 |
| | NDSHIELD | | | | | 1.00 | 1094.09 | 00.00 | 1094.09 |
| | NDSHIELD PA | D | | | | 4.00 | | 00.00 | 10.04 XV |
| | REPAIR KIT | | | | | _5.00 | 156.83 776.81 | | NY 2330.4315 |
| M ADHESI | E SEALANT | | | | | 3.00 2 | 933.06 | | NC 933.06 |
| M SRS CO | TROL UNIT | | | | | 1.00 2.00 | 136.78 | | 745/273.56 |
| M SRS AC | ELERATION SI | ENSOR | | | | 1.00 | 1379.92 | | 7 1379.927 |
| M LH/R E | HAUST MUFFLE | ER | | | | 1.00 | 1180.45 | | × 1180.45 |
| M RH/R E | HAUST MUFFLE | ER | | | | 1.00 | 119.37 | | 7 119.37 |
| M IH/R F | HAUST MUFFLE | ER BRACKET | | | | 1.00 | 167.85 | | 7. 167.85 |
| M LH/R E | HAUST MUFFLE | ER INNER SHIELDI | NG | | | 1.00 | 107.03 | 00.00 | H 101.03 |


Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worm or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50k of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or change. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





Cycle & Carriage Industries Pte Limited **Authorised Dealer** Company No. 196400367W GST Reg No. MR-8500111 X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT 64 CECIL STREET #04/#05 IOB BUILDING SINGAPORE 049711 63476100

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No Engine No

Make/Model Colour/Trim

Vehicle & Document Information

36672

/ 13/02/2019 SKE5505X

WDD2050402R4570561

27491031605743

MB/MB C 180 AVANTGARDE/AVANTGARDE 029 992 Selenite Gr/ 041 138 ARTICO Magm

| ccount N | o Terma | Date/Time Prin | ited | CSE | | Operator | | | | | | ATTLE OF SE | Water the same |
|---|--------------------------------|----------------|-----------|------------|------|---------------|---------|--------------|--------|------------|--|-------------|--------------------|
| 1000576 | Credit | 02/09/2019/ | 23:04 | AQ | | 305 / A1 | an Quek | Ai Lun | | | | | |
| | | Descriptio | n of Good | is / Servi | ces | | | Q | ty | Unit Price | Disc% | Ą | nount |
| LLH/R | EXHAUST MUEEL | NO THE SHIP | LDING_ | 6 6 | - | A 18 18 18 00 | | 1.(| 0 | | 00.00 | F. E | 77.97 |
| LHA | AGELAND | NO | ΓΔ | N | OF | | | 1. | 0 | 02.52 | 00.00 | | 702-52 |
| 程 開/報 | MASUR AND | 140 | | 118 | | | | M Messes 1.0 | 10 # V | NO2.52 | 00.00 | 7 | 67.60 |
| | LICENSE PLATE | LAMP | | | | | | 2.0 | | 28.84 | 00.00 | de- | 57.68 1 1635.44 |
| 100000000000000000000000000000000000000 | BUMPER | | | | | | | 1.0 | | 1635.44 | 00.00 | 20- | 258.66 |
| | BOTTOM PANEL | | | | | | | | 0 | 258.66 | 00.00 | 09- | 291.84 |
| | BOTTOM PANEL | | | | | | | | 9 | 291.84 | | Le | 33.30 |
| | BOTTOM BRACKE | | | | | | | 51.0 | | 33.30 | 00.00 | Il - | 33.96 |
| | BOTTOM BRACKE | | | | | | 1 | 14.0 | 0/1 | 176.11 | | Inn | 704.44 |
| | PARKING SENSO | | | | | 0 | 11/ | 1 12 | | | 00.00 | ue - | 25.40 |
| | PARKING SENSO | | | | | 1111 | 16 | J 1.0 | | | 00.00 | dis- | 39.80 |
| | BOTTOM HANDER | | | | 117- | MIL | IIT | 1.0 | | 104.89 | 00.00 | cu- | 104.89 |
| | BOTTOM HANDER | | | | >11 | MALL | 70 | 1.0 | 0 | 133.40 | | Ris - | 133.40 |
| | BOTTOM HANDER | | | 1 | 11 | IIV | | 1.0 | | 122.99 | | 049. | 122.99 |
| | HANDFREE ASSI | | | 2 1 | 1 1 | 10 | | 1.0 | | 122.99 | 00.00 | Di. | 122.99 |
| REAR | HANDFREE ASSI | 21 CORE D MA | E10- | 7 | 11 . | | | 1.0 | | 130.18 | 00.00 | 7 | 130.18 |
| REAR | PARKING SENSO BASIC MOUNTIN | K MIKING DAK | TESS. | 7) | • | | | 1.0 | | 91.92 | Company of the later of the lat | 41 | 91.92 |
| CI/R | BASIC MOUNTIN | C LOW DAMES | - | | | | | 1.0 | | 56.64 | 00.00 | res | 56.64 |
| LH/R | BASIC MOUNTIN | C COD BINETER | _ | | | | | 1.0 | | 56.64 | 00.00 | ne- | 56.64 |
| | TOP BASIC MOU | | | | | | | 1.0 | | 32.64 | 00.00 | dis | 32.64 |
| LH/R | TOP BASIC MOU | NTING FOR BUR | IDED | | | | | 1.0 | | 32.14 | 00.00 | dix | 32.14 |
| KH/K | BUMPER SIDE B | DACKET | | | | | | 1.0 | | 55.82 | 00.00 | na | 55.82 |
| LU/K | BUMPER SIDE S | TARII ITY | | | | | | 1.0 | | | 00.00 | all | 56.01 |
| | BOOT LID | TOPICALI | | | | | *6 | 1.0 | | 2127.67 | 00.00 | ht- | 2127.67 |
| | BOOT LID SEAL | | | | | | | 1.0 | | 195.71 | 00.00 | de | 195.71 |
| | BOOT LID INNE | R TRIM | | | | | | 1.0 | | 231.33 | 00.00 | de | 231.33 |
| | BOOT LID CLOS | | RIVE UNI | T | | | | 1.0 | | 940.97 | 00.00 | 7 - | 940.97 |
| I H /D | BOOT LID HING | F LEVER | | | | | | 1.0 | 0 | 249.05 | 00.00 | bt. | 249.05 |
| DH/D | BOOT LID HING | E LEVER | | | | | | 1.0 | 0 | 249.05 | 00.00 | SF. | 249.05 |
| CAN I | BOOT LID DRIV | E UNIT BRACKE | T | | | | | 1.0 | | 81.77 | 00.00 | , , | 81.77 |
| DEAD | BOOT LID GARN | ISH | | | | | | 1.0 | 0 | 132.35 | 00.00 | do- | 132.35 |
| | EMBLEM | | | | | | 8 | 1.0 | 0 | 89.09 | 00.00 | we- | 89.09 |


Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Extinated costs quanted are excluding \$57. We would mention that the above extinate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally wore or damaged parts are discovered after work has started and mended for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of SQI of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or me. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seel or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT 64 CECIL STREET #04/#05 IOB BUILDING SINGAPORE 049711 63476100

Date/Time Printed

Terms

Account No

Vehicle & Document Information WIP No 36672

SKE5505X

2.00

1.00

1.00

/ 13/02/2019

Reg No/Reg Date Date In/Mileage

WDD2050402R457056

Chassis No Engine No

27491031605743

Make/Model Colour/Trim

Operator

CSF

MB/MB C 180 AVANTGARDE/AVANTGARDE

029 992 Selenite Gr/ 041 138 ARTICO Magm

WI000576 Credit 02/09/2019/ 23:04 A0 305 / Alan Quek Ai Lun Unit Price Disc% Amount Description of Goods / Services Qty 00.00 47 69 REAR STAR EMBLEM AN OFFICIA 2.20 60.00 287.44 1.00 287.44 00.00 REAR BOOT LID LOCK 1.00 465.12 00.00 465.12 REAR BOOT LID U-SHAPED STRIKER 173.56247 REAR BOOT LID U-SHAPED STRIKER DRIVE 173.56 00.00 651.93 00.00 651.93 REAR CROSS MEMBER REAR SPARE WHEEL WELL - 1 hoto. 1.00 538.00 00.00 538.00 / and 41.34 41.34 00.00 REAR SPARE WHEEL WELL BOTTOM COVER .00 100 131.12 131.12 00.00 LOADING EDGE PANEL 20 48.94 00 LH/R BOOT LID COMPARTMENT SIDE TRIM 48.94 00.00 48.94 1.00 48.94 00.00 RH/R BOOT LID COMPARTMENT SIDE TRIM 366.82×45 366.82 00.00 REAR BOOT LID COMPARTMENT FLOOR BOARD 1.00 1414.23 1414.23 00.00 1.00 REAR END PANEL 1.00 2196.72 00.00 be 2196.72 LH/R FENDER 2196.72 1.00 2196.72 00.00 RH/R FENDER 59.34 00.00 118.68 2.00 REAR FENDER INSULATION 51.58

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed Alka october by Repairer

REAR FENDER AIR FLAP

LH/R WHEEL ARCH

RH/R WHEEL ARCH

Signature:

Date:

Alan Quek

Cycle & Carriage Industries Pte Ltd Body Care & Repair Center DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272

Email: alan.mek@ovelecerriage.com.sg

78925.580

Nett 7% GST on 74859.05 74.859.05 5240.13

184.184

184.18K AM

Total Pavable

25.79 00.00

184.18 00.00

184.18 00.00

80,099,18

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worm or demaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 w.mercedes-benz.com.sg