

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19015650/APS3N2

Date: 21/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : XD3817K	Insured Vehicle No :	SH7215J
Date of Loss: 30/08/2019	Nature of Claim: TP	Claim No: MCT19080775

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD3817K	Engine No:	E13CUN15015
Make & Model:	HINO FS1ETKA, 12.9 D (M)	Chassis No:	JHDFS1ETKXXX12004
Reg. Date:	22/09/2009 (Man. Year: 2009)	Odometer:	229554 km
Colour:	Yellow		
Engine Capacity:	12913 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Indforce 6 mm	Rear Left Side:	Indforce 6 mm
Front Right Side:	Indforce 6 mm	Rear Right Side:	Indforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,300.00	10,954.80	4,345.20	28.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	2,250.00	1,330.00	37.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,880.00	13,204.80	5,675.20	30.06
Approved Total (Overridden) (\$\$)		10,000.00		
Nett Amount (\$\$)	18,880.00	10,000.00	8,880.00	47.03
+ Loss of Use (7.0 x S\$150.00/day) (\$\$)		1,050.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		11,057.45		

INSPECTION

Date of Assignment:	03/09/2019	
Date Inspected:	03/09/2019 Inspected At:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Apr 2020)	
Parts:	N/A	HINO FS1ETKA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD3817K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,908.00 F	*1,908.00 FL
2	1		*FRONT BUMPER LOWER GARNISH	Deformed	588.00 F	*588.00 FL
3	1		*FRONT R/H BUMPER APRON PANEL	Distorted	358.00 F	*358.00 FL
4	1		*FRONT BUMPER INNER FRAME	Not Necessary	835.00 F	*- FL
5	1		*FRONT R/H BUMPER SIDE GARNISH (BLACK)	Missing	205.00 F	*205.00 FL
6	1		*FRONT GRILLE LOWER	Not Necessary	485.00 F	*- FL
7	1		*FRONT R/H HEADLAMP	Cracked	1,980.00 F	*1,980.00 FL
8	1		*FRONT R/H HEADLAMP BRACKET	Cracked	388.00 F	*388.00 FL
9	1		*FRONT R/H SIGNAL LAMP	Cracked	335.00 F	*335.00 FL
10	1		*FRON R/H CORNER PANEL	Cracked	650.00 F	*650.00 FL
11	1		*FRON R/H CORNER PANEL INNER RUBBER	Not Necessary	85.00 F	*- FL
12	1		*FRONT R/H DOOR	Distorted	3,850.00 F	*3,850.00 FL
13	1		*FRONT R/H DOOR LOWER COVER	Cracked	535.00 F	*535.00 FL
14	1		*FRONT R/H DOOR EURO4 LOGO	Necessary	60.00 F	*60.00 FL
15	1		*FRONT R/H DOOR SIGNAL LAMP	Not Necessary	158.00 F	*- FL
16	1		*FRONT R/H DOOR HINGE LOWER	Not Necessary	125.00 F	*- FL
17	1		*FRONT R/H DOOR WEATHERSTRIP	Not Necessary	385.00 F	*- FL
18	1		*FRONT R/H UPPER STEP BOARD	Not Necessary	395.00 F	*- FL
19	1		*FRONT R/H UPPER STEP GARNISH	Cracked	645.00 F	*645.00 FL
20	1		*FRONT R/H LOWER STEP BOARD	Not Necessary	395.00 F	*- FL
21	1		*FRONT R/H LOWER STEP GARNISH	Deformed	670.00 F	*670.00 FL
22	1		*FRONT R/H LOWER STEP GARNISH REFLECTOR	Not Necessary	35.00 F	*- FL
23	1		*FRONT R/H LOWER STEP GARNISH LAMP	Not Necessary	230.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	15,300.00	12,172.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,217.20
Total Parts (\$\$)	15,300.00	10,954.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT FRONT R/H DOOR & COMPONENTS	New	280.00	120.00
2	TO CHECK WIRING	New	100.00	50.00
3	TUFF KOTE	New	200.00	80.00
4	PANEL BEATING	New	1,200.00	800.00
5	SPRAY PAINTING	New	1,800.00	1,200.00
Gross Labour Cost (\$\$)			3,580.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >