

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19015658/R1QF3E2

Date: 05/02/2020

REFERENCE

| | | | |
|-------------------|-----------------------|------------------|---------------|
| Insured/Claimant: | JOSEPH PEH CHIN LEONG | Policy No: | 2100394198-04 |
| Date of Loss: | 02/09/2019 | Nature of Claim: | OD |
| | | Claim No: | 6404588414SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SGS2156M | | |
| Make & Model: | AUDI A4, 1.8 TFSI MU Ambition (A) | Engine No: | CJE090532 |
| Reg. Date: | 28/11/2014 (Man. Year: 2014) | Chassis No: | WAUZZZ8K8FA048868 |
| Colour: | White | Odometer: | 107946 km |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | S\$69,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 225/55 R16 | Rear Tyre Size: | 225/55 R16 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 24,133.00 | 14,305.60 | 9,827.40 | 40.72 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 10,792.00 | 6,682.00 | 4,110.00 | 38.08 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 34,925.00 | 20,987.60 | 13,937.40 | 39.91 |
| Approved Total (Overridden) (S\$) | | 16,200.00 | | |
| - Excess (S\$) | 800.00 | 800.00 | 0.00 | 0.00 |
| (S\$) | 34,125.00 | 15,400.00 | 18,725.00 | 54.87 |
| + GST 7.00/7.00% (S\$) | 2,388.75 | 1,078.00 | 1,310.75 | 54.87 |
| Nett Amount (S\$) | 36,513.75 | 16,478.00 | 20,035.75 | 54.87 |

INSPECTION

| | | |
|---------------------|------------|-----------------------------------|
| Date of Assignment: | 04/09/2019 | |
| Date Inspected: | 04/09/2019 | Inspected At: |
| | | Premium Automobiles Pte Ltd (UBI) |
| | | 24 BENOI SECTOR |
| | | SINGAPORE 629857 |

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Repair limit \$14,400.00.

Repairer agreed to repair at \$18,000.00.

Balance of \$3,600.00 will be bear by Insured and Insurance 50% each at \$1,800.00.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Torn | 2,100.00 FS | *1,680.00 FS |
| 2 | 1 | | *FRONT BUMPER FIXING PARTS | Necessary | 234.00 FS | *187.20 FS |
| 3 | 1 | | *FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE | Cracked | 207.00 FS | *165.60 FS |
| 4 | 1 | | *FRONT BUMPER GRILLE - LOWER CENTRE | Cracked | 123.00 FS | *98.00 FS |
| 5 | 1 | | *FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE | Serviceable | 177.00 FS | *- FS |
| 6 | 1 | | *RADIATOR GRILLE | Broken | 1,005.00 FS | *804.00 FS |
| 7 | 1 | | *FRONT BUMPER AIR GUIDE GRILLE - LH | Missing | 123.00 FS | *98.00 FS |
| 8 | 1 | | *FRONT BUMPER VENT GRILLE - RH | Missing | 123.00 FS | *98.00 FS |
| 9 | 2 | | *FRONT BUMPER WHEEL SPOILER - LH/RH | Scratched | 90.00 FS | *72.00 FS |
| 10 | 1 | | *FRONT BUMPER REINFORCEMENT | Bent | 802.00 FS | *641.60 FS |
| 11 | 1 | | *FRONT BUMPER FOAM FILLER PIECE | Cracked | 113.00 FS | *90.40 FS |
| 12 | 1 | | *FRONT BUMPER COVER | Serviceable | 116.00 FS | *- FS |
| 13 | 1 | | *FRONT BUMPER BRACKET - LH | Serviceable | 207.00 FS | *- FS |
| 14 | 2 | | *FRONT BUMPER SUPPORT | Serviceable | 23.00 FS | *- FS |
| 15 | 1 | | *FRONT BUMPER GUIDE SECTION - LH | Cracked | 33.00 FS | *26.08 FS |
| 16 | 1 | | *FRONT FENDER - LH | Bent | 904.00 FS | *722.80 FS |
| 17 | 1 | | *FRONT FENDER ATTACHMENT PARTS | Necessary | 52.00 FS | *41.60 FS |
| 18 | 1 | | *FRONT FENDER BRACKET - LH | Necessary | 48.00 FS | *37.92 FS |
| 19 | 1 | | *DEFORMATION ELEMENT BRACKET - REAR LH | Serviceable | 45.00 FS | *- FS |
| 20 | 1 | | *FRONT FENDER BRACE - LOWER LH | Bent | 107.00 FS | *85.60 FS |
| 21 | 1 | | *STONE CHIP GUARD | Necessary | 67.00 FS | *52.96 FS |
| 22 | 1 | | *FRONT FENDER ADHESIVE TAPE | Not Necessary | 50.00 FS | *- FS |
| 23 | 1 | | *FRONT WHEEL HOUSING LINER | Cracked | 223.00 FS | *178.40 FS |
| 24 | 1 | | *FRONT WHEEL HOUSING LINER ATTACHMENT PARTS | Necessary | 41.00 FS | *32.80 FS |
| 25 | 1 | | *BONNET | Bent | 2,549.00 FS | *2,039.20 FS |
| 26 | 1 | | *BONNET ATTACHMENT PARTS | Not Necessary | 152.00 FS | *- FS |
| 27 | 1 | | *BONNET CATCH HOOK | Serviceable | 127.00 FS | *- FS |
| 28 | 1 | | *BONNET GAS FILLED STRUT - LH | Serviceable | 109.00 FS | *- FS |
| 29 | 1 | | *BONNET EDGE PROTECTION - FRONT | Serviceable | 25.00 FS | *- FS |
| 30 | 1 | | *BONNET LID LOCK | Serviceable | 196.00 FS | *- FS |
| 31 | 1 | | *BONNET LID LOCK CABLE - FRONT / REAR | Serviceable | 111.00 FS | *- FS |
| 32 | 1 | | *SIGNAL HORN - HIGH TONE LH | Serviceable | 184.00 FS | *- FS |
| 33 | 1 | | *SIGNAL HORN SPRING SHACKLE - HIGH TONE LH | Serviceable | 23.00 FS | *- FS |
| 34 | 1 | | *HEADLIGHT MOUNTING - LH | Cracked | 107.00 FS | *85.60 FS |
| 35 | 1 | | *HEADLIGHT BRACKET - LH | Cracked | 96.00 FS | *76.56 FS |
| 36 | 1 | | *HEADLIGHT - LH | Scratched | 2,152.00 FS | *1,721.60 FS |
| 37 | 1 | | *DRIVING LIGHT POWER MODULE | Serviceable | 520.00 FS | *- FS |
| 38 | 1 | | *GAS DISCHARGE LAMP CONTROL UNIT | Serviceable | 1,051.00 FS | *- FS |
| 39 | 1 | | *GAS DISCHARGE LAMP | Serviceable | 398.00 FS | *- FS |
| 40 | 1 | | *HEADLIGHT HOSE - LH | Serviceable | 32.00 FS | *- FS |
| 41 | 1 | | *HEADLIGHT RETAINING PLATE - LH | Cracked | 22.00 FS | *17.12 FS |
| 42 | 1 | | *HALOGEN FOG LAMP - LH | Missing | 242.00 FS | *193.60 FS |
| 43 | 1 | | *HEADLIGHT LIFT CYLINDER - LH | Cracked | 192.00 FS | *153.20 FS |
| 44 | 1 | | *HEADLIGHT HOSE | Serviceable | 170.00 FS | *- FS |
| 45 | 1 | | *HEADLIGHT T-PIECE | Serviceable | 14.00 FS | *- FS |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|--------------------|-------------|--------------|
| 46 | 1 | | *HEADLIGHT CONNECTING PIECE - STRAIGHT | Serviceable | 26.00 FS | *- FS |
| 47 | 1 | | *HEADLIGHT WASHER SYSTEM PUMP | Serviceable | 96.00 FS | *- FS |
| 48 | 1 | | *HEADLIGHT WASHER PUMP INSULATOR | Serviceable | 19.00 FS | *- FS |
| 49 | 1 | | *WASHER RESERVIOR | Serviceable | 200.00 FS | *- FS |
| 50 | 1 | | *HEADLIGHT FUEL FILLER NECK | Serviceable | 87.00 FS | *- FS |
| 51 | 1 | | *WINDSCREEN WASHER SYSTEM PUMP | Serviceable | 118.00 FS | *- FS |
| 52 | 1 | | *COOLANT RADIATOR LOCK CARRIER | Cracked | 928.00 FS | *742.00 FS |
| 53 | 1 | | *COOLANT REGULATOR SUPPORT | Cracked (1pc only) | 69.00 FS | *27.36 FS |
| 54 | 1 | | *A/C CONDENSER | Serviceable | 677.00 FS | *- FS |
| 55 | 1 | | *REFRIGERANT HOSE | Serviceable | 508.00 FS | *- FS |
| 56 | 1 | | *REFRIGERANT PIPE | Bent | 289.00 FS | *231.20 FS |
| 57 | 1 | | *PRESSURE RELIEF VALVE | Serviceable | 48.00 FS | *- FS |
| 58 | 1 | | *PRESSURE SENSOR | Serviceable | 175.00 FS | *- FS |
| 59 | 1 | | *EXTERNAL TEMPERATURE SENSOR | Serviceable | 54.00 FS | *- FS |
| 60 | 1 | | *TEMPERATURE SENSOR BRACKET | Cracked | 17.00 FS | *13.04 FS |
| 61 | 1 | | *CHARGE AIR COOLER | Bent | 513.00 FS | *410.40 FS |
| 62 | 1 | | *COOLER PRESSURE PIPE | Serviceable | 494.00 FS | *- FS |
| 63 | 1 | | *COOLER RADIATOR | Bent | 1,246.00 FS | *996.80 FS |
| 64 | 2 | | *COOLER RADIATOR RUBBER BUSH - UPPER | Necessary | 12.00 FS | *18.72 FS |
| 65 | 1 | | *READY MIX COOLANT | Necessary | 84.00 FS | *67.20 FS |
| 66 | 1 | | *COOLANT TWIN FAN RING | Serviceable | 237.00 FS | *- FS |
| 67 | 1 | | *RADIATOR FAN | Serviceable | 779.00 FS | *- FS |
| 68 | 1 | | *RADIATOR FAN | Serviceable | 673.00 FS | *- FS |
| 69 | 1 | | *COOLANT AIR GUIDE - LH | Cracked | 24.00 FS | *18.64 FS |
| 70 | 1 | | *COOLANT SECURING STRIP - LOWER | Serviceable | 21.00 FS | *- FS |
| 71 | 1 | | *NOISE INSULATION | Cracked | 579.00 FS | *463.20 FS |
| 72 | 1 | | *CAUTION SIGN | Not Necessary | 13.00 FS | *- FS |
| 73 | 1 | | *A/C STICKER | Necessary | 22.00 FS | *16.96 FS |
| 74 | 1 | | *FRONT NO PLATE | Bent | 40.00 FS | *40.00 FS |
| 75 | 1 | | *SUNDRIES | Necessary | 600.00 FS | *60.24 FS |
| 76 | 1 | | *TOP UP FROM INSURANCE | | - | *1,800.00 FS |

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **24,133.00** **14,305.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|------------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE AND RECOVER VEHICLE FROM SCENE OF ACCIDENT. | New | 280.00 | 280.00 |
| 2 | TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY. | New | 360.00 | 360.00 |
| 3 | TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. | New | 1,200.00 | 1,200.00 |
| 4 | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS HEADLIGHT. RENEW FRONT LOCK. | New | 5,220.00 | 3,000.00 |
| 5 | TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET. | New | 3,300.00 | 1,650.00 |
| 6 | TO CARRY OUT WHEEL ALIGNMENT. TO INSPECT LHS FRONT SUSPENSION FOR FURTHER DAMAGES. | New | 240.00 | 0.00 |
| 7 | TO CARRY OUT DIAGNOSTIC CHECKS. | New | 192.00 | 192.00 |
| Gross Labour Cost (S\$) | | | 10,792.00 | 6,682.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >