

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19015661/KPA3Q2

**Date:** 12/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SLV9859Y **Insured Vehicle No :** SGB6665Z

Date of Loss: 30/08/2019 Nature of Claim: TP Claim No: 6084215879SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLV9859Y</b>		
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Engine No:	L15B5460947
Reg. Date:	24/01/2018 (Man. Year: 2017)	Chassis No:	GK81200796
Colour:	Metallic Dark Blue	Odometer:	33844 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,482.40	1,208.80	273.60	18.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	650.00	600.00	48.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,732.40</b>	<b>1,858.80</b>	<b>873.60</b>	<b>31.97</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	191.27	130.12	61.15	31.97
<b>Nett Amount (\$\$)</b>	<b>2,923.67</b>	<b>1,988.92</b>	<b>934.75</b>	<b>31.97</b>
<b>+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (\$\$)</b>		535.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>2,525.92</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>2,520.00</b>		

### INSPECTION

Date of Assignment: 03/09/2019

Date Inspected: 04/09/2019 Inspected At:

Chew Goon Motor (AMK)  
Blk 10 Ang Mo Kio Industrial Park 2A,  
#01-15/16 & 17, AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Mtg Cracked	1,392.00 FL	*1,150.00 FL
2	14		*REAR BUMPER CLIPS	Necessary	56.00 FL	*56.00 FL
3	1		*BOOT BADGE SHUTTLE	Necessary	55.00 FL	*55.00 FL
4	1		*REAR BUMPER REVERSE SENSOR	Scratched	280.00 FS	*200.00 FS
					<b>Sub Total (S\$)</b>	<b>1,783.00</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>300.60</b>
					<b>Total Parts (S\$)</b>	<b>1,482.40</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CONDUCT REAR ELECTRICAL CHECK AND DISMANTLE /REPLACE REVERSE SENSOR ,MODULE ETC	New	120.00	50.00
2	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF TAILGATE ,END PANEL & PARTS REPLACEMENT	New	400.00	200.00
3	TO SPRAY PAINTING AFFECTED AREAS	New	580.00	400.00
4	TO RESEAL PAINT PROTECTION (DIAMONDBRITE) TO SPRAY PAINT AREAS	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,250.00</b>	<b>650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >