

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **03.09.2019**

Accident Date : 30.08.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Honda Shuttle" Reg. No. SLV9859Y Claiming Against Your Insured Reg. No. SGB6665Z		
1pc	Rear Bumper <i>1150</i>		<i>Not in item</i> 1,392.00 ✓
14pcs	Rear Bumper Clips	4.00	<i>m</i> 56.00 —
1pc	Boot Badge "Shuttle"		<i>m</i> 55.00 —
			1,503.00
	Less 20%		300.60
			1,202.40
	Rear Bumper Reverse Sensor		<i>Sen</i> 280.00 <i>20012</i> SN
	To Conduct Rear Electrical Check and Dismantle / Replace Reverse Sensor, Module etc		120.00 <i>501</i>
	Labour Charge - Panel Beating, Repairing Of Tailgate, End Panel & Parts Replacement		400.00 <i>200</i>
	To Spray Painting Affected Areas		580.00 <i>400</i>
	To Reseal Paint Protection (Diamondbrite) to Spray Paint Areas		150.00 <i>X</i>
		Total :	2,732.40
	<i>Not Authorized</i> <i>Repairing B4 painting</i> <i>3 days</i> <i>81858.80</i>		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be as involved and is subject to confirmation

Acknowledged by Repairer
Signature:
Date: