



Case Details

Case Reference Number : BUS/08/19/5059
 Type of Repair : Accident Repair
 Vehicle Registration Number : SMB125J

Company Type : SMRT Buses Ltd
 Estimation ID : EST-8347-ID
 Assigned By : Claiming Case Owner Team

Insurance Company Name : SMRT
 Accident Date and Time : 30/08/2019 02:32 PM
 Vehicle Age(In Months) : 119

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Repl
One Time Key In	Main			IU Bracket	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace / NPC
Standard	Main			SMRT STICKERS	1	75.00	75.00	0.00	75.00	Replace	1	75.00	Replace / NPC
Standard	Main	BODY LH	6010213	PANEL,SKIRT:L1,FOR MB OC500 BUS	1	162.20	162.20	10.00	145.98	Replace	1	145.9	Replace / OD
Standard	Main	VE	6009511	LAMP,FRONT FOG,LEFT SIDE FOR MB OC500LE	1	300.00	300.00	10.00	270.00	Replace	1	270.0	Replace / MIS
Standard	Main	GLASS	6009351	WINDSCREEN,FRT:CENTRE,FOR MB OC500 BUS	1	6,210.00	6,210.00	10.00	5,589.00	Replace	1	5,589	Replace / CRA
Standard	Main	GLASS	6010197	GLASS,PANEL:FRONT DOOR,FOR MB OC500 BUS	1	862.50	862.50	10.00	776.25	Replace	1	776.2	Replace / BR
Standard	Main	CONSUMABLE	4021335	SEALANT:SIKATAACK-MOVE TRANSPORTATION	14	37.00	518.00	0.00	518.00	Replace	14	518.0	Replace / NPC
Standard	Main	CONSUMABLE	4006313	PRIMER (SIKA 206 G+P)	1	80.00	80.00	0.00	80.00	Replace	1	80.00	Replace / NPC
Standard	Main	CONSUMABLE	4006315	ACTIVATOR	1	80.00	80.00	0.00	80.00	Replace	1	80.00	Replace / NPC
Standard	Main	BODY LH	6009358	COVER,HEADLAMP:LH,FOR MB OC500 BUS	1	621.00	621.00	10.00	558.90	Replace	1	558.9	Replace / BR
Standard	Main	VE	6009508	HEADLAMP FOR MERCEDES OC500 LE, RIGHT	1	1,276.50	1,276.50	10.00	1,148.85	Replace	1	1,148	Replace / BR
Standard	Main	VE	6009700	LAMP,BLINKER:FRONT,LEFT,FOR MB OC 500 LE	1	155.30	155.30	10.00	139.77	Replace	1	139.7	Replace / BR
Total Spare Part Cost									9,416.75		Surveyor Total		9,416.75
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)		20.00
Final Spare Part Cost									7,533.40		Final Sur Total		7,533.40

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	--------------	-----------	-------------------------	-------------------------	---------

Total: 2,120.00 1,590.00

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & INSTALL FRONT WINDSCREEN , WINDSCREEN WEATHERSTRIP & TRIMMING	1,060.00	795.00	
2	Main	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,060.00	795.00	
Total:			2,120.00	1,590.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	602.00	432.00	
Total:			602.00	432.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	ADVERTISEMENT STICKER	480.00	480.00	
Total:			480.00	480.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	7,533.40 <i>9466.75</i>	7,533.40
Total Labour Cost	2,120.00	1,590.00
Total Spray Painting	602.00	432.00
Other	480.00	480.00
Overall Total	10,735.40 <i>12668.75</i>	11,918.75
Lump Sum Repair Option	☐	☒
Lump Sum Total	0.00	11,900.00
Surveyor Approved Amount		11,900.00
No of Repair Days*	6	5
Remarks	-	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com
Surveyor Name		STEVE CHEN
Signature		
Survey Date	03/09/2019	

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during **resurvey**
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: