

FBG7918X

7216

6/9/19

金國摩哆私人有限公司
KIM KOCK MOTOR PTE LTD
Unit 27A, Jurong Port Road, #01-19,
Singapore 619101
Tel: 6265 0226 Fax: 6265 2588

(TP-Polic) TO wing — \$45 - 30

TO wing go do idac \$35 - 30

(Repair) Front Fork Assy — \$150 120sn

Front mudguard — \$78 - cut

Head light Assy — \$265 - cut

Head cowling Assy — \$285 - cut

(L) Head side fairing spc — \$195 cut

(L) Front signal 1pc — \$78 cut

(L) Signal Front side cover \$98 cut

Handle
Handle Bar — \$130 bt

clutch lever — \$28 bro

Handle Grip — \$48 at

(L/R) Air intake
indac cover — \$96 at
Windscreen

Wiskin 1pc — \$85 cut

(L) Head side fairing spc — \$195 - x Replaced.

Handle Bar Balance R/L — \$68 dis

Brake pedal — \$78 dd

AJER Pipe Pullstem — \$395 dis

Rear CIVI Box — \$155 cut

Side stand — \$58 R7

Gear Pedal — \$85 bt

Labour — \$280

Tauhkh 97495749
WP' 5/9/19 23pm

Lumpsum
Resurvey after repair

04 days

surveillance

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2362-

10% - 2125.80

380

2505.80

4/5/2000

200-

(7) \$2930