

ASS. REC. BY:

REF: CS/U01 19015684/K9f3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Jenny Lew

of U01

Date/Time: 4.9.19 17.08pm

Estimated Cost:

Bill to:

~~OD/TP~~ WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SHC 5612R

Insured: SFU 9686E

at Workshop m/s Transcab

Tel:

of NO 2 Ank Street 63

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 31.8.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4.9.19 5.00pm

Person Contacted:

Amanda

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 5612R - CS/PC1 180-2494/K9d3n2

D.O.A. - 11/12/2018

SFU 9686E - CF/AG0700 3422/9W

D.O.A. - 07/11/2017

ASS. REC. BY:

REF: UOI

Kenneth

## ASSIGNMENT

From:

Date: 5/9/19

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHC 5612R

at Workshop m/s

Transcab

of

No. 2 MKR St 63

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>1 up</sup>

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SHC 5612R

Yr Regn:

10, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make:

Perout Ltd. 1995

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

541615

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

V1-1ABC 15 AUG 279412

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

Pailun 215/60R16

R: Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9 mm

R/Bal.

7 mm

L/Bal.

9 mm

L/Bal.

7 mm

D.O.A.

31/8/19

D.O.I.

5/9/19

Survey held at

Des. of Damages: ☒ Front / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

C/Sy @ 7700 (Lat @ 43530.88, 85%)

RECEIVED 10 SEP 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 10/9/19

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee:

☐

Site Insp. (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + P + SI

Folio:

Office:

580

580

11/9/19

41x 25 = 1025

250 + 1025

60

19.

1354

Report Format:

7P

Lump Sum / LBS: / %

7700



United Overseas Insurance Limited  
3 Anson Road #28-01 Springleaf Tower  
Singapore 079909  
Tel (65) 6222 7733  
Fax (65) 6327 3869 / 6327 3870  
Email: ContactUs@uoi.com.sg  
uoi.com.sg  
Co. Reg. No. 197100152R

To :	Trans-Cab Services Pte Ltd Attn: Amanda -Accident Department	Fax : 62571330
From :	Jenny Lew	Fax : 63273869
Date :	4.9.2019	Our ref: SFU9686E (DHOM120001691404) Yr ref : SHC5612R

**FACSIMILE MESSAGE**

WITHOUT PREJUDICE

**REQUEST FOR PRE-REPAIR SURVEY - SHC5612R  
ACCIDENT INVOLVING SFU9686E AND SHC5612R ON 31.8.2019**

We refer to your letter and email dated 4.9.2019.

Pursuant to the amended Pre-action Protocol for Non-Injury Motor Accident (NIMA), we enclose a list of our Surveyors, for your attention.

In this case you have proposed to appoint M/s LKK Auto Consultants Pte Ltd from our list, to conduct the pre-repair survey on without prejudice basis.

Please seek your client's instruction for the repair after the inspection has been completed and inform our Surveyors to carry out a Post-Repair Inspection.

We reserve all our rights in this matter.

Thank you.

Regards

Jenny Lew  
Claims Dept

cc. LKK Auto Consultants Pte Ltd  
Fax: 62564315  
Attn : Shiau Chan

For your immediate attention.  
fy

## Shiau Chan (LKKAUTO)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Tuesday, 10 September 2019 1:49 PM  
**To:** Shiau Chan (LKKAUTO)  
**Subject:** RE: TP VEHICLE SHC 5612R (DOA: 31/08/2019) -- AAD1909-017  
**Attachments:** image002.wmz; image008.wmz

Hi Shiau Chan

Amount confirmed \$ 7,700 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Shiau Chan (LKKAUTO) [mailto:[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)]  
**Sent:** Tuesday, 10 September, 2019 10:01 AM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** RE: TP VEHICLE SHC 5612R (DOA: 31/08/2019) -- AAD1909-017

Dear Wai Yin,

Sorry for typo error.

The repair cost should be at Lump Sum \$7,700.00 before GST and 3 repair days.

Best Regards,  
**Shiau Chan (Ms)** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Monday, 9 September 2019 5:29 PM  
**To:** Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Subject:** RE: TP VEHICLE SHC 5612R (DOA: 31/08/2019) -- AAD1909-017

Hi Shiau Chan

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	878K

**Vehicle Details**

Vehicle No.:	SHC5612R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	02 Sep 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001862
Chassis No.:	VF1ABL15AUC279412
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	14 Oct 2014
First Registration Date:	14 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Oct 2022
PARF Rebate Amount:	\$9,373.00

**Intended COE Rebate Details**

COE Expiry Date:	13 Oct 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,938.00
COE Rebate Amount:	\$19,820.00
<b>Total Rebate Amount:</b>	<b>\$29,193.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Sep 2019

OK

Brief Details.

On 31/08/2019 at about 1830hrs, I was driving my taxi (SHC5612R) along River Valley Road towards Kim Seng Road on the extreme left lane. When I was about to approach a side T-junction, there was a car (SFU9686E) on the opposite direction wanting to turn right to Mohamed Sultan Rd. The car then turn right and I was unable to stop in time. Hence, the front part of my taxi hit the left side of the car. There were damages on left side of the car. There were also damages on the front bumper and on the bonnet of my car. No injuries on any party during that point of time and no police attended. The driver's particulars are as follows: Mae Kuan, 93654805. I went to Peace Family Clinic and is certified unfit for work for 3 days.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/09/2019 13:33
Date Of Accident	31/08/2019 18:30
Exact Location Of Accident	RIVER VALLEY ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5612R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

### Driver

Name of Driver	CHENG SHAO YONG
NRIC No	S7212823J
Date Of Birth	08/04/1972
Occupation	OUTDOOR
Date Of Driving Pass	12/04/2011
Driving Experience	8 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84854525
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 521 WOODLANDS DRIVE 14 #05-331
Postcode	730521
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Please see the attach Police Report T/20190901/7020.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFU9686E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MAE KUAN
NRIC/Passport Number	
Contact Number	93654805
Address	
Postcode	
Insurance Company Name	



Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name CHENG SHAO YONG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHC5612R

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please see the attach police report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Amanda  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Police Report Pg. 1



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20190901/7020

3 of 3

Report No. T/20190901/7020

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPHQ /  
YEO GEAK ENG CECILIA  
Contact No.: 65476404

Authentication Stamp  
NP168

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
01/09/2019 22:13

Classification Of Case:

## Police Report Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190901/7020

1 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190901/7020

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 01/09/2019 22:13		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: CHENG SHAO YONG			Address: 521 WOODLANDS DRIVE 14 #05-331 FRAGRANT WOODS SINGAPORE 730521		
ID Type / ID No.: NRIC NO / S7212823J			Contact No.: Home/Office:		Mobile: 84854525
Nationality: SINGAPORE CITIZEN			Email: alan72.csy@gmail.com		
Sex: Male	Age: 47	Date of Birth: 08/04/1972	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation:			Driving Licence Information: Class: 2B,3A		Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 31/08/2019 18:30	Type of Location: Straight Road
Location:  RIVER VALLEY ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SFU9686E	Car	BMW		Silver	Slightly Damaged	0
SHC5612R	Taxi	RENAULT		Red	Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20190901/7020

2 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190901/7020

**CONTINUATION OF REPORT**

<b>Driver</b>			
Name	CHENG SHAO YONG	ID No.	S7212823J
Related Vehicle	SHC5612R (Taxi)	Contact No.	84854525
Hospital/Clinic	PEACE FAMILY CLINIC	Class of Driving Licence & Expiry Date	Class: 2B,3A Date of Expiry: NIL
Date Treatment	01/09/2019	Date Discharge	01/09/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

**Brief Details.**

On 31/08/2019 at about 1830hrs, I was driving my taxi (SHC5612R) along River Valley Road towards Kim Seng Road on the extreme left lane. When I was about to approach a side T-junction, there was a car (SFU9686E) on the opposite direction wanting to turn right to Mohamed Sultan Rd. The car then turn right and I was unable to stop in time. Hence, the front part of my taxi hit the left side of the car. There were damages on left side of the car. There were also damages on the front bumper and on the bonnet of my car. No injuries on any party during that point of time and no police attended. The driver's particulars are as follows: Mae Kuan, 93654805. I went to Peace Family Clinic and is certified unfit for work for 3 days.

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5612R****AAD1909-017**

*Not Notified*  
*11 Sep @ 7700h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

05 SEP 2019

**SHC 5612R**

VF1ABL15AUC279412

RENAULT

LATITUDE

31.8.19

**UOI**

14/10/2014

**PART****LIST**

1	1	BUMPER COVER FRT	\$	B <sub>1</sub>	747.20	✓
2	1	BUMPER SPOILER FRT	\$	D <sub>1</sub>	344.70	✓
3	1	BUMPER ABSORBER FRT	\$	T <sub>1</sub>	394.68	✓
4	1	BUMPER RETAINER FRT LH	\$	D <sub>1</sub>	101.40	✓
5	1	BUMPER SUPPORT FRT	\$	S <sub>1</sub>	10.70	X
6	1	BUMPER RETAINER FRT RH	\$	D <sub>1</sub>	101.40	✓
7	1	BUMPER SUPPORT FRT	\$	S <sub>1</sub>	10.70	X
8	1	BUMPER UNDERTRAY FRT	\$	C <sub>M</sub>	292.50	✓
9	1	BUMPER GRILLE LOWER FRT	\$	D <sub>1</sub>	147.00	✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	M <sub>1</sub>	207.21	✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	M <sub>1</sub>	207.21	✓
12	1	BUMPER BEAM FRT	\$	B <sub>1</sub>	663.70	✓
13	1	TOW COVER FRT	\$	S <sub>1</sub>	60.90	X
14	1	RADIATOR GRILLE	\$	C <sub>M</sub>	969.90	✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	N <sub>1</sub>	225.36	✓
16	1	RADIATOR GRILLE FRAME	\$	C <sub>M</sub>	686.00	✓
17	1	FRAME FULL SUPPORT PANEL	\$	C <sub>M</sub>	592.70	✓
18	1	FRAME FULL SUPPORT BRACKET	\$	N <sub>1</sub>	41.60	X
19	1	FRONT BRACE PANEL	\$	N <sub>1</sub>	177.22	X
20	1	HORN	\$	S <sub>1</sub>	449.90	X
21	1	HORN BRACKET	\$	N <sub>1</sub>	21.90	X
22	1	HEADLAMP LH	\$	C <sub>M</sub>	743.60	✓
23	1	HEADLAMP RH	\$	S <sub>1</sub>	743.60	X
24	1	HEADLAMP PANEL FRT LH	\$	N <sub>1</sub>	127.70	X
25	1	HEADLAMP PANEL FRT RH	\$	N <sub>1</sub>	128.30	X
26	1	BONNET	\$	B <sub>1</sub>	1,312.70	✓
27	1	BONNET INSULATOR	\$	S <sub>1</sub>	294.30	X
28	1	BONNET STRUT LH	\$	S <sub>1</sub>	53.30	X
29	1	BONNET STRUT RH	\$	S <sub>1</sub>	53.30	X
30	1	BONNET HINGE LH	\$	N <sub>1</sub>	236.50	X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5612R****AAD1909-017**

31	1	BONNET HINGE RH	\$	<i>M</i>	237.40	X
32	1	BONNET LOCK	\$	<i>M</i>	152.80	X
33	1	BONNET CABLE	\$	<i>SL</i>	55.20	X
34	1	BONNET CABLE COVER	\$	<i>SL</i>	80.60	X
35	1	BONNET SEAL OUTER	\$	<i>SL</i>	83.20	X
36	1	BONNET SEAL INNER	\$	<i>SL</i>	70.10	X
37	1	FENDER PANEL FRT LH	\$	<i>B</i>	414.40	✓
38	1	WHEELARCH FRT LH	\$	<i>CMS</i>	112.30	✓
39	1	FENDER BRACKET LOWER LH	\$	<i>M</i>	11.80	} X
40	1	FENDER INSULATOR LH	\$	<i>SL</i>	65.50	
41	1	FENDER PANEL FRT RH	\$	<i>M</i>	437.10	
42	1	WHEELARCH FRT RH	\$	<i>SL</i>	191.40	
43	1	FENDER BRACKET LOWER RH	\$	<i>SL</i>	11.80	
44	1	FENDER INSULATOR RH	\$	<i>SL</i>	66.30	
45	1	WIPER RESERVOIR	\$	<i>SL</i>	179.60	
46	1	WIPER RESERVOIR NECK	\$	<i>SL</i>	29.30	
47	1	WIPER RESERVOIR MOTOR	\$	<i>SL</i>	82.60	
48	1	AIR CLEANER LOWER	\$	<i>SL</i>	271.26	
49	1	AIR CLEANER HOSE	\$	<i>SL</i>	175.85	} X
50	1	BASE BATTERY TRAY	\$	<i>SL</i>	363.40	
51	1	AIR CLEANER BOX	\$	<i>SL</i>	464.20	
52	1	TURBO DUCT	\$	<i>SL</i>	1,027.80	
53	1	A/C HEATER VALVE	\$	<i>SL</i>	484.50	
54	1	SUBFRAME OUTER FRT	\$	<i>SL</i>	1,094.20	
55	1	SUBFRAME BRACKET OUTER LH	\$	<i>M</i>	49.00	
56	1	SUBFRAME BRACKET OUTER RH	\$	<i>M</i>	49.00	
57	1	ENGINE UNDERTRAY	\$	<i>CMS</i>	564.98	✓
58	1	A/C CONDENSER	\$	<i>SL</i>	1,537.80	} X
59	1	A/C CONDENSER GARNISH LH UPPER	\$	<i>SL</i>	57.30	
60	1	A/C CONDENSER GARNISH RH UPPER	\$	<i>SL</i>	56.70	
61	1	A/C CONDENSER GARNISH LH	\$	<i>SL</i>	67.90	
62	1	A/C CONDENSER GARNISH RH	\$	<i>SL</i>	67.70	
63	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	<i>SL</i>	187.20	
64	1	A/C PIPE CONDENSER TO EXPANSION VALVE	\$	<i>SL</i>	380.20	
65	1	A/C PIPE COMPRESSOR	\$	<i>SL</i>	222.70	
66	1	A/C PIPE	\$	<i>SL</i>	486.50	
67	1	A/C COMPRESSOR	\$	<i>SL</i>	2,142.30	
68	1	AIR COOLER	\$	<i>SL</i>	598.90	} X
69	1	AIR INTERCOOLER HOSE (LONG)	\$	<i>SL</i>	1,014.13	



**Trans-cab Auto Services Pte Ltd****AAD1909-017**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5612R**

70	1	AIR INTERCOOLER HOSE (Short)
71	1	TRANSMISSION COOLER
72	1	TRANSMISSION COOLER PAD
73	1	RADIATOR
74	2	RADIATOR STUD UPPER
75	2	RADIATOR BUSH UPPER
76	2	RADIATOR MTG LOWER
77	1	RADIATOR FAN COWLING
78	1	RADIATOR FAN MOTOR LH
79	1	RADIATOR FAN MOTOR RH
80	1	RADIATOR TANK
81	1	RADIATOR HOSE UPPER
82	1	RADIATOR HOSE LOWER
83	1	RADIATOR TANK HOSE
84	1	STEERING PINION RACK L70Y

\$	Sh	375.14
\$	Sh	1,219.30
\$	Sh	9.50
\$	Sh	871.20
\$	Sh	11.10
\$	Sh	11.10
\$	Sh	30.10
\$	Sh	417.00
\$	Sh	826.70
\$	Sh	821.20
\$	Sh	174.80
\$	Sh	97.50
\$	Sh	254.10
\$	Sh	56.20
\$	Sh	3,765.30
<b>TOTAL</b>	<b>\$</b>	<b>32,732.35</b>
<b>10%</b>	<b>\$</b>	<b>3,273.23</b>
	<b>\$</b>	<b>29,459.11</b>

**Special Nett**

1	1SET	RADIATOR GRILLE FRAME CLIP
2	1SET	BUMPER CLIP FRT
3	1	BUMPER BRACKET CLIP FRT LH
4	1	BUMPER SUPPORT CLIP FRT LH
5	1	BUMPER BRACKET CLIP FRT RH
6	1	BUMPER SUPPORT CLIP FRT RH
7	1	TOW COVER FRT
8	1SET	RADIATOR GRILLE SCREW
9	1SET	BUMPER GRILLE LOWER CLIP
10	1SET	FRAME FULL SUPPORT PANEL CLIP
11	2	FRAME FULL SUPPORT PANEL NUT
12	2	FRAME FULL SUPPORT PANEL STUD
13	1	Windscreen moulding
14	1	FRONT WINDSCREEN SEALANT
15	1	FRONT WINDSCREEN INNER SPONGE SEAL
16	1SET	Front licence plate with holder
17	1SET	WHEELARCH CLIP FRT LH
18	1SET	WHEELARCH CLIP FRT RH

\$	nn	52.00
\$	nn	66.00
\$	nn	12.00
\$	nn	10.50
\$	nn	12.00
\$	nn	10.50
\$	Sh	14.50
\$	nn	16.00
\$	nn	69.00
\$	nn	70.00
\$	nn	20.00
\$	nn	30.00
\$	nn	120.00
\$	nn	253.80
\$	nn	100.00
\$	Rt	80.00
\$	nn	30.50
\$	nn	30.50

**Trans-cab Auto Services Pte Ltd****AAD1909-017**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5612R**

19	1	Front left tyre	\$	sn	330.00	X
20	1	Front left tyre rim	\$	sn	380.00	X
21	1	Front right tyre	\$	sn	330.00	X
22	1	Front right tyre rim	\$	sn	380.00	X
23	6	BONNET INSULATOR CLIP L70Y	\$	nn	7.30	X
24	2	BONNET CABLE CLIP L70Y	\$	nn	6.31	X
25	2	BONNET CABLE COVER SCREW L70Y	\$	nn	10.85	X
<b>TOTAL</b>			<b>\$</b>		<b>2,441.77</b>	

<b>TOTAL PARTS</b>	<b>\$</b>	<b>31,900.88</b>
--------------------	-----------	------------------

**LABOUR**

To remove and refit interior fittings, trimings,  
garnish, fittings and other, to enable repair.

\$	nn	380.00	X
----	----	--------	---

Panel beating, knocking and straightening the  
necessary portion, remove and renewal of parts,  
adjust and realign the same

\$		7,500.00	5000
----	--	----------	------

Putty and spray painting of the affected portion.

\$		7,500.00	6600
----	--	----------	------

To check steering geometry and computer wheel  
alignment

\$	nn	220.00	X
----	----	--------	---

To remove and renew power steering oil & pump, oil  
cooler pipe and final checking and testing.

\$		440.00	500
----	--	--------	-----

To transfer of front windscreen fittings and conduct  
water seepage test

\$	nn	200.00	X
----	----	--------	---

To vacuum, replace, refix and recharge air  
condenser

\$		380.00	1000
----	--	--------	------

Labour charge to mount and dismount vehicle on  
jig bench, to facilitate repair.

\$	nn	380.00	X
----	----	--------	---

To transfer of front bumper fittings, attachment and  
perform water seepage test.

\$	nn	380.00	X
----	----	--------	---

**Trans-cab Auto Services Pte Ltd**

AAD1909-017

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5612R

To rust-proofing of the affected areas.	\$	170.00	601
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	501
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	4 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To replace, refix and top up coolant for radiator	\$	nn 170.00	X
Towing Fees	\$	170.00	501
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00	X

**TOTAL \$ 19,330.00****Over All Total \$ 51,230.88****Repair Days (LUMP SUM)****25 DAYS****3 day,**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer:

Signature:


Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD		Ref : CS/UOI19015684/Kqf3n2		
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909		Date : 17-09-2019		
		Code : UOI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SFU 9686E	Veh. Inspected	SHC 5612R	
Policy No.	DHOM120001691404	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	JENNY LEW	Assign Date	04/09/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC279412	Colour	METALLIC WHITE / RED	
Odometer	541615	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	SAILUN	9 mm	
L/H Front Tyre	215/60 R16	SAILUN	9 mm	
R/H Rear Tyre	215/60 R16	GITI	7 mm	
L/H Rear Tyre	215/60 R16	GITI	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	31/08/2019	Inspection Date	05/09/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5612R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	BUMPER COVER FRT	BENT	747.20	747.20
1	BUMPER SPOILER FRT	DISTORTED	344.70	344.70
1	BUMPER ABSORBER FRT	TORN	394.68	394.68
1	BUMPER RETAINER FRT LH	DISTORTED	101.40	101.40
1	BUMPER SUPPORT FRT	SERVICEABLE	10.70	-
1	BUMPER RETAINER FRT RH	DISTORTED	101.40	101.40
1	BUMPER SUPPORT FRT	SERVICEABLE	10.70	-
1	BUMPER UNDERTRAY FRT	CRACKED	292.50	292.50
1	BUMPER GRILLE LOWER FRT	DISTORTED	147.00	147.00
1	BUMPER FOG LAMP GRILLE LH	MISSING	207.21	207.21
1	BUMPER FOG LAMP GRILLE RH	MISSING	207.21	207.21
1	BUMPER BEAM FRT	BENT	663.70	663.70
1	TOW COVER FRT	SERVICEABLE	60.90	-
1	RADIATOR GRILLE	CRACKED	969.90	969.90
1	RADIATOR GRILLE BADGE "RENAULT"	NECESSARY	225.36	225.36
1	RADIATOR GRILLE FRAME	CRACKED	686.00	686.00
1	FRAME FULL SUPPORT PANEL	CRACKED	592.70	592.70
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	41.60	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HORN	SERVICEABLE	449.90	-
1	HORN BRACKET	TO REPAIR SEE LABOUR	21.90	-
1	HEADLAMP LH	CRACKED	743.60	743.60
1	HEADLAMP RH	SERVICEABLE	743.60	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	127.70	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	128.30	-
1	BONNET	BENT	1,312.70	1,312.70
1	BONNET INSULATOR	SERVICEABLE	294.30	-
1	BONNET STRUT LH	SERVICEABLE	53.30	-
1	BONNET STRUT RH	SERVICEABLE	53.30	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	236.50	-

Report Ref No. CS/UOI19015684/Kqf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	237.40	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	152.80	-
1	BONNET CABLE	SERVICEABLE	55.20	-
1	BONNET CABLE COVER	SERVICEABLE	80.60	-
1	BONNET SEAL OUTER	SERVICEABLE	83.20	-
1	BONNET SEAL INNER	SERVICEABLE	70.10	-
1	FENDER PANEL FRT LH	BENT	414.40	414.40
1	WHEELARCH FRT LH	CRACKED	112.30	112.30
1	FENDER BRACKET LOWER LH	TO REPAIR SEE LABOUR	11.80	-
1	FENDER INSULATOR LH	SERVICEABLE	65.50	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	437.10	-
1	WHEELARCH FRT RH	SERVICEABLE	191.40	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	11.80	-
1	FENDER INSULATOR RH	SERVICEABLE	66.30	-
1	WIPER RESERVOIR	SERVICEABLE	179.60	-
1	WIPER RESERVOIR NECK	SERVICEABLE	29.30	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	82.60	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE	SERVICEABLE	175.85	-
1	BASE BATTERY TRAY	SERVICEABLE	363.40	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	TURBO DUCT	SERVICEABLE	1,027.80	-
1	A/C HEATER VALVE	SERVICEABLE	484.50	-
1	SUBFRAME OUTER FRT	SERVICEABLE	1,094.20	-
1	SUBFRAME BRACKET OUTER LH	TO REPAIR SEE LABOUR	49.00	-
1	SUBFRAME BRACKET OUTER RH	TO REPAIR SEE LABOUR	49.00	-
1	ENGINE UNDERTRAY	CRACKED	564.98	564.98
1	A/C CONDENSER	SERVICEABLE	1,537.80	-
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	57.30	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	56.70	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	67.90	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	67.70	-

Report Ref No. CS/UOI19015684/Kqf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	A/C PIPE CONDENSER TO COMPRESSOR	SERVICEABLE	187.20	-
1	A/C PIPE CONDENSER TO EXPANSION VALVE	SERVICEABLE	380.20	-
1	A/C PIPE COMPRESSOR	SERVICEABLE	222.70	-
1	A/C PIPE	SERVICEABLE	486.50	-
1	A/C COMPRESSOR	SERVICEABLE	2,142.30	-
1	AIR COOLER	SERVICEABLE	598.90	-
1	AIR INTERCOOLER HOSE (LONG)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER	SERVICEABLE	1,219.30	-
1	TRANSMISSION COOLER PAD	SERVICEABLE	9.50	-
1	RADIATOR	SERVICEABLE	871.20	-
2	RADIATOR STUD UPPER	SERVICEABLE	11.10	-
2	RADIATOR BUSHD UPPER	SERVICEABLE	11.10	-
2	RADIATOR MTG LOWER	SERVICEABLE	30.10	-
1	RADIATOR FAN COWLING	SERVICEABLE	417.00	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	826.70	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	821.20	-
1	RADIATOR TANK	SERVICEABLE	174.80	-
1	RADIATOR HOSE UPPER	SERVICEABLE	97.50	-
1	RADIATOR HOSE LOWER	SERVICEABLE	254.10	-
1	RADIATOR TANK HOSE	SERVICEABLE	56.20	-
1	STEERING PINION RACK L70Y	SERVICEABLE	3,765.30	-
	LESS 10% DISCOUNT		-3,273.23	-882.89
			29,459.11	7,946.05
<b>SPECIAL NETT ITEMS</b>				
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NECESSARY	52.00	52.00
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-

Report Ref No. CS/UOI19015684/Kqf3n2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	120.00	-
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	BENT	80.00	45.00
1	SET WHEELARCH CLIP FRT LH (SN)	NECESSARY	30.50	30.50
1	SET WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	30.50	-
1	FRONT LEFT TYRE (SN)	SERVICEABLE	330.00	-
1	FRONT LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	FRONT RIGHT TYRE (SN)	SERVICEABLE	330.00	-
1	FRONT RIGHT TYRE RIM (SN)	SERVICEABLE	380.00	-
6	BONNET INSULATOR CLIP L70Y (SN)	NOT NECESSARY	7.30	-
2	BONNET CABLE CLIP L70Y (SN)	NOT NECESSARY	6.31	-
2	BONNET CABLE COVER SCREW L70Y (SN)	NOT NECESSARY	10.85	-
			2,441.76	193.50
	<b>LABOUR</b>			
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRAME FULL SUPPORT BRACKET, FRONT BRACE PANEL, HORN BRACKET, HEADLAMP PANEL FRT LH, HEADLAMP PANEL FRT RH, BONNET HINGE LH, BONNET HINGE RH, BONNET LOCK, FENDER BRACKET LOWER LH, FENDER PANEL FRT RH, SUBFRAME BRACKET OUTER LH AND SUBFRAME BRACKET OUTER RH.		7,500.00	500.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		7,500.00	660.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REMOVE AND RENEW POWER STEERING OIL & PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.		440.00	50.00
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	200.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.		380.00	100.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-

Report Ref No. CS/UOI19015684/Kqf3n2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO VACUUM, REPLACE, REFILL AND RECHARGE AIR INTERCOOLER.		170.00	50.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO REPLACE, REFILL AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TOWING FEES.		170.00	50.00
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
			19,330.00	1,490.00
	<b>GRAND TOTAL</b>		<b>51,230.87</b>	<b>9,629.55</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>7,700.00</b>

Report Ref No. CS/UOI19015684/Kqf3n2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.