

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19015688/KBA3Q2
Date: 10/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLR6372A	Insured Vehicle No :	SKC2977Y
Date of Loss:	31/08/2019	Nature of Claim:	TP
		Claim No:	8540572397SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR6372A	Engine No:	3A92UGB5934
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AHH006358
Reg. Date:	23/08/2017 (Man. Year: 2017)	Odometer:	67760 km
Colour:	Metallic Pearl White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,792.90	2,131.40	661.50	23.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,450.00	210.00	12.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,452.90	3,581.40	871.50	19.57
+ GST 7.00/7.00% (S\$)	311.70	250.70	61.00	19.57

Nett Amount (S\$)	4,764.60	3,832.10	932.50	19.57
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		4,200.10		
Global Sum Settlement (S\$)		4,100.00		

INSPECTION

Date of Assignment: 03/09/2019

Date Inspected: 04/09/2019

Estimated Period of Repair: 6.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	708.00 FN	*708.00 FN
2	1		*REAR BUMPER LH SIDE RETAINER	Cracked	26.00 FN	*26.00 FN
3	6		*REAR BUMPER CLIPS	Necessary	21.00 FN	*21.00 FN
4	1		*REAR BUMPER LH REFLECTOR	Serviceable	20.00 FN	*- FN
5	1		*REAR PANEL	Repair	567.00 FN	*- FN
6	1		*REAR BOOT	Bent	828.00 FN	*828.00 FN
7	1		*REAR BOOT LOGO	Necessary	39.00 FN	*39.00 FN
8	1		*REAR BOOT EMBLEM -ATTRAGE	Necessary	42.00 FN	*42.00 FN
9	1		*REAR BOOT INNER LOCK	Dented	206.00 FN	*206.00 FN
10	1		*REAR BOOT INNER RUBBER	Not Necessary	148.00 FN	*- FN
11	1		*LH TAILLAMP	Mtg Cracked	276.00 FN	*276.00 FN
12	1		*REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	3,081.00	2,346.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	288.10	214.60
Total Parts (\$\$)	2,792.90	2,131.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	700.00
2	PUTTY & RESPRAY PAINTING	New	800.00	720.00
3	RUSTPROOFING	New	60.00	30.00
Gross Labour Cost (\$\$)			1,660.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >