

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19015691/KBA3Q2

**Date:** 29/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**

**Vehicle No :** SKS8620C

**Insured Vehicle No :** SKG2097R

Date of Loss: 30/08/2019

Nature of Claim: TP

Claim No: 3120190070SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKS8620C**

Make & Model: BMW 730LI, 3.0 AT ABS D/AB 2WD 4DR NAV  
HID SR (A)

Engine No: 05997287N52B30AF

Reg. Date: 19/03/2010 (Man. Year: 2009)

Chassis No: WBAKB22010CN74288

Colour: Metallic Pearl White

Odometer: 229566 km

Engine Capacity: 2996 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/50Z R18

Rear Tyre Size: 245/50Z R18

Front Left Side: KAPSEN 7 mm

Rear Left Side: KAPSEN 7 mm

Front Right Side: KAPSEN 7 mm

Rear Right Side: KAPSEN 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,693.70	758.90	934.80	55.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	250.00	180.00	70.00	28.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,943.70</b>	<b>938.90</b>	<b>1,004.80</b>	<b>51.70</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>750.00</b>		
<b>(S\$)</b>	1,943.70	750.00	1,193.70	61.41
<b>+ GST 7.00/7.00% (S\$)</b>	136.06	52.50	83.56	61.41
<b>Nett Amount (S\$)</b>	<b>2,079.76</b>	<b>802.50</b>	<b>1,277.26</b>	<b>61.41</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 04/09/2019

Date Inspected: 06/09/2019 Inspected At:

Supreme Auto Service Pte Ltd (HQ)  
176 Sin Ming Drive #02-01, Sin Ming  
Autocare  
Singapore 575721

Estimated Period of Repair: 1.0 days

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SIDE MIRROR LH	Broken	758.90 F	*758.90 F
2	1		*FRONT SIDE MIRROR COVER	Repair	108.30 F	*- F
3	1		*FRONT SIDE MIRROR BRACKET WITH MOTOR	*Check	826.50 F	*- F
F=Franchise part.						
Total Parts (S\$)					1,693.70	758.90

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	100.00	60.00
2	TO REPLACE AND INSTALL THE PARTS MENTIONED ABOVE	New	150.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>250.00</b>	<b>180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >