

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19015693/EGA3Q2

Date: 24/06/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMH8610R	Insured Vehicle No :	SHC8135G
Date of Loss: 02/09/2019	Nature of Claim: TP	Claim No: MCT19090045

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH8610R		
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Engine No:	LEB7104438
Reg. Date:	12/02/2019 (Man. Year: 2018)	Chassis No:	GP72003393
Colour:	Red	Odometer:	48556 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	782.00	782.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	370.00	250.00	120.00	32.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,152.00	1,032.00	120.00	10.42
+ GST 7.00/7.00% (S\$)	80.64	72.24	8.40	10.42
Nett Amount (S\$)	1,232.64	1,104.24	128.40	10.42
+ Car Rental (2.0 x S\$107.00/day) (S\$)		214.00		
Nett Liability (S\$)		1,318.24		
Global Sum Settlement (S\$)		1,300.00		

INSPECTION

Date of Assignment:	30/09/2019	
Date Inspected:	30/09/2019	Inspected At:
		Hua Hong Pte Ltd (Sungei Kadut)
		25D Sungei Kadut Street 1
		Singapore 729332
Estimated Period of Repair:	1.0 days	

Adjuster: CHEN TSUE YEE

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Apr 2020)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH8610R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR (LH) COMPLETE	Broken	527.50 FL	*527.50 FL
2	1		*FRONT DOOR GLASS (LH)	Cut	450.00 FL	*450.00 FL
					Sub Total (\$)	977.50
					- List Item Discount on L Items 20.00/20.00% (\$)	195.50
					Total Parts (\$)	782.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE FRONT LH DOOR TRIM TO CHARGE LH SIDE MIRROR & CHANGE FRONT LH DOOR GLASS	New	250.00	150.00
2	TO PERFORM WIRE CHECKING	New	20.00	20.00
3	TO SPRAY LH SIDE MIRROR COVER	New	100.00	80.00
Gross Labour Cost (\$\$)			370.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >