

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 2-Sep-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLS7310S	Vic	
MODEL	: TOYOTA COROLLA ALTIS 1.6	MROS3REH604573268.	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>			
		DATE	: 1-Sep-19
		TIME	: 1400HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT LH DOOR <i>Repair</i>	1	\$ 1,322.30	\$ 1,322.30
2	BONNET <i>New</i>	1	\$ 1,255.90	\$ 1,322.30
3	FRONT BUMPER <i>Distorted</i>	1	\$ 594.00	\$ 594.00
4	FRONT BUMPER SIDE RETAINER <i>New</i>	1	\$ 62.00	\$ 62.00
5	FRONT BUMPER REINFORCEMENT SPONGE <i>not needed</i>	1	\$ 180.00	\$ 180.00
6	FRONT BUMPER FOGLAMP GARNISH <i>lit</i>	1	\$ 168.00	\$ 168.00
7	FRONT BUMPER FOGLAMP <i>needed</i>	1	\$ 380.00	\$ 380.00
8	FRONT HEADLAMP <i>needed</i>	1	\$ 2,553.60	\$ 2,553.60
9	FRONT HEADLAMP LOWER BRACKET <i>needed</i>	1	\$ 52.00	\$ 52.00
10	FRONT FENDER <i>Distorted</i>	1	\$ 422.50	\$ 422.50
11	FRONT FENDER EMBLEM "VVT-I" <i>New</i>	1	\$ 63.20	\$ 63.20
12	FRONT FENDER INNER COWLING <i>ton</i>	1	\$ 230.00	\$ 230.00
13	FRONT WHEEL HOUSE PANEL <i>Repair</i>	1	\$ 523.10	\$ 523.10
14	AIR CLEANER BOX ASSY <i>needed</i>	1	\$ 480.00	\$ 354.10
15	AIR CLEANER BOX PIPE <i>needed</i>	1	\$ 255.90	\$ 235.10
16	FRONT LH LOWER ARM <i>Bent</i>	1	\$ 354.10	\$ 354.10
17	FRONT LH STABILIZING LINK <i>New</i>	1	\$ 235.10	\$ 235.10
18	FRONT KNUCKLE ARM LH <i>Bent</i>	1	\$ 232.10	\$ 232.10
19	FRONT KNUCKLE ARM BEARING LH <i>me</i>	1	\$ 187.20	\$ 187.20

20	FRONT SHOCK ABSORBER LH <i>Bent</i>	1	\$	326.50	\$	326.50	<i>✓</i>
----	-------------------------------------	---	----	--------	----	--------	----------

6394.40
4795.80

TOTAL PRICE \$ 9,797.20
LESS 25% \$ 2,449.30
SUB TOTAL PRICE \$ 7,347.90

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS (SET) <i>Ne</i>	1	\$ 20.00	\$ 20.00
2	HEADLAMP CLIPS <i>Ne</i>	1	\$ 20.00	\$ 20.00
3	FRONT FENDER COWLING CLIPS <i>Ne</i>	1	\$ 20.00	\$ 20.00
4	FRONT WHEEL RIM LH <i>lit</i>	1	\$ 950.00	\$ 950.00
5	FRONT WHEEL TYRE LH <i>Ne</i>	1	\$ 280.00	\$ 280.00

510

TOTAL \$ 1,290.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	700.
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	800.
3	TO REMOVE AND REFIX FRONT LH DOOR	\$ 250.00	x
4	TUFF COAT	\$ 250.00	x
5	WIRING CHECK	\$ 250.00	30
6	REFOCUS HEADLAMP BEAM	\$ 60.00	x
7	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 350.00	220
8	FOUR WHEEL ALIGNMENT	\$ 120.00	80.

TOTAL

\$3,680.00

1830

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,637.90
TOTAL LABOUR COST : \$ 3,680.00
TOTAL REPAIR COST : \$ 12,317.90

APPROVED DETAILS

SURVEYOR

CONTACT NO

PART BY PART / LUMP SUM

NO OF DAYS

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
 - To display damaged part(s) during resurvey
 - Part(s) are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary report must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FAX

Adrian Lj
1/203/09/19.

06 Days.

total 7135.80.

48 : 5.7K