

Code	Description	WU	Price SGD
86451R00	R + R LEFT FRONT WHEELHOUSE SHELL	3.0	15.00
77000R00	RENEW R/R DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY	18.0	90.00
87755R00	R + R R/SILL TRIM	3.0	15.00
86520R00	RENEW REAR BUMPER (REMOVED)	11.0	55.00
86630R00)	R + R REAR BUMPER CARRIER	4.0	20.00
87111R00	REAR SCREEN R + R INCLUDES: REAR SEAT BACKREST AND ALL REQUIRED TRIMS REMOVE AND REFIT	22.0	110.00
69200R00)	R + R BOOTLID	5.0	25.00
NO NUMBER	RENEW R/R SIDE PANEL	72.0	360.00
71601R00 ZAX	RENEW R/R INNER SIDE PANEL	34.0	170.00
85875R00)	R + R R/R SILL MOULDING	1.0	5.00
68869R00)	R + R R/LOAD COMPARTMENT TRIM	1.0	5.00
85710R00	R + R BOOT CARPET	2.0	10.00
68869R0B)	R + R L/- AND R/BOOT TRIM (ADD)	2.0	10.00
59700R00)	R/HAND BRAKE CABLE REMOVE + REFIT	1.0	5.00
59700R0B)	R + R HANDBRAKE CABLE/S ADD/WORK	1.0	5.00
52951R00)	R + R LEFT FRONT WHEEL	1.0	5.00
52951R0B)	R + R FRONT WHEEL/WHEELS ADD WORK	1.0	5.00
55400R00)	R + R REAR AXLE INCLUDES: WHEELS AND CONTROL ROD R + R REAR STAILIZER	3.0	15.00
55400R00)	RENEW REAR AXLE CARRIER (REMOVED) INCLUDES: R + R REAR STAILIZER	1.0	5.00
28301R00)	R + R L/REAR TRAILING LINK	2.0	10.00
52723R00)	R + R R/R STEERING KNUCKLE (WHEEL REMOVED) INCLUDES: ENG S-ABSORB, REAR TRAIL ARM AND REAR LOWER AXLE RADIUS ARM R + R	1.0	5.00
52723R00)	RENEW R/R STEERING KNUCKLE (REMOVED) INCLUDES: BRAKE DISC, BRAKE BACK PLATE, WHEEL HUB AND RR UPP AXLE STEERING R + R	5.0	25.00
58415R00)	R + R LEFT REAR BRAKE DISC	2.0	10.00
55310R00)	R + R L/R SHOCK ABSORBER	1.0	5.00
55310R00)	DIS + ASS L/R AND R/R SPRING STRUT (REM)	5.0	25.00
55201R00)	R + R L/R LOWER CONTROL ARMS FRONT	1.0	5.00
55250R00)	R + R LEFT REAR CONTROL ARM FRONT	1.0	5.00
55250R00)	R + R RIGHT REAR CONTROL ARM FRONT	1.0	5.00
52910R00)	R + R L/F TYRE (WHEEL REMOVED) INCLUDES: BALANCE WHEEL	1.0	5.00
52910R00)	R + R R/R TYRE (WHEEL REMOVED) INCLUDES: BALANCE WHEEL	1.0	5.00
52910R0C)	R + R TYRE/WHEEL (ADD/WORK)	1.0	5.00
28700R00	R + R REAR MUFFLER	4.0	20.00
56800A00	ALIGN REAR TOE	4.0	20.00
1482	RIGHT FRONT DOOR REPAIR	20.0*	100.00
2711	REAR PANEL REPAIR	20.0*	100.00
2931	BOOTLID REPAIR	20.0*	100.00
3482	R/R SIDE PANEL CPL REPAIR	20.0*	100.00
3572	R/R REARLAMP SUPP REPAIR	20.0*	100.00
3900	BOOTFLOOR CPL REPAIR	20.0*	100.00

Code	Description	WU	Price SGD
3916	R/R FLOOR PANEL REPAIR	20.0*	100.00
3992	R/R SIDE MEMBER REPAIR	20.0*	100.00

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	37.60	376.0	1,880.00
Total of Labour			1,880.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description		WU	Price SGD
	RIGHT FRONT DOOR NEW PART PAINTING		15.0	
	R/R DOOR NEW PART PAINTING		14.0	
	REAR PANEL NEW PART PAINTING		20.0	
	R/R REARLAMP SUPP SURFACE PAINT		4.0	
	R/R WHEELHOUSE SURFACE PAINT		5.0	
	R/SILL PANELLING NEW PART PAINT K1R		6.0	
	REAR BUMPER NEW PART PAINT K1R		12.0	
	BOOTLID OUT PANEL NEW PART PAINT K1R		5.0	
	BOOTLID REPAIR PAINTING <50%		17.0	
	R/R SIDE PANEL CPL REPAIR PAINTING >50%		17.0	
	BOOTFLOOR CPL SURFACE PAINT		10.0	

Paint Material Per Part

Code	Description	Price SGD
1482	RIGHT FRONT DOOR NEW PART PAINTING	35.06
1782	R/R DOOR NEW PART PAINTING	31.03
2711	REAR PANEL NEW PART PAINTING	21.41
3572	R/R REARLAMP SUPP SURFACE PAINT	2.11
4102	R/R WHEELHOUSE SURFACE PAINT	5.28
2208	R/SILL PANELLING NEW PART PAINT K1R	20.24
2583	REAR BUMPER NEW PART PAINT K1R	49.91
2935	BOOTLID OUT PANEL NEW PART PAINT K1R	10.47
2931	BOOTLID REPAIR PAINTING <50%	27.00
3482	R/R SIDE PANEL CPL REPAIR PAINTING >50%	15.41
3900	BOOTFLOOR CPL SURFACE PAINT	27.63

Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			125.0	
Preparation Main Work Metal		1.70	17.0	85.00
Preparation Comp. Work Plastic		0.30	3.0	15.00
Total		10 WU/h	14.50	145.0

Material Cost - Paint

New Part Painting	87.50
New Part Painting - Plastic K1R	80.62
Repair Painting	42.41
Surface-/Blend Paint	35.02
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	272.65

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0841	L/F WHEELHOUSE COVER	868112T500		120.00
1782	R/R DOOR	770042T000		765.00
1984	R/R DR FRM FRT TRIM	831452T000		0.00
1986	R/R DOOR FRM UP TRIM	831342T000		0.00
1988	R/R DOOR FRT MLDG	863912T000		0.00
1992	R/R UPP DOOR MLDG	838602T000		0.00
2208	R/SILL PANELLING	877522T000		286.00
2583	REAR BUMPER	866112T500		696.00
2618	R/R BUMPER BRACKET	866142T501		29.00
2640	REAR BUMPER SUPPORT	866312T500		607.00
2641	L/R C-MEMBER BRACKET	866412T500		54.00
2652	R/R VENT GRILLE	975103V000		30.00
3160	REAR SCREEN BOND KIT	ZK20063001A		0.00
3163	REAR SCREEN FIX SET	USE SINGLE PARTS		
3169	LWR REAR WINDOW MLDG	871302T000		98.00
3171	REAR SCREEN SUPPORTS	861143D000		0.00
3173	REAR SCREEN SPACER	871143K000		0.00
3288	R/R OUTER LAMP	924122T510		421.00
3414	R/R REFLECTOR	924062T500		26.00
3486	R/R OUTER SIDE PANEL	715042TC00		1,205.00
4102	R/R WHEELHOUSE	716022T500		809.00
4202	R/R WHEELHOUSE CVR	868222T500		212.00
7201	L/F WHEEL	529102T100		246.00
7211	L/F WHEEL COVER	529602T100		120.00
7227	L/F TYRE	205/65 R 16 .. H		100.00
7248	R/R ABS SENSOR	599302T000	- shld (A)	232.00
9081	REAR AXLE SUBFRAME	554053R800		654.00
9182	R/R WHEEL HUB/BRG	527303S200		349.00
9202	R/R SHOCK ABSORBER	553112T230		313.00
9212	R/R BUFFER	553483M000	(A)	60.00 Sup
9232	R/R DAMPER BRACKET	553303R011		79.00
9306	R/R STRG KNUCKLE	527202T010		525.00
9316	R/R CONTROL ARM	552802T100		159.00
9386	R/R LWR CONTROL ARM	552203S050		351.00
9392	R/F CONTROL ARM FRT	552503R000		163.00
9394	R/R UPP CONTROL ARM	551003R050		84.00
9552	R/R WHEEL	529102T100		246.00
9560	R/R WHEEL COVER	529602T100		116.00
9566	R/R TYRE	205/65 R 16 .. H		100.00

f: OEM Parts

n: Non-OEM Parts

u: Used parts

Savings**0.00**

Subtotal	9,255.00
Subtotal Discount(+35.00%)	-3,239.25
Total	6,015.75

Extras

Code	Description	Price SGD
1000	Rr. bumper clips	48.00*
1003	Door sticker	100.00*
1004	Rr. fender sticker	60.00*
1006	Sealant	50.00*
1007	Sundry	30.00*
1008	Towing fee	50.00*
1009	Check alignment	60.00*
	Total Extras	398.00

Final Calculation

	SGD	SGD
Parts	9,255.00	
Total Discount(+35.00%)	-3,239.25	
Total Parts		6,015.75
Labour Time Base 10 WU/h		
Total 376.0 WU X 50.00 SGD/h	1,880.00	
Total of Labour		1,880.00
Total Of Extras		398.00
Paint Work Time Base 10 WU/h		
Labour Cost 145.0 WU X 50.00 SGD/h	725.00	
Material Cost	272.65	
Total Paint Including Material		997.65
Repair Cost Excludes GST		9,291.40
GST (+7.0%)		650.40
Repair Cost Included GST		9,941.80

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Finalized

Insurer Reference:
Repairer Reference: SHB8789A
Date calculated: 14/10/2019 12:46 PM

Full Report
Registration: SHB8789A
Printed: 14/10/2019 12:46 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	03/09/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle
Manufacturer: KIA
Model: OPTIMA (TF)
Sub Model: 2 LUXE
Model Sheet Number: 28 36 38
Registration: SHB8789A
VIN number:
Odometer:
Model Specs
2.0 LTR 121KW

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
86451R00	R + R LEFT FRONT WHEELHOUSE SHELL		3.0	15.00
77000R00	RENEW R/R DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY		18.0	90.00
87755R00	R + R R/SILL TRIM		3.0	15.00
86520R00	RENEW REAR BUMPER (REMOVED)		11.0	55.00
86630R00)	R + R REAR BUMPER CARRIER		4.0	20.00
87111R00	REAR SCREEN R + R INCLUDES: REAR SEAT BACKREST AND ALL REQUIRED TRIMS REMOVE AND REFIT		22.0	110.00
69200R00)	R + R BOOTLID		5.0	25.00
NO NUMBER	RENEW R/R SIDE PANEL		72.0	360.00
71601R00 ZAX	RENEW R/R INNER SIDE PANEL		34.0	170.00
85875R00)	R + R R/R SILL MOULDING		1.0	5.00
68869R00)	R + R R/LOAD COMPARTMENT TRIM		1.0	5.00
85710R00	R + R BOOT CARPET		2.0	10.00
68869R0B)	R + R L/- AND R/BOOT TRIM (ADD)		2.0	10.00
59700R00)	R/HAND BRAKE CABLE REMOVE + REFIT		1.0	5.00
59700R0B)	R + R HANDBRAKE CABLE/S ADD/WORK		1.0	5.00
52951R00)	R + R LEFT FRONT WHEEL		1.0	5.00
52951R0B)	R + R FRONT WHEEL/WHEELS ADD WORK		1.0	5.00
55400R00)	R + R REAR AXLE INCLUDES: WHEELS AND CONTROL ROD R + R REAR STAILIZER		3.0	15.00
55400R00)	RENEW REAR AXLE CARRIER (REMOVED) INCLUDES: R + R REAR STAILIZER		1.0	5.00
28301R00)	R + R L/REAR TRAILING LINK		2.0	10.00
52723R00)	R + R R/R STEERING KNUCKLE (WHEEL REMOVED) INCLUDES: ENG S-ABSORB, REAR TRAIL ARM AND REAR LOWER AXLE RADIUS ARM R + R		1.0	5.00
52723R00)	RENEW R/R STEERING KNUCKLE (REMOVED) INCLUDES: BRAKE DISC, BRAKE BACK PLATE, WHEEL HUB AND RR UPP AXLE STEERING R + R		5.0	25.00
58415R00)	R + R LEFT REAR BRAKE DISC		2.0	10.00
55310R00)	R + R L/R SHOCK ABSORBER		1.0	5.00
55310R00)	DIS + ASS L/R AND R/R SPRING STRUT (REM)		5.0	25.00
55201R00)	R + R L/R LOWER CONTROL ARMS FRONT		1.0	5.00
55250R00)	R + R LEFT REAR CONTROL ARM FRONT		1.0	5.00
55250R00)	R + R RIGHT REAR CONTROL ARM FRONT		1.0	5.00
52910R00)	R + R L/F TYRE (WHEEL REMOVED) INCLUDES: BALANCE WHEEL		1.0	5.00
52910R00)	R + R R/R TYRE (WHEEL REMOVED) INCLUDES: BALANCE WHEEL		1.0	5.00
52910R0C)	R + R TYRE/WHEEL (ADD/WORK)		1.0	5.00
28700R00	R + R REAR MUFFLER		4.0	20.00
56800A00	ALIGN REAR TOE		4.0	20.00
1482	RIGHT FRONT DOOR REPAIR		20.0*	100.00
2711	REAR PANEL REPAIR		20.0*	100.00
2931	BOOTLID REPAIR		20.0*	100.00

Code	Description	WU	Price SGD
3482	R/R SIDE PANEL CPL REPAIR	20.0*	100.00
3572	R/R REARLAMP SUPP REPAIR	20.0*	100.00
3900	BOOTFLOOR CPL REPAIR	20.0*	100.00
3916	R/R FLOOR PANEL REPAIR	20.0*	100.00
3992	R/R SIDE MEMBER REPAIR	20.0*	100.00

Labour Cost
Panel / Mechanical Labour

Hrs **WU**
37.60 **376.0** **1,880.00**

Total of Labour

1,880.00

Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description	WU	Price SGD
	RIGHT FRONT DOOR NEW PART PAINTING	15.0	
	R/R DOOR NEW PART PAINTING	14.0	
	REAR PANEL NEW PART PAINTING	20.0	
	R/R REARLAMP SUPP SURFACE PAINT	4.0	
	R/R WHEELHOUSE SURFACE PAINT	5.0	
	R/SILL PANELLING NEW PART PAINT K1R	6.0	
	REAR BUMPER NEW PART PAINT K1R	12.0	
	BOOTLID OUT PANEL NEW PART PAINT K1R	5.0	
	BOOTLID REPAIR PAINTING <50%	17.0	
	R/R SIDE PANEL CPL REPAIR PAINTING >50%	17.0	
	BOOTFLOOR CPL SURFACE PAINT	10.0	

Paint Material Per Part

Code	Description	Price SGD
1482	RIGHT FRONT DOOR NEW PART PAINTING	35.06
1782	R/R DOOR NEW PART PAINTING	31.03
2711	REAR PANEL NEW PART PAINTING	21.41
3572	R/R REARLAMP SUPP SURFACE PAINT	2.11
4102	R/R WHEELHOUSE SURFACE PAINT	5.28
2208	R/SILL PANELLING NEW PART PAINT K1R	20.24
2583	REAR BUMPER NEW PART PAINT K1R	49.91
2935	BOOTLID OUT PANEL NEW PART PAINT K1R	10.47
2931	BOOTLID REPAIR PAINTING <50%	27.00
3482	R/R SIDE PANEL CPL REPAIR PAINTING >50%	15.41
3900	BOOTFLOOR CPL SURFACE PAINT	27.63

Labour Cost - Paint

Factor

50.00 SGD/h

Time Paint

125.0

Preparation Main Work Metal

1.70

17.0

85.00

Preparation Comp. Work Plastic

0.30

3.0

15.00

Total

10 WU/h

14.50

145.0

725.00

Material Cost - Paint

New Part Painting
New Part Painting - Plastic K1R
Repair Painting
Surface-/Blend Paint
Material-constant Metal
Material-constant Plastic
Total

Price SGD
87.50
80.62
42.41
35.02
18.10
9.00
272.65

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0841	L/F WHEELHOUSE COVER	868112T500		120.00
1782	R/R DOOR	770042T000		765.00
1984	R/R DR FRM FRT TRIM	831452T000		0.00
1986	R/R DOOR FRM UP TRIM	831342T000		0.00
1988	R/R DOOR FRT MLDG	863912T000		0.00
1992	R/R UPP DOOR MLDG	838602T000		0.00
2208	R/SILL PANELLING	877522T000		286.00
2583	REAR BUMPER	866112T500		696.00
2618	R/R BUMPER BRACKET	866142T501		29.00
2640	REAR BUMPER SUPPORT	866312T500		607.00
2641	L/R C-MEMBER BRACKET	866412T500		54.00
2652	R/R VENT GRILLE	975103V000		30.00
3160	REAR SCREEN BOND KIT	ZK20063001A		0.00
3163	REAR SCREEN FIX SET	USE SINGLE PARTS		
3169	LWR REAR WINDOW MLDG	871302T000		98.00
3171	REAR SCREEN SUPPORTS	861143D000		0.00
3173	REAR SCREEN SPACER	871143K000		0.00
3288	R/R OUTER LAMP	924122T510		421.00
3414	R/R REFLECTOR	924062T500		26.00
3486	R/R OUTER SIDE PANEL	715042TC00		1,205.00
4102	R/R WHEELHOUSE	716022T500		809.00
4202	R/R WHEELHOUSE CVR	868222T500		212.00
7201	L/F WHEEL	529102T100		246.00
7211	L/F WHEEL COVER	529602T100		120.00
7227	L/F TYRE	205/65 R 16 .. H		100.00
7248	R/R ABS SENSOR	599302T000	(A)	232.00
9081	REAR AXLE SUBFRAME	554053V150DS		654.00
9182	R/R WHEEL HUB/BRG	527303S200		349.00
9202	R/R SHOCK ABSORBER	553112T230		313.00
9212	R/R BUFFER	553483M000	(A)	60.00
9232	R/R DAMPER BRACKET	553303R011		79.00
9306	R/R STRG KNUCKLE	527202T010		525.00
9316	R/R CONTROL ARM	552802T100		159.00
9386	R/R LWR CONTROL ARM	552203S050		351.00
9392	R/F CONTROL ARM FRT	552503R000		163.00
9394	R/R UPP CONTROL ARM	551003R050		84.00
9552	R/R WHEEL	529102T100		246.00
9560	R/R WHEEL COVER	529602T100		116.00
9566	R/R TYRE	205/65 R 16 .. H		100.00
				0.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings

Subtotal	9,255.00
Subtotal Discount(+35.00%)	-3,239.25
Total	6,015.75

Extras

Code	Description	Price SGD
1000	Rr. bumper clips	48.00*
1003	Door sticker	100.00*
1004	Rr. fender sticker	60.00*
1006	Sealant	50.00*
1007	Sundry	30.00*
1008	Towing fee	50.00*
1009	Check alignment	60.00*
	Total Extras	398.00

Final Calculation

	SGD	SGD
Parts	9,255.00	
Total Discount(+35.00%)	-3,239.25	
Total Parts		6,015.75
Labour Time Base 10 WU/h		
Total 376.0 WU X 50.00 SGD/h	1,880.00	
Total of Labour		1,880.00
Total Of Extras		398.00
Paint Work Time Base 10 WU/h		
Labour Cost 145.0 WU X 50.00 SGD/h	725.00	
Material Cost	272.65	
Total Paint Including Material		997.65
Repair Cost Excludes GST		9,291.40
GST (+7.0%)		650.40
Repair Cost Included GST		9,941.80

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2019		04 Sep 2019 16:57 Edit Adj Rpt	S\$7,400.00 Edit Estimates	S\$7,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GRAB RENTALS PTE.LTD., Co. Reg. No.: 201617200G								
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHB8789A	Date of Loss:	03/09/2019 13:00 - :59 [68 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 604769	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLV7027U	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	Premier Taxis Pte Ltd - Changi South (HQ) 23 CHANGI SOUTH AVENUE 2, #01-02, 486443 Changi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 04/10/2019]								
Driver/Custodian (Insured):	LIEW SHAN HONG (51 / Male) , NRIC: S6803724G, Tel: +6591691865 Email:								
Adj Asg. Remarks:	on WP. CAR IN. OI:Grab. Liab: clear. Contact: Liew @ 6544 6689. Please contact us ASAP if you cannot attend this assignment.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
MSIG_SG (04/09/2019): Cancellation of Assignment: SHB8789A									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB8789A (604769)
[SLV7027U]
TP
PREMIER TAXIS PTE LTD
Sep 3 2019 1:00PM
[GRAB RENTALS PTE.LTD.]
Premier Taxis Pte Ltd - Changi South

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	04/09/19 15:03	Accident Statement From: SC - Reg. No: SLV7027U, Claimant: GRAB RENTALS PTE.LTD.		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/09/19 11:57	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/09/19 09:07	General View		Load JPG	☒
2	09/09/19 09:07	General View		Load JPG	☒
3	09/09/19 09:07	General View		Load JPG	☒
4	09/09/19 09:07	General View		Load JPG	☒
5	09/09/19 09:07	General View		Load JPG	☒
6	09/09/19 09:07	General View		Load JPG	☒
7	09/09/19 09:07	General View		Load JPG	☒
8	09/09/19 09:07	General View		Load JPG	☒
9	09/09/19 09:07	General View		Load JPG	☒
10	09/09/19 09:07	General View		Load JPG	☒
11	09/09/19 09:07	General View		Load JPG	☒
12	09/09/19 09:07	General View		Load JPG	☒
13	09/09/19 09:07	General View		Load JPG	☒
14	09/09/19 09:07	General View		Load JPG	☒
15	09/09/19 09:07	General View		Load JPG	☒
16	09/09/19 09:07	General View		Load JPG	☒
17	09/09/19 09:07	General View		Load JPG	☒
18	09/09/19 09:07	General View		Load JPG	☒
19	09/09/19 09:07	General View		Load JPG	☒
20	09/09/19 09:07	General View		Load JPG	☒
21	09/09/19 09:07	General View		Load JPG	☒
22	09/09/19 09:07	General View		Load JPG	☒
23	09/09/19 09:07	General View		Load JPG	☒
24	09/09/19 09:07	General View		Load JPG	☒
25	09/09/19 09:07	General View		Load JPG	☒
26	09/09/19 09:07	General View		Load JPG	☒
27	09/09/19 09:07	General View		Load JPG	☒
28	09/09/19 09:07	General View		Load JPG	☒
29	09/09/19 09:07	General View		Load JPG	☒
30	09/09/19 09:07	General View		Load JPG	☒
31	09/09/19 09:07	General View		Load JPG	☒
32	09/09/19 09:07	General View		Load JPG	☒
33	09/09/19 09:07	General View		Load JPG	☒
34	09/09/19 09:07	General View		Load JPG	☒
35	09/09/19 09:07	General View		Load JPG	☒
36	09/09/19 09:07	General View		Load JPG	☒
37	09/09/19 09:07	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
38	09/09/19 09:07	General View	 Load JPG	☒
39	09/09/19 09:07	General View	 Load JPG	☒
40	09/09/19 09:07	General View	 Load JPG	☒
41	09/09/19 09:07	General View	 Load JPG	☒
42	09/09/19 09:07	General View	 Load JPG	☒
43	09/09/19 09:07	General View	 Load JPG	☒
44	09/09/19 09:07	General View	 Load JPG	☒
45	09/09/19 09:07	General View	 Load JPG	☒
46	09/09/19 09:07	General View	 Load JPG	☒
47	09/09/19 09:07	General View	 Load JPG	☒
48	09/09/19 09:07	General View	 Load JPG	☒
49	09/09/19 09:07	General View	 Load JPG	☒
50	09/09/19 09:07	General View	 Load JPG	☒
51	09/09/19 09:07	General View	 Load JPG	☒
52	09/09/19 09:07	General View	 Load JPG	☒
53	09/09/19 09:07	General View	 Load JPG	☒
54	09/09/19 09:07	General View	 Load JPG	☒
55	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
56	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
57	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
58	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
59	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
60	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
61	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
62	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
63	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
64	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
65	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
66	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
67	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
68	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
69	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
70	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
71	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
72	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
73	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
74	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
75	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
76	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
77	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
78	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
79	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
80	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
81	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
82	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
83	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
84	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
85	14/10/19 08:37	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/09/19 15:03	TPD SHB8789A GIA REPORT From: SC - Reg. No: SLV7027U, Claimant: GRAB RENTALS PTE.LTD.	 Load PDF	
2	04/09/19 15:04	TPD SHB8789A - PRI	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	04/09/19 15:47	Email - Survey 05/09/19	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/10/19 09:51	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19015711/K1VF3E2
Date: 24/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29114756MKF
Claimant Vehicle No: SHB8789A Insured Vehicle No: SLV7027U
Date of Loss: 03/09/2019 Nature of Claim: TP Claim No: 604769

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB8789A Engine No: D4FDDH308854
Make & Model: KIA OPTIMA, 1.7 D (A) Chassis No: KNAGM414ME5452749
Reg. Date: 30/12/2013 (Man. Year: 2013) Odometer: 0 km
Colour: Silver
Engine Capacity: 1685 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16
Front Left Side: Hankook 7 mm Rear Left Side: Hankook 7 mm
Front Right Side: Hankook 7 mm Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,231.20	6,303.75	2,927.45	31.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,292.65	2,987.65	305.00	9.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,523.85	9,291.40	3,232.45	25.81
Approved Total (Overridden) (\$\$)		7,400.00		
(\$\$)	12,523.85	7,400.00	5,123.85	40.91
+ GST 7.00/7.00% (\$\$)	876.67	518.00	358.67	40.91
Nett Amount (\$\$)	13,400.52	7,918.00	5,482.52	40.91

INSPECTION

Date of Assignment: 04/09/2019
Date Inspected: 05/09/2019 Inspected At: Premier Taxis Pte Ltd - Changi South (HQ)
23 CHANGI SOUTH AVENUE 2, #01-02
Singapore 486443

Estimated Period of Repair: 10.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Oct 2019)
Parts: 143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHB8789A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/F WHEELHOUSE COVER	Grazed	120.00 FL	*120.00 FL
2	1		*RIGHT FRONT DOOR	Repair	761.00 FL	*- FL
3	1		*R/F DOOR RR MOULDING (NPA)	Serviceable	0.00 FL	*- FL
4	1		*R/F UPP DOOR MLDG (NPA)	Serviceable	0.00 FL	*- FL
5	1		*R/R DOOR	Buckled	765.00 FL	*765.00 FL
6	1		*R/R DR FRM FRT TRIM (NPA)	Serviceable	0.00 FL	*- FL
7	1		*R/R DOOR FRM UP TRIM (NPA)	Serviceable	0.00 FL	*- FL
8	1		*R/R DOOR FRT MLDG (NPA)	Serviceable	0.00 FL	*- FL
9	1		*R/R UPP DOOR MLDG (NPA)	Serviceable	0.00 FL	*- FL
10	1		*R/R DOOR FRAME SEAL	Serviceable	76.00 FL	*- FL
11	1		*R/SILL PANELLING	Deformed	286.00 FL	*286.00 FL
12	1		*REAR BUMPER	Cracked	696.00 FL	*696.00 FL
13	1		*L/R BUMPER BRACKET	Serviceable	29.00 FL	*- FL
14	1		*R/R BUMPER BRACKET	Cracked	29.00 FL	*29.00 FL
15	1		*REAR BUMPER SUPPORT	Cracked	607.00 FL	*607.00 FL
16	1		*L/R C-MEMBER BRACKET	Cracked	54.00 FL	*54.00 FL
17	1		*R/R C-MEMBER BRACKET	Serviceable	54.00 FL	*- FL
18	1		*REAR BUMPER DAMPER	Serviceable	114.00 FL	*- FL
19	1		*R/R VENT GRILLE	Missing	30.00 FL	*30.00 FL
20	1		*REAR PANEL	Repair	250.00 FL	*- FL
21	1		*REAR BUMPER SPOILER	Serviceable	66.00 FL	*- FL
22	1		*BOOTLID OUT PANEL	Serviceable	260.00 FL	*- FL
23	1		*L/BOOTLID HINGE	Serviceable	66.00 FL	*- FL
24	1		*R/BOOTLID HINGE	Serviceable	66.00 FL	*- FL
25	1		*REAR SCREEN BOND KIT (NPA)	Necessary	0.00 FL	*- FL
26	1		*SET REAR SCREEN FIX (NPA)	Necessary	0.00 FL	*- FL
27	1		*LWR REAR WINDOW MLDG	Cracked	98.00 FL	*98.00 FL
28	1		*REAR SCREEN SUPPORTS (NPA)	Not Necessary	0.00 FL	*- FL
29	1		*REAR SCREEN SPACER (NPA)	Not Necessary	0.00 FL	*- FL
30	1		*R/R OUTER LAMP	Cracked	421.00 FL	*421.00 FL
31	1		*R/R INNER LAMP	Serviceable	350.00 FL	*- FL
32	1		*R/R REFLECTOR	Cracked	26.00 FL	*26.00 FL
33	1		*R/R OUTER SIDE PANEL	Buckled	1,205.00 FL	*1,205.00 FL
34	1		*R/R REARLAMP SUPP	Repair	218.00 FL	*- FL
35	1		*R/R FLOOR PANEL	Repair	65.00 FL	*- FL
36	1		*R/R WHEELHOUSE	Buckled	809.00 FL	*809.00 FL
37	1		*R/R WHEELHOUSE CVR	Buckled	212.00 FL	*212.00 FL
38	1		*REAR PANEL TRIM	Serviceable	74.00 FL	*- FL
39	1		*R/F LWR CONTROL ARM	Serviceable	439.00 FL	*- FL
40	1		*R/F STRUT	Serviceable	330.00 FL	*- FL
41	1		*R/F STEERING KNUCKLE	Serviceable	547.00 FL	*- FL
42	1		*L/F WHEEL	Bent	246.00 FL	*246.00 FL
43	1		*L/F WHEEL COVER	Cracked	120.00 FL	*120.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*L/F TYRE (\$200.00) (50%)	Cut	200.00 FL	*100.00 FL
45	1		*LWR FRT ENGINE COVER	Serviceable	44.00 FL	*- FL
46	1		*L/LWR ENG COMP COVER	Serviceable	144.00 FL	*- FL
47	1		*REAR AXLE SUBFRAME	Bent	654.00 FL	*654.00 FL
48	1		*R/R WHEEL HUB / BRG	Bent	349.00 FL	*349.00 FL
49	1		*R/R SHOCK ABSORBER	Bent	313.00 FL	*313.00 FL
50	1		*R/R DAMPER BRACKET	Bent	79.00 FL	*79.00 FL
51	1		*R/R STRG KNUCKLE	Bent	525.00 FL	*525.00 FL
52	1		*R/R CONTROL ARM	Bent	159.00 FL	*159.00 FL
53	1		*R/R LWR CONTROL ARM	Bent	351.00 FL	*351.00 FL
54	1		*R/F CONTROL ARM FRT	Bent	163.00 FL	*163.00 FL
55	1		*R/R UPP CONTROL ARM	Bent	84.00 FL	*84.00 FL
56	1		*R/R WHEEL	Bent	246.00 FL	*246.00 FL
57	1		*R/R WHEEL COVER	Cracked	116.00 FL	*116.00 FL
58	1		*R/R TYRE (\$200.00) (50%)	Cut	200.00 FL	*100.00 FL
59	1		*RR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
60	1		*RR BUMPER PROTECTOR	Not Necessary	80.00 FS	*- FS
61	1		*BOOTLID STICKER	Not Necessary	100.00 FS	*- FS
62	1		*DOOR STICKER	Necessary	100.00 FS	*100.00 FS
63	1		*RR FENDER STICKER	Necessary	60.00 FS	*60.00 FS
64	1		*RR LINER CLIPS	Not Necessary	28.00 FS	*- FS
65	1		*SEALANT	Necessary	50.00 FS	*50.00 FS
66	1		*SUNDRY	Necessary	50.00 FS	*30.00 FS
67	1		*R/R ABS SENSOR	Shorted	232.00 FL	*232.00 FL
68	1		*R/R BUFFER	Necessary	60.00 FL	*60.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,924.00	9,543.00
- List Item Discount on L Items 35.00/35.00% (\$\$)	4,692.80	3,239.25
Total Parts (\$\$)	9,231.20	6,303.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	50.00	50.00
2	CHECK ALIGNMENT	New	80.00	60.00
3	433.0 WU X 50.00 SGD/H	New	2,165.00	1,880.00
4	LABOUR COST 145.0 WU X 50.00 SGD/H	New	725.00	725.00
5	MATERIAL COST	New	272.65	272.65
Gross Labour Cost (S\$)			3,292.65	2,987.65

Report was unsubmitted during this print-out.

< END OF ESTIMATES >