

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20002248/UKA3Q2

Date: 09/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994102

Claimant
Vehicle No : SJL9096H **Insured Vehicle No :** SJX384Y

Date of Loss: 21/01/2020 Nature of Claim: TP Claim No: 7461284929SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL9096H		
Make & Model:	NISSAN TEANA, 2.0 CVT (A)	Engine No:	MR20723634A
Reg. Date:	16/12/2008 (Man. Year: 2008)	Chassis No:	JN1BDUJ32Z0000631
Colour:	White	Odometer:	130667 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,242.80	5,280.10	3,962.70	42.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,310.00	2,220.00	1,090.00	32.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	12,552.80	7,500.10	5,052.70	40.25
Approved Total (Overridden) (\$)		6,000.00		
(S\$)	12,552.80	6,000.00	6,552.80	52.20
+ GST 7.00/7.00% (S\$)	878.70	420.00	458.70	52.20
Nett Amount (S\$)	13,431.50	6,420.00	7,011.50	52.20
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,927.45		

INSPECTION

Date of Assignment: 10/02/2020

Date Inspected: 10/02/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	1,266.10 F	*1,209.60 FL
2	1		*BOOTLID OUTER CHROME MOULDING TOP	Not Necessary	399.50 F	*- FL
3	1		*BOOTLID OUTER CHROME MOULDING LOWER	Bent / Cracked	229.80 F	*188.60 FL
4	1		*BOOTLID INNER LOCK	Twisted	109.50 F	*109.50 FL
5	1		*BOOTLID LOCK STICKER	Not Necessary	66.80 F	*- FL
6	1		*BOOTLID WEATHERSTRIP	Twisted	188.20 F	*186.30 FL
7	1		*BOOTLID INNER TRIM	Not Necessary	211.20 F	*- FL
8	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	30.00 F	*- FL
9	1		*REAR BUMPER	Distorted	860.00 F	*820.00 FL
10	2		*REAR BUMPER CHROME MOULDINGS	Cracked	290.00 F	*290.00 FL
11	1		*REAR BUMPER BEAM	Bent	340.50 F	*340.50 FL
12	2		*REAR BUMPER BEAM BRACKETS	Dented	210.00 F	*183.40 FL
13	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	71.00 F	*- FL
14	1		*SET REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
15	1		*TAILLAMPS	O/S Cracked	799.60 F	*480.50 FL
16	2		*TAILLAMP HOUSING PANELS	Repair	500.00 F	*- FL
17	1		*REAR END PANEL	Badly Dented	583.60 F	*566.00 FL
18	1		*REAR END PANEL TOP GARNISH	Twisted	109.60 F	*109.60 FL
19	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	699.20 F	*650.00 FL
20	2		*REAR FLOOR PANEL TOP SIDE SPONGES	Deformed / Torn	430.00 F	*420.00 FL
21	1		*REAR BUMPER SPONGE	Not Necessary	283.20 F	*- FL
22	2		*REAR FENDER INNER TRIMS	Not Necessary	770.00 F	*- FL
23	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
24	1		*SET REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
25	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
26	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,242.80	5,839.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	558.90
Total Parts (\$)	9,242.80	5,280.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	120.00	80.00
4	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
5	TO TRANSFER BOOTLID COMPONENTS	New	100.00	60.00
6	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
7	TO SPRAY RUST PROOFING	New	100.00	60.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,080.00	800.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,080.00
Gross Labour Cost (\$)			3,310.00	2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >