, i	Marau 5	ASSIGNMI				
From (Person	a): (hong Boon Se	or of CTI	y2	Da	te/Time: 59-19 b	48p.M
Estimated Co			Bill to:	-1111110-12	0.8000000000 <del>.2</del>	(8/1)
		ES/EVA/INV/MV/C	CS			
To Inspect V		XE 3276R		Insured:	XD GIIH	1
	m/s Mah han			Tel: _(	282	
	8 Defu Lany					
Policy No:	mucusn'	7266819000	Claim No:	SAMIADO	104159 COV	
Sum Insured			Excess:			
Make of Veh	The second secon			D.0	D.A. 30.8.2019	
(Client's Recor	The second secon		Sĩ Hui		O.A. 30.8. 2019	
(Client's Recor	rd)   REP.   REV 24)   59.19   16p. w	Person Contacted:		1	I.O.D Endorsement:	
(Client's Recon	7 REP. / REV 24   59.19   -16 p w	Person Contacted:		Vehi	I.O.D Endorsement:	
(Client's Recon	Action/Instruction	Person Contacted:  Person Contacted:  Stimute  NA 14 P1900699	n/ 15		1.O.D. Endorsement: cle IN JOUT	
(Client's Recon CA / REV Date/Time;	Action/Instruction	Person Contacted:	n/ 15		I.O.D Endorsement:	
(Client's Recon CA / REV Date/Time;	Action/Instruction	Person Contacted:  Person Contacted:  Stimute  NA 14 P1900699	n/ rs		1.O.D. Endorsement: cle IN JOUT	

REC. BY: Marcus	
-	SSIGNMENT
	Veh No: X = 3276 R Yr Regn: 8 17
Date:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
ated Cost:	Truck / Trailer or
TP/WS/TP RES/OD RES/EVA/INV/MV	
spect Vehicle No: XE 3276R	111 1 430
orkshop m/s Meh liga	
	Sp.Reading 236907 T/Radio: Insured / Std / NI / NA
ed:	Eng/No:
y No.	C/No: FVSISJA20256
ns No.	Gen. Cond: Good / Fair / Poor / Burnt
Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
ent's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
of Veh:	Modi : Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 298/60 n 22-5
olicy Condition)	R:
5-10-10-10-10-10-10-10-10-10-10-10-10-10-	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or FILLINZS
or Market Value:	Front Rear
C Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6/6 mm
/ PR Seen: Consistent? : Yes or No	L/Bal. 6/6 / 6mm
Repairs: 7/0 days Res.: Yes or No	D.O.A. 30/8/19 D.O.I. 5/3/19
Sum: % 3 Val.: Yes or No	Survey held at
1 REV 1 REP. 1 24 HRS MA 31780	
Vehicle: IN / 0 Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
	The Ord / Chassis Halle / Body Chastac discuss as a component
Control Contro	ud with Sihui (Red \$ 9763.71, 38%)
9/0 1/0 1/ 200 0	1 . S. S. 1001 2 Bohz 21 200/1
111 MS \$ 10, 200 CONTIC	ma win seven (10 10 10 10 10 10)
1	
	RECEIVED 1 2 SEP 2019
N N	
"Time, File Pass to? : Preli. Report	Days Of Repair: (0
Ng MMm □: Final Report	Resurvey No. of Trip: 2 Survey Fee:
e/Time, File Return to?	Transportation:
Add	Fee:: Site Insp (\$ )S+RS,Si
NEW TO	: Interview (\$ ) Photos
eport Format: MER-TP	: Tech. Invs (\$ ) Others

### Nivitha (LKK Auto)

From:

Chong Boon Sen <booksen.chong@sg.cntaiping.com>

Sent:

Thursday, 5 September 2019 12:48 PM

To:

Jacqueline Tan; Claims Dept of CTI; Elaine Cheong; Alfred Toh; Chee So Chow

Cc:

jeromesoh@visionlawllc.com; 'Si Hui Goh'; assignments

Subject:

RE: URGENT ATTENTION: RE: OUR REF: SNM19D204159-XD6311H-CML - FW: Pre

Repair Survey cases (Reminder)

#### WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

### Chong Boon Sen

Claims Executive Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Jacqueline Tan [mailto:jactan@visionlawllc.com]

Sent: Thursday, 5 September, 2019 12:07 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Elaine Cheong

<elaine.cheong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow

<sochow.chee@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: jeromesoh@visionlawllc.com; 'Si Hui Goh' <sihui.g@gmail.com>

Subject: RE: URGENT ATTENTION: RE: OUR REF: SNM19D204159-XD6311H-CML - FW: Pre

Repair Survey cases (Reminder)

ACCIDENT INVOLVING XE 3276 R & XD 6311 H ON 30-8-2019

Dear Sirs/Mdm.

Refer to the above matter and the tele-conversation with Boon Sen, please be informed that our client is agreeable to appoint LKK Auto Consultant as the SJE.

Please be informed that the said vehicle can be inspected at:

Venue:

Mah Lian Motor Vehicle Repairer

#### No.38 Defu Lane 9

### Singapore 539278

Contact Person:

Mr Goh / Ms Si Hui (6282 3336)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Regards

Jacqueline Tan Secretary Vision Law LLC 133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Tel: 6534-2811, Fax: 6535-6802

From: Jacqueline Tan [mailto:jactan@visionlawllc.com]

Sent: Thursday, 5 September, 2019 11:17 AM

To: 'Claims Dept of CTI'; 'Elaine Cheong'; 'Alfred Toh'; 'Chee So Chow'; 'jeromesoh@visionlawllc.com' Subject: URGENT ATTENTION: RE: OUR REF: SNM19D204159-XD6311H-CML - FW: Pre Repair

Survey cases (Reminder)

ACCIDENT INVOLVING XE 3276 R & XD 6311 H ON 30-8-2019

Dear Sirs/Mdm.

Refer to the above matter, we put on record that the 2 clear days' notice had lapsed. Please be informed that our client will proceed with the repair in lieu of your failure to revert with your proposal of your list of surveyor for appointment of SJE.

Regards

Jacqueline Tan Secretary Vision Law LLC 133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Tel: 6534-2811, Fax: 6535-6802

From: Claims Dept of CTI [mailto:claimsdept@sg.cntaiping.com]

Sent: Thursday, 5 September, 2019 9:18 AM

To: Elaine Cheong; Alfred Toh; Chee So Chow; jeromesoh@visionlawllc.com; jactan@visionlawllc.com

Subject: OUR REF: SNM19D204159-XD6311H-CML - FW: Pre Repair Survey cases (Reminder)

Dear Elaine.

Please conduct PRS for XE3276R.

Note: officer in charge - Elaine Cheong 63896530.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Jerome Soh [mailto:jeromesoh@visionlawllc.com]

Sent: Wednesday, 4 September, 2019 11:45 AM

To: Irene Tay < irene.tay@sg.cntaiping.com >; Claims Dept of CTI < claimsdept@sg.cntaiping.com >; Chong

Boon Sen <br/>
Subject: Pre Repair Survey cases (Reminder)

Dear all.

Refer to the above matter and as spoken earlier, let us know your surveyor list thank you.

Jerome Soh Assistant Secretary Vision Law LLC 133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Singapore 053413

Tel: 6534-2811 Fax: 6535-6802

From: Jerome Soh [mailto:jeromesoh@visionlawllc.com]

Sent: Wednesday, 4 September, 2019 8:35 AM

To: 'claimsdept@sg.cntaiping.com'; 'Chong Boon Sen'

Cc: 'Jacqueline Tan'

Subject: Pre Repair Survey cases

Dear all,

Let us have your surveyor list as soon as possible.

Jerome Soh
Assistant Secretary
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 050412

Singapore 059413

Tel: 6534-2811 Fax: 6535-6802

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490
DISCLAIMER:
The contents of this email (including any attachments) are confidential and privileged and only intended the recipient(s) addressed above. If you received this email
by error, please notify the sender immediately and destroy it (and all attachments) without reading, storin and/or disseminating any of its contents (in any form) to any
person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of an errors or omissions in the contents resulting from email
transmission or any illegal or unauthorised usage or tampering of its email system.
This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com
VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490
DISCLAIMER:
The contents of this email (including any attachments) are confidential and privileg and only intended for the recipient(s) addressed above. If you received this email
by error, please notify the sender immediately and destroy it (and all attachments)

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.

#### SGCARMART.COM

Login 5

New Cars \*\*

Used Cars

Sell My Car

Directory

Products

Insurance

Articles



AVIVA

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Advertiser Login Post an Ad

•

Ways of Selling

Dec 2017 Lexus GS200T Luxury Special Offer \$188,800!



Speedo Motoring StarAd



Browse by Category

11 vehicles

Mitsubishi Fuso fv51

Model

Sort by Date Posted

Price

Depreciation

Reg Date Any

Any

Eng Cap

Mileage

Any

Search Selection

Mitsubishi Fuso fv51

Any

Any

Mitsubishi Fuso Super Great FV51J (COE till 11/2023)

\$79,800

\$18,890 /yr

27-Nov-2008

12,882 cc

Fuel Type: Diesel

10 Wheels Tipper Truck, Well Maintained By Previous Owner, High Loan And High Trade-In Is Available, Call Now For Viewing.

Convince Auto

Posted: 02-Sep-2019

Tags: 2008 Mitsubishi Fuso, 2008 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso,

Used Mitsubishi

Mitsubishi Fuso Super Great FV51S

\$148,800

\$23,680 /yr

18-Dec-2015

11,967 cc

Fuel Type: Diesel

10 Wheels PK19502 With Hooklift, Excellent Condition! New Paintwork, High Loan, High Trade-in, Call Now For Viewing!

Convince Auto

Posted: 01-Sep-2019

Tags: 2015 Mitsubishi Fuso, 2015 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso,



Mitsubishi Fuso Super Great FV51J

\$88,800

\$27,560 /yr

26-Nov-2012

12,882 cc

Fuel Type: Diesel

Condition Like New. Will Immediate Transfer Ownership So Buy With Worries Free. Flexible Loan Options Available, Call Now.

Grande Auto Credit

Posted: 01-Sep-2019

Tags: 2012 Mitsubishi Fuso, 2012 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso,

Used Mitsubishi



Mitsubishi Fuso Super Great

\$45,000

\$14,670 /yr

04-Oct-2002

11,945 cc

FV517 Tipper (COE till

09/2022) Fuel Type: Diesel

Beautiful Year 2002 10 Wheeler Tipper Lorry, High Loan, Competitive Rate Is Available, High Trade-In, Please Call Now To Find More!

Convince Auto

Posted: 30-Aug-2019

Tags: 2002 Mitsubishi Fuso, 2002 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso,

Used Mitsubishi

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



Compare

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

wner ID Type:	Business
wner ID:	121L
ehicle Details	
ehicle No.:	XE3276R
ehicle to be Exported:	No
ntended Deregistration Date:	06 Sep 2019
ehicle Make:	MITSUBISHI
ehicle Model:	FUSO FV51SJD2DEA
rimary Colour:	White
Nanufacturing Year:	2017
ngine No.:	OM457LA457972C0333521
Chassis No.:	FV51SJA20256
Maximum Power Output:	2
pen Market Value:	\$101,028.00
Original Registration Date:	02 Aug 2017
First Registration Date:	02 Aug 2017
ransfer Count:	0
ctual ARF Paid:	\$5,052.00
ntended PARF Rebate Details	
ARF Eligibility:	No
ARF Eligibility Expiry Date:	•
ARF Rebate Amount:	\$0.00
ntended COE Rebate Details	
OE Expiry Date:	01 Aug 2027
OE Category:	C - Goods Vehicle & Bus
OE Period(Years):	10
QP Paid:	\$40,212.00
COE Rebate Amount:	\$31,780.00
Total Rebate Amount:	\$31,780.00

The information contained herein is correct as at 06 Sep 2019

OK

# MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg GST:M90362564P RCB NO:201327339E

5/9/19 1/5 # 16,200 ES1700556 The phil Allery-05 Sep 2019

China Taiping Insurance (Singapore) Pte Ltd M/S:

TEL:

Estimate No: 05 Sep 2019 Date: 5103384313-01 Policy No: Veh Reg No: XE3276R FAX: -MITSUBISHI FUSO Make/Model: ATTN: Motor Claim Department FV51SJD2DEA

FV51SJA20256 Chassis No: SOON HUA BEE CONST Your Ref No:

OM457LA457972C03335 Engine No: Claim Type: Third Party

02/08/2017 Reg. Date: Accident Date: 30/08/2019

Estimate Repair Cost to Vehicle No :XE3276R

- 2	Description		U/Price	Quantity	List Price	Amount
	Description .				SS	S\$
	List Price	2 1/				_
1	Front Panel	1300/ 120	5,177.32	1 PC	5,177.32	
2	Front Panel Lock Assy - LH	767	162.99	1 PC	162,99	
3	Front Panel Lock Hook - LH	lwl	30.33	1 PC	30.33	
4	Front Panel Shockabsorber	1/10	514.26	1 PC	514.26	
5	Front Inner Panel Reinforcement	1200	1,572.57	1 PC	1,572.57	
6	Front Panel Lid Cable	11	211.85	1 PC	211.85	
7	Front Grille Upper	cne	521.79	1 PC	521.79	-
8	Front Grille Lower	CN		1 PC	727.97 -	
9	Emblem " FUSO "	su	295.33	1 PC	295.33 -	
10	Front Corner Panel - LH	CM		1 PC	468.21 -	_
11	Front Corner Panel Bracket Lower - LH	11	1000000		107.00 D	
12	Front Corner Panel Bracket Center - LH	11	24110		32.78 ℃	7
13	Front Corner Panel Side Lamp - LH	11	195.03		195.03 🛦	7.00
14	Front Corner Panel Bottom Seal - LH	11	84.23	1 PC	84.23 ১	
15	Wiper Washer Tank Assy	1-	478.33	1 PC	478.33	
16	Wiper Tube Assy	11	56.73	1 PC	56.73	
17	Clutch Fluid Reservoir Assy	11	145.13	1 PC	170.10	X.
18	Radiator Spare Tank	11	1,021.90	1 PC	1,021.90	X
19	Aircond Blower Assy	cne	1,130.88	1 PC	1,130.88	_
20	Aircond Cooling Coil Assy	cn	2,106.56	1 PC	2,106.56 -	
21	Aircond Evaporator Unit Assy	cm	1,949.29	1 PC	1,949.29 -	
22	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	11	869.49	1 PC	869.49>	
23	Aircond Suction Pipe	12	338.25		338.25	
24	Aircond Discharge Hose	11	334.76	1 PC	334.76	X
25	- 300 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	11	2,497.39	1 PC	2,497.39	
26		11	528.17	7 1 PC	528.17	×
27		11	362.01	1 PC	362.01	
28		1.	1,818.00	1 PC	1,818.00	×
29		2	1 199.74	4 1 PC	199.74	
30		11	279.84	4 1 PC	279.84	×
31		00/34	1,076.5	1 PC	1,076.51	
31		n	66.74		200.220	X
33		11	155.2		465.75	X
34		CN	▲ 1,680.0		1,680.05	
35		Cu			670.89	

# MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278

TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg

GST:M90362564P RCB NO:201327339E

M/S: China Taiping Insurance (Singapore) Pte Ltd

Estimate No:

ES1700556

\_

Date:

FAX: -

05 Sep 2019

2

Policy No:

5103384313-01

TEL:

ATTN: Motor Claim Department

Veh Reg No: Make/Model: XE3276R MITSUBISHI FUSO

and the second s

SOON HUA BEE CONST

1933 10315466

FV51SJD2DEA

Your Ref No: Claim Type:

Third Party

Chassis No: Engine No: FV51SJA20256 OM457LA457972C03335

2

Accident Date:

30/08/2019

Reg. Date:

02/08/2017

Estimate Repair Cost to Vehicle No :XE3276R

	Description	U/Price	Quantity	List Price	Amount
				SS	SS
				28,311.55	
			Less 25%	7,077.89	21,233.71
	Labour				_
36	Labour to remove & refit windscreen glass ,rubber seal , IU bracket .	150.00	1 JOB	150.00	120
37	Labour to remove & refit aircond system, pipe, hose, condendor, air drier & top up oil and gas, etc.	580,00	1 JOB	580.00	200
38	Labour charge to cut & weld & dismantle & remove & refit all	2,500.00	1 JOB	2,500.00	2200
39	above parts .  To spray & painting all accident affected area .	1,500.00	1 JOB	1,500.00	1100
				4,730.00	4,730.00
		22 7 7 2 3 1		Total	S\$ 25,963.71
			Add GS7	Γ@ 7%	1,817.46
			Total Amount	Payable	S\$ 27,781.17

TOTAL: SINGAPORE DOLLAR TWENTY SEVEN THOUSAND SEVEN HUNDRED EIGHTY ONE AND CENTS SEVENTEEN ONLY 33370 .19

For MAH LIAN MOTOR VEHICLE REPAIRER

AUTHORISED SIGNATURE

KK Auto Consultants hence notify members of the following:

- . The state of the spray painting
- arranged part(s) during resurvey
- a se subject to confirmation
- . The state story is on a "Without Prejudice" basis
- Instruction (s) is allowed
- Supprementary item(s) must be resurveyed and is authorities final approval from Insurance Company

Acknowledged by Repaire

Signatures

Defet

P-2256.06
252
16722.04
20342.04

## MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg GST:M90362564P RCB NO:201327339E

M/S: China Taiping Insurance (Singapore) Pte Ltd

> Estimate No: ES1700556 Date: 11 Sep 2019 Policy No: 5103384313-01 FAX: -Veh Reg No: XE3276R

TEL:

Make/Model: ATTN: Motor Claim Department MITSUBISHI FUSO

FV51SJD2DEA

Your Ref No:

SOON HUA BEE CONST

Chassis No:

FV51SJA20256

Claim Type:

Third Party

Engine No:

OM457LA457972C03335

2

Accident Date:

30/08/2019

Reg. Date:

02/08/2017

#### Estimate Repair Cost to Vehicle No :XE3276R

	Description		U/Price	Quantity	List Price	Amount
					SS	SS
		Supplementary Parts	s to Repa	ir		
	List Price					
1	Dashboard Assy	11	3,254.77	1 PC	3,254.77	<
2	Dashboard Reinforcement	M	1,415.50	1 PC	1,415.50 🖎	<
3	Rear Cabin Spring Bellow	11	993.99	1 PC	993.99 X	(
4	Aircond Heater Hose	cur	67.86	1 PC	67.86	_
5	Aircond Heater Hose	647	72.08	1 PC	72.08	
6	Center Console Dashboad	; cha	1,786.72	1 PC	1,786.72	
7	Front Door Pillar - LH	m/sw	2,284.45	1 PC	2,284.45	
		t.		\$ <del>1</del>	9,875.37	
				Less 25%	2,468.84	7,406.54
				Murcus v	Total	S\$ 7,406.54
				GST	Amount	S\$ 518.46
				Total Amount	Payable	S\$ 7,925.00

For MAH LIAN MOTOR VEHICLE REPAIRER

AUTHORISED SIGNATURE

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

Odometer:

CS/CTI19015731/UQF3N2

Date:

17/09/2019

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMCVSN19266819000

Claimant

XE3276R

Insured Vehicle No:

XD6311H

Vehicle No:

Nature of

Date of Loss:

30/08/2019

Claim:

TP

Claim No:

SNM19D204159C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

XE3276R

Make & Model:

MITSUBISHI FUSO, 12.0 D FP51SDR3VDEA (M) Engine No: 02/08/2017 (Man. Year: 2017) Chassis No:

OM457LA457972C0333521 FV51SJA20256

236907 km

Reg. Date: Colour:

White

Engine Capacity:

11967 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** 

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

51.45

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

295/80R22.5

Rear Tyre Size:

295/80R22.5 (D/D)

Front Left Side: Front Right Side: Firenza 6 mm Firenza 6 mm Rear Left Side: Rear Right Side:

35,706.10

Firenza 6/66/6 mm Firenza 6/66/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts	Repairer's 28,640.19	Adjuster's 16,722.04	Difference 11,918.15	Diff % 41.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,730.00	3,620.00	1,110.00	23.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,370.19	20,342.04	13,028.15	39.04
Approved Total (Overridden) (S\$)		16,200.00		
(S\$)	33,370.19	16,200.00	17,170.19	51.45
+ GST 7.00/7.00% (S\$)	2,335.91	1,134.00	1,201.91	51.45

INSPECTION

Date of Assignment:

06/09/2019

Date Inspected:

05/09/2019 Inspected At:

Nett Amount (S\$)

Mah Lian Motor Vehicle Repairer (HQ)

18,372.10

NO. 38 DEFU LANE 9 Singapore 539278

17,334.00

Estimated Period of Repair:

10.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

Adjuster Report Page 2 of 5

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Amount

### REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 17 Sep 2019)

Parts: N/A MITSUBISHI FUSO 12.0 D FP51SDR3VDEA (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XE3276R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

Renairer's

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Re	com	mended Parts
No.	Qtv	Part No. Particulars

NO.	Gty	rait No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Badly Dented	5,177.32 FL	*5,177.32 FL
2	1		*FRONT PANEL LOCK ASSY-LH	Twisted	162.99 FL	*162.99 FL
3	1		*FRONT PANEL LOCK HOOK-LH	Twisted	30.33 FL	*30.33 FL
4	1		*FRONT PANEL SHOCKABSORBER	Bent	514.26 FL	*514.26 FL
5	1		*FRONT INNER PANEL REINFORCEMENT	<b>Badly Dented</b>	1,572.57 FL	*1,572.57 FL
6	1		*FRONT PANEL LID CABLE	Not Necessary	211.85 FL	*-FL
7	1		*FRONT GRILLE UPPER	Cracked	521.79 FL	*521.79 FL
8	1		*FRONT GRILLE LOWER	Cracked	727.97 FL	*727.97 FL
9	1		*EMBLEM FUSO	Necessary	295.33 FL	*295.33 FL
10	1		*FRONT CORNER PANEL-LH	Cracked	468.21 FL	*468.21 FL
11	1		*FRONT CORNER PANEL BRACKET LOWER-LH	Not Necessary	107.00 FL	*- FL
12	1		*FRONT CORNER PANEL BRACKET CENTER-LH	Not Necessary	32.78 FL	*-FL
13	1		*FRONT CORNER PANEL SIDE LAMP-LH	Not Necessary	195.03 FL	*-FL
14	1		*FRONT CORNER PANEL BOTTOM SEAL-LH	Not Necessary	84.23 FL	*-FL
15	1		*WIPER WASHER TANK ASSY	Not Necessary	478.33 FL	5 Sec. 2007
16	1		*WIPER TUBE ASSY	Not Necessary	56.73 FL	*- FL
17	1		*CLUTCH FLUID RESERVOIR ASSY	Not Necessary	145.13 FL	*-FL
18	1		*RADIATOR SPARE TANK	Not Necessary	1,021.90 FL	*-FL
19	1		*AIRCOND BLOWER ASSY	Cracked		*1,130.88 FL
20	1		*AIRCOND COOLING COIL ASSY	Cracked	The first transfer of the foreign of the first transfer of the fir	*2,106.56 FL
21	1		*AIRCOND EVAPORATOR UNIT ASSY	Cracked	1,949.29 FL	*1,949.29 FL
22	1		*AIRCOND AIR DRIER	Not Necessary	869.49 FL	*-FL
23	1		*AIRCOND SUNCTION PIPE	Not Necessary	338.25 FL	
24	1		*AIRCOND DISCHARGE HOSE	Not Necessary	334.76 FL	*-FL
25	1		*AIRCOND CONDENSOR ASSY	Not Necessary	2,497.39 FL	
26	1		*AIRCOND CONDENSOR FAN MOTOR	Not Necessary	528.17 FL	*-FL
27	1		*AIRCOND CONDENSOR FAN COWLING	Not Necessary	362.01 FL	
28	1		*AIRCOND CONDENSOR BRACKET	Not Necessary	1,818.00 FL	
29	1		*AIRCOND CONDENSOR HOSE	Not Necessary	199.74 FL	207
30	1		*AIRCOND LIQUID HOSE	Not Necessary	279.84 FL	
31	1		*WIPER PANEL	Dented/Bent		*1,076.51 FL
32	3		*WIPER BLADE	Not Necessary	200.22 FL	
33	3		*WIPER ARM	Not Necessary	465.75 FL	1) 25/07/20
34			*FRONT WINDSCREEN	Cracked		*1,680.05 FL
35	1		*FRONT WINDSCREEN RUBBER SEAL	Cut	670.89 FL	t : : : : : : : : : : : : : : : : : : :
36	1		*DASHBOARD ASSY	Not Necessary	3,254.77 FL	
37	1		*DASHBOARD REINFORCEMENT	Not Necessary	1,415.50 FL	*-FL
38	1		*REAR CABIN SPRING BELLOW	Not Necessary	993.99 FL	
39	1		*AIRCOND HEATER HOSE	Cut	67.86 FL	
40	1		*AIRCOND HEATER HOSE	Cut	72.08 FL	*72.08 FL
41	1		*CENTER CONSOLE DASHBOARD	Cracked		*1,786.72 FL
42 F=Fra	nchise :	part. L=ListIte	*FRONT DOOR PILLAR-LH	Dented/Bent	2,284.45 FL	*2,284.45 FL
		- Elouv		Sub Total (S\$)	38,186.92	22,296.06

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
			- List Item Discount on L Items 25.00/25.00% (S\$	9,546.73	5,574.02
			Total Parts (S\$	28,640.19	16,722.04
			Report was unsubmitted during this print-out.		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	LABOUR TO REMOVE & REFIT WINDSCREEN GLASS, RUBBER SEAL, IU BRACKET	New	150.00	120.00
2	LABOUR TO REMOVE & REFIT AIRCOND SYSTEM,PIPE,HOSE,CONDENSOR,AIR DRIER & TOP UI OIL AND GAS,ETC	New	580.00	200.00
3	LABOUR CHARGE TO CUT & WELD & DISMANTLE & REMOVE & REFIT ALL ABOVE PARTS	New	2,500.00	2,200.00
4	TO SPRAY & PAINTING ALL ACCIDENT AFFECTED AREA	New	1,500.00	1,100.00
	Gross Labo	our Cost (S\$)	4,730.00	3,620.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >