

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19015749/T	T1qf3s2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date: 16-09-2019  Code: FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHC 844X	Veh. Inspected	SHB 3682G	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D19005167MFSH	Excess (\$)	0.00	
	Assign From	MERINA CHIA SAN SAN	Assign Date	05/09/2019	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI 140	c.c	1685	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	KMHLB41UMFU061822	Colour	YELLOW	
	Odometer	686875	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
	L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
	R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
	L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	Г	General Information			
	Accident Date	07/08/2019	Inspection Date	06/09/2019	
	Survey held at	31 CORPORATION ROAD			
_	Repairer	DING AUTO PTE LTD			
5a.	Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				