

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant\_as@yahoo.com.sg

RCB No. 53138015K

## Automobile Inspection Report

To: Hoe Geok Heng  
c/o 2 Kaki Bukit Ave 2  
#01-17 Kaki Bukit Autohub  
Singapore 417921

Date : 07/08/2018

Reference No : CAS/18-08/013

### General Information

Registration No. : SJF 770K  
Accident Date : 26/06/2018

### Particulars of Damaged Vehicle

Colour	: Silver	Make & Model	: Mercedes Benz C200
Engine Capacity	: 1796 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 180697	Engine No.	: 27195031018862
Chassis No.	: WDD2040412A114195	Steering	: In Order
Registration Date	: 14/04/2008	Brake	: In Order

### Tyre Condition

	Size	Make	Balance
R/H Front Tyre	225/45R17	BRIDGESTONE	80%
L/H Front Tyre	225/45R17	BRIDGESTONE	80%
R/H Rear Tyre	225/45R17	BRIDGESTONE	80%
L/H Rear Tyre	225/45R17	BRIDGESTONE	80%

### Inspection

Repairer : Twincar Automotive Pte Ltd  
2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921

### Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$14,558.60  
Revised Amount : \$10,500.00  
Less Excess : -  
Nett Total : \$10,500.00

### Remarks

- (A) Survey was done on 28/06/2018
- (B) Re-survey was done on 28/06/2018
- (C) Re-survey after repair was done on 02/07/2018
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : SJF 770K

Our ref : CAS/18-08/013

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$10,500.00** on a contractual basis. Under normal circumstances, the repair period would be about **6 (Six)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)

MSAAA

Constant Appraiser Services

Vehicle No : SJF 770K

Our ref: CAS/18-08/013

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - LIST ITEMS</u>					
1	1pc	Rear bootlid	Dented/Buckled R	1,311.00	<del>1,311.00</del>
2	1pc	Rear bootlid 'C&C' emblem	Necessary <i>nee</i>	56.00	56.00 ✓
3	1pc	Rear bootlid 'C200' emblem	Necessary <i>nee</i>	60.00	60.00 ✓
4	1pc	Rear bootlid 'KOMPRESSOR' emblem	Necessary <i>nee</i>	88.00	88.00 ✓
5	1pc	Rear bootlid 'logo' emblem	Necessary <i>nee</i>	40.00	40.00 ✓
6	1pc	Rear bootlid inner pull garnish	Deformed <i>suc</i>	135.00	<del>135.00</del>
7	1pc	Rear bootlid inner trim board	Deformed <i>suc</i>	425.00	<del>425.00</del>
8	1pc	Rear bootlid mechanism lock	Bent/Jammed <i>Jim</i>	237.00	237.00 ✓
9	2pcs	Rear bootlid number plate lamp L/R @ \$45.00	Necessary <i>XNC</i>	90.00	<del>90.00</del>
10	1pc	Rear bootlid outer garnish	Necessary <i>suc</i>	261.00	<del>261.00</del>
11	1pc	Rear bootlid outer handle button switch	Damaged <i>suc</i>	135.00	<del>135.00</del>
12	1pc	Rear bootlid weather strip	Distorted <i>CRU</i>	132.00	132.00 ✓
13	1pc	Rear bumper	Dented/Broken <i>CRU</i>	1,466.00	<del>1,466.00</del> 1300 ✓
14	1pc	Rear bumper center bracket	Broken <i>BR</i>	135.00	135.00 ✓
15	1pc	Rear bumper center chrome moulding	Necessary <i>nee</i>	99.00	99.00 ✓
16	2pcs	Rear bumper chrome moulding L/R @ \$85.00	Necessary <i>nee</i>	170.00	170.00 ✓
17	1pc	Rear bumper lower lid	Dented/Deformed <i>CRU</i>	385.00	<del>385.00</del> 300 ✓
18	1pc	Rear bumper reinforcement	Dented/Bent <i>BT</i>	562.00	<del>562.00</del> 480 ✓
19	2pcs	Rear bumper reverse sensor @ \$131.00 X 2	Damaged <i>short</i>	524.00	<del>524.00</del> 260 ✓
20	4pcs	Rear bumper reverse sensor 'O' ring @ \$12.50	Necessary <i>nee</i>	50.00	<del>50.00</del> 20 ✓
21	2pcs	Rear bumper side retainer L/R @ \$32.00	Necessary <i>nee</i>	64.00	64.00 ✓
22	1pc	Rear bumper tow hook cover	Serviceable	56.00	X -
23	1pc	Rear end panel	Dented/Warped <i>R</i>	891.00	<del>891.00</del>
24	1pc	Rear end panel top garnish	Deformed <i>CRU</i>	195.00	<del>195.00</del> 105 ✓
25	1pc	Rear floor panel top trim board	Serviceable	545.00	X -
26	2pcs	Rear taillamp inner rubber gasket L/R @ \$21.00	Necessary <i>nee</i>	42.00	42.00 ✓
27	2pcs	Rear taillamp L/R @ \$455.00	Broken <i>CRU</i>	910.00	<del>910.00</del> 800 ✓
28	2pcs	Rear taillamp lower bracket L/R @ \$65.00	Broken <i>R</i>	130.00	<del>130.00</del>
29	2pcs	Rear taillamp side garnish L/R @ \$55.00	Cut <i>CRU</i>	110.00	110.00 ✓
				9,304.00	8,703.00
Less 10%				(930.40)	(870.30)

Constant Appraiser Services

Vehicle No : SJF 770K

Our ref : CAS/18-08/013

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u>					
			Sub total	8,373.60	7,832.70
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1pc	Rear bootlid camera	Damaged <i>X NC</i>	800.00	<del>800.00</del>
2	1set	Rear bootlid inner pull garnish clips - set	Necessary <i>nc</i>	60.00	<del>60.00</del> 20
3	1set	Rear bootlid inner trim board clips - set	Necessary <i>nc</i>	30.00	<del>30.00</del> 15
4	1pc	Rear bootlid number plate	Serviceable <i>suc</i>	25.00	<del>X -</del>
5	1pc	Rear bootlid number plate holder	Serviceable <i>suc</i>	50.00	<del>X -</del>
6	1set	Rear bootlid outer garnish clips - set	Necessary <i>nc</i>	60.00	<del>48.00</del> 20
7	1set	Rear bumper clips - set	Necessary <i>nc</i>	100.00	<del>60.00</del> 30
8	1set	Rear end panel top garnish clips - set	Necessary <i>nc</i>	60.00	<del>30.00</del> 15
9	1pc	Rear floor panel insulator mat	Not Necessary <i>NC</i>	300.00	<del>X 0.00</del>
10	2pcs	Rear taillamp side garnish clips L/R – set @ \$80.00	Necessary <i>nc</i>	160.00	<del>30.00</del> 20
			Sub total	10,018.60	8,890.70
<u>LABOUR &amp; MISC. CHARGES</u>					
1		To reset system after repair works		400.00	<del>360.00</del> 180
2		To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor		120.00	<del>80.00</del> 30
3		To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)		140.00	<del>100.00</del> X
4		To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper <i>3ps</i>		1,800.00	<del>1,500.00</del> 600
5		To remove and reinstall exhaust pipe		160.00	<del>X -</del>
6		To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident <i>315 67</i>		1,800.00	<del>1,400.00</del> 700
7		To apply anti-rust chemical on repaired and replaced panel		120.00	<del>X 60.00</del>
			Grand total	14,558.60	12,390.70
Recommended cost of lump sum repair (To its pre-accident condition)					10,500.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 770K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR BOOTLID	TO REPAIR SEE LABOUR	1,311.00	-
1	REAR BOOTLID 'C&C' EMBLEM	NECESSARY	56.00	56.00
1	REAR BOOTLID 'C200' EMBLEM	NECESSARY	60.00	60.00
1	REAR BOOTLID 'KOMPRESSOR' EMBLEM	NECESSARY	88.00	88.00
1	REAR BOOTLID 'LOGO' EMBLEM	NECESSARY	40.00	40.00
1	REAR BOOTLID INNER PULL GARNISH	SERVICEABLE	135.00	-
1	REAR BOOTLID INNER TRIM BOARD	SERVICEABLE	425.00	-
1	REAR BOOTLID MECHANISM LOCK	JAMMED	237.00	237.00
2	REAR BOOTLID NUMBER PLATE LAMP L/R @ \$45.00 (NECESSARY)	NOT CONSISTENT WITH THE IMPACT	90.00	-
1	REAR BOOTLID OUTER GARNISH	SERVICEABLE	261.00	-
1	REAR BOOTLID OUTER HANDLE BUTTON SWITCH	SERVICEABLE	135.00	-
1	REAR BOOTLID WEATHERSTRIP	CRUSHED	132.00	132.00
1	REAR BUMPER	CRUSHED	1,466.00	1,300.00
1	REAR BUMPER CENTER BRACKET	BROKEN	135.00	135.00
1	REAR BUMPER CENTER CHROME MOULDING	NECESSARY	99.00	99.00
2	REAR BUMPER CHROME MOULDING L/R @ \$85.00	NECESSARY	170.00	170.00
1	REAR LOWER BUMPER LID	CRUSHED	385.00	300.00
1	REAR BUMPER REINFORCEMENT	BENT	562.00	480.00
4	REAR BUMPER REVERSE SENSOR @ \$131.00	SHORTED 2PCS ONLY	524.00	262.00
4	REAR BUMPER REVERSE SENSOR 'O' RING @ \$12.50	NECESSARY	50.00	20.00
2	REAR BUMPER SIDE RETAINER L/R @\$32.00	NECESSARY	64.00	64.00
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	56.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	891.00	-
1	REAR END PANEL TOP GARNISH	CRUSHED	195.00	105.00
1	REAR FLOOR PANEL TOP TRIM BOARD	SERVICEABLE	545.00	-
2	REAR TAILLAMP INNER RUBBER GASKET L/R @ \$21.00	NECESSARY	42.00	42.00
2	REAR TAILLAMP L/R @ \$455.00	CRUSHED	910.00	800.00
2	REAR TAILLAMP LOWER BRACKET L/R @ \$65.00	TO REPAIR SEE LABOUR	130.00	-

Report Ref No. CS1/AIG19015750/Htd3s2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR TAILLAMP SIDE GARNISH L/R @\$55.00	CRUSHED	110.00	110.00
	LESS 10% DISCOUNT		-930.40	-450.00
			8,373.60	4,050.00
	<b>SPECIAL NETT ITEMS</b>			
1	REAR BOOTLID CAMERA (DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	800.00	-
1	SET REAR BOOTLID INNER PULL GARNISH CLIPS (SN)	NECESSARY	60.00	20.00
1	SET REAR BOOTLID INNER TRIM BOARD CLIPS (SN)	NECESSARY	30.00	15.00
1	REAR BOOTLID NUMBER PLATE (SN)	SERVICEABLE	25.00	-
1	REAR BOOTLID NUMBER PLATE HOLDER (SN)	SERVICEABLE	50.00	-
1	SET REAR BOOTLID OUTER GARNISH CLIPS (SN)	NECESSARY	60.00	20.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	60.00	15.00
1	REAR FLOOR PANEL INSULATOR MAT (NOT NECESSARY) (SN)	NOT CONSISTENT WITH THE IMPACT	300.00	-
2	REAR TAILLAMP SIDE GARNISH CLIPS L/R - SET @\$80.00 (SN)	NECESSARY	160.00	20.00
			1,645.00	120.00
	<b>LABOUR</b>			
	TO RESET SYSTEM AFTER REPAIR WORKS.		400.00	180.00
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		120.00	30.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	NOT NECESSARY	140.00	-
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		1,800.00	600.00
	TO REMOVE AND REINSTALL EXHAUST PIPE.	NOT NECESSARY	160.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS. REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOTLID, REAR END PANEL AND REAR TAILLAMP LOWER BRACKET L/R.		1,800.00	700.00

Report Ref No. CS1/AIG19015750/Htd3s2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	120.00	-
			4,540.00	1,510.00
	<b>GRAND TOTAL</b>		<b>14,558.60</b>	<b>5,680.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,550.00</b>

Report Ref No. CS1/AIG19015750/Htd3s2

LEE HOCK ANN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.