

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19015752/GGA3Q2

Date: 14/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMN5030C	Insured Vehicle No :	SHA2394A
Date of Loss: 26/08/2019	Nature of Claim: TP	Claim No: MCT19080685

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN5030C	Engine No:	A25A5115914
Make & Model:	TOYOTA CAMRY, 2.5 (A)	Chassis No:	JTNB23HK703023134
Reg. Date:	14/08/2019 (Man. Year: 2018)	Odometer:	10100 km
Colour:	White		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Goodyear 9 mm	Rear Left Side:	Goodyear 9 mm
Front Right Side:	Goodyear 9 mm	Rear Right Side:	Goodyear 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,757.01	3,804.98	4,952.03	56.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	1,450.00	130.00	8.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	10,337.01	5,254.98	5,082.03	49.16
Approved Total (Overridden) (\$)		4,200.00		
(S\$)	10,337.01	4,200.00	6,137.01	59.37
+ GST 7.00/7.00% (S\$)	723.59	294.00	429.59	59.37
Nett Amount (S\$)	11,060.60	4,494.00	6,566.60	59.37
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,061.45		
Global Sum Settlement (S\$)		5,000.00		

INSPECTION

Date of Assignment:	05/09/2019	
Date Inspected:	05/09/2019 Inspected At:	Green Forest Automobile Pte Ltd (Kaki Bukit)
		8 Kaki Bukit Avenue 4, #05-25,,
		Premier@Kaki Bukit
		Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)
Parts:	143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN5030C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	1,250.00 F	*1,250.00 FL
2	1		*REAR BOOT LID EMBLEM LOGO	Necessary	76.10 F	*76.10 FL
3	1		*REAR BOOT LID CAMRY LOGO	Not Necessary	74.00 F	*- FL
4	1		*REAR BOOT LID INNER LOCK	Bent	325.00 F	*325.00 FL
5	1		*REAR BOOT LID INNER RUBBER	Torn	128.10 F	*128.10 FL
6	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	458.00 F	*- FL
7	2		*REAR BOOT LID SIDE REFLECTOR	Not Necessary	770.00 F	*- FL
8	1		*BOOT LID HYBRID LOGO	Necessary	35.00 F	*35.00 FL
9	1		*REAR BOOT LID NUMBER PLATE	Scratched	50.00 F	*50.00 FL
10	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	166.20 F	*- FL
11	1		*REAR BOOT LID NUMBER PLATE GARNISH	Not Necessary	281.50 F	*- FL
12	2		*REAR TAIL LAMP	Cracked	1,316.00 F	*900.00 FL
13	4		*REAR TAIL LAMP CLIPS	Not Necessary	26.00 F	*- FL
14	1		*REAR BUMPER	Deformed	850.00 F	*650.00 FL
15	2		*REAR BUMPER SIDE BRACKET	Not Necessary	262.40 F	*- FL
16	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	166.40 F	*- FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	531.51 F	*531.51 FL
18	1		*REAR BUMPER INNER SPONGE	Not Necessary	128.20 F	*- FL
19	10		*REAR BUMPER CLIPS	Necessary	65.00 F	*65.00 FL
20	1		*REAR BUMPER LOWER COVER	Not Necessary	385.00 F	*- FL
21	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	350.00 F	*- FL
22	1		*REAR END PANEL	Buckled	681.20 F	*681.20 FL
23	1		*REAR END PANEL TOP GARNISH	Deformed	381.40 F	*381.40 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	8,757.01	5,073.31
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,268.33
Total Parts (\$)	8,757.01	3,804.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX CUSHION	New	100.00	60.00
2	TO REMOVE & REFIX REVERSE SENSOR	New	100.00	0.00
3	TO CHECK WIRING	New	60.00	30.00
4	TUFF KOTE	New	120.00	60.00
5	PANEL BEATING	New	600.00	700.00
6	SPRAY PAINTING	New	600.00	600.00
Gross Labour Cost (\$)			1,580.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >