

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference:
Repairer Reference: SJT2888T-TP-MSIG
Date calculated: 05/09/2019 5:10 PM

Full Report
Registration: SJT2888T
Printed: 05/09/2019 5:10 PM

Final Calculation

	SGD	SGD
Parts	10,545.00	
Addition(+15.00%)	1,581.75	
Total Parts		12,126.75
Labour Time Base 10 WU/h		
Total 171.0 WU X 50.00 SGD/h	855.00	805
Total of Labour		855.00
Total Of Extras		420.00
Paint Work Time Base 10 WU/h		
Labour Cost 194.0 WU X 50.00 SGD/h	970.00	1410
Material Cost	363.81	600.00
Total Paint Including Material		1,333.81
Repair Cost Excludes GST		14,735.56
GST (+7.0%)		1,031.49
Repair Cost Included GST		15,767.05

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference:
Repairer Reference: SJT2888T-TP-MSIG
Date calculated: 11/11/2019 6:34 PM

Full Report
Registration: SJT2888T
Printed: 11/11/2019 6:34 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	DARREN SNG	Currency:	SGD
Claim Reference:		Date of Incident:	04/09/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	LEXUS
Model:	ES (V6)
Sub Model:	200
Model Sheet Number:	24 23 20
Registration:	SJT2888T
VIN number:	
Odometer:	

Model Specs

FROM 04/2014	3 ZONE AUTO AIR CON	LED HEADLAMP	HEADLAMP WASHERS
PARK PILOT SYSTEM	2.5 LTR 135KW	VERS GEN COUNTRIES	PREPARE OFF VEHICLE
THREE COAT PEARL			


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: FRT BUMPER , RADIATOR GRILLE, PARK SENSOR AND REQUIRED ATTACHED PARTS REMOVE AND REFIT	23.0		115.00
NO NUMBER	R + R FRONT BUMPER DAMPER	1.0		5.00
NO NUMBER	RENEW LEFT FRONT BUMPER BRACKET	1.0		5.00
NO NUMBER	RENEW RIGHT FRONT BUMPER BRACKET	1.0		5.00
B040)	ADJUST HEADLAMPS	3.0		15.00
B040)	RENEW BOTH HEADLAMPS	3.0		15.00
B290	RENEW END PANEL (BUMPER REMOVED) INCLUDES: R + R BOOT FLOOR CARPET AND ALL TRIMS IN THE REPAIR SECTION	38.0		190.00
B360	RENEW BOOT LID INCLUDES: R + R BOOT LID, CONVERT ATTACHED PARTS	12.0		60.00
811201)	R + R L/NUMBER PLATE LAMP	2.0		10.00
811201)	R + R R/NUMBER PLATE LAMP	2.0		10.00
NO NUMBER	R + R L/R BUMPER BRACKET	2.0		10.00
NO NUMBER	R + R R/R BUMPER BRACKET	2.0		10.00
B410	R + R REAR BUMPER CARRIER	1.0		5.00
B420	RENEW REAR BUMPER INCLUDES: BUMPER AND ALL REQUIRED ATTACHED PARTS R + R	11.0		55.00
B407	R + R L/OUTER REAR LAMP	2.0		10.00
B407	R + R R/OUTER REAR LAMP	2.0		10.00
0471	BONNET REPAIR	15.0*		75.00
0475	L/F HINGE REPAIR	5.0*		25.00
0476	R/F HINGE REPAIR	5.0*		25.00
1009	FRONT PANEL REPAIR	10.0*		50.00
2953	L/R HINGE REPAIR	5.0*		25.00
2954	R/R HINGE REPAIR	5.0*		25.00
3901	REAR FLOOR PANEL REPAIR	10.0*		50.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		16.10	161.0	805.00
Total of Labour				805.00

Paint

Code	Description - THREE COAT PEARL	SYSTEM AZT	Time Basis 10 WU/h	
			WU	Price SGD
	FRT BUMPER SUPPORT SURFACE PAINT		4.0	
	BONNET NEW PART PAINTING		31.4	
	FRONT PANEL SURFACE PAINT		7.0	
	REAR BUMPER SUPPORT SURFACE PAINT		4.0	
	END PANEL NEW PART PAINTING		24.9	
	BOOTLID NEW PART PAINTING		23.1	
	L/F CTR PARK AID SEN NEW PART PAINT K1R		4.5	
	R/F CTR PARK AID SEN NEW PART PAINT K1R		4.5	

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - THREE COAT PEARL	WU	Price SGD
	L/F OUT PARK AID SEN NEW PART PAINT K1R	4.5	
	R/F OUT PARK AID SEN NEW PART PAINT K1R	4.5	
	FRONT BUMPER NEW PART PAINT K1N	19.4	
	R/F BUMPER COVER NEW PART PAINT K1R	4.5	
	GRILLE NEW PART PAINT K1R	5.7	
	L/H-LAMP WASHER LID NEW PART PAINT K1R	4.5	
	R/H-LAMP WASHER LID NEW PART PAINT K1R	4.5	
	REAR COVER BUMPER NEW PART PAINT K1N	21.9	
	L/R OUT PARKING SENS NEW PART PAINT K1R	4.5	
	R/R OUT PARKING SENS NEW PART PAINT K1R	4.5	
	L/R CTR PARK SENSOR NEW PART PAINT K1R	4.5	
	R/R CTR PARK SENSOR NEW PART PAINT K1R	4.5	
	L/F WING SURFACE PAINT	8.6	
	R/F WING SURFACE PAINT	8.6	
	L/R SIDE PANEL SURFACE PAINT	11.8	
	R/R SIDE PANEL SURFACE PAINT	11.8	
	REAR FLOOR PANEL SURFACE PAINT	12.0	

Paint Material Per Part

Code	Description	Price SGD
0340	FRT BUMPER SUPPORT SURFACE PAINT	2.49
0471	BONNET NEW PART PAINTING	100.87
1009	FRONT PANEL SURFACE PAINT	16.93
2640	REAR BUMPER SUPPORT SURFACE PAINT	2.49
2711	END PANEL NEW PART PAINTING	32.54
2931	BOOTLID NEW PART PAINTING	65.23
0267	L/F CTR PARK AID SEN NEW PART PAINT K1R	0.62
0268	R/F CTR PARK AID SEN NEW PART PAINT K1R	0.62
0269	L/F OUT PARK AID SEN NEW PART PAINT K1R	0.62
0270	R/F OUT PARK AID SEN NEW PART PAINT K1R	0.62
0283	FRONT BUMPER NEW PART PAINT K1N	86.56
0300	R/F BUMPER COVER NEW PART PAINT K1R	0.62
0410	GRILLE NEW PART PAINT K1R	6.23
0627	L/H-LAMP WASHER LID NEW PART PAINT K1R	1.25
0628	R/H-LAMP WASHER LID NEW PART PAINT K1R	1.25
2583	REAR COVER BUMPER NEW PART PAINT K1N	99.72
2669	L/R OUT PARKING SENS NEW PART PAINT K1R	0.62
2670	R/R OUT PARKING SENS NEW PART PAINT K1R	0.62
2671	L/R CTR PARK SENSOR NEW PART PAINT K1R	0.62
2672	R/R CTR PARK SENSOR NEW PART PAINT K1R	0.62
0741	L/F WING SURFACE PAINT	13.48
0742	R/F WING SURFACE PAINT	13.48
3481	L/R SIDE PANEL SURFACE PAINT	31.34
3482	R/R SIDE PANEL SURFACE PAINT	31.34
3901	REAR FLOOR PANEL SURFACE PAINT	40.84

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	50.00 SGD/h			
Time Paint			244.0	
Preparation Main Work Metal		2.50	25.0	125.00
Preparation Comp. Work Plastic		0.80	8.0	40.00
Preparation Multi-Coat		0.50	5.0	25.00
Total	10 WU/h	28.20	282.0	1,410.00

Material Cost - Paint	Price SGD
New Part Painting	198.64
New Part Painting - Plastic K1R	14.31
New Part Painting - Plastic K1N	186.28
Surface-/Blend Paint	152.39
Material-constant Metal Preparation	28.60
Material-constant Multi-Coat	9.30
Material-constant Plastic	12.70
Total	602.22

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0257	FRONT NUMBER PLATE	KNPL3		0.00
0283	FRONT BUMPER	52119 3T912		350.00
0300	R/F BUMPER COVER	52128 33912		20.00
0317	L/F OUT BUMPER BRKT	52146 33060		30.00
0318	R/F OUT BUMPER BRKT	52145 33060		30.00
0344	FRONT BUMPER	52611 33220		65.00
	DAMPING			
0365	CLIP FASTENING	52161 02030		15.00
0410	GRILLE	53111 33440		360.00
0420	GRILLE MOULDING	53121 33050		120.00
0423	RADIATOR GRILL SEAL	53155 33050		50.00
0431	GRILLE BADGE	90975 02125		160.00
0483	CLIP FASTENING	90467 09050		15.00
0561	LEFT HEADLAMP ASSY	81106 33B00		850.00
0562	RIGHT HEADLAMP ASSY	81105 33D00		850.00
1015	UPPER AIR GUIDE	53295 33080		125.00
2583	REAR COVER BUMPER	52159 33953		340.00
2607	L/R OUT BUMPER BRKT	52158 33030		40.00
2608	R/R OUT BUMPER BRKT	52157 33030		40.00
2621	REAR DECAL STRIPE	PT747 33130		0.00
2625	REAR BUMPER DAMPER	52615 33140		60.00
2640	REAR BUMPER SUPPORT	52171 33160		190.00
2671	L/R CTR PARK SENSOR	89341 33200C1		150.00
2672	R/R CTR PARK SENSOR	89341 33200C1		150.00
2702	REAR NUMBER PLATE	KNPL6		0.00
2711	END PANEL	58307 33171		280.00
2931	BOOTLID	64401 33650		400.00
2944	BOOTLID SEAL	64461 33100		110.00
2977	BOOT/TAILGATE LOCK	64600 33180		180.00
2979	BOOTLID TRIM	76801 33440		120.00
3013	REAR BADGE	90975 02078		30.00
3015	MANUFACTURER BADGE	75447 33170		30.00
3017	VERSION BADGE	75442 33390		35.00

Code	Description	Part Number	Supplier	Price SGD
3281	L/R OUTER LAMP	81561 33570		300.00
3282	R/R OUTER LAMP	81551 33570		300.00
3361	L/NUMBER PLATE LAMP	81270 33100		80.00
3403	L/R INNER LAMP	81591 33240		230.00
4985	END PANEL TRIM	58387 33150C0		150.00
1006	FRT GRILLE STOPPER	X2 (A)		16.00

f: OEM Parts	Savings	0.00
n: Non-OEM Parts	Subtotal	6,271.00
u: Used parts	Addition(+15.00%)	940.65
	Total	7,211.65

Extras

Code	Description	Price SGD
1000	FRT NUMBER PLATE -	35.00*
1002	RR NUMBER PLATE -	35.00*
1005	DIAGNOSE & RESET FAULT CODE	150.00*
	Total Extras	220.00

Final Calculation

	SGD	SGD
Parts	6,271.00	
Addition(+15.00%)	940.65	
Total Parts		7,211.65
Labour Time Base 10 WU/h		
Total 161.0 WU X 50.00 SGD/h	805.00	
Total of Labour		805.00
Total Of Extras		220.00
Paint Work Time Base 10 WU/h		
Labour Cost 282.0 WU X 50.00 SGD/h	1,410.00	
Material Cost	602.22	
Total Paint Including Material		2,012.22
Repair Cost Excludes GST		10,248.87
GST (+7.0%)		717.42
Repair Cost Included GST		10,966.29

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717
Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

rt
3T
M

TAX INVOICE

M/S: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

NO: DL19222244

BLK 3 PIONEER ROAD NORTH

PAGE: 1

#01-18

DATE: 12/09/2019

SINGAPORE 629487

A/C CODE: LDSAT11

ES25

TERMS: CR

YAO SHENG

VAT NO:

SJT2888T


98

Part No	Description	Location	Qty	Unit Price	Amount
1 TS2119-31922	BUMPER FR #283.	DB2A	1	350.00	350.00 ✓
2 TS2146-33060 ✓	FRT BUMPER RETAINER LH	DU1AS2-18 #317	1 ✓	30.00	30.00 ✓
3 TS2145-33060 ✓	FR BUMPER RETAINER RH	DU1AD32-18 #218	1 ✓	30.00	30.00 ✓
4 TS2611-33220	FR BUMPER SPONGE	DB1E40 #344	1	65.00	65.00 ✓
5 TS2161-33040 ✓	CLIP FRONT BUMPER	DU1AD10-10 #365	10 ✓	1.50	15.00 ✓
6 TS2138-33912 ✓	FR TOW OVR	DU1A91 #300	1 ✓	20.00	20.00 ✓
7 TS3155-33050 ✓	RAD GRILLE SEAL	DU1G2 #423	1 ✓	50.00	50.00 ✓
8 TS3111-33440	GRILLE	DB1K4 #410	1	360.00	360.00 ✓
9 TS3121-33050 ✓	FRT GRILLE CHROME	DU2A3 #420	1 ✓	120.00	120.00 ✓
10 T90975-02123	FR LEXUS LOGO	ED1AS2-3 #431	1	160.00	160.00 ✓
11 T81145-33040	HEADLAMP UNIT RH HID	DB1H28 #562	1	850.00	850.00 ✓
12 T81185-33040	HEADLAMP UNIT LH HID	DB2EB18 #561	1	850.00	850.00 ✓
13 TS3205-33050 ✓	SUPPORT TOP GARNISH	DU1P1-3 #1015	1 ✓	125.00	125.00 ✓
14 T90457-07211	CLIP TOP GARNISH	DD1AS3-5 #483	10	1.50	15.00 ✓
15 T81270-33100	LIC PLATE LAMP LH	DU212-3 #3361	1	80.00	80.00 ✓
16 TS2159-33943	BUMPER REAR	DB2H #2583	1	340.00	340.00 ✓
17 TS2157-33030 ✓	BUMPER SIDE BKT REAR RH	DU1AD10-5 #2605	1 ✓	40.00	40.00 ✓
18 TS2156-33030 ✓	BUMPER SIDE BKT REAR LH	DU1AD10-5 #2607	1 ✓	40.00	40.00 ✓
19 TS2171-33100	BUMPER REINFORCEMENT	DB1H121 #2640	1	150.00	150.00 ✓
20 TS2615-33140	REAR BUMPER SPONGE	DB1E55 #2625	1	60.00	60.00 ✓

Print: LEX 12/9/2019 10:01:05 AM

Contd.

total \$6271/-



合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

ort
8T
PM

TAX INVOICE

MS SNG WHITE MOTOR & PANEL SERVICE PTE LTD

NO.

DL1922224

Part No	Description	Location	Qty	Unit Price	Amount
21 T8341-33204C	REAR BUMPER SENSOR	DD1731	#26912	150.00	300.00
22 T64401-33660	BOOT LID	DB1E3	#2931	400.00	400.00
23 T64401-33100 ✓	BOOT W/STRIP	DD2M9-LH	#2984	110.00	110.00
24 T75447-33080	BOOT PLATE (LEXUS 30380)	DD2A2-1	#3018	30.00	30.00
25 T9075-02078	RR LOGO LENS	DD1A2-2	#3015	30.00	30.00
26 T75442-33390	ES250 LOGO	DD1A2-18	#3017	35.00	35.00
27 T75801-33460 ✓	RR LIC PLATE GARNISH CHROME	DD1F18-3	#2979	120.00	120.00
28 T81591-33240	BOOT LAMP LH	DBDD3	#3403	230.00	230.00
29 T81561-33570	TAIL LAMP UNIT LH	DB1C2	#3281	300.00	300.00
30 T81551-33570	TAIL LAMP UNIT RH	DBDD2	#3282	300.00	300.00
31 T64800-33180 ✓	BOOT INNER LOCK	DD1B15	#2979	140.00	140.00
32 T58387-33130C0V	T LAMP PANEL TOP GARNISH	DD1E04	#4985	150.00	150.00
33 T58307-33170	END PANEL	DB1C31	#2711	280.00	280.00
TOTAL QUANTITY			22	TOTAL	SIN 255.00
				ADD GST @ 7%	437.85
				GRAND TOTAL	SIN 6,692.85


Print LSK 11/9/2019 10:01:06 AM

SALES MAN: LSK

Print LSK 11/9/2019 10:01:06 AM

Handwritten signature

Sng Ah Tee Motor Pte Ltd



合興汽車零件私人有限公司
HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

port
188T
PM

MS: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

BLK 3 PIONEER ROAD NORTH

#01-18

SINGAPORE 628457

ES25

YAO SHEN

TAX INVOICE

NO. DLI9222376

PAYEE

DATE 16/04/2019

A/C CODE LLSA111

TERMS CR

Part No	Description	Location	Qty	Unit Price	Amount
753384-68010	STOPPER-GRILLE #126	DD1A121	2	SIN 8.00	SIN 16.00
TOTAL QUANTITY			2	TOTAL	SIN 16.00
				ADD GST @ 7%	1.12
				GRAND TOTAL	SIN 17.12

Print LSK 16/04/2019 00:57 AM

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Finalised

Insurer Reference:
Repairer Reference: SJT2888T-TP-MSIG
Date calculated: 03/12/2019 9:17 AM

Full Report
Registration: SJT2888T
Printed: 03/12/2019 9:17 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	04/09/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	LEXUS
Model:	ES (V6)
Sub Model:	200
Model Sheet Number:	24 23 20
Registration:	SJT2888T
VIN number:	
Odometer:	

Model Specs

FROM 04/2014	3 ZONE AUTO AIR CON	LED HEADLAMP	HEADLAMP WASHERS
PARK PILOT SYSTEM	2.5 LTR 135KW	VERS GEN COUNTRIES	PREPARE OFF VEHICLE
THREE COAT PEARL			


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: FRT BUMPER , RADIATOR GRILLE, PARK SENSOR AND REQUIRED ATTACHED PARTS REMOVE AND REFIT	23.0	115.00	
NO NUMBER	R + R FRONT BUMPER DAMPER	1.0	5.00	
NO NUMBER	RENEW LEFT FRONT BUMPER BRACKET	1.0	5.00	
NO NUMBER	RENEW RIGHT FRONT BUMPER BRACKET	1.0	5.00	
B040)	ADJUST HEADLAMPS	3.0	15.00	
B040)	RENEW BOTH HEADLAMPS	3.0	15.00	
B290	RENEW END PANEL (BUMPER REMOVED) INCLUDES: R + R BOOT FLOOR CARPET AND ALL TRIMS IN THE REPAIR SECTION	38.0	190.00	
B360	RENEW BOOT LID INCLUDES: R + R BOOT LID, CONVERT ATTACHED PARTS	12.0	60.00	
811201)	R + R L/NUMBER PLATE LAMP	2.0	10.00	
811201)	R + R R/NUMBER PLATE LAMP	2.0	10.00	
NO NUMBER	R + R L/R BUMPER BRACKET	2.0	10.00	
NO NUMBER	R + R R/R BUMPER BRACKET	2.0	10.00	
B410	R + R REAR BUMPER CARRIER	1.0	5.00	
B420	RENEW REAR BUMPER INCLUDES: BUMPER AND ALL REQUIRED ATTACHED PARTS R + R	11.0	55.00	
B407	R + R L/OUTER REAR LAMP	2.0	10.00	
B407	R + R R/OUTER REAR LAMP	2.0	10.00	
0471	BONNET REPAIR	15.0*	75.00	
0475	L/F HINGE REPAIR	5.0*	25.00	
0476	R/F HINGE REPAIR	5.0*	25.00	
1009	FRONT PANEL REPAIR	10.0*	50.00	
2953	L/R HINGE REPAIR	5.0*	25.00	
2954	R/R HINGE REPAIR	5.0*	25.00	
3901	REAR FLOOR PANEL REPAIR	10.0*	50.00	
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		16.10	161.0	805.00
Total of Labour				805.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - THREE COAT PEARL		WU	Price SGD
	FRT BUMPER SUPPORT SURFACE PAINT		4.0	
	BONNET NEW PART PAINTING		31.4	
	FRONT PANEL SURFACE PAINT		7.0	
	REAR BUMPER SUPPORT SURFACE PAINT		4.0	
	END PANEL NEW PART PAINTING		24.9	
	BOOTLID NEW PART PAINTING		23.1	
	L/F CTR PARK AID SEN NEW PART PAINT K1R		4.5	
	R/F CTR PARK AID SEN NEW PART PAINT K1R		4.5	

Code	Description - THREE COAT PEARL	WU	Price SGD
	L/F OUT PARK AID SEN NEW PART PAINT K1R	4.5	
	R/F OUT PARK AID SEN NEW PART PAINT K1R	4.5	
	FRONT BUMPER NEW PART PAINT K1N	19.4	
	R/F BUMPER COVER NEW PART PAINT K1R	4.5	
	GRILLE NEW PART PAINT K1R	5.7	
	L/H-LAMP WASHER LID NEW PART PAINT K1R	4.5	
	R/H-LAMP WASHER LID NEW PART PAINT K1R	4.5	
	REAR COVER BUMPER NEW PART PAINT K1N	21.9	
	L/R OUT PARKING SENS NEW PART PAINT K1R	4.5	
	R/R OUT PARKING SENS NEW PART PAINT K1R	4.5	
	L/R CTR PARK SENSOR NEW PART PAINT K1R	4.5	
	R/R CTR PARK SENSOR NEW PART PAINT K1R	4.5	
	L/F WING SURFACE PAINT	8.6	
	R/F WING SURFACE PAINT	8.6	
	L/R SIDE PANEL SURFACE PAINT	11.8	
	R/R SIDE PANEL SURFACE PAINT	11.8	
	REAR FLOOR PANEL SURFACE PAINT	12.0	

Paint Material Per Part

Code	Description	Price SGD
0340	FRT BUMPER SUPPORT SURFACE PAINT	2.49
0471	BONNET NEW PART PAINTING	100.87
1009	FRONT PANEL SURFACE PAINT	16.93
2640	REAR BUMPER SUPPORT SURFACE PAINT	2.49
2711	END PANEL NEW PART PAINTING	32.54
2931	BOOTLID NEW PART PAINTING	65.23
0267	L/F CTR PARK AID SEN NEW PART PAINT K1R	0.62
0268	R/F CTR PARK AID SEN NEW PART PAINT K1R	0.62
0269	L/F OUT PARK AID SEN NEW PART PAINT K1R	0.62
0270	R/F OUT PARK AID SEN NEW PART PAINT K1R	0.62
0283	FRONT BUMPER NEW PART PAINT K1N	86.56
0300	R/F BUMPER COVER NEW PART PAINT K1R	0.62
0410	GRILLE NEW PART PAINT K1R	6.23
0627	L/H-LAMP WASHER LID NEW PART PAINT K1R	1.25
0628	R/H-LAMP WASHER LID NEW PART PAINT K1R	1.25
2583	REAR COVER BUMPER NEW PART PAINT K1N	99.72
2669	L/R OUT PARKING SENS NEW PART PAINT K1R	0.62
2670	R/R OUT PARKING SENS NEW PART PAINT K1R	0.62
2671	L/R CTR PARK SENSOR NEW PART PAINT K1R	0.62
2672	R/R CTR PARK SENSOR NEW PART PAINT K1R	0.62
0741	L/F WING SURFACE PAINT	13.48
0742	R/F WING SURFACE PAINT	13.48
3481	L/R SIDE PANEL SURFACE PAINT	31.34
3482	R/R SIDE PANEL SURFACE PAINT	31.34
3901	REAR FLOOR PANEL SURFACE PAINT	40.84

Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			244.0	
Preparation Main Work Metal		2.50	25.0	125.00
Preparation Comp. Work Plastic		0.80	8.0	40.00
Preparation Multi-Coat		0.50	5.0	25.00
Total	10 WU/h	28.20	282.0	1,410.00

Material Cost - Paint

	Price SGD
New Part Painting	198.64
New Part Painting - Plastic K1R	14.31
New Part Painting - Plastic K1N	186.28
Surface-/Blend Paint	152.39
Material-constant Metal Preparation	28.60
Material-constant Multi-Coat	9.30
Material-constant Plastic	12.70
Total	602.22

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0257	FRONT NUMBER PLATE	KNPL3		0.00
0283	FRONT BUMPER	52119 3T912		350.00
0300	R/F BUMPER COVER	52128 33912		20.00
0317	L/F OUT BUMPER BRKT	52146 33060		30.00
0318	R/F OUT BUMPER BRKT	52145 33060		30.00
0344	FRONT BUMPER	52611 33220		65.00
	DAMPING			
0365	CLIP FASTENING	52161 02030		15.00
0410	GRILLE	53111 33440		360.00
0420	GRILLE MOULDING	53121 33050		120.00
0423	RADIATOR GRILL SEAL	53155 33050		50.00
0431	GRILLE BADGE	90975 02125		160.00
0483	CLIP FASTENING	90467 09050		15.00
0561	LEFT HEADLAMP ASSY	81106 33B00		850.00
0562	RIGHT HEADLAMP ASSY	81105 33D00		850.00
1015	UPPER AIR GUIDE	53295 33080		125.00
2583	REAR COVER BUMPER	52159 33953		340.00
2607	L/R OUT BUMPER BRKT	52158 33030		40.00
2608	R/R OUT BUMPER BRKT	52157 33030		40.00
2621	REAR DECAL STRIPE	PT747 33130		0.00
2625	REAR BUMPER DAMPER	52615 33140		60.00
2640	REAR BUMPER SUPPORT	52171 33160		190.00
2671	L/R CTR PARK SENSOR	89341 33200C1		150.00
2672	R/R CTR PARK SENSOR	89341 33200C1		150.00
2702	REAR NUMBER PLATE	KNPL6		0.00
2711	END PANEL	58307 33171		280.00
2931	BOOTLID	64401 33650		400.00
2944	BOOTLID SEAL	64461 33100		110.00
2977	BOOT/TAILGATE LOCK	64600 33180		180.00
2979	BOOTLID TRIM	76801 33440		120.00
3013	REAR BADGE	90975 02078		30.00
3015	MANUFACTURER BADGE	75447 33170		30.00
3017	VERSION BADGE	75442 33390		35.00

Code	Description	Part Number	Supplier	Price SGD
3281	L/R OUTER LAMP	81561 33570		300.00
3282	R/R OUTER LAMP	81551 33570		300.00
3361	L/NUMBER PLATE LAMP	81270 33100		80.00
3403	L/R INNER LAMP	81591 33240		230.00
4985	END PANEL TRIM	58387 33150C0		150.00
1006	FRT GRILLE STOPPER	X2		16.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	6,271.00
Addition(+15.00%)	940.65
Total	7,211.65

Extras

Code	Description	Price SGD
1000	FRT NUMBER PLATE -	35.00*
1002	RR NUMBER PLATE -	35.00*
1005	DIAGNOSE & RESET FAULT CODE	150.00*
	Total Extras	220.00

Final Calculation

	SGD	SGD
Parts	6,271.00	
Addition(+15.00%)	940.65	
Total Parts		7,211.65
Labour Time Base 10 WU/h		
Total 161.0 WU X 50.00 SGD/h	805.00	
Total of Labour		805.00
Total Of Extras		220.00
Paint Work Time Base 10 WU/h		
Labour Cost 282.0 WU X 50.00 SGD/h	1,410.00	
Material Cost	602.22	
Total Paint Including Material		2,012.22
Repair Cost Excludes GST		10,248.87
GST (+7.0%)		717.42
Repair Cost Included GST		10,966.29

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 3 December 2019 11:40 AM
To: 'Sharon Sng'; SUR; Taufikh (LKKAUTO)
Subject: RE: SJT 2888T-DOA: 4/9/2019 (finalise)

Dear Sharon,

WITHOUT PREJUDICE

Finalize amount \$10,248.87 @ 8 working days.

Kindly send Final invoice and all supporting documents directly to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Tuesday, 12 November 2019 9:24 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: RE: SJT 2888T-DOA: 4/9/2019 (finalise)

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-Please note that all offer/acceptance is made without prejudice.-

From: Veron Chen (LKKAUTO)
Sent: Tuesday, November 5, 2019 12:05 PM
To: Sharon Sng <sharon@sngahtee.com>; SUR <sur@lkkauto.com>; 'SAMANTHA TAN' <sam@sngahtee.com>
Subject: RE: SJT 2888T-DOA: 4/9/2019

Dear Sharon/Samantha,

WITHOUT PREJUDICE

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 17 October 2019 4:30 PM

To: Sharon Sng <sharon@sngahtee.com>; SUR <sur@lkkauto.com>; 'SAMANTHA TAN' <sam@sngahtee.com>

Subject: SJT 2888T-DOA: 4/9/2019

Dear Sharon/Samantha,

WITHOUT PREJUDICE

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Sep 2019 16:57 Sendback Est	05 Sep 2019 17:23 S\$14,735.56	06 Sep 2019 13:45 Edit Adj Rpt	S\$10,248.87 Edit Estimates	S\$10,248.87 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: DELI HUB CATERING PTE LTD , Co. Reg. No.: 200414557H									
Main Claimant: TAN ZHIWEI , ID: S8208431B									
Vehicle Reg. No.:	SJT2888T	Date of Loss:	04/09/2019 09:00 - :59 [62 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 605293	Policy/Cover Note No.:	B29120951MKF (Comprehensive) Coverage: 01/04/2019 - 31/03/2020						
Vehicle Reg. No. (Insured):	GBE618T	Policy No. (Claimant):	GA110880						
		Excess:							
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 06/10/2019]								
Adj Asg. Remarks:	on WP. Car in, request survey on 06/09/19 after 11am. Manual assigned to LKK via email 05/09/19. Liab: NR. Contact: Samantha @ 6268 6183.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJT2888T (605293)
[GBE618T]
TP
TAN ZHIWEI
Sep 4 2019 9:00AM
[DELI HUB CATERING PTE LTD]
Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	☒	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	05/09/19 17:23	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/09/19 14:13	Adjuster Immediate Advice		Load HTM	
Photos/Images			3 per page	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/09/19 13:51	General View		Load JPG	☒
2	09/09/19 13:51	General View		Load JPG	☒
3	09/09/19 13:51	General View		Load JPG	☒
4	09/09/19 13:51	General View		Load JPG	☒
5	09/09/19 13:51	General View		Load JPG	☒
6	09/09/19 13:51	General View		Load JPG	☒
7	09/09/19 13:51	General View		Load JPG	☒
8	09/09/19 13:51	General View		Load JPG	☒
9	09/09/19 13:51	General View		Load JPG	☒
10	09/09/19 13:51	General View		Load JPG	☒
11	09/09/19 13:51	General View		Load JPG	☒
12	09/09/19 13:51	General View		Load JPG	☒
13	09/09/19 13:51	General View		Load JPG	☒
14	09/09/19 13:51	General View		Load JPG	☒
15	09/09/19 13:51	General View		Load JPG	☒
16	09/09/19 13:51	General View		Load JPG	☒
17	09/09/19 13:51	General View		Load JPG	☒
18	09/09/19 13:51	General View		Load JPG	☒
19	09/09/19 13:51	General View		Load JPG	☒
20	09/09/19 13:51	General View		Load JPG	☒
21	09/09/19 13:51	General View		Load JPG	☒
22	09/09/19 13:51	General View		Load JPG	☒
23	09/09/19 13:51	General View		Load JPG	☒
24	09/09/19 13:51	General View		Load JPG	☒
25	09/09/19 13:51	General View		Load JPG	☒
26	09/09/19 13:51	General View		Load JPG	☒
27	09/09/19 13:51	General View		Load JPG	☒
28	09/09/19 13:51	General View		Load JPG	☒
29	09/09/19 13:51	General View		Load JPG	☒
30	09/09/19 13:51	General View		Load JPG	☒
31	09/09/19 13:51	General View		Load JPG	☒
32	09/09/19 13:51	General View		Load JPG	☒
33	09/09/19 13:51	General View		Load JPG	☒
34	09/09/19 13:51	General View		Load JPG	☒
35	09/09/19 13:51	General View		Load JPG	☒

Assessment Reports			1 per page ▾	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
36	09/09/19 13:51	General View		☒
37	09/09/19 13:51	General View		☒
38	09/09/19 13:51	General View		☒
39	09/09/19 13:51	General View		☒
40	09/09/19 13:51	General View		☒
41	09/09/19 13:51	General View		☒
42	09/09/19 13:51	General View		☒
43	09/09/19 13:51	General View		☒
44	09/09/19 13:51	General View		☒
45	09/09/19 13:51	General View		☒
46	09/09/19 13:51	General View		☒
47	09/09/19 13:51	General View		☒
48	09/09/19 13:51	General View		☒
49	09/09/19 13:51	General View		☒
50	09/09/19 13:51	General View		☒
51	09/09/19 13:51	General View		☒
52	09/09/19 13:51	General View		☒
53	09/09/19 13:51	General View		☒
54	09/09/19 13:51	General View		☒
55	09/09/19 13:51	General View		☒
56	09/09/19 13:51	General View		☒
57	09/09/19 13:51	General View		☒
58	09/09/19 13:51	General View		☒
59	09/09/19 13:51	General View		☒
60	09/09/19 13:51	General View		☒
61	09/09/19 13:51	General View		☒
62	09/09/19 13:51	General View		☒
63	09/09/19 13:51	General View		☒
64	09/09/19 13:51	General View		☒
65	09/09/19 13:51	General View		☒
66	09/09/19 13:51	General View		☒
67	09/09/19 13:51	General View		☒
68	09/09/19 13:51	General View		☒
69	09/09/19 13:51	General View		☒
70	09/09/19 13:51	General View		☒
71	09/09/19 13:51	General View		☒
72	09/09/19 13:51	General View		☒
73	09/09/19 13:51	General View		☒
74	09/09/19 13:51	General View		☒
75	09/09/19 13:51	General View		☒
76	09/09/19 13:51	General View		☒
77	09/09/19 13:51	General View		☒
78	09/09/19 13:51	General View		☒
79	09/09/19 13:51	General View		☒
80	09/09/19 13:51	General View		☒
81	03/12/19 09:53	Reinspection Photo		☒
82	03/12/19 09:53	Reinspection Photo		☒
83	03/12/19 09:53	Reinspection Photo		☒
84	03/12/19 09:53	Reinspection Photo		☒
85	03/12/19 09:53	Reinspection Photo		☒
86	03/12/19 09:53	Reinspection Photo		☒
87	03/12/19 09:53	Reinspection Photo		☒
88	03/12/19 09:53	Reinspection Photo		☒

Assessment Reports			1 per page	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
89	03/12/19 09:53	Reinspection Photo	Load JPG	☒
90	03/12/19 09:53	Reinspection Photo	Load JPG	☒
91	03/12/19 09:53	Reinspection Photo	Load JPG	☒
92	03/12/19 09:53	Reinspection Photo	Load JPG	☒
93	03/12/19 09:53	Reinspection Photo	Load JPG	☒
94	03/12/19 09:53	Reinspection Photo	Load JPG	☒
95	03/12/19 09:54	Reinspection Photo	Load JPG	☒
96	03/12/19 09:54	Reinspection Photo	Load JPG	☒
97	03/12/19 09:54	Reinspection Photo	Load JPG	☒
98	03/12/19 09:54	Reinspection Photo	Load JPG	☒
99	03/12/19 09:54	Reinspection Photo	Load JPG	☒
100	03/12/19 09:54	Reinspection Photo	Load JPG	☒
101	03/12/19 09:54	Reinspection Photo	Load JPG	☒
102	03/12/19 09:54	Reinspection Photo	Load JPG	☒
103	03/12/19 09:54	Reinspection Photo	Load JPG	☒
104	03/12/19 09:54	Reinspection Photo	Load JPG	☒
105	03/12/19 09:54	Reinspection Photo	Load JPG	☒
106	03/12/19 09:54	Reinspection Photo	Load JPG	☒
107	03/12/19 09:54	Reinspection Photo	Load JPG	☒
108	03/12/19 09:54	Reinspection Photo	Load JPG	☒
109	03/12/19 09:54	Reinspection Photo	Load JPG	☒
110	03/12/19 09:54	Reinspection Photo	Load JPG	☒
111	03/12/19 09:54	Reinspection Photo	Load JPG	☒
112	03/12/19 09:54	Reinspection Photo	Load JPG	☒
113	03/12/19 09:54	Reinspection Photo	Load JPG	☒
114	03/12/19 09:54	Reinspection Photo	Load JPG	☒
115	03/12/19 09:54	Reinspection Photo	Load JPG	☒
116	03/12/19 09:54	Reinspection Photo	Load JPG	☒
117	03/12/19 09:54	Reinspection Photo	Load JPG	☒
118	03/12/19 09:54	Reinspection Photo	Load JPG	☒
119	03/12/19 09:54	Reinspection Photo	Load JPG	☒
120	03/12/19 09:54	Reinspection Photo	Load JPG	☒
121	03/12/19 09:54	Reinspection Photo	Load JPG	☒
122	03/12/19 09:54	Reinspection Photo	Load JPG	☒
123	03/12/19 09:54	Reinspection Photo	Load JPG	☒
124	03/12/19 09:54	Reinspection Photo	Load JPG	☒
125	03/12/19 09:54	Reinspection Photo	Load JPG	☒

Documentation			1 per page	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	05/09/19 17:22	CI,IC,DL	Load TIF	
2	05/09/19 17:22	AUDATEX	Load PDF	
3	05/09/19 17:22	E-filed GIA report	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/09/19 13:35	Acknowledge PRI	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	06/09/19 13:39	Survey Request - Manual Assigned	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/12/19 14:06	SUPPLEMENTARY	Load PDF	
2	03/12/19 14:09	PARTS INVOICE	Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	05/09/19 17:22	CI,IC,DL	Load TIF	
2	05/09/19 17:22	AUDATEX	Load PDF	
3	05/09/19 17:22	E-filed GIA report	Load PDF	
1	06/09/19 13:35	Acknowledge PRI	Load PDF	
1	06/09/19 13:39	Survey Request - Manual Assigned	Load PDF	
1	03/12/19 14:06	SUPPLEMENTARY	Load PDF	
2	03/12/19 14:09	PARTS INVOICE	Load PDF	

Assessment Reports			Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		1 per page	Thumbnail	Print
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print		
1	05/09/19 09:26	Accident Statement		Load HTM			
2	05/09/19 09:30	Addendum Sheet		Load TIF			
3	05/09/19 09:30	Accident Statement Addm. #1		Load HTM			
Photos/Images						3 per page	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print		
1	04/09/19 12:57	Accident Photo		Load JPG			
2	04/09/19 12:57	Accident Photo		Load JPG			
3	04/09/19 12:57	Accident Photo		Load JPG			
4	04/09/19 12:57	Accident Photo		Load JPG			
5	04/09/19 12:57	Accident Photo		Load JPG			
6	04/09/19 12:57	Accident Photo		Load JPG			
7	04/09/19 12:57	Accident Photo		Load JPG			
8	04/09/19 12:57	Accident Photo		Load JPG			
9	04/09/19 12:57	Accident Photo		Load JPG			
10	04/09/19 12:57	Accident Photo		Load JPG			
11	04/09/19 12:57	Accident Photo		Load JPG			
12	04/09/19 12:57	Accident Photo		Load JPG			
13	04/09/19 12:57	Accident Photo		Load JPG			
14	04/09/19 12:57	Accident Photo		Load JPG			
15	04/09/19 12:57	Accident Photo		Load JPG			
16	04/09/19 12:57	Accident Photo		Load JPG			
17	04/09/19 12:57	Accident Photo		Load JPG			
18	04/09/19 12:57	Accident Photo		Load JPG			
19	04/09/19 12:57	Accident Photo		Load JPG			
20	04/09/19 12:57	Accident Photo		Load JPG			
21	04/09/19 12:57	Accident Photo		Load JPG			
22	04/09/19 12:57	Accident Photo		Load JPG			
23	04/09/19 12:57	Accident Photo		Load JPG			
24	04/09/19 12:57	Accident Photo		Load JPG			
25	04/09/19 12:57	Accident Photo		Load JPG			
26	04/09/19 12:57	Accident Photo		Load JPG			
27	04/09/19 12:58	Accident Photo		Load JPG			
28	04/09/19 12:58	Accident Photo		Load JPG			
29	04/09/19 12:58	Accident Photo		Load JPG			
30	04/09/19 12:58	Accident Photo		Load JPG			
Documentation						1 per page	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print		
1	04/09/19 12:59	Sketch Plan		Load TIF			
2	05/09/19 09:28	POLICE REPORT		Load TIF			

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19015786/T1VD3S2
Date: 03/12/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B29120951MKF
Claimant Vehicle No : SJT2888T **Insured Vehicle No :** GBE618T
Date of Loss: 04/09/2019 **Nature of Claim:** TP **Claim No:** 605293

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJT2888T**
 Make & Model: LEXUS ES250, 2.5 (A) Engine No: 2ARE861347
 Reg. Date: 23/06/2014 (Man. Year: 2014) Chassis No: JTHBJ1GG402056329
 Colour: White Odometer: 104232 km
 Engine Capacity: 2494 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,126.75	7,211.65	4,915.10	40.53
Miscellaneous Items	420.00	220.00	200.00	47.62
Labour	855.00	805.00	50.00	5.85
Paintwork Labour	1,333.81	2,012.22	-678.41	-50.86
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,735.56	10,248.87	4,486.69	30.45
+ GST 7.00/7.00% (S\$)	1,031.49	717.42	314.07	30.45
Nett Amount (S\$)	15,767.05	10,966.29	4,800.76	30.45

INSPECTION

Date of Assignment: 06/09/2019 Present Location: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
 Date Inspected: 06/09/2019 Inspected At: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
 Blk 3 Pioneer Road North, #01-18
 Singapore 628457
 Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Dec 2019)
Parts:	143	LEXUS ES250 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT2888T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT GRILLE STOPPER (WCP)	Necessary	-	*16.00 F
2	1	NA	*BONNET (WCP)	Repair	700.00 F	*- F
3	1	NA	*BONNET LOCK (WCP)	Not Necessary	65.00 F	*- F
4	1	NA	*BOOT/TAILOUT LOCK (WCP)	Bent	180.00 F	*180.00 F
5	1	NA	*BOOTLID (WCP)	Bent	400.00 F	*400.00 F
6	1	NA	*BOOTLID SEAL (WCP)	Torn	110.00 F	*110.00 F
7	1	NA	*BOOTLID TRIM (WCP)	Deformed	120.00 F	*120.00 F
8	1	NA	*BOOTLID TRIM (WCP)	Not Necessary	550.00 F	*- F
9	1	NA	*CLIP FASTENING (WCP)	Necessary	15.00 F	*15.00 F
10	1	NA	*CLIP FASTENING (WCP)	Necessary	15.00 F	*15.00 F
11	1	NA	*CTR BUMPER GRILLE (WCP)	Not Necessary	70.00 F	*- F
12	1	NA	*END PANEL (WCP)	Bent	280.00 F	*280.00 F
13	1	NA	*END PANEL TRIM (WCP)	Deformed	150.00 F	*150.00 F
14	1	NA	*F/SUPP PANEL TOP (WCP)	Not Necessary	15.00 F	*- F
15	1	NA	*FRONT BUMPER (WCP)	Deformed	350.00 F	*350.00 F
16	1	NA	*FRONT BUMPER DAMPING (WCP)	Deformed	65.00 F	*65.00 F
17	1	NA	*FRONT PANEL (WCP)	Repair	520.00 F	*- F
18	1	NA	*FRT BUMPER SUPPORT (WCP)	Not Necessary	170.00 F	*- F
19	1	NA	*FRT NO PLATE REINF (WCP)	Not Necessary	50.00 F	*- F
20	1	NA	*GRILLE (WCP)	Cracked	360.00 F	*360.00 F
21	1	NA	*GRILLE BADGE (WCP)	Missing	160.00 F	*160.00 F
22	1	NA	*GRILLE MOULDING (WCP)	Cracked	120.00 F	*120.00 F
23	1	NA	*L/F CTR PARK AID SEN (WCP)	Not Necessary	150.00 F	*- F
24	1	NA	*L/F HINGE (WCP)	Repair	50.00 F	*- F
25	1	NA	*L/F OUT BUMPER BRKT (WCP)	Deformed	30.00 F	*30.00 F
26	1	NA	*L/F OUT PARK AID SEN (WCP)	Not Necessary	150.00 F	*- F
27	1	NA	*L/H-LAMP WASHER LID (WCP)	Not Necessary	20.00 F	*- F
28	1	NA	*L/H-LAMP WASHER MOT (WCP)	Not Necessary	240.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
29	1	NA	*L/NUMBER PLATE LAMP (WCP)	Cracked	80.00 F	*80.00 F
30	1	NA	*L/R CTR PARK SENSOR (WCP)	Not Working	150.00 F	*150.00 F
31	1	NA	*L/R HINGE (WCP)	Repair	75.00 F	*- F
32	1	NA	*L/R INNER LAMP (WCP)	Cracked	230.00 F	*230.00 F
33	1	NA	*L/R OUT BUMPER BRKT (WCP)	Necessary	40.00 F	*40.00 F
34	1	NA	*L/R OUTER LAMP (WCP)	Cracked	300.00 F	*300.00 F
35	1	NA	*L/R OUT PARKING SENS (WCP)	Not Necessary	150.00 F	*- F
36	1	NA	*L/R UPP BUMPER BRKT (WCP)	Not Necessary	50.00 F	*- F
37	1	NA	*LEFT HEADLAMP ASSY (WCP)	Cracked	850.00 F	*850.00 F
38	1	NA	*MANUFACTURER BADGE (WCP)	Necessary	30.00 F	*30.00 F
39	1	NA	*R/F BUMPER COVER (WCP)	Deformed	20.00 F	*20.00 F
40	1	NA	*R/F CTR PARK AID SEN (WCP)	Not Necessary	150.00 F	*- F
41	1	NA	*R/F HINGE (WCP)	Repair	50.00 F	*- F
42	1	NA	*R/F OUT BUMPER BRKT (WCP)	Deformed	30.00 F	*30.00 F
43	1	NA	*R/F OUT PARK AID SEN (WCP)	Not Necessary	150.00 F	*- F
44	1	NA	*R/H-LAMP WASHER LID (WCP)	Not Necessary	50.00 F	*- F
45	1	NA	*R/H-LAMP WASHER MOT (WCP)	Not Necessary	240.00 F	*- F
46	1	NA	*R/NUMBER PLATE LAMP (WCP)	Not Necessary	80.00 F	*- F
47	1	NA	*R/R CTR PARK SENSOR (WCP)	Missing	150.00 F	*150.00 F
48	1	NA	*R/R HINGE (WCP)	Repair	75.00 F	*- F
49	1	NA	*R/R INNER LAMP (WCP)	Not Necessary	230.00 F	*- F
50	1	NA	*R/R OUT BUMPER BRKT (WCP)	Necessary	40.00 F	*40.00 F
51	1	NA	*R/R OUTER LAMP (WCP)	Cracked	300.00 F	*300.00 F
52	1	NA	*R/R OUT PARKING SENS (WCP)	Not Necessary	150.00 F	*- F
53	1	NA	*R/R UPP BUMPER BRKT (WCP)	Not Necessary	50.00 F	*- F
54	1	NA	*RADIATOR GRILL SEAL (WCP)	Necessary	50.00 F	*50.00 F
55	1	NA	*REAR BADGE (WCP)	Necessary	30.00 F	*30.00 F
56	1	NA	*REAR BUMPER DAMPER (WCP)	Deformed	60.00 F	*60.00 F
57	1	NA	*REAR BUMPER SUPPORT (WCP)	Bent	190.00 F	*190.00 F
58	1	NA	*REAR COVER BUMPER (WCP)	Deformed	340.00 F	*340.00 F
59	1	NA	*REAR DECAL STRIPE (NPA)	Not Necessary	0.00 F	*- F
60	1	NA	*RIGHT HEADLAMP ASSY (WCP)	Cracked	850.00 F	*850.00 F
61	1	NA	*RR END PANEL TOP (WCP)	Not Necessary	20.00 F	*- F
62	1	NA	*SCREW (WCP)	Not Necessary	20.00 F	*- F
63	1	NA	*UPPER AIR GUIDE (WCP)	Deformed	125.00 F	*125.00 F
64	1	NA	*VERSION BADGE (WCP)	Necessary	35.00 F	*35.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part.						
Sub Total (S\$)					10,545.00	6,271.00
+ Margin on L,N Items 15.00/15.00% (S\$)					1,581.75	940.65
Total Parts (S\$)					12,126.75	7,211.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	DIAGNOSE & RESET FAULT CODE	250.00	150.00
2	1	FRT NUMBER PLATE (BENT)	35.00	35.00
3	1	RR NUMBER PLATE (BENT)	35.00	35.00
4	1	TOP UP AIRCON GAS (NOT NECESSARY)	100.00	0.00
Sub Total (S\$)			420.00	220.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Labour	New	970.00	1,410.00
2	Total Paint Materials	New	363.81	602.22
Labour Items				
3	Total Panel/Mechanical Labour	New	855.00	805.00
Gross Labour Cost (S\$)			2,188.81	2,817.22

Report was unsubmitted during this print-out.

< END OF ESTIMATES >