

ASS. REC. BY:

REF: CS3/CY119015817/Gcd302

Special Instruction:

Surveyor: Ando AinaASSIGNMENT (Office)From (Person): Murim

Irene Tay

of

CYI

Date/Time: 6/9/19 @ 14:30pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBB 2781 G

Insured:

YP 8413J

at Workshop in/s

Equator Brotherhood

Tel:

6384 6939

of

25 Keiki Bukit Rd 4 #03-79 Synergy

Policy No:

DMCVSN30517619000

Claim No:

SNM19D204093C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:30pm @ 6/9/19

Person Contacted:

Mr. Tun

Vehicle IN/OUT

| Date/Time | Action/Instruction |
|-----------|--------------------|
| | Johny (X) |
| | FBB 2781 G-X |
| | YP 8413J-X |
| | No GIA |
| | |
| | |
| | |

Surveyor: PHS
Ed.

REF: CI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Equator Brotherhood

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: B27816 Yr Regn: -

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CB 400 C.C. 399

Colour: Red A/C: Insured / Std / NI / NA

Sp.Reading: 57473 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 120/60 R17

R: 160/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 06-08-19

Survey held at w/s 4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$ 2000 - \$ 3000

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee: 150

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

) S + RS \$ _____

) Photos

) Others

Report Format : PRQ

Lump Sum / I.B.I. (\$) _____

TOTAL 150

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--------------------------------|---------|---------------|-------------|--|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 05 Sep 2019 | | 06 Sep 2019 14:30 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|-----------|---|------------------------|------------------------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | | | | | | | | | |
| Main Claimant: YAMOTO ENERGY PTE LTD | | | | | | | | | |
| Vehicle Reg. No.: | | FBB2781G | Date of Loss: | 30/08/2019 08:00 - :59 | | | | | |
| Claim Type: | | TP / SNM19D204093C02 | Policy/Cover Note No.: | DMCVSN30517619000 | | | | | |
| Vehicle Reg. No. (Insured): | | YP8413J | Policy No. (Claimant): | | | | | | |
| | | Excess: | S\$0.00 | | | | | | |
| Repairer: | | Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb, 417800 Kaki Bukit - Tel: 63846939 / 90113391 | | | | | | | |
| Handling Insurer: | | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192] | | | | | | | |
| Adjuster: | | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/09/2019] | | | | | | | |
| Adj Asg. Remarks: | | PLEASE SURVEY AND REVERT | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Friday, 6 September 2019 2:13 PM
To: kelly.cheng@alt.sg; assignments; Asher Sng (LKK Auto)
Subject: FW: OUR REF: SNM19D204093-YP8413J-THP - FW: PRE-REPAIR SURVEY NOTIFICATION - YOUR REF: YP 8413 J REF: AL.INS.2019.FBB2781G(PDPI)KC
Attachments: PRS letter.pdf

Dear Sir/Mdm (LKK),

We refer to the above matter.

Please assist to get your surveyor to conduct PRI.

Regards,

6389 6131

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896192 | F:(65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, September 4, 2019 5:22 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; kelly.cheng@alt.sg
Subject: OUR REF: SNM19D204093-YP8413J-THP - FW: PRE-REPAIR SURVEY NOTIFICATION - YOUR REF: YP 8413 J REF: AL.INS.2019.FBB2781G(PDPI)KC

Dear Irene,

Please conduct PRS for FBB2781G.

Note : officer in charge – Irene Tay 63896192.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: kelly.cheng@alt.sg [<mailto:kelly.cheng@alt.sg>]

Sent: Wednesday, September 04, 2019 12:43 PM

To: Claims Dept of CTI; Ong Chin Kiat

Cc: elin.cqw@gmail.com; equator.brotherhood@gmail.com; vincent@alt.sg; allister@alt.sg; cho.tsui@alt.sg; 'Jeremy Peh'

Subject: PRE-REPAIR SURVEY NOTIFICATION - YOUR REF: YP 8413 J REF: AL.INS.2019.FBB2781G(PDPI)KC

WITHOUT PREJUDICE

Dear Sirs/Mdm,

We refer to the above matter.

We enclosed herewith our Pre-Repair Survey Notification Letter dated 4th September 2019 for your immediate attentions.

Kindly revert to us within the next 2 working days.

Thank you.

Best Regards

Kelly Cheng

For and on behalf of
Allister Lim

ALLISTER LIM & THRUMURGAN
ADVOCATES & SOLICITORS
111 North Bridge Road
#11-04 Peninsula Plaza
Singapore 179098
Telephone : 6438 3303
Facsimile : 6438 1211

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at mail@alt.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.



Virus-free. www.avg.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Your Ref: YP 8413 J

Our Ref: AL.INS.2019.FBB2781G(PDPI)KC

4th September 2019

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD BY PDX & EMAIL ONLY
3, Anson Road
#16-00, Springleaf Tower
Singapore 079909

PDX Intercompany Exchange Pte Ltd

010808805153
FROM Allister Lim & Thrumurgan
PDX Box No. 8144

Dear Sirs,

**ACCIDENT INVOLVING FBB 2781 G / YP 8413 J ON 30th AUGUST 2019 ALONG
UPPER THOMSON ROAD AT ABOUT 08:25 HOURS**

We act for the owner of vehicle no. FBB 2781 G.

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair survey of our client's motor vehicle at the under-stated workshop: -


EQUATOR BROTHERHOOD

25 Kaki Bukit Road 4
#03-79
Singapore 417800
Person In-Charge: Willie
Mobile Number: 9011 3391

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair survey and our client's repairers shall proceed to repair our client's vehicle without further reference.

Please contact our staff, Kelly / Jeremy / Cho at 6438 3303 / 6422 2185 or email us at Kelly.cheng@alt.sg / Jeremy.peh@alt.sg / Cho.tsui@alt.sg for future correspondences.

Yours faithfully


f. ALLISTER LIM

ALLISTER LIM & THRUMURGAN

...CLAIM SUBFOLDER...(Pending for Survey Report)












































| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 05 Sep 2019 | | 06 Sep 2019 14:30 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |























































| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|------------------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | -, Co. Reg. No.: - | | | | | | | | |
| Main Claimant: | YAMOTO ENERGY PTE LTD | | | | | | | | |
| Vehicle Reg. No.: | FBB2781G | Date of Loss: | 30/08/2019 08:00 - :59 | | | | | | |
| Claim Type: | TP / SNM19D204093C02 | Policy/Cover Note No.: | DMCVSN30517619000 | | | | | | |
| Vehicle Reg. No. (Insured): | YP8413J | Policy No. (Claimant): | | | | | | | |
| | | Excess: | S\$0.00 | | | | | | |
| Repairer: | Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb, 417800 Kaki Bukit - Tel: 63846939 / 90113391 | | | | | | | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 17/09/2019] | | | | | | | | |
| Adj Asg. Remarks: | PLEASE SURVEY AND REVERT | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

























Claim Documents

***FBB2781G (SNM19D204093C02)**
[YP8413J]

TP
YAMOTO ENERGY PTE LTD
Aug 30 2019 8:00AM
[-]
Equator Brotherhood

| Upload Documents | | Upload Photos | Compose New Letter | View View in Browser <input type="button" value="v"/> | |
|----------------------------------|-----------------|-----------------------------------|--|--|--|
| Photos/Images | | | 3 per page <input type="button" value="v"/> | <input checked="" type="checkbox"/> | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print | |
| 1 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 2 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 3 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 4 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 5 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 6 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 7 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 8 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 9 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 10 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 11 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 12 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 13 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 14 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 15 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 16 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 17 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 18 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 19 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 20 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 21 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 22 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 23 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 24 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 25 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 26 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 27 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 28 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 29 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 30 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 31 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 32 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 33 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 34 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 35 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 36 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 37 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 38 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 39 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 40 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 41 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 42 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |
| 43 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> | |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 44 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 16/09/19 16:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 14/10/19 09:23 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 84 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 85 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 86 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 87 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 88 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 89 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 90 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 91 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 92 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 93 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 94 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 95 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 96 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 97 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 98 | 14/10/19 09:24 | Dismantled Parts | Load JPG | <input checked="" type="checkbox"/> |
| 99 | 14/10/19 09:24 | Dismantled Parts | Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 100 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 101 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 102 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 103 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 104 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 105 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 106 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 107 | 14/10/19 09:24 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 108 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 109 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 110 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 111 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 112 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 113 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 114 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 115 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 116 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 117 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 118 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 119 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 120 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 121 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 122 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 123 | 14/10/19 09:24 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |

Documents Checklist

| | | | |
|--|-----------------------|----------------------|-----------------------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19015817/GCD3E2

Date: 21/10/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30517619000

Claimant
Vehicle No : FBB2781GInsured
Vehicle No : YP8413J

Date of Loss: 30/08/2019

Nature of Claim: TP

Claim
No: SNM19D204093C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBB2781G**

Make & Model: HONDA CB400, 399cc

Engine No: HIDDEN

Reg. Date: (Man. Year:)

Chassis No: HIDDEN

Colour: Red

Odometer: 57473 km

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

Front Tyre Size: 120/60 R17

Rear Tyre Size: 160/60 R17

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 06/09/2019

Date Inspected: 06/09/2019 Inspected At:

Equator Brotherhood (HQ)
25 kaki bukit rd 4 #03-79 synergy @
kb
Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Sep 2019)

Parts: N/A HONDA CB400 399cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBB2781G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >