, " (ASS. REC. BY		REF: CSIMSG1901	5821/DEP20	2 Special Instruction:				
1	Surveyor	Bryan		ENT (Office)					
Menmen	From (Person): Butine Than	n of MS:	1G	Date/Time: 06/09/2019				
	Estimated Co	ot:		Bill to:	Bill to:				
		OD (TP)/WS/TP RES/OD RES/EVA/INV/MV/CS							
		chicle No: SHA	Insured: SKa 4736P						
		m/s Chung N		Tel: 6483 6016					
	of BIK to	#01-05/06 A							
	Policy No: 1	304638430AX	,	Claim No: 66	4584				
	Sum Insured:			Excess:					
	Make of Veh (Client's Recor				D.O.A. 02/09/2019				
	CA / REV	/ REP. / REV 241	HRS Person Contacted:	Lynn	H.O.D. Endorsement:				
	Total Control of the				Vellick HV0001				
	Date/Time	Action/Instruction	(V) Estimate						
		SKG ATSUP	×						
		SHA 7621L CCH/12219019655/71463 Die A 23/08/2019							
				-1					

711

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Sil	bestried	Ad) Assigned	Adl Rpt	Adj	Submitted	Ens Austr	Wid S	tatus	
Main	03 Sep 2019			06 Sep 2019 15:24 Assign					1	Yew Assignm Cancel Case	rent
	Main	$\neg \Gamma$	Re	ference	V .	Claim Deta	nils	Do	cument	s]	Show All
CLAIM S	UBFOLDER DE	TAILS					2.0		[Creat	ed by insure	er]
nsured:			SIM PL	JAY GEK, ID: SE	012323Z						
Main Clair	mant:		COMFO	ORT TRANSPORT	ATION PT	ELTD, Co	Reg. No.:	199303821R			
/ehicle Re	eg. No.:		SHA7621L			Date of Loss:		[51 Mo	02/09/2019 00:00 - :59 [51 Months and 26 Days From LTA Reg Date (Man Yr)]		
Claim Typ	Salm Type:		TP / 604584		Policy/Cover Note No.:		80463843QMX (Comprehensive) Coverage: 28/11/2018 - 27/11/2019				
Vehicle Reg. No. (Insured):		SKQ4736P			Policy No. (Claimant):		A. C. C. C.				
						Excess					
Repairer:			Chunn 648360	Motor Work Pts 16	ttd - Ami	k (HQ) Blk	10 #01-05/0	36, AMK Auto	point, 56	55047 Ang Mo	Kia - Tel:
Handling	Insurer:		MSIG 1 2545]	Insurance (Sings	spore) Pte	. Ltd. (HQ)) - Tel: +65 (6827 7888	[Handle	d by Pauline	Tham - 6594
Adjuster			LKK AL	to Consultants	Pte Ltd (H	Q) - Tel: 62	256-3561	[Imm.Adv	ice due	07/09/201	19]
Driver/Cu	stodian (Insured	i):		H HUA () , NRIC							
Adj Asg. F	Remarks:			Liab: NR. Agree o 19 / 6542 7162.	n SJE, Assi	gn: LKK Au	to Consultani	ts Pte Ltd. Co	ntact: M	s Lynn or Ms	Irene at
ASSOCI	ATED MAIL RE	CEIVED							New All	Compos	e Case Mail
There are	no mail for this	case.									
E		ares.					ONLY SERVICE	WEST-1000 41			A Secondocal
ALL ASS	OCIATED TAS	KS				View	All Sear	ch Tasks	Creat	e New Task	Complete
Due Da	(44)	Турп	Task 6	iroup Subjec	t Handi	er Ass	igned By	Complete	ed On	Created	On Dane?

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	WELLY.
/ehicle No.:	SHA7621L
/ehicle to be Exported:	Yes
ntended Deregistration Date:	17 Sep 2019
/ehicle Make:	HYUNDAI
/ehicle Model:	140 1.7L CRDI AT ABS AIRBAG 4DR
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	D4FDEU483130
Chassis No.:	KMHLB41UMFU068856
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$20,209.00
Original Registration Date:	07 May 2015
First Registration Date:	07 May 2015
Fransfer Count:	0
Actual ARF Paid:	\$12,793.00
ntended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 May 2023
PARF Rebate Amount:	\$9,594.00
ntended COE Rebate Details	
COE Expiry Date:	06 May 2023
COE Category;	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,756.00
COE Rebate Amount:	\$23,065.00
Total Rebate Amount:	\$32,659.00
Message	

The information contained herein is correct as at 17 Sep 2019

Note: This document has not been finalised, LKK Auto Consultants Pte Ltd (Co. Reg. No:199007195R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-6805 Email: sur@lkkauto.com;assignments@lkkauto.com

Ta:

MSIG Insurance (Singapore) Pte, Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From:

LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Pauline Tham

Date:

18 Sep 2019

Preliminary Advice

Insured Vehicle No TP Vehicle No

: SKQ4736P

: SHA7621L

Accident Date

:S\$

: 02/09/2019

Make

: HYUNDAI 140

Assignment Date

: 06/09/2019

Est. Duration of Repair

: 14.00

Date of Inspection Inspection At

: 06/09/2019

: CHUNNI MOTOR WORK PTE LTD - AMK (HQ) BLK 10 #01-05/06, AMK AUTOPOINT

SINGAPORE 568047

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:5\$	54,721,12
Revised Amount	:\$\$	36,927,80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	36,927.80

Lump Sum Repair

Total Loss Consideration

New for Old Value	:5\$
Pre-Accident Value	:5\$
COE / PARF Rebate	:5\$
Salvage Value	:S\$
Margin for Repair	:5\$

Remarks

The vehicle is economical/not economical for repair,

The above survey was conducted on a 'without prejudice' basis.

MCD619117371 / ComfortDelGro Engineering Pto Ltd - Loyang ENTRY DATE & TIME: 04:09/2019 16:56 SUBMITTED BY: Jame! Lim Slang Gok Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 05/09/2019 14:29

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the ledgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	04/09/2019 16:56
Date Of Accident	02/09/2019 21:20
Exact Location Of Accident	SENGKANG CENTRAL TWDS HOUGANG AVE 5 NEAR BUANGKOK
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number Insured/Policyholder	SHA7621L
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	140
Exact Purpose for which vehicle was being utime of accident	used at
Are you claiming under your own insurance for repair to your vehicle?	policy NO
If No. Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
T 010	THEO OF DEVICE AND OD THEFT

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

Policy Number MCOM0015

Cover Note Number

Driver

 Name of Driver
 TEO AH CHUA

 NRIC No
 \$0102617H

 Date Of Birth
 15/03/1952

 Occupation
 OUTDOOR

 Date Of Driving Pass
 14/08/1979

Driving Experience 40 YEARS AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96934751

Fax Number

Contact Number

EMail Address NOEMAIL

Address

BLK 157 JALAN TECK WHYE

#14-115

Postcode

680157

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

3

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

YES

ambulance? Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

1

Details of Police Action

YES

Was the accident reported to the police? If Yes, Please state which Police Station

POLICE STATION NAME (OTHER)

CHOA CHU KANG NPC

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT NO: T/20190903/2057

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKQ4736P

Vehicle Make/Model/Colour

MAZDA

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SBS1Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

BUS

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

TEO AH CHUA Name

Approximate Age

RIGHT LEG, CHEST AND KNEE Injuries Sustain

SHA7621L Injured person in which vehicle? YES Were seat belts worn?

Was this injured conveyed to hospital by

YES ambulance?

Address Postcode

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 Interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (II) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (II) for complying with requirements under any regulations, laws or court orders.

COMFORT	TRANSP	ORTATION PTE L	TD
CO.	REG. NO.	199303821R	

feo.

Lisa

Policyholder's Signature Date & Time: 4/9/2019 Driver's Signature (If driver is not the policyholder) Date & Time:4/9/2019@12;30hrs Reporting Centre Personnel's Signature Name: NRIC/FIN No.: SKETCH PLAN



On 02.09.2019 @ 21:20Hrs A-SHA 7621L B-SKQ 4736P C-SBS 1Z (Bus)

Along Sengkang Central Twds Hougang Ave 6 Near Buangkok MRT

Refer to the Police Report No : T/20190903/2057
And Amendment Police Statement

Declaration

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Soi

Lisa

policyholder's Signature Date & Time 04.09,2019 Oriver's Signature(If driver is not the policyholder)
Date & Time: 04.09.2019 @ 12:30hrs

Reporting Centre Personnel's Signature Name :

NRIC/FIN No:





1 of 3

Report No. T/20190903/2057

Police Station Of Origin: Choa Chu Kang N.P.C 20 Choa Chu Kang Street 52 #01-02 SINGAPORE 689286 Tel No: 1800-7659999

REPORT	OF A T	RAFFIC	ACCIDENT

Date/Time Report Made: 03/09/2019 13:28		Vide Report No.:	Station Diary No.:			
Informa	ntsiPartic	ulars I Lacon a	是空間為1000年1000年100	WAR TANKS OF THE STATE OF		
Name of TEO AH	Informant: CHUA		Address: APT BLK 157 JALAN 680157	TECK WHYE #14-115 SINGAPORE		
ID Type / ID No.: NRIC NO / S0102617H			Contact No.: Home/Office:			
Nationality: SINGAPORE CITIZEN		Email:				
Sex: Age: Date of Birth: Male 67 15/03/1952		Type of Informant: Driver				
Race: Chinese		Language:	Institution / School Name:			
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:				

<u> </u>	Injury	Drink	Date/Time of	Type of Location:
Type of Accident:	Others	Drive: No	Accident: 02/09/2019 21:20	Type or cocation.
Location: Along Road 1 COMPASSVA Buangkok MF		g Central)		
Weather:		Road Surface: Dry	F	toad Speed Limit:
Traffic Flow:		Traffic Control:	107	raffic Volume: ight
Type of Collis	sion: ving Vehicles - Head	d On		nyone conveyed by mbulance:

Details of Ve	ehiclelinvolved	OF THE PERSON OF	大学者400年代的	A MENDERAL T. BO	N. POCKONET AND	
Vehicle No.	Type Exc.	Make A	Model	Color	Condition	No of Passenger
SHA7621L	TAXI					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin: Choa Chu Kang N.P.C 20 Choa Chu Kang Street 52 #01-02 SINGAPORE 689286 Tel No: 1800-7659999 2 of 3 Report No. T/20190903/2057

CONTINUATION OF REPORT

Name	TEO AH CHUA		ID No.		S0102617H			
Related Vehicle	SHA7621L (TAXI)			SHA7621L (TAXI)		Conta	ct No.	96934751
Hospital/Clinic	TAN TOCK SENG HOSPITAL		Class Drivin Licen Expir	g	Class: 3 Date of Expiry: NIL			
Date Treatment	02/09/2019	Date Disc	harge	NIL				
No. of Days gran	ted Medical Leave 07	Degree of		NIL				

Brief Details.

On 02/09/2019 at 2120hrs, I was driving my Taxi bearing SHA 7621L along Sengkang Central heading towards Hougang area. While I was driving on the first lane, I suddenly saw a car driving against the road flow on my lane, I immediately tried to move to the 2nd lane but the car still hit my taxi head on and went to hit a bus about 100 meters away before coming to a stop. Due to the accident, I suffered injuries on my left leg area. I was then conveyed to Tan Tock Seng Hospital and was seen by the doctor and was given 07 days of medical leave. There is CCTV camera installed in my taxi.

3 of 3



Police Station Of Origin: Choa Chu Kang N.P.C 20 Choa Chu Kang Street 52 #01-02 SINGAPORE 689286 Tel No: 1800-7659999

Report No. T/20190903/2057

CONTINUATION OF REPORT

Sketch Plan

NP188

Informant is not able to provide sketch plan

ĕ

8

Signature Of Officer Recording The Report	Signature Of Informant:
Signature Of Interpreter School Police	
Signature Of Interpreter:	Date/Time: _03/09/ 2019 13 :28
Officer In Charge Of Case: TP / AEIT / SI MOHAMAD ZULFAZDLI BIN ABDULLAH Contact No.: 65476204	Classification Of Case:

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have



Traffic Police Department Charge Office 10 Ubi Avenue 3 Singapore 408865

(ª

TRAFFIC POLICE
AMENDMEN.

NP 168 No.	: T/20190903/2057	Name	: TEO AH CHUA
Accident Date/Time		Address	: Blk 157 Jalan Teck Whye
Vehicle(s) Involved	2120hrs : SHA7621L SKQ4736P SBS1Z	NRIC No Tel No Date	#14-115 S(680157) : S0102617H : 96934751 : 04/09/2019
Dear Sir / Madam			_
	olving SHA7621L, SKQ4 entral near Buangkok MR7 e Bow		on 02/09/2019 at 2120 hours
police report at _Ch	oa Chu Kang NPC	03/09/2019	(date) 1328 hours (time) make a (Police Station/NPP/NPC)
In NP 168 - T/2019	90903/2057		
I would like to add i my Taxi and anothe	r bus, SBS1Z. I had suffere an Tock Seng Hospital. Ho	used by vehic ed left knee a	le, SKQ4736P. The vehicle hit onto nd toe injuries and had been given 7 going home from the hospital, I felt
Yours Faithfully,			
leo.			
(Signature)			
		ICIAL USE	
If a police	officer recorded these ame	ndments, plea	se complete the following.
Name / Rank No	: W/Sgt T140357 Kirvar	ni	
Date and Time	: 04/09/2019 @ 1120hrs	5	
Station Dairy No	: 41		
Signature	: Le		

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7621L

MAKE

MODEL : HYUNDAI i40

DATE : 5.09.2019

TEL : 6542 5119

FAX : 6542 6039 MSIG

Qty	Parts Description/ Labour	Type	Un	it Price			
	BonnetDental				S	2,265.90	1
	Bonnet Hinge (LH/RH)		S	41.00	S	82.00	۰
	Bonnet Lock 145VL				5	36.90	×
	Bonnet Absorber Hul		\$	58.10	S	116.20	X
	Bonnet Insulator Sylv				S	196.50	×
	Bonnet Insulator Clips SVL				S	8.40	X
	Bonnet Cable # NH				S	28.60	7
	Radiator Grille MH				S	251.00	
	Radiator Grille H Emblem Na				S	27.50	
	Front Bumper Cover Town				S	544.50	
	Front Bumper Sponge ML				S	99.20	×
	Front Bumper Reinforcement Hall		1		S	402.10	X
	Front Bumper Grille (RH) Wolken I disloted				S	99.20 402.10 41.60	L
	Front Bumper Bracket Top (LH/RH)		s	22.40	S	44.80	X
	Front Bumper Bracket (LH/RH) S broken H	61.4	S	24.60	3	49.20	
	Headlamp Support Top Cover NH	LAM	1650		s	222.60	
	Headlamp Support Panel Assy bakan				s	907.40	
	Headlamp (RH) broken				S	1,388.00	110
	Headlamp Halogen Bulb (RH) Hal				S		
	Radiator >>-				S	698.30	XX
	Radiator Fan Blade, Cowling, Motor Assy				S	792.95	×
	Radiator Bracket (RH/LH) Nul		5	6.50	S	13.00	×
	Radiator Hose Upper			5050	S	36.50	×
	Radiator Hose Lower NA				s	36.50	XXXX
	Radiator Expansion Tank hoke				S	28.30	L
	Radiator Guard Nut		s	20.00	S	40.00	>
	Horn Unit (LH/RH)		S	73.80	S	147.60	X
	Horn Wire 104				5	156.50	X
	Front Fender (RH) Byc				S	566.30	L
	Front Fender Apron Panel (RH) Buc		Sal	318-50	S	637.00	-
	Front Fender Shield (RH) deposed		21.3	,,,,,	5	174.90	-
	Aircon Condenser				S	927.50	X
	Aircon Suction & Liquid Hose +4-1				\$	624.00	
	Aircon Discharge Hose LLL				S	162.60	XXX
	Aircon Compressor				S	2,578.00	×
	Front Door (RH) Bac		SH	1128.20	s	2,256.40	í
	Front Door Rubber dumel				S	290.50	L
	Front Door Gear / Regulator (RH) Novely hard	in			S	250.60	Z
	Front Door Hinge Upper (RH)				S	36.10	1
	Front Door Hinge Lower (RH) 15+				5	36.10	
	Front Door Check (RH)		10	. / .	S	39.20	L
	Front Door Inner Lock (RH)		179	06.70	S	290.80	L
	Front Door Key Lock Set (RH) horker			22	S	186.50	_
	Front Door Outer Handle (RH) has but				S	36.30	L
	Front Door Outer Moulding (RH)				S	47.10	1
35	Front Door Mirror Assy (RH) hotel				S	670.00	L
2	Front Door Power Motor, RH				S	296.40	7

0-	Party Decode the / I - V	Type Unit Price			SHA 7621L Amount		
ty	Parts Description/ Labour	Туре	Unit Price				
	Front Door Trim Board (RH) & mondy brike	(S	973.50		
	Door Centre Pillar Outer (RH) # 15 nc		2000	S	2,527.80		
	Frt Safety Belt (Assy) (LH/RH) activated		s 475.40	\$	950.80		
	Rocker Panel Outer Garnish booken deshed pol			5	341.40		
	Rocker Panel Outer			S	1,310.60		
	Rear Door (RH)		9H 1100.55	S	2 ,201. T0		
	Rear Door Hinge Lower (RH) A Hu		7000 000 11 00000	S	53.40		
	Rear Door Check (RH) A HIL			S	66.50		
	Front Windscreen Glass CAC		1	\$	1,017.80		
	Front Windscreen Moulding Wee		AND THE R. P. LEWIS CO. L. P.	S	113.30		
	Front Windscreen Pillar Outer(RH)		SH 872.72	S	1,745.50		
	Wiper Panel Top Garnish NL			S	222.60		
	Wiper Link W			S	169.20		
	Wiper Container hystoc			\$	61.90		
	Wiper Container Motor Ten			S	75.00		
	Front Wheel Rim (/RH) VIA			S	325.30		
	Front Wheel Hub Cap (RH) 154		1	S	107.10		
	Front Wheel Bearing & Dem			5	540.50		
	Front Shock Absorber (Assy) (RH) 2 167			S	342.20		
	Front Shock Absorber Mounting (RH)			S	108.80		
	Front Drive Shaft (RH) 2 64			\$	1,030.80		
	Rack & Pinion Assy & Down			s	969.60		
	STG Tie End 🕏 🖒 +			S	62.60		
	Stabilizer Bar Z dustoward			S	252.30		
	Stabilizer Bar Bush (RH) H		1	S	X 16.40		
	Stabilizer Bar Link 7 15+			S	61.10		
	Stabilizer Bracket Nut			S	24.00		
	Front Suspension Lower Arm (RH) & 15+			5	529.30		
	Knuckle Arm (RH) Foliation			S	552.00		
	Engine Mounting			S	456.30		
	Engine Under Cover Not			S	334.60		
	S 500		20773.70	0	2,094.40		
	Engine Crossmember > KA		2011710	2	279.60		
	Engine Mtg (Rear)		1	3			
	Gearbox Mounting	ľ		2	215.40		
	Steering Wheel Horn Button Assy Dow			S	864.00		
	Inter Cooler 1-4-1			S	1,032.50		
	Inter Cooler Mounting (2 PCS) He			S	25.90		
	ABS Sensor,RH & Dan NH			5	234.00		
	Auto Gear Oil ha			S	110.40		
	Airbag Complete Privar activate			S	2,948.50		
	Airbag Control Module activited		1	S	1,140.40		
	Steering Angle Assy Z. Daw			S	1,150.60		
	Sensor Assy Impact -Frt Inpact		2600000	\$	198.30		
	Airbay Sensor Cotunted		\$ 580.00	S	1,160.00		
	Electric Power Steering NW		28680.40	S	3,641.00		
	SUB TOTAL		DESCRIPTION OF STREET	_	51,421.05		
	LESS 20%		22944.32		10,284.21		

				SHA 7621L
ty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender Advertisement Logo (RH) Nec			\$ 100.00
	Front Door Comfort Logo (RH) Hec			\$ 75.00
	Front Door Advertisement Logo (RH) Hec			\$ 100.00
	Rear Door Advertisement Logo (RH)			\$ 100.00
	Rear Door Comfortdelgro & Apps Sticker (RH) 14	400		\$ 80.00
	Front Windscreen Sealant Lie			\$ 46.00
	Front ERP Sticker			\$ 26.00
	Front Tyre (RH) +ory			\$ 216.00
	Gearbox ≥ D-w		4000	\$ 8,000:00
			8162.97	\$ 8,743.00
			8162.11	
	Labour Charge			1/20 (J.A. 1000)
	Panel Beating		}	\$ 1,600.00
	Spray Painting Charge			\$ 1,200.00
	Wiring Charge			\$ 80.00
	Tuff Ketc			\$ 80.00
	Towing Charge			S 50.00
	Transfer of Door		S 80.00	\$ 460.00
	Remove/Refix Undercarriage (FRT)		555	S 120.00
	FRT Wheel Alignment			\$ 90.00
	Remove/Refix Aircon & Refill Gas			s -80.00
	Remove/Refix Dashboard		3050.00	\$ 80.00
	Remove/Refix Front Windscreen Glass			5 100.00
				\$ 80.00
	Remove/Refix Cushion & Upholstery Front			
	Re-set Frt ABS System			
	Re-set Frt & Rear Power Window System		S 80.00	The second second
	R/Refix Air Bag/Steering Wheel/Dashboard/Seat			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 150.00
	TOTAL LABOUR		34167-29	\$ 4,310.00
	ECTRA TE TOTAL			\$ 54,189.84
	estimate total	Supp		20.00 mm
	06/09/249 @ 1600m	-	34878.9	43000012
	I Hother	RS	18000	Book
	2 John Hodays	,		VAINE
	1 1/21	L	K Auto Consultants I	nence notify
	- Jan		Repairer of the follo	
			to resurvey before/after sp to display damaged part(s)	
) 1 - 1 1-		erts prices are subject to	confirmation
	det things		hird party survey is on a "i	Whout Prejudice" basi
			to illegal modification(s) is	Charles and the same and the sa
			Supplementary Item(s) mus strubject to final approval f	rom Indurance Compa
		Ac Sk	Anowledged by Repairer	
	This is an initial estimate based on a visual inspection of th	_		in annual control

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 7621L (Supplmentary)

DATE :11.09.2019 TEL: 6542 5119

.

MAKE :

EAV + 6542 6039

ODEL	: HYUNDAI i40		: 6542 6039	W. Contraction
Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Brake Booster Pump Dadw			S 664.1
		1 1		
	SUB TO	TAY		\$ 664.1
	LESS	TO VICTOR A		\$ 132.8
	DISCOUNTED TO			\$ 531.2
	Discourted to			-
	141	: 1 I		
	1 199	2015		
	1 m	0		
	2 te Audo			
	246 M.CO			
	2			
		1 1		
		4 1		
	Unique de la companya			
	ESTIMATE TO	TAL		\$ 531.
	This is an initial estimate based on a visual inspection			

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 7621L (Supplementary)

MAKE :

TEL : 6542 5119

DATE: 19.09.2019

DEL	: HYUNDAI i40		: 6542 6039	1
Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Brake Hose 24		70 5	\$ 238.00
	- A			
	SUB TOTAL			S 238.0
	LESS 20%			S 47.6
	DISCOUNTED TOTAL			\$ 190.4
	DISCOUNTED TOTAL			1
	()			1
	21			
	2XK ALD			
				1
	F /			
			1	
				1
	/			
		1		
				1
		1		1
			I	

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

...CLAIM SUBFOLDER...(Pending for Survey Report)

	FOLDER TRA		Table 4 Common A	1440	_	0.417	El elle included in a	Ins Auth'ed	Status	
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	_	Ad3:	Submitted	Ins Auth ed	1101101	for Survey
Main	03 Sep 2019		06 Sep 2019 15:24 Edit Adj Rpt	5\$18,00 Edit fist	0.000	1000	8,000.00 sw Apt		Pending for Surve Report Cancel Case	
	Main	R	eference		aim De	tails		Document		Show All
CLAIM SU	BFOLDER DE	TAILS					[Created	by insurer]		
Insured:	SIM PUAT	GEK, ID: \$801	2323Z					17		
Main Claimant:	COMFORT	TRANSPORTAT	ION PTE LTD, Co	a. Reg. Na.:	1993038	321R				
Vehicle Reg No.:	SHA762	SHA7621L Date						9 00:00 - :59 and 26 Days Fro	manufacture and the Contraction of the Association in	ite (Man Yr)]
Claim Type	TP / 604	TP / 604584						MX (Comprehens 28/11/2018 - 27/		
Vehicle Reg No. (Insured):		SKQ4736P				io. int):				
					Excess			411 441 441 441	*******	
Repairer:	Chunni M	otor Work Pte L	d - Amk (HQ) Blk	10 #01-05/	36, AMK	Autop	oint, 568047	Ang Mo Kib - Tel	64836016	
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (HQ) - Tel: +65	6827 78	88 [Handled by	Pauline Tham -	6594 2545]	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 63	256-3561	Handle	d by B	RYAN TANI	[Final Rpt	due 06/10/	2019]
Driver/Cust dian (Insured):		HUA () . NRIC: S	8132917F, Tel: +	6598755789	Email:					
Adj Asg. Remarks:	on WP. Lia	b: NR. Agree on 5	DE, Assign: LKK Au	to Consultan	ts Pte Li	d. Con	tact: Ms Lyn	n or Ms Irene at t	65425119 / 65	42 7162.
ASSOCIAT	ED MAIL RE	CEIVED						Vie	w All Corr	pose Case Mai
There are n	o mail for this	case.								
ALL ASSO	CIATED TAS	KS=				-	View All :	Search Tasks (Create New Tas	k Complete
Due Date	e Priority	Type Task	Group Subje	ct Handi	er	Assign	ed By	Completed On	Created	On Done

...CLAIM SUBFOLDER...(Pending for Survey Report)

	OLDER TRA	P to the second	Ref. Benjamie	Add Date	0.00	Callengian de	Ins Auth'ed	Statu	
	06 Can 2019			2019 06 Sep 2019 S\$18,000.00 S\$18,000.00				Pend Repo	ing for Survey
	Main	R	eference	Clair	m Details		Documents		Show All
CLAIM SUI	BFOLDER DE	TAILS GEK. ID: S801	21217			[Created	by insurer]		
Main Claimant:	BRU, SHIS	CALLED THE SHARE	ION PTE LTD, Co	. Reg. No.: 19	9303821R				
Vehicle Reg No.:	SHA762	11.		Di	ate of Loss		9 00:00 - :59 s and 26 Days Fro	m LTA Re	g Date (Man Yr)]
Claim Type:	TP / 604	584		11000	licy/Cover ate No.:		QMX (Comprehens) 28/11/2018 - 27/1		
Vehicle Reg. No. (Insured):		SKQ4736P							
Repairer:	Chunni M	otor Work Pte L	td - Amk (HQ) Blk		cess: AMK Auto	point, 568047	7 Ang Mo Kio - Tel:	648360	16
Handling Insurer:	The second second		ore) Pte. Ltd. (HQ)			A CONTRACTOR OF THE PARTY			Name of the last o
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [H	andled by I	BRYAN TAN] [Final Rpt	due 06/	10/2019]
Driver/Custo dian (Insured):		HUA () , NRIC: S	8132917F, Tel: +	6598755789 E	mail:				
Adj Asg. Remarks:	on WP. Lie	b: NR. Agree on S	DE. Assign: LKK Au	to Consultants	Pte Ltd. Co	ntact: Ms Lyr	nn or Ms Irene at 6	5425119	/ 6542 7162.
ASSOCIAT	ED MAIL RE	CEIVED					Vie	w All	Compose Case Mai
There are n	o mail for this	case.							
ALL ASSO	CIATED TAS	KS ^E				View All	Search Tasks C	reate New	Task Complete
Due Date	Priority	Type Task	Group Subject	ct Handler	Assig	ned By	Completed On	Cre	ated On Done

LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19015821/DTF3E2

Date:

30/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

80463843QMX

Claimant Vehicle No :

SHA7621L

Insured Vehicle No:

SKQ4736P

Date of Loss:

02/09/2019

Nature of Claim:

TP

Claim No: 604584

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHA7621L

Make & Model:

HYUNDAI 140, 1.7 L CRDI AT ABS AIRBAG 4DR

Engine No:

D4FDEU483130

Reg. Date:

100

07/05/2015 (Man. Year: 2015)

Chassis No: Odometer: KMHLB41UMFU068856

Colour:

Blue

1685 cc

Engine Capacity: Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition: Yes

Handbrake (Serviceable):

CONDITION OF TYRES

205/60 R16

Rear Tyre Size:

205/60 R16

Front Tyre Size: Front Left Side: Front Right Side:

Hankook 5 mm Hankook 5 mm

Rear Left Side: Rear Right Side: Hankook 5 mm Hankook 5 mm

0 km

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50,601.52	31,815.85	18,785.67	37.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,310.00	3,050.00	1,260.00	29.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	54,911.52	34,865.85	20,045.67	36.51
Approved Total (Overridden) (S\$)		18,000.00		
(S\$)	54,911.52	18,000.00	36,911.52	67.22
+ GST 7.00/7.00% (S\$)	3,843.81	1,260.00	2,583.81	67.22
Nett Amount (S\$)	58,755.33	19,260.00	39,495.33	67.22

INSPECTION

Date of Assignment:

06/09/2019

Date Inspected:

06/09/2019 Inspected At:

Chunni Motor Work Pte Ltd - Amk

(HQ)

Blk 10 #01-05/06, AMK Autopoint

Singapore 568047

Estimated Period of Repair:

18.0 days

Adjuster: BRYAN TANI Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

ASSESSMENT OF DAMAGES REPAIR SUM: \$18,000.00

BOOK VALUE AS AT 02.09.2019 : \$43,588.01 (EST)

LTA REIMBURSEMENT VALUE AS AT:17.09.2019: \$32,659.00

NETT VALUE: \$10,929.01

REPAIR DETAILS

Referen	ce	
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2019)
Parts:	143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitte	d, no print-code for SHA7621L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,265.90 FL	*2,265.90 FL
2	2		*BONNET HINGE (LH/RH)	Bent	82.00 FL	*82.00 FL
3	1		*BONNET LOCK	Serviceable	36.90 FL	*-FL
4	2		*BONNET ABSORBER	Not Necessary	116.20 FL	*-FL
5	1		*BONNET INSULATOR	Serviceable	196.50 FL	*-FL
6	1		*BONNET INSULATOR CLIPS	Serviceable	8.40 FL	*-FL
7	1		*BONNET CABLE	Not Necessary	28.60 FL	*-FL
8	1		*RADIATOR GRILLE	Not Necessary	251.00 FL	*-FL
9	1		*RADIATOR GRILLE H EMBLEM	Not Necessary	27.50 FL	*-FL
10	1		*FRONT BUMPER COVER	Torn	544.50 FL	*544.50 FL
11	1		*FRONT BUMPER SPONGE	Not Necessary	99.20 FL	*-FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	402.10 FL	*-FL
13	1		*FRONT BUMPER GRILLE (RH)	Broken / Dislodged	41.60 FL	*41.60 FL
14	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	
15	1		*FRONT BUMPER BRACKET (LH/RH)	O/S Broken / N/S Not Necessary	49.20 FL	*24.60 FL
16	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*-FL
17	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
18	1		*HEADLAMP (RH)	Broken	1,388.00 FL	*1,388.00 FL
19	1		*HEADLAMP HALOGEN BULB (RH)	Not Necessary	14.40 FL	
20	1		*RADIATOR	Not Necessary	698.30 FL	
21	1		"RADIATOR FAN BLADE, COWLING, MOTOR ASSY	Not Necessary	792.95 FL	
22	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*-FL
23	1		*RADIATOR HOSE UPPER	Not Necessary	36.50 FL	*-FL
24	1		*RADIATOR HOSE LOWER	Not Necessary	36.50 FL	
25	1		*RADIATOR EXPANSION TANK	Broken	28.30 FL	*28.30 FL
26	2		*RADIATOR GUARD	Not Necessary	40.00 FL	
27	2		*HORN UNIT (LH/RH)	Not Necessary	147.60 FL	
28	1		*HORN WIRE	Not Necessary	156.50 FL	
29	1		*FRONT FENDER (RH)	Buckled	566.30 FL	and the second second second second
30	1		*FRONT FENDER APRON PANEL (RH)	Buckled	509.60 FS	
31	1		*FRONT FENDER SHIELD (RH)	Deformed	174.90 FL	
32	1		*AIRCON CONDENSER	Not Necessary	927.50 FL	*-FL
33	1		*AIRCON SUCTION & LIQUID HOSE	Not Necessary	624,00 FL	*-FL
34	1		*AIRCON DISCHARGE HOSE	Not Necessary	162.60 FL	*-FL
35	1		*AIRCON COMPRESSOR	Not Necessary	2,578.00 FL	*-FL
36	4		*FRONT DOOR (RH)	Buckled		*1,128.20 FS
37	1		*FRONT DOOR RUBBER	Deformed	290.50 FL	*290.50 FL
38	1		*FRONT DOOR GEAR / REGULATOR (RH)	Mtg Broken	250.60 FL	*250.60 FL
39	1		*FRONT DOOR HINGE UPPER (RH)	Bent	36.10FL	*36.10 FL
40	1		*FRONT DOOR HINGE LOWER (RH)	Bent	36.10FL	*36.10FL
41	1		*FRONT DOOR CHECK (RH)	Bent	39.20 FL	*39.20 FL
75.5	17.		Report was unsubmitted du	[PC010]	30.201L	JULEUT L

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
12	1	NO.	*FRONT DOOR INNER LOCK (RH)	Damaged	290.80 FL	*290.80 FL
13	1		*SET FRONT DOOR KEY LOCK (RH)	Broken	186.50 FL	*186.50 FL
14	1		*FRONT DOOR OUTER HANDLE (RH)	Broken	36.30 FL	*36.30 FL
15	1		*FRONT DOOR OUTER MOULDING (RH)	Bent	47.10FL	*47.10 FL
46	4		*FRONT DOOR POWER MOTOR, RH	Not Necessary	296.40 FL	*-FL
	1		*FRONT DOOR TRIM BOARD (RH)	Mtg Broken	973.50 FL	*973.50 FL
47	1		*DOOR CENTRE PILLAR OUTER (RH)	Buckled		*2,527.80 FL
48				Activated	950.80 FL	
49	2		*FRT SAFETY BELT (ASSY) (LH/RH)	La Tarant A Removal and Conf.	341.40 FL	
50	1		*ROCKER PANEL OUTER GARNISH	Broken / Dislodged		*-FL
51	1		*ROCKER PANEL OUTER	Repair	1,310.60 FL	
52	1		*REAR DOOR (RH)	Buckled		*1,100.55FS
53	1		*REAR DOOR HINGE LOWER (RH)	Not Necessary	53.40 FL	*-FL
54	1		*REAR DOOR CHECK (RH)	Not Necessary	66.50 FL	*-FL
55	1		*FRONT WINDSCREEN GLASS	Cracked	1,017.80 FL	*1,017.80 FL
56	1		*FRONT WINDSCREEN MOULDING	Necessary	113.30 FL	*113.30 FL
57	1		*FRONT WINDSCREEN PILLAR OUTER (RH)	Dented	1,396.40 FS	*872.72FS
58	1		*WIPER PANEL TOP GARNISH	Not Necessary	222.60 FL	*-FL
59			*WIPER LINK	Not Necessary	169.20 FL	*-FL
7	1		*WIPER CONTAINER	Broken	61.90 FL	*61.90 FL
60			# 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		75.00 FL	*75.00 FL
61	1		*WIPER CONTAINER MOTOR	Damaged	325.30 FL	*325.30 FL
62	1		*FRONT WHEEL RIM (RH)	Bent		The second second second
63	1		*FRONT WHEEL HUB CAP (RH)	Bent	107,10FL	
64	1		*FRONT WHEEL BEARING	Damaged	540.50 FL	*540.50 FL
65	1		*FRONT SHOCK ABSORBER (ASSY) (RH)	Bent	342.20 FL	*342.20 FL
66	1		*FRONT SHOCK ABSORBER MOUNTING (RH)	Bent	108.80 FL	*108.80 FL
67	1		*FRONT DRIVE SHAFT (RH)	Bent	1,030.80 FL	*1,030.80 FL
68	1		*RACK & PINION ASSY	Damaged	969.60 FL	*969.60 FL
69	1		*STG TIE END	Bent	62.60 FL	
70	1		*STABILIZER BAR	Distorted	252.30 FL	*252.30 FL
				Not Necessary	16.40 FL	*-FL
71	1		*STABILIZER BAR BUSH (RH)	Bent	61.10FL	*61.10 FL
72	1		*STABILIZER BAR LINK	254 Harris		*-FL
73	1		*STABILIZER BRACKET	Not Necessary	24.00 FL	
74	1		*FRONT SUSPENSION LOWER ARM (RH)	Bent	529.30 FL	
75	1		*KNUCKLE ARM (RH)	Distorted		*552.00 FL
76	1		*ENGINE MOUNTING	Bent	456.30 FL	
77	1		*ENGINE UNDER COVER	Not Necessary	334.60 FL	*-FL
78	1		*ENGINE CROSSMEMBER	Bent	2,094.40 FL	*2,094.40 FL
79	1		*ENGINE MTG (REAR)	Not Necessary	279.60 FL	*-FL
80	1		*GEARBOX MOUNTING	Not Necessary	215.40 FL	*-FL
81	1		*STEERING WHEEL HORN BUTTON ASSY	Damaged	864.00 FL	*864.00 FL
82	1		*INTER COOLER	Not Necessary	1,032.50 FL	
			*INTER COOLER MOUNTING	Not Necessary	25.90 FL	
83	2			(1) (1) (1) (1) (1) (1) (1) (1)	234.00 FL	
84	1		*ABS SENSOR, RH	Not Necessary		
85	1		*AUTO GEAR OIL	Not Necessary	110.40 FL	
86	1		*AIRBAG COMPLETE	Driver Activated		*2,948.50 FL
87	1		*AIRBAG CONTROL MODULE	Activated		*1,140.40FL
88	1		*STEERING ANGLE ASSY	Damaged		*1,150.60 FL
89	1		*SENSOR ASSY IMPACT - FRT INPACT	Not Necessary	198.30 FL	*-FL
90	2		*AIRBAG SENSOR	Activated	1,160.00 FL	*1,160.00 FL
91	1		*ELECTRIC POWER STEERING	Not Necessary	3,641.00 FL	*-FL
92	1		*FRONT FENDER ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00FS
93	1		*FRONT DOOR COMFORT LOGO (RH)	Necessary	75.00 FS	*75.00 FS
94	1		*FRONT DOOR ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	
05	4		*REAR DOOR ADVERTISEMENT LOGO (RH)	Nanassani	100.00 FS	*100.00 FS
95	1		KEAR DOOR ADVERTISEMENT LOGO (KIT)	(voucesally	100,001	100.001

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
96	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
97	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
98	1		*FRONT ERP STICKER	Necessary	26.00 FS	*26.00 FS
99	1		*FRONT TYRE (RH)	Torn	216.00 FS	*216.00 FS
100	4		*GEARBOX	Damaged	8,000.00 FS	*4,000.00 FS
101	1		*BRAKE BOOSTER PUMP	Dented	664.10 FL	*664.10 FL
102	1		*FRONT BRAKE HOSE	Bent	238.00 FL	*238.00 FL
103	1 inchise	nart Sa	*FRONT DOOR MIRROR ASSY (RH) SpcNett. L=ListItemDisc.	Broken	670.00 FL	*670.00 FL
		part.		Sub Total (S\$)	59,698.15	37,729.07
			- List Item Discount on	L Items 20.00/20.00% (S\$)	9,096.63	5,913.22
				Total Parts (S\$)	50,601.52	31,815.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,600.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,200.00	1,000.00
3	WIRING CHARGE	New	80.00	30.00
4	TUFF KOTE	New	80.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	TRANSFER OF DOOR	New	160.00	120.00
7	REMOVE / REFIX UNDERCARRIAGE (FRT)	New	120.00	100.00
8	FRT WHEEL ALIGNMENT	New	90.00	60.00
9	REMOVE / REFIX AIRCON & REFILL GAS	New	80.00	60.00
10	REMOVE / REFIX DASHBOARD	New	80.00	60.00
11	REMOVE / REFIX FRONT WINDSCREEN GLASS	New	100.00	80.00
12	REMOVE / REFIX CUSHION & UPHOLSTERY FRONT	New	80.00	0.00
13	RE-SET FRT ABS SYSTEM }	New	80.00	300.00
14	RE-SET FRT & REAR POWER WINDOW SYSTEM)	New	160.00	0.00
15	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	150.00	0.00
16	R/REFIX AIRBAG / STEERING WHEEL / DASHBOARD / SEAT }	New	200.00	0.00
	Gross Labo	ur Cost (S\$)	4,310.00	3,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >