

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG19015868/R1QD3E2

Date: 03/01/2020

REFERENCE

Insured/Claimant:	GAN KONG YEW	Policy No:	2100490004	
Date of Loss:	04/09/2019	Nature of Claim:	OD	Claim No: 5080469588SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW5232A		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN016797
Reg. Date:	16/11/2016 (Man. Year: 2016)	Chassis No:	WAUZZZF49HA019791
Colour:	Grey	Odometer:	91990 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$99,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,097.00	2,643.44	5,453.56	67.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,012.00	1,522.00	6,490.00	81.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,109.00	4,165.44	11,943.56	74.14
+ GST 7.00/7.00% (S\$)	1,127.63	291.58	836.05	74.14
Nett Amount (S\$)	17,236.63	4,457.02	12,779.61	74.14

INSPECTION

Date of Assignment: 06/09/2019

Date Inspected: 06/09/2019 Inspected At:

281 ALEXANDRA ROAD
Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,015.00 FS	*1,612.00 FS
2	1		*REAR BUMPER FIXING PARTS	Serviceable	66.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Serviceable	203.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Cut	227.00 FS	*181.20 FS
5	2		*REAR LIGHT REFLECTOR - LH/RH	Serviceable	76.00 FS	*- FS
6	1		*REAR PARKING AID SENSOR - INNER / OUTER (3PCS)	Not Working (1Pc Only)	693.00 FS	*184.80 FS
7	4		*REAR PARKING AID SENSOR SEAL RING	Necessary	12.00 FS	*10.24 FS
8	1		*BUMPER WIRING SET	Serviceable	618.00 FS	*- FS
9	1		*REAR BUMPER CARRIER	Bent	819.00 FS	*655.20 FS
10	2		*REAR BUMPER SEAL	Not Necessary	25.00 FS	*- FS
11	2		*REAR BUMPER GUIDE SECTION - LH/RH	Serviceable	40.00 FS	*- FS
12	2		*REAR BUMPER UPPER GUIDE SECTION - LH/RH	Serviceable	81.00 FS	*- FS
13	1		*REAR CROSS PANEL	Serviceable	238.00 FS	*- FS
14	1		*CROSS PANEL REINFORCEMENT	Serviceable	461.00 FS	*- FS
15	1		*CROSS PANEL TRIM	Serviceable	154.00 FS	*- FS
16	1		*REAR SILENCER	Serviceable	999.00 FS	*- FS
17	1		*REAR SILENCER DUAL CLIP	Serviceable	45.00 FS	*- FS
18	1		*EXHAUST SILENCER BRACKET	Serviceable	38.00 FS	*- FS
19	1		*BOOT LID CONTROL UNIT	Serviceable	387.00 FS	*- FS
20	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
21	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
22	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
23	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					8,097.00	2,643.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	New	360.00	280.00
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER,	New	480.00	0.00
3	TO DISMANTLE AND RENEW REAR BUMPER. CUT OUT AND REWELD END PANELLING. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	3,500.00	500.00
4	TO RESPRAY REAR BUMPER, SPARE WHEEL HOUSING AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT.	New	3,000.00	550.00
5	TO RENEW REAR EXHAUST SILENCER AND ALIGN TO POSITION.	New	480.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECKS.	New	192.00	192.00
Gross Labour Cost (\$\$)			8,012.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >