

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19015876/GSF3E2

Date: 13/07/2020

REFERENCE

Insured/Claimant:	ZEE YENG PENG	Policy No:	1800103386	
Date of Loss:	05/09/2019	Nature of Claim:	OD	Claim No: 5323615867SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD6885Z		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZ812326
Reg. Date:	30/08/2018 (Man. Year: 2018)	Chassis No:	WAUZZZGA0JA071739
Colour:	Yellow	Odometer:	10580 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$106,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	44,809.76	21,601.52	23,208.24	51.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	43,944.00	23,719.00	20,225.00	46.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	88,753.76	45,320.52	43,433.24	48.94
+ GST 7.00/7.00% (\$\$)	6,212.76	3,172.44	3,040.32	48.94
Nett Amount (\$\$)	94,966.52	48,492.96	46,473.56	48.94

INSPECTION

Date of Assignment:	09/09/2019		
Date Inspected:	06/09/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	25.0 days		

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT BUMPER - LH / RH	Deformed	1,572.00 FS	*1,256.80 FS
2	1		*FRONT BUMPER CONNECTING PIECE - CENTRE	Deformed	134.00 FS	*107.20 FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	314.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Cut	179.00 FS	*143.20 FS
5	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Cut	308.00 FS	*245.60 FS
6	2		*FRONT BUMPER END CAP - LH / RH	Necessary	62.00 FS	*48.80 FS
7	1		*FRONT BUMPER SPOILER	Cut	273.00 FS	*218.00 FS
8	1		*RADIATOR GRILLE	Cracked	1,301.00 FS	*1,040.80 FS
9	1		*STRIKER PLATE	Not Necessary	114.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	71.00 FS	*56.08 FS
11	1		*FRONT BUMPER CARRIER	Bent	625.00 FS	*499.60 FS
12	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Deformed	64.00 FS	*41.84 FS
13	1		*FRONT BUMPER COVER	Broken	91.00 FS	*72.56 FS
14	1		*CAUTION SIGN	Necessary	13.00 FS	*9.76 FS
15	1		*AIRCON STICKER	Necessary	7.00 FS	*5.12 FS
16	1		*FRONT FENDER - LH	Not Necessary	1,047.00 FS	*- FS
17	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	36.00 FS	*- FS
18	1		*FRONT FENDER BRACKET - LH	Not Necessary	43.00 FS	*- FS
19	1		*FRONT FENDER BRACE - LH	Not Necessary	29.00 FS	*- FS
20	1		*FRONT WHEEL COVER - LH	Necessary	294.00 FS	*234.80 FS
21	2		*FRONT BUMPER ADAPTER - LH / RH	Not Necessary	64.00 FS	*- FS
22	1		*FRONT WHEEL COVER - RH	Necessary	294.00 FS	*234.80 FS
23	1		*LED HEADLIGHT - LH	Broken	4,491.00 FS	*3,592.80 FS
24	1		*MAIN BEAM HEADLIGHT MOUNTING	Broken	107.00 FS	*85.60 FS
25	1		*HEADLIGHT WASHER SYSTEM LIFT CYLINDER - LH	Not Necessary	128.00 FS	*- FS
26	1		*BONNET	Repair	2,549.00 FS	*- FS
27	2		*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
28	3		*BONNET IMPACT PROTECTION - LH / RH / CENTRE	Not Necessary	82.00 FS	*- FS
29	1		*BONNET RELEASE ELEMENT	Not Necessary	53.00 FS	*- FS
30	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	53.00 FS	*- FS
31	1		*COOLANT RADIATOR LOCK CARRIER	Cracked	907.00 FS	*725.60 FS
32	2		*AIR GUIDE - LH / RH	Cracked	54.00 FS	*42.72 FS
33	1		*AIR GUIDE - UPPER CENTRE	Cracked	19.00 FS	*15.20 FS
34	1		*FRONT NO. PLATE	Bent	40.00 FS	*40.00 FS
35	1		*REAR BUMPER	Deformed	1,074.00 FS	*859.20 FS
36	1		*REAR BUMPER FIXING PARTS	Not Necessary	314.00 FS	*- FS
37	1		*REAR BUMPER SPOILER - LH	Cut	259.00 FS	*207.20 FS
38	1		*REAR LIGHT REFLECTOR - LH / RH	N/S Cut / O/S Not Necessary	54.00 FS	*21.52 FS
39	2		*REAR PARKING AID SENSOR - OUTER	Not Necessary	462.00 FS	*- FS
40	2		*REAR PARKING AID SENSOR - INNER	Not Necessary	462.00 FS	*- FS
41	1		*SET REAR BUMPER WIRING	Not Necessary	472.00 FS	*- FS
42	1		*REAR BUMPER CARRIER	Not Necessary	501.00 FS	*- FS
43	1		*REAR BUMPER HOLDING STRAP - LH / RH	N/S Cut / O/S Not Necessary	24.00 FS	*8.96 FS
44	1		*REAR BUMPER GUIDE SECTION - LH / RH		98.00 FS	*38.72 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				N/S Cut / O/S Not Necessary		
45	1		*REAR LID	Buckled	2,195.00 FS	*1,756.00 FS
46	1		*REAR LID ATTACHMENT PARTS	Not Necessary	109.00 FS	*- FS
47	2		*REAR LID HINGE	Repair	275.00 FS	*- FS
48	2		*REAR LID LOCK STRIKER	Not Necessary	265.00 FS	*- FS
49	1		*REAR LID FLAP GASKET	Necessary	106.00 FS	*84.40 FS
50	1		*REAR LID LOCK STRIKER	Not Necessary	227.00 FS	*- FS
51	1		*BONNET LOCK COVER	Not Necessary	11.00 FS	*- FS
52	1		*REAR LID BOWDEN CABLE	Not Necessary	51.00 FS	*- FS
53	1		*REAR LID SERVOMOTOR	Not Necessary	272.00 FS	*- FS
54	1		*BONNET COVER GUARD ANTI THEFT GUARD	Not Necessary	14.00 FS	*- FS
55	4		*DRIVE UNIT BRACKET - LH / RH	Not Necessary	178.00 FS	*- FS
56	2		*REAR LID DRIVE UNIT	Not Necessary	3,308.00 FS	*- FS
57	1		*LICENSE PLATE TRIM	Not Necessary	213.00 FS	*- FS
58	1		*AUDI EMBLEM	Necessary	113.00 FS	*90.00 FS
59	1		*Q2 INSCRIPTION	Necessary	87.00 FS	*69.28 FS
60	1		*TFSI INSCRIPTION	Necessary	87.00 FS	*69.28 FS
61	1		*REAR WINDOW	Cracked	711.00 FS	*568.80 FS
62	1		*PRIMER	Necessary	19.00 FS	*14.88 FS
63	1		*WIPER MOTOR	Not Necessary	420.00 FS	*- FS
64	1		*WIPER ARM	Not Necessary	76.00 FS	*- FS
65	1		*WIPER BLADE	Not Necessary	24.00 FS	*- FS
66	1		*WIPER CAP	Not Necessary	18.00 FS	*- FS
67	1		*ADDITIONAL BRAKE LIGHT	Not Necessary	166.00 FS	*- FS
68	1		*SPOILER FIXING PARTS	Necessary	121.00 FS	*96.40 FS
69	1		*FOAM STRIPS	Necessary	121.00 FS	*96.40 FS
70	2		*REAR WHEEL COVER - LH / RH	Necessary	312.00 FS	*248.80 FS
71	1		*REAR LID TRIM PANEL - UPPER	Cut	211.00 FS	*168.80 FS
72	1		*REAR LID TRIM PANEL - LOWER	Cut	447.00 FS	*357.20 FS
73	1		*LUGGAGE COMPARTMENT COVER	Cut	394.00 FS	*314.80 FS
74	1		*REAR CROSS PANEL	Buckled	224.00 FS	*178.80 FS
75	1		*CROSS PANEL REINFORCEMENT	Bent	669.00 FS	*535.20 FS
76	1		*REAR CROSS PANEL TRIM	Not Necessary	141.00 FS	*- FS
77	1		*REAR FENDER - LH	Buckled	2,057.00 FS	*1,645.60 FS
78	1		*REAR FENDER INNER PANEL - LH REAR	Buckled	677.00 FS	*541.60 FS
79	1		*WHEEL HOUSING OUTER - LH	Buckled	696.00 FS	*556.40 FS
80	1		*REAR FENDER CONNECTING PLATE - LH	Repair	66.00 FS	*- FS
81	2		*VENT TRIM - REAR	Deformed	60.00 FS	*48.32 FS
82	1		*SIDE MEMBER CROSS PANEL	Not Necessary	59.00 FS	*- FS
83	1		*WHEEL HOUSING LINER - LH	Torn	189.00 FS	*150.80 FS
84	1		*WHELE HOUSING LINER ATTACHMENT PARTS	Necessary	52.00 FS	*41.20 FS
85	1		*PILLAR C TRIM - LH	Cut	561.00 FS	*448.40 FS
86	1		*C-PILLAR TRIM CLIP	Necessary	23.00 FS	*17.92 FS
87	1		*C-PILLAR TRIM CLIP	Necessary	12.00 FS	*10.40 FS
88	1		*SET FOAM STRIPS	Necessary	126.00 FS	*100.40 FS
89	1		*PLASTIC PRIMER	Not Necessary	101.00 FS	*- FS
90	1		*LUGGAGE COMPARTMENT TRIM	Cut	831.00 FS	*664.40 FS
91	1		*REAR DOOR - LH	Repair	2,285.00 FS	*- FS
92	1		*OUTER DOOR SEAL - LH	Not Necessary	119.00 FS	*- FS
93	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
94	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
95	1		*OUTER DOOR SEAL - LH	Not Necessary	53.00 FS	*- FS
96	1		*REAR DOOR COVER - LH	Not Necessary	206.00 FS	*- FS
97	1		*REAR NO PLATE	Not Necessary	40.00 FS	*- FS
98	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
99	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
100	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
101	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
102	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
103	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
104	1		*SUNDRIES	Necessary	2,000.00 FS	*96.80 FS
105	1		*END PANEL CONNECTING PLATE LHS	Bent	29.44 FS	*29.44 FS
106	1		*THREADED STUD FOR END PANEL	Necessary	20.00 FS	*20.00 FS
107	1		*BUNGS FOR END PANEL AND REAR LID	Deformed	87.36 FS	*87.36 FS
108	1		*BLIND RIVET STUD FOR LHS REAR FENDER	Necessary	13.28 FS	*13.28 FS
109	1		*TAILLIGHT LHS	Cracked	965.60 FS	*965.60 FS
110	1		*TRIM FOR TAILLIGHT LHS	Cut	22.16 FS	*22.16 FS
111	1		*ADDITIONAL RADIATOR	Not Necessary	837.00 FS	*- FS
112	1		*UPPER BRACKET FOR RADIATOR	Missing	61.28 FS	*61.28 FS
113	1		*SEALING STRIP FOR ADDITIONAL RADIATOR RHS	Necessary	12.48 FS	*12.48 FS
114	1		*SEALING STRIP FOR ADDITIONAL RADIATOR LHS	Necessary	12.48 FS	*12.48 FS
115	1		*COOLANT FOR RADIATOR	Necessary	67.20 FS	*67.20 FS
116	1		*RADIATOR SEAL RHS OUTER	Necessary	4.48 FS	*4.48 FS
117	1		*AIR COND CONDENSER	Bent	402.00 FS	*402.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 44,809.76 21,601.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,200.00	1,200.00
3	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER, HEADLIGHT AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,000.00	2,000.00
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	New	2,800.00	1,650.00
5	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER	New	800.00	800.00
6	TO REMOVE AND RENEW REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
7	TO REMOVE AND REINSTALL REAR WIRE HARNESS, ALL ELECTRICAL TRAYS FOR FUSE AND RELAYS, AUDIO EQUIPMENT, CONTROL UNITS, INCLUDING REAR LID WIRING AND MULTI-LOCK SYSTEM, AND AUTOMATIC TAIL GATE ASSY	New	1,200.00	1,200.00
8	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	280.00	280.00
9	TO REMOVE AND REINSTALL ALL REAR PASSENGER SEATS, LUGGAGE COMPARTMENT TRIMS, PILLARS, CURTAIN AIRBAGS, DISLODGE ROOF LINER	New	1,800.00	1,800.00
10	TO RENEW REAR WINDSCREEN AND LHS SIDE WINDOW	New	700.00	700.00
11	TO REMOVE AND REINSTALL EXHAUST ASSY AND REAR SUSPENSION TO FACILITATE CAR O-LINER REPAIRS	New	2,800.00	0.00
12	TO SET UP AND PLACE VEHICLE ON CAR O-LINER	New	2,400.00	2,400.00
13	TO REMOVE REAR BUMPER, REAR LID, LINKAGES AND LHS REAR DOOR. CUT OUT AND WELD REAR CROSS PANEL, REINFORCEMENTS, LHS REAR FENDER, OUTER WHEEL HOUSE AND CONNECTING PLATES. RENEW LHS REAR DOOR, REAR BUMPER AND REAR LID. REINSTALL ALL PARTS REMOVED	New	14,400.00	5,750.00
14	TO CARRY OUT JOINT SEALER WORKS, STONE CHIP TREATMENT. RESPRAY LHS REAR DOOR, REAR BUMPER, REAR LID, LHS REAR FENDER, INNER WHEEL HOUSE AND CONNECTING PLATES, LHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL AND END PANELLING	New	8,300.00	4,675.00
15	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	240.00
16	TO CARRY OUT DIAGNOSTIC CHECKS	New	384.00	384.00
Gross Labour Cost (\$\$)			43,944.00	23,719.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >