

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19015904/T1ES3Q2

Date: 02/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SLW4223J **Insured Vehicle No :** SLR6875R

Date of Loss: 04/09/2019 **Nature of Claim:** TP **Claim No:** 6923811799SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW4223J	Engine No:	DAX005746
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (A)	Chassis No:	WAUZZZF8H2025014
Reg. Date:	19/06/2017 (Man. Year: 2017)	Odometer:	28506 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,660.00	1,999.12	3,660.88	64.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,012.00	3,477.00	4,535.00	56.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	13,672.00	5,476.12	8,195.88	59.95
+ GST 7.00/7.00% (\$\$)	957.04	383.33	573.71	59.95
Nett Amount (\$\$)	14,629.04	5,859.45	8,769.59	59.95
+ Loss of Use (4.0 x S\$90.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		2.00		
+ Other Costs (\$\$)		780.00		
Nett Liability (\$\$)		7,001.45		

INSPECTION

Date of Assignment: 10/09/2019

Date Inspected: 10/09/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER -RH	Bent	1,301.00 FS	*1,040.80 FS
2	1		*FRONT FENDER BRACE -RH	Not Necessary	206.00 FS	*- FS
3	1		*FRONT FENDER BRACKET -RH	Not Necessary	16.00 FS	*- FS
4	1		*FRONT WHEEL COVER -LH/RH	O/S Cut / N/S Not Necessary	1,154.00 FS	*922.40 FS
5	1		*FRONT DOOR -RH (NPA)	Repair	0.00 FS	*- FS
6	1		*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
7	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
8	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	239.00 FS	*- FS
9	1		*OUTER DOOR SEAL	Not Necessary	185.00 FS	*- FS
10	1		*DOOR CATCH	Not Necessary	132.00 FS	*- FS
11	1		*FRONT DOOR COVER-RH	Not Necessary	661.00 FS	*- FS
12	1		*TYRE PRESSURE DATA PLATE	Not Necessary	35.00 FS	*- FS
13	1		*WHEEL HOUSING LINER -RH	Not Necessary	246.00 FS	*- FS
14	1		*WHEEL SPOILER -RH	Not Necessary	139.00 FS	*- FS
15	1		*FRONT ALUMINIUM RIM -RH	Not Necessary	923.00 FS	*- FS
16	4		*ALUMINIUM RIM RUBBER VALVE	Not Necessary	13.00 FS	*- FS
17	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 5,660.00 1,999.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHTING WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES .INSPECT FOR DAMAGES	New	280.00	0.00
3	TO DISMANTLE FRONT BUMPER ,RHS FRONT FENDER AND RHS FRONT DOOR .TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	3,200.00	1,000.00
4	TO RESPRAY RHS FRONT FENDER ,RHS FRONT DOOR ,DOOR COVER AND BOTH FRONT WHEEL ARCH TRIMS	New	3,700.00	1,925.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			8,012.00	3,477.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >