

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD19015912/BGA3Q2

**Date:** 28/07/2020

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00006033-01

**Claimant**  
**Vehicle No :** SKW9841D **Insured Vehicle No :** SLF5316H

Date of Loss: 27/08/2019 Nature of Claim: TP Claim No: 1201900025544

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW9841D		
Make & Model:	MAZDA 5, 2.0 (A)	Engine No:	PE10279001
Reg. Date:	24/11/2015 (Man. Year: 2015)	Chassis No:	JM6CW1071G0122804
Colour:	White	Odometer:	79159 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,283.76	1,985.68	3,298.08	62.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	1,060.00	1,500.00	58.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,843.76</b>	<b>3,045.68</b>	<b>4,798.08</b>	<b>61.17</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,843.76</b>	<b>2,400.00</b>	<b>5,443.76</b>	<b>69.40</b>
<b>+ Car Rental (5.0 x S\$180.00/day) (S\$)</b>		900.00		
<b>+ Doc/Search Fee (S\$)</b>		29.00		
<b>Nett Liability (S\$)</b>		<b>3,329.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,300.00</b>		

### INSPECTION

Date of Assignment: 09/09/2019

Date Inspected: 09/09/2019 Inspected At:

160 SIN MING DR #01-14 SIN MING  
AUTO CITY SINGAPORE 575722  
Repairer: Team Autopro Pte Ltd (KAKI  
BUKIT)

Estimated Period of Repair: 4.0 days

**Adjuster:** Lim Teow Guan

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2020)
<b>Parts:</b>	M1-MPV	MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKW9841D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	995.80 FL	*- FL
2	1		*FRONT BUMPER	Cracked	977.50 FL	*689.90 FL
3	1		*FRONT BUMPER SIDE RETAINER	Necessary	35.80 FL	*35.80 FL
4	1		*FRONT BUMPER BRACKET RH	Cracked	58.60 FL	*40.20 FL
5	1		*FRONT BUMPER FOG LAMP	Not Necessary	156.00 FL	*- FL
6	1		*FRONT BUMPER FOG LAMP COVER	Repeated	38.20 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP GARNISH	Broken	78.30 FL	*78.30 FL
8	1		*HEADLAMP	Cracked	1,145.70 FL	*1,145.70 FL
9	1		*HEADLAMP LOWER BRACKET	Not Necessary	67.50 FL	*- FL
10	1		*FRONT FENDER	Repair	968.30 FL	*- FL
11	1		*FRONT FENDER INNER TRIM	Torn	105.60 FL	*105.60 FL
12	1		*FRONT FENDER INNER SHIELD	Not Applicable	115.30 FL	*- FL
13	1		*FRONT KNUCKLE ARM	Not Necessary	347.90 FL	*- FL
14	1		*FRONT KNUCKLE ARM BEARING	Not Necessary	266.80 FL	*- FL
15	1		*FRONT LOWER ARM	Bent	311.60 FL	*311.60 FL
16	1		*FRONT SHOCK ABSORBER	Not Necessary	220.80 FL	*- FL
17	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
18	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
19	1		*HEADLAMP SEAL	Not Necessary	40.00 FS	*- FS
20	1		*FRONT SPORT RIM	Not Necessary	352.00 FS	*- FS
21	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,461.70</b>	<b>2,467.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,177.94	481.42
<b>Total Parts (\$\$)</b>	<b>5,283.76</b>	<b>1,985.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE /RENEW ACCIDENT DAMAGED ,TO PANEL BEAT ,RESHAPE ALIGN AND REPLACE PARTS	New	1,000.00	600.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIR N RECONNECT CHECK FUNCTION	New	80.00	30.00
3	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED FOR RUST PROOFING	New	100.00	30.00
4	TO SUPPLY PAINT MATERIALS AND NECESSARY ITEMS TO RESPRAY ACCIDENT DAMAGED	New	1,000.00	400.00
5	TO REMOVE & REFIT FRONT UNDER CARRIAGE FOR CHECK AND REPLACE PARTS	New	300.00	0.00
6	APPLY SEALANT	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,560.00</b>	<b>1,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >