

ASS. REC. BY:

REF:

PWP

ASSIGNMENT

From:

Date:

9/9/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKW 9841 D

at Workshop m/s

Team Autopro

of

160 Sin Ming Drive # 01-14

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKW 9841 D

Yr Regn:

24/11/2015

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 5

C.C 1998

Colour

WHITE

A/C:

Insured / Std / NI / NA

Sp. Reading

79 159

T/Radio:

Insured / Std / NI / NA

Eng/No:

9E1027001

C/No:

JM6CW1071G0122804

Gen. Cond:

☒ Good / Fair / Poor / Burnt

Steering:

☒ In order / Jammed / Leaked / Burnt or

Brake:

☒ In order / Jammed / Leaked / Burnt or

Modi:

Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

225/45/17

R:

225/45/17

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

27/8/19

D.O.I.

9/9/19

Survey held at

Team Autopro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 2,000/2 - 3,000/2

MV 61,000/2

PV 50,889/2

NV 10,111/2

Team Autopro
1/10/19

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / L.B.I. (\$