i nu n	From (Person): Gnoh Pay Loons of Sn	10	Date/Time: 9.4.19 14.54pm
	Estimated Cost:	Bill to:	
	OD FIP WS TP RES OD RES EVA INV MV CS	S	
	To Inspect Vehicle No: G83 2252A		Insured: XE 3246C
	at Workshop m/s <u>Vision Autowork Pte Ltd</u>		Tel: 6341 6789
	of 8 Kaki Bukit Ave 4 #08-09		
	Policy No: DIAMTHCV5001928	Claim No: _	CMTD1904236
	Sum Insured:	Excess:	
	Make of Veh: (Client's Record)		D.O.A 06/09/2019
	CA / REV / REP. / REV 24 HRS Date/Time: 9.9.9 3.46 p. m Person Contacted:	mi chelle	H.O.D-Endorsement: Vehicle IN LOUT
	Date/Time Action/Instruction () Estimate		
	X 5 3246C NA /CT2 19015857/NA	DORUG	Pioc1ps)
	GBJ 2252A: NA/CTZ19615857/N4		
	6/9/19 @ 5.30 pm Informed Grack P. 15/10/19 @ 10.35 an varised to guals	au loons	we are pending estimate
	15/10/19 @ ID Was verised to small	Pau bon	p via Menacen.

Date/Time, File Pass to?	: Preli. Report	Day	s Of Repair:		
Date/Time, File Return to?	: Final Report	Res	urvey No. of Trip:	Survey Fee: Transportation:	450
)		Add Fee:	: Site Insp (\$)S+RS,SI	11
		Г	: Interview (\$) Photos	
Report Format :	MERTP		: Tech. Invs (\$) Others	
ump Sum / I.D.I: (\$	6200)	: Weekend (\$)	
/				TOTAL	46

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

GNOH PAU LOONG

Date:

15 Oct 2019

Preliminary Advice

Insured Vehicle No : XE3246C

TP Vehicle No

: GBJ2252A

Accident Date

: 06/09/2019

Make

: TOYOTA HIACE

Assignment Date

: 09/09/2019

Date of Inspection : 10/09/2019

Est. Duration of Repair

: 9.00

Inspection At

: VISION AUTOWORK PTE LTD (HQ)

8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT

SINGAPORE 415875

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,329.88
Revised Amount	:S\$	7,810.08
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,810.08
Lump Sum Repair	:S\$	6,200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status			
Main	06 Sep 2019		09 Sep 2019 14:54 Assign				New Assign Cancel Case			
	Main	Re	eference	Clair	m Details	Docume	nts	Show All		
CLAIM S	UBFOLDER DET	TAILS			100	ICre	ated by insu	rorl		
Insured: Main Clain	nant:	TEPIA HOPE	OB TRADING & T TECHNIK PTE LT	RANSPORT SE D, Co. Reg. N	RVICES PTE. LTD., o.: 200606254N	Co. Reg. No.: 20)1407566G	ieij		
Vehicle Re	g. No.:	GBJ2	252A	Dat	e of Loss:	06/09 [6 Mc Reg (Days From LTA			
Claim Typ	e:	TP/	CMTD1904236	Poli	cy/Cover Note No.:	D19MTHCVE001928 (Comprehensive)				
Vehicle Reg. No. (Insured):		XE324	700		Policy No. (Claimant):		prenensive)			
Repairer:		Vision Tel: 63	Excess: Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit Tel: 6341 6789							
Handling I	nsurer:	Sompo 632952	Insurance Sing	apore Pte. Ltd.	(HQ) - Tel: 6461 6	555 [Handled b	y GNOH PAU	LOONG -		
Adjuster:			LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Final Rpt due 18/09/2019]							
Driver/Cus	todian (Insured)	LIU KE	LIU KECHENG () , NRIC: G6654574T, Tel: +6597818010 Email:							
Adj Asg. R	emarks:	WS: MI	CHELLE 9856 481	5		Lillon.				
ASSOCIA	TED MAIL REC	EIVED				View All	1 Commo	se Case Mail		
SOMPO	_SG (09/09/2019): Cancellation	of Assignment: 0	BJ2252A		VIEW AII	Compo	se case mail		
E (c)										
ALL ASS	CIATED TASK	s			View All Search	n Tasks Crea	ate New Task	Complete		
Due Dat	- Fridity	Type Task G	roup Subject	Handler	Assigned By	Completed On	Created	- AND DECEMBER		

Shiau Chan (LKKAuto)

From:

Do-Not-Reply <do-not-reply@merimen.com>

Sent:

Tuesday, 10 September 2019 5:20 PM

To:

do-not-reply@merimen.com

Cc:

SUR

Subject:

TP VEHICLE GBJ 2252A (YOUR REF: CMTD1904236)

This mail is associated with: *GBJ2252A (CMTD1904236) [XE3246C]

TP

HOPE TECHNIK PTE LTD

Sep 6 2019 11:00AM

[TEPIAOB TRADING & TRANSPORT SERVICES PTE. LTD.]

Vision Autowork Pte Ltd

Dear Pou Loong,

Please be informed that we have inspected the vehicle GBJ 2252A on 10/09/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms) LKK Auto Consultants Pte Ltd Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by: SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software. www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particulars	Company
Owner ID Type:	5.1802//8658995
Owner ID:	254N
/ehicle Details	CD 10050A
/ehicle No.:	GBJ2252A
/ehicle to be Exported:	No
ntended Deregistration Date:	15 Oct 2019
/ehicle Make:	TOYOTA
/ehicle Model:	HIACE VAN TURBO 4DR AT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1KD2833547
Chassis No.:	JTFHT02P800246726
Maximum Power Output:	-
Open Market Value:	\$29,255.00
Original Registration Date:	15 Feb 2019
First Registration Date:	15 Feb 2019
Transfer Count:	1
Actual ARF Paid:	\$1,463.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	(H)
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Feb 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$13,685.00
COE Rebate Amount:	\$12,774.00
Total Rebate Amount:	\$12,774.00

The information contained herein is correct as at 15 Oct 2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	07/09/2019 11:02
Date Of Accident	06/09/2019 11:00
Exact Location Of Accident	T JUNC OF PENJURU RD & TEBAN GARDENS CRES
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	GBJ2252A
Insured/Policyholder	
Name Of Registered Owner	HOPE TECHNIK PTE LTD
Co Reg No	200606254N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68770693
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE, LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1908021900
Cover Note Number	12N
Driver	
Name of Driver	MOHAMAD JAFRY BIN SAMSUDIN
NRIC No	S8703798C
Date Of Birth	13/02/1987
Occupation	OUTDOOR
Date Of Driving Pass	30/05/2007
Driving Experience	12 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90191014
Fax Number	
Contact Number	

NOEMAIL

Address

BLK 95 BEDOK NORTH AVE 4 #14-1409

Postcode

460095

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

COLLISION - MAJOR/MINOR RD

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO 2

Number of vehicles (including own vehicle) involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

WITH DRIVER

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

XE3246C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report partechly the status, of the accident to speed up the clear
- 2. This Form most be completed by the Policyholder and/or the Authorised Driver
- information provided must be an trustiful and accurate as possible. Any will be exerpt establish or with bodging of meterial facts may allow inscrease companies to repudiate policy liability.
- The residence and acceptance of this Form by insurance companies is not an admission of points hability on the part of the insurance. companies
- Any fahe reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre extabilished by the General insurance Association of Singapore (G/A) for archiving and that copies of this report will for a fine be made available upon application to
- If By the songreent of this report to the insurers, you hereby consent to the problems of this report at the centre and to occurs of the report being more available aformulat-
- S. Consent under the Personal Data Protection Art (POPA)

Landarstand, acknowledge, agree and consent that

- (a) My imputer, my workshop and the General insurance Association of languages ("GIA") may are permitted to collect, soc. disclose knot/or process my personal data/personal information set out in this (form) and any other personal information. provided by the or possessed by my insurer (sollectively the "Personal information") and iffactive and therefor each presented by an operation of a processor of the processor Monetary Authority of Singapore and any relevant government agency/authority (such as the police), far the purposets.
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary resent gations relating to the clares,
 - (ii) energying the accident and/or my claims.
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
 - (iv) administering my clumb employing the making of correspondence, statements, massive, septimize socious in me, which double evalue disclosure of certain personal data about me to bring about relevely of the same as well as on the external tower of envisions/mail packages), and/or
 - (v) complying with applicable taw in administering, proceeding, handling one or stealing with my colonic (resectively the Purposes'
- all insurery), who have insured vehicle(s) involved in this accident and the insurers' lawyers/law form, heav/are permitted to collect, use, discreasing another process my Personal Information for one or more of the above Purposes, and
- my Fersonal information may lean be disclosed by any of the respect ending Cik to their their party envice provides or agents/oxidely their leavent/leak ferms), which may be when outside of Singapore, for one or more of the score Party envi
- my Personal Information will also be collected and used to compile claims history for the purpose of haud defection. investigation and management in present and all future claims.
- in) the information to collected under (it) above may be shared / disclosed
 - (i) to all trisurers writter any other third parses that avoid in evaluating, investigating, controling or managing fitted. regulators, law enforcement and government opinions as responding recurred for the purposes stated, or

(i.i. for complying with recurrence to under any regulations, laws or court in duri-

Fahryhalder 1 Digitation

gechn/4

Reporting Co. SECTION.

Accident Sketch Plan

.

1	
SKETCH PLAN	4
Texas Goldens	A: 6502252A
- 4	3= XE3246C
TEDA	
	7- Durction Of
11	Penjulu Road and Teban Gordons Cresco
DESCRIBE CIRCUMSTANCES OF THE ACCIO	DÉNT.
DESCRIBE CIRCUMSTANCES OF THE PROPE	A
	Rofer to attenti
	/
/	
DECLARATION	
The tecaning gapping production and the	At A
Date & Force: Co. Co. Co. Co. Co. Co.	Separature Reporting Control for Institute in a residence of the Separature in a residence of the Separature in the Sepa
Early &	500,000

Accident Sketch Plan

On 06.09.19 at about 11:00 hours at T-Junction of Penjuru Road and Teban Gardens Crescent. After I took the exit from AYE and entered Penjuru Road (towards Penjuru Road Roundabout) as I was travelling straight on my lane, suddenly vehicle (B) coming out from Teban Gardens Crescent failed to stop at the stop line and collided onto left hand side portion of my vehicle (A).

Vehicle (A): GBJ 2252A

Vehicle (B): XE 3246C

14

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E) 8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778 E-mail:visionautowork@gmail.com

DATE: 06.09.19

TO

: SOMPO MOTOR CLAIMS DEPTS

JTFHT02P800246726.

VEHICLE NO

: GBJ2252A

MODEL

: TOYOTA HIACE

Xiao Chen.

DATE OF ACCIDENT

: 06.09.19

TIME OF ACCIDENT

: 11:00HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL: PARTS

S/N	IM DETAIL : PARTS DESCRIPTION	QTY	172	NIT LIST PRICE	TC	PRICE
1	ROOF LINING tom	1	\$	1,269.10	\$	1,269.10
2	REAR SIDE PANEL LH Ristorted	1	\$	1,848.00	\$	1,848.00
3	REAR SIDE CORNER LOWER INNER PANEL LH	1	\$	187.50	\$	187.50
4	REAR SIDE INNER PANEL LH Devled	1	\$	1,469.40	\$	1,469.40
5	REAR SIDE PANEL INNER TRIM BOARD LH	1	\$	198.40	\$	198.40
6	REAR SIDE INNER LOWER PANEL RH	1	\$	1,140.40	\$	1,140.40
7	REAR WHEEL HOUSE PANEL LH	1	s	1,176.80	s	1,176.80
8	REAR FLOOR MAT XH ~	1	\$	1,098.40	\$	1,098.40
9	REAR PANEL RAILWAY LH Distorte	1_	\$	794.90	\$	794.90
10	REAR PANEL RAILWAY END GARNISH LH	1	\$	69.70	\$	69.70
	REAR MUDFLAP LH Relad	1	s	84.50	\$	84.50
12	TAIL LAMP LH Hol Hu	1	\$	434.00	\$	434.00
13	TAIL LAMP INNER COVER GARNISH LH	1	\$	74.40	\$	74.40
	REAR BUMPER TOIN	1	\$	388.00	\$	388.00
15	REAR BUMPER SIDE RETAINER NEC LH	2	\$	36.00	\$	72,00
16	REAR WHEEL CAP LH Midsing	1	\$	190.00	\$	190,00
17	REAR WHEEL HUP LH	1	\$	390.00	\$	390.00
18	REAR WHEEL HUP BEARING LH	1	\$	187.00	\$	187.00
19	REAR ALXE ZM-1	1	s	1,989.00	\$	1,989.00
20	REAR SHOCK ABSORBER LH	1	\$	325.00	s	325.00

5680.10

TOTAL PRICE

LESS 25%

\$ 13,386.50

4260.07

SUB TOTAL PRICE

\$ 10,039.88

3,346.63

S/N	DESCRIPTION	QTY	UNI	T S/NETT	тот	AL S/NETT
1	ROOF LINING CLIP (SET) HEU	1	\$	120.00	\$	120.00
2	REAR SIDE PANEL SEALANT LH	1	s	120.00	\$	120.00
3	REAR SIDE CORNER INNER PANEL SEALANT LH	1	\$	80.00	\$	80.00
4	REAR SIDE INNER PANEL SEALANT LH	1	\$	120.00	s	120.00

60 60 TO : SOMPO MOTOR CLAIMS DEPTS

VEHICLE NO : **GBJ2252A**MODEL : TOYOTA HIACE

DATE OF ACCIDENT : 06.09.19
TIME OF ACCIDENT : 11:00HRS

	AL CONTRACTOR OF THE CONTRACTO	4	•	60.00	\$	60.00 30
5	REAR SIDE PANEL INNER TRIM BOARD CLIP LH (SET)	- 1	\$	00.00	Ψ	00.00
6	REAR SIDE INNER LOWER PANEL SEALANT LH 2	1	\$	120.00	\$	120.00
7	REAR WHEEL HOUSE PANEL SEALANT LH	1	\$	150.00	\$	150.00
8	REAR FLOOR MAT CLIP (SET) XX	1	\$	80.00	\$	80.00 +
9	REAR FLOOR TOP BOARD (SPECIAL TYPE)	1	\$	850.00	\$	850.00 385
	TAIL LAMP CLIP (SET)	1	\$	60.00	\$	60.00
11	TAIL LAMP INNER COVER GARNISH CLIP LH (SET)	1	s	60.00	S	60.00
12	REAR BUMPER CLIP (SET) New	1	\$	80.00	\$	80.00 30
13	REAR WHEEL TYRE LH LAT	1	\$	280.00	\$	280.00 18 3
14	REAR WHEEL RIM LH LA	1	\$	150.00	\$	150.00 120
15	BRAKE OIL Z NC	1	s	40.00	\$	40.00
16	GEAR BOX OIL	1	\$	380.00	\$	380.00

TOTAL \$ 2,750.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION		PRICE	ADJUSTED COST	
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$	2,800.00	1200	
2	SPRAY PAINTING TO AFFECTED AREA	\$	1,800.00	1000.	
3	TUFF COAT	\$	250.00	100	
4	WIRING CHECK	\$	180.00	33.	
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$	250.00	80.	
6	CONDUCT WATER LEAKAGE TEST	\$	80.00	X.	
7	REMOVE AND REFIX SLIDING DOOR LH	\$	80.00	/	
8	REMOVE AND REFIX REAR SIDE PANEL RAILWAY LH	\$	150.00	×	
ç	REMOVE AND REFIX REAR UNDERCARRIAGE	s	650.00	X	
1(FOUR WHEEL ALIGHMENT	\$	120.00	80.	
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	s	180.00	×	

2570

TO : SOMPO MOTOR CLAIMS DEPTS

VEHICLE NO : GBJ2252A

MODEL : TOYOTA HIACE

DATE OF ACCIDENT : 06.09.19
TIME OF ACCIDENT : 11:00HRS

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,789.88 TOTAL LABOUR COST : \$ 6,540.00 TOTAL REPAIR COST : \$ 19,329.88

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

SERVICE ADVISOR

SERVICE ADVISOR

ABBY

HP: 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian hiry 4s 10/09/19.

total: 787007 L/s: 6.2K

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

D19MTHCVE001928

Engine No:

Odometer:

Chassis No:

CS/SMO19015926/AQF3N2

1KD2833547

22003 km

JTFHT02P800246726

Date:

16/10/2019

REFERENCE

Handling Insurer:

Sompo Insurance Singapore Pte.

Ltd.

Claimant Vehicle No:

Date of Loss:

06/09/2019

GBJ2252A

Insured Vehicle No:

Nature of Claim:

Policy No:

TP

XE3246C

Claim No:

CMTD1904236

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

GBJ2252A

Make & Model:

TOYOTA HIACE, 3.0 D (M) 15/02/2019 (Man. Year: 2018)

Black

Reg. Date: Colour:

2982 cc

Engine Capacity:

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

195 R15C

Rear Tyre Size: Rear Left Side:

195 R15C

Front Left Side: Front Right Side: Bridgestone 6 mm Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,789.87	5,300.07	7,489.80	58.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,540.00	2,570.00	3,970.00	60.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,329.87	7,870.07	11,459.80	59.29
Approved Total (Overridden) (S\$)		6,200.00		
(S\$)	19,329.87	6,200.00	13,129.87	67.93
+ GST 7.00/7.00% (S\$)	1,353.09	434.00	919.09	67.93
Nett Amount (S\$)	20,682.96	6,634.00	14,048.96	67.93

INSPECTION

Date of Assignment:

09/09/2019

Date Inspected:

10/09/2019 Inspected At:

Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09

PREMIER @ KAKI BUKIT Singapore 415875

Estimated Period of Repair:

9.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 Oct 2019)

Parts: N/A TOYOTA HIACE 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBJ2252A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ROOF LINING	Torn	1,269.10 FL *	
	1		*REAR SIDE PANEL LH	Distorted	1,848.00 FL *	
2 3	1		*REAR SIDE CORNER LOWER INNER PANEL LH	Not Necessary	187.50 FL	*-FL
4	1		*REAR SIDE INNER PANEL LH	Dented	1,469.40 FL *	1,469.40 FL
5	1		*REAR SIDE PANEL INNER TRIM BOARD LH	Torn	198.40 FL	*198.40 FL
6	1		*REAR SIDE INNER LOWER PANEL RH	Repair	1,140.40 FL	*-FL
7	1		*REAR WHEEL HOUSE PANEL LH	Repair	1,176.80 FL	*-FL
8	1		*REAR FLOOR MAT	Not Necessary	1,098.40 FL	*-FL
9	1		*REAR PANEL RAILWAY LH	Distorted	794.90 FL	*495.00 FL
10	1		*REAR PANEL RAILWAY END GARNISH LH	Deformed	69.70 FL	*69.70 FL
11	1		*REAR MUDFLAP LH	Deformed	84.50 FL	*84.50 FL
12	1		*TAIL LAMP LH	Not Necessary	434.00 FL	*-FL
13	1		*TAIL LAMP INNER COVER GARNISH LH	Not Necessary	74.40 FL	*-FL
14	1		*REAR BUMPER	Torn	388.00 FL	*388.00 FL
15	1		*REAR BUMPER SIDE RETAINER	N/s Necessary	72.00 FL	*36.00 FL
16	1		*REAR WHEEL HUP LH	Not Necessary	390.00 FL	*-FL
17	1		*REAR WHEEL HUP BEARING LH	Not Necessary	187.00 FL	*-FL
18	1		*REAR AXLE	Not Necessary	1,989.00 FL	*-FL
19	1		*REAR SHOCK ABSORBER LH	Not Necessary	325.00 FL	*-FL
20	1		*REAR WHEEL CAP LH	Missing	142.50 FS	*60.00 FS
21	1		*SET ROOF LINING CLIP	Necessary	120.00 FS	*60.00 FS
22	1		*REAR SIDE PANEL SEALANT LH	Necessary	120.00 FS	
23	1		*REAR SIDE CORNER INNER PANEL SEALANT LH	Not Necessary	80.00 FS	
24	1		*REAR SIDE INNER PANEL SEALANT LH	Not Necessary	120.00 FS	
25	1		*SET REAR SIDE PANEL INNER TRIM BOARD CLIP	Necessary	60.00 FS	
26	1		*REAR SIDE INNER LOWER PANEL SEALANT LH	Not Necessary	120.00 FS	
27	1		*REAR WHEEL HOUSE PANEL SEALANT LH	Not Necessary	150.00 FS	
28	1		*SET REAR FLOOR MAT CLIP	Not Necessary	80.00 FS	
29	1		*REAR FLOOR TOP BOARD (SPECIAL TYPE)	Cracked	850.00 FS	
30	1		*SET TAIL LAMP CLIP	Not Necessary	60.00 FS	*-FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
31	1		*SET TAIL LAMP INNER COVER GARNISH CLIP LH	Not Necessary	60.00 FS	*-FS
32	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
33	1		*REAR WHEEL TYRE LH	Cut	280.00 FS	*180.00 FS
34	1		*REAR WHEEL RIM LH	Cut	150.00 FS	*120.00 FS
35	1		*BRAKE OIL	Necessary	40.00 FS	*40.00 FS
36	1		*GEAR BOX OIL	Necessary	380.00 FS	*80.00 FS
F=Fra	nchise	part. S=S	pcNett, L=ListItemDisc.			
				Sub Total (S\$)	16,089.00	6,720.10
			- List Item Discount on L Items 25	5.00/25.00% (S\$)	3,299.13	1,420.03
				Total Parts (S\$)	12,789.87	5,300.07
			Report was unsubmitted during this pri	nt-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended l	abour
---------------	-------

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items		12112 21 2 2 1	4 000 00
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	2,800.00	1,200.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	1,000.00
3	TUFF COAT	New	250.00	100.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	80.00
6	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
7	REMOVE AND REFIX SLIDING DOOR LH	New	80.00	80.00
8	REMOVE AND REFIX REAR SIDE PANEL RAILWAY LH	New	150.00	0.00
9	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
10	FOUR WHEEL ALIGHMENT	New	120.00	80.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
	Gross Labor	ur Cost (S\$)	6,540.00	2,570.00
	Report was unsubmitted duri	ing this print-out.		

< END OF ESTIMATES >