

2267/2003

ASS. REC. BY:

REF: CS/MSG/9015945/Ktd30

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Crystal Lee

of

MS19

Date/Time: 9/9/19 @ 4:15pm

Estimated Cost:

Bill to:

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBS1Z

Insured:

SKQ 4736P

at Workshop m/s

Comfort Delgro

Tel:

96901177

of

205 Briddell Road

Policy No:

604534

Claim No:

60463848 QMX

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

10/9/19

H.O.D. Endorsement:

Date/Time: 4:43pm @ 9/9/19

Person Contacted:

Mr Chan

Vehicle IN/OUT

| Date/Time | Action/Instruction |
|-----------|---|
| | Estimate / |
| | SBS1Z - NA/NA/ 7020944/13 |
| | SKQ 4736 - CS/MSG/9015821 / D/Ps |
| 11/9/19- | Revised preli advise via menmen |
| | Part by Part \$ 6735.26 (Red: 1377.70; 16%) |

EVA: 2/11/2017

DOA: 2/19/2019

REF: MS19

ASS. PBC BY:

ASSIGNMENT

From: Date: 10/9/2019

Veh No: SBS1Z Yr Regn: 08/15

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD ☒ TP ☐ WS ☐ / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or Double Deck Bus

To Inspect Vehicle No: SBS1Z

Make: Volvo 8C006 C.C. 9364

at Workshop m/s Comfort Delgro

Colour: Green A/C: Insured / Std / NI / NA

of 205 Braddell Road

Sp. Reading: 294593 T/Radio: Insured / Std / NI / NA

Insured: (Blk D)

Eng/No:

Policy No.

C/No: YV3S4P928F A172629

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured: Excess:

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: ☒ Nil / S/Rim / STD A/Rim or

(Policy Condition)

Morning
look for Mr. Chan

Tyre Size: F: 275/70R22.5

R: ———— CO

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-------------------------------------|-----|
| <input checked="" type="checkbox"/> | |
| N/S | O/S |
| | |

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / (D)

TOYO / YOKO or

Continental

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 4 mm

R/Bal. 88 88 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 4 mm

L/Bal. 88 88 mm

Est. Repairs: 07 days Res.: Yes or No

D.O.A. 2/9/19

D.O.I. 10/9/19

Lum Sum: 1.31% 3 Val.: Yes or No

Survey held at

✓

CA / REV / REP. / 24 HRS (up)

Des. of Damages ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or


Vehicle: IN / OUT

Date: Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 07 OCT 2019


 4/10/2019

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 7

1) 4110 Typist

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

Survey Fee: 150

Transportation:

3 + PS, SI

Photos:

Other:

TOTAL

Report Format: TP

Lump Sum / 10: 6735.76

☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)

11

161

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Monday, 9 September 2019 4:15 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: SAS Report SBS1Z.PDF

GAS Bus - SBS 1Z Third Part Claim against SKQ4736P

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Eileen Ang
Sent: Monday, 9 September, 2019 4:04 PM
To: Helene Phua <helene_phua@sg.msig-asia.com>
Cc: Crystal Lee <crystal_lee@sg.msig-asia.com>
Subject: FW: GAS Bus - SBS 1Z Third Part Claim against SKQ4736P

Hi Helene,

Folder created.

From: Motor Survey
Sent: Monday, 9 September, 2019 3:06 PM
To: Helene Phua <helene_phua@sg.msig-asia.com>; Eileen Ang <eileen_ang@sg.msig-asia.com>
Cc: Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Subject: FW: GAS Bus - SBS 1Z Third Part Claim against SKQ4736P

@ HP, I have manually assign this.

@ EA, please create folder.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Sam Tan Kiam Meng [<mailto:samtan@cdge.com.sg>]

Sent: Monday, 9 September, 2019 2:37 PM

To: Motor Survey <motorsurvey@sg.msig-asia.com>

Cc: Denis Teo Chin Chye <denisteo@sparkcarcare.com>; Chan Foo Heng <chanfh@cdge.com.sg>; Patrick Chung Chan Kim <patrickchung@cdge.com.sg>

Subject: GAS Bus - SBS 1Z Third Part Claim against SKQ4736P

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Hi Claims Team,

Please check liability for the mentioned accident case.

Kindly take note that this is a public service bus we cannot hold for too long, it is presently in our workshop ready to inspect by your surveyor.

GAS Bus - **SBS 1Z** Third Part Claim against **SKQ4736P**

Please contact **Mr. Chan Foo Heng** from CDGE should you have any queries.

HP: 9690 1177

Address:

COMFORTDELGRO ENGINEERING PTE LTD

205 Braddell Road, Singapore 579701

BLK D - BUS ACCIDENT REPAIR

Warmest Regards

Sam Tan | ComfortDelGro Engineering Pte Ltd | BAR 🚗

☎ (65)6383 7369 | 📠 (65)6286 0309 | ✉ samtan@cdge.com.sg

Address: 205 Braddell Road, Singapore 579701

🌱 Please consider the environment before printing this e-mail

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a

written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 11 Sep 2019

Preliminary Advice

Insured Vehicle No : SKQ4736P

TP Vehicle No : SBS1Z

Accident Date : 02/09/2019

Make : VOLVO B9TL

Assignment Date : 10/09/2019

Date of Inspection : 10/09/2019

Est. Duration of Repair : 7.00

Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)
205 BRADDELL ROAD
SINGAPORE 579701

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 8,112.96 |
| Revised Amount | :S\$ | 6,739.26 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 6,739.26 |

Lump Sum Repair :S\$

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---|
| Date Of Report | 05/09/2019 17:09 |
| Date Of Accident | 02/09/2019 21:00 |
| Exact Location Of Accident | SENGKANG CTRL 67601 - BUANGKOK STN EXIT B |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------------|
| Vehicle Registration Number | SBS1Z |
| Insured/Policyholder | |
| Name Of Registered Owner | GO AHEAD SINGAPORE PTE LTD |
| Co Reg No | 201541900C |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-63847169 |

Vehicle Particulars

| | |
|--|-------------------------------|
| Manufacturer | VOLVO |
| Model | B9TL-9.4 D AUTO TURBO ABS (A) |
| Exact Purpose for which vehicle was being used at time of accident | COMMERCIAL PURPOSE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | BUS |

Insurance Company

| | |
|---------------------------|--------------------------------|
| Name of Insurance Company | MS FIRST CAPITAL INSURANCE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | YES |
| Policy Number | D-18091603MFBP |
| Cover Note Number | |

Driver

| | |
|----------------------|-------------------------|
| Name of Driver | YUHANIWAN BIN ZAMALUDIN |
| NRIC No | G2626063P |
| Date Of Birth | 15/10/1982 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 11/06/2015 |
| Driving Experience | 4 YEARS AND 2 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-81431351 |
| Fax Number | |
| Contact Number | |
| EMail Address | NOEMAIL |

| | |
|---|--------------------------------------|
| Address | 5 LORONG 15 KG DESA MELAYU MAJIDI |
| Postcode | 81100 |
| Was driver an employee of the Insured's Company | YES |
| If No, Relationship of the Driver with the Insured | |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|------------------------------|
| Type Of Accident | COLLIDED INTO PARKED VEHICLE |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 5 |

Details of Police Action

| | |
|---|--|
| Was the accident reported to the police? | YES |
| If Yes, Please state which Police Station | |
| Police Station Name | PASIR RIS NEIGHBOURHOOD POLICE CENTRE |
| Police Station Address | ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE |
| Police Station Contact | TEL NO: 1800-5852999 - FAX NO: 65855261 |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

MY BUS JUST ENTERED THE ABOVE-MENTIONED LOCATION WHEN I NOTICED A BLACK MAZDA 6 TRAVELLED AGAINST THE TRAFFIC FLOW, COLLIDED ONTO A STATIONARY BLUE COMFORT-DELGRO HYUNDAI I40 TAXI [SHA7621L] THAT WAS WAITING BEFORE THE SIGNALIZED JUNCTION OF COMPASSVALE BOW X SENGKANG CTRL BEFORE COLLIDING ONTO THE FRONT BUMPER OF MY BUS WHERE MY BUS FRON WINDSCREEN CRACKED. BOTH THE TAXI DRIVER AS WELL AS THE MAZDA DRIVER WERE SUBSEQUENTLY CONVEYED TO TTSH VIA AMBULANCE

Attachment(s)

| | |
|---|------------------|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Remarks/ Reasons: | DIFFERENT FORMAT |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|-------------------|
| Vehicle Registration Number | SKQ4736P |
| Vehicle Make/Model/Colour | DARK BLUE MAZDA 6 |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | |
| NRIC/Passport Number | |

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

YUHANIWAN BIN ZAMALUDIN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SBS1Z

Were seat belts worn?

NO


Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan



POLICE REPORT 1



**SINGAPORE
POLICE FORCE**



T/20190903/2008

1 of 3

Police Station Of Origin:

Pasir Ris N.P.C

1 Pasir Ris Drive 4 #01-01 SINGAPORE

519457

Tel No: 1800-5852999

Report No. T/20190903/2008

REPORT OF A TRAFFIC ACCIDENT

| | | |
|--|-------------------------------------|--------------------------|
| Date/Time Report Made: 03/09/2019 02:17 | Vide Report No.: F/20190902/0161 | Station Diary No.: 21 |
|--|-------------------------------------|--------------------------|

Informant's Particulars

| | | | | |
|---|------------|------------------------------|---|----------------------------|
| Name of Informant: YUHANIWAN BIN ZAMALUDIN | | | Address: 2 Loyang Way Go-Ahead Singapore SINGAPORE 508776 | |
| ID Type / ID No.: FIN NO / G2626063P | | | Contact No.: Home/Office: Mobile: 81431351 | |
| Nationality: MALAYSIAN | | | Email: | |
| Sex: Male | Age: 36 | Date of Birth: 15/10/1982 | Type of Informant: Driver | |
| Race: Malay | | | Language: English | Institution / School Name: |
| Occupation: Bus driver | | | Driving Licence Information: Class: 2B,3,4A Date of Expiry: 04/05/2020 | |

General Information of the Accident

| | | | | |
|--|---|-----------------------------|---|------------------------------------|
| Type of Accident: | Injury Conveyed By Ambulance | Drink Drive: No | Date/Time of Accident: 02/09/2019 21:00 | Type of Location: Straight Road |
| Location: Along Road 1 SENGKANG CENTRAL | | | | |
| Weather: Clear | Road Surface: Dry | Road Speed Limit: | | |
| Traffic Flow: Dual Carriage Way | Traffic Control: Not Controlled | Traffic Volume: Moderate | | |
| Type of Collision: Between Moving Vehicles - Head To Rear | Anyone conveyed by ambulance: Yes | | | |

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
|-------------|-----------------------|---------|---------|---------------|----------------------|-----------------|
| SBS1Z | Bus/Coach/Mi nibus | VOLVO | | Multi-Colored | Slightly Damaged | 4 |
| SHA7621L | Car | HYUNDAI | | Blue | Seriously Damaged | 0 |
| SKQ4736P | Car | MAZDA | Mazda 6 | Grey | Seriously Damaged | 0 |

Details of Person Involved

| | | |
|---------------------------------|--------------------------------|--|
| Any Pedestrian Involved: No | | |
| No. of Pedestrians Injured: NIL | Use of Pedestrian Crossing: NA | |

POLICE REPORT 2



**SINGAPORE
POLICE FORCE**



T/20190903/2008

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

2 of 3

Report No. T/20190903/2008

CONTINUATION OF REPORT

| Driver | | | |
|-----------------------------------|---------------------------|--|--|
| Name | YUHANIWAN BIN ZAMALUDIN | ID No. | G2626063P |
| Related Vehicle | SBS1Z (Bus/Coach/Minibus) | Contact No. | 81431351 |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: 2B,3,4A Date of Expiry: 04/05/2020 |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |

Brief Details.

On the mentioned date, time and place, I was alighting my passengers at the bus-stop in front of Buangkok MRT when suddenly a passenger who was at the bus-stop shouted that there is a car coming. Upon looking at the direction of where the passenger is pointing, I saw a grey colour car driving against the flow of traffic in my direction. The car hit onto an on-coming taxi before hitting the front portion of my bus. The driver of the car was trapped and was assisted by the passer-by.

As a result of the accident, the front portion of the bus was dented in. Neither the passengers in my bus or myself was injured.

POLICE REPORT 3



**SINGAPORE
POLICE FORCE**



T/20190903/2008

3 of 3

Report No. T/20190903/2008


Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

| | |
|--|---|
| Signature Of Officer Recording The Report: G / SI KAMARUZZAMAN BIN MAHMOOD  | Signature Of Informant:  |
| Signature Of Interpreter: Not applicable | Date/Time: 03/09/2019 02:17 |
| Officer In Charge Of Case: TP / GIT / SI ONG CHEE HIEN Contact No.: 65476887 | Classification Of Case: |
| Authentication Stamp NP158 <div data-bbox="420 1892 917 2083" data-label="Text">  <p>SINGAPORE POLICE FORCE</p>  SIGNATURE </div> | |

Accident Photo



Accident Photo





ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : Third Party - GASVehicle No. : SBS 1ZMake & Model : VOLVO B9TLYear of Manufacture : 2015Chassis No. : YV3S4P928FA172629Ins Company : NAEngine No. : 194309Excess : NAPolicy No. : NADate of Accident : 2/9/2019Time of Accident : 21:00

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : Chan Foo Heng

Signature : _____

Parts (a) Cost / List Price Items \$ 3,714.40Less 10% \$ 371.44Total of Cost / List \$ 3,342.96(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 3,342.96Labour (Appendix B) \$ 4,770.00Total Repair Cost \$ 8,112.96

The above total will be subjected to 7% G.S.T.

Contact No

Operations

63837369 – Chan Foo Heng / Sam Tan

chanfh@cdge.com.sgsamtan@cdge.com.sg

Not Authorized
Returning By paint

HP: 96910663

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a without Prejudice basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Name of Surveyor : _____

Company : MSIG InsuranceSurvey conducted on : 10/9/19Remarks By Surveyor(a) The repair of this vehicle is not authorized / is not authorized until further notice.(b) Recommended Days of Repair : 07 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : LeDate: 10/9/19

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SBS 1Z Case Owner : Chan Foo Heng

Make & Model : VOLVO B9TL Year Manufacture : 2015

Chassis No : YV3S4P928FA172629 Engine No : 194309

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : Third Party - GAS

| S/No | Part Description | QTY | Cost Price | List Price | Nett Price | S/N | Disposition By Surveyor |
|------|---|-----|---------------------|------------|------------|-----|-------------------------|
| 1 | N/S CORNER BUMPER - CLASS 2 <i>CM</i> | 1 | \$ 562.00 | | | | ✓ |
| | M6x50 - FLANGE SOCKET BUTTON SCREW S/S | 1 | \$ <i>hi</i> 3.00 | | | | ✓ |
| 3 | FRT NS CORNER DEFLECTOR COMP MOULD - C | 1 | \$ <i>CM</i> 196.00 | | | | ✓ |
| 4 | FRONT MID BUMPER COMP MOULD - CLASS 2 | 1 | \$ <i>Bo</i> 553.00 | | | | ✓ |
| 5 | FRONT FIBREGLASS CORNER FIX BRACKET N/S | 1 | \$ <i>By</i> 44.00 | | | | ✓ |
| 6 | STAINLESS STEEL HINGE;FRONT FRAME <i>hi</i> | 2 | \$ 89.00 | | | | ✓ |
| 7 | FRONT BUMPER LOCK MECHANISM <i>By</i> | 1 | \$ 1,220.00 | | | | ✓ |
| 8 | N/S crash bracket <i>By</i> | 1 | \$ 35.00 | | | | ✓ |
| 9 | SPRING LOADED DOOR BOLT <i>hi</i> | 2 | \$ 58.00 | | | | ✓ |
| 10 | Bumper attachment bracket <i>hi</i> | 1 | \$ 35.00 | | | | ✓ |
| 11 | BUMPER ATTACHMENT PLATE <i>hi</i> | 2 | \$ 9.00 | | | | ✓ |
| 12 | BUMPER HINGE LOCATING BLOCK <i>hi</i> | 1 | \$ 36.00 | | | | ✓ |
| 13 | BUMPER ATT BKT <i>By</i> | 1 | \$ 56.00 | | | | ✓ |
| 14 | FRT HANGING STRAP;FRT FRAME <i>hi</i> | 1 | \$ 33.00 | | | | X |
| 15 | DIPPED BEAM HEADLAMP <i>hi CM</i> | 1 | \$ 258.00 | | | | ✓ |
| 16 | BLANKING PLATE FOR DAY TIME RUNNING LIG | 1 | \$ <i>hi</i> 69.00 | | | | ✓ |
| 17 | REGUALTOR <i>By</i> | 1 | \$ 130.00 | | | | ✓ |
| 18 | GO AHEAD Sticker <i>hi</i> | 1 | \$ 30.00 | | | | ✓ |
| 19 | Front Number Plate <i>By</i> | 1 | \$ 60.00 | | | | 40 |
| 20 | M6X35 M1/B38 BIGHEAD BOLT <i>hi</i> | 1 | \$ 8.00 | | | | ✓ |
| 21 | M6 LUG NUT - ZINC NICKEL <i>hi</i> | 2 | \$ 10.40 | | | | ✓ |
| 22 | Bolt & Nut M6 X 40 <i>hi</i> | 8 | \$ 40.00 | | | | ✓ |
| 23 | Bolt & Nut M8 X 25 <i>hi</i> | 6 | \$ 30.00 | | | | ✓ |
| 24 | PLEXUS ADHESIVE <i>hi</i> | 1 | \$ 150.00 | | | | ✓ |
| 25 | | | | | | | |
| 26 | <i>108</i> | | | | | | |
| 27 | | | | | | | |
| 28 | | | | | | | |
| 29 | | | | | | | |
| 30 | | | | | | | |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62815767

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : Third Party - GASVehicle No. : SBS 1ZMake & Model : VOLVO B9TLYear of Manufacture : 2015Chassis No. : YV3S4P928FA172629Ins Company : NAEngine No. : 194309Excess : NAPolicy No. : NADate of Accident : 2/9/2019Time of Accident : 21:00

Suggested Days of Repair :

In-house Vehicle Assessor**Repair Estimates**

Parts (a) Cost / List Price Items \$ 3,714.40
 Less 10% \$ 371.44
 Total of Cost / List \$ 3,342.96

(b) Nett Price Items \$ -
 Less -
 Total of Nett Item -

(c) Special Nett Items \$ -
3,295.26

Total Parts Cost (Appendix A) \$ 3,342.96Labour (Appendix B) \$ 4,770.00Total Repair Cost \$ 8,112.96Case Owner : Chan Foo Heng

Signature :

Contact No
Operations

63837369 - Chan Foo Heng / Sam Tan

chanfh@cdge.com.sgsamtan@cdge.com.sg

Not Authorized
Resurvey By painy

HP: 96910663

86735.26 ✓ OK

Kenneth Kong @ 1KK auto.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor :

Company :

Survey conducted on :

Remarks By Surveyor(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.(b) Recommended Days of Repair : 07 day(s)(c) Resurvey : Required / ☒ Not Required(d) Excess : \$ -

(e) Signature of surveyor :

Date:

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62815767

Spare Parts

Vehicle No : SBS 1Z Case Owner : Chan Foo Heng

Make & Model : VOLVO B9TL Year Manufacture : 2015

Chassis No : YV3S4P928FA172629 Engine No : 194309

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : Third Party - GAS

| S/No | Part Description | QTY | Cost Price | List Price | Nett Price | S/N | Disposition By Surveyor |
|------|--|-----|---------------------|------------|------------|-----|-------------------------|
| 1 | N/S CORNER BUMPER - CLASS 2 <i>CM</i> | 1 | \$ 562.00 | | | | ✓ |
| | M6x50 - FLANGE SOCKET BUTTON SCREW S/S | 1 | \$ <i>4.1</i> 3.00 | | | | ✓ |
| | FRT NS CORNER DEFLECTOR COMP MOULD - C | 1 | \$ <i>CM</i> 196.00 | | | | ✓ |
| 4 | FRONT MID BUMPER COMP MOULD - CLASS 2 | 1 | \$ <i>55</i> 553.00 | | | | ✓ |
| 5 | FRONT FIBREGLASS CORNER FIX BRACKET N/S | 1 | \$ <i>44</i> 44.00 | | | | ✓ |
| 6 | STAINLESS STEEL HINGE;FRONT FRAME <i>1.1</i> | 2 | \$ 89.00 | | | | ✓ |
| 7 | FRONT BUMPER LOCK MECHANISM <i>Ry</i> | 1 | \$ 1,220.00 | | | | ✓ |
| 8 | N/S crash bracket <i>Ry</i> | 1 | \$ 35.00 | | | | ✓ |
| 9 | SPRING LOADED DOOR BOLT <i>Me</i> | 2 | \$ 58.00 | | | | ✓ |
| 10 | Bumper attachment bracket <i>1.1</i> | 1 | \$ 35.00 | | | | ✓ |
| 11 | BUMPER ATTACHMENT PLATE <i>1.1</i> | 2 | \$ 9.00 | | | | ✓ |
| 12 | BUMPER HINGE LOCATING BLOCK <i>1.1</i> | 1 | \$ 36.00 | | | | ✓ |
| 13 | BUMPER ATT BKT <i>Ry</i> | 1 | \$ 56.00 | | | | ✓ |
| 14 | FRT HANGING STRAP;FRT FRAME <i>1.1</i> | 1 | \$ 33.00 | X | | | X |
| 15 | DIPPED BEAM HEADLAMP <i>1.1</i> | 1 | \$ 258.00 | | | | ✓ |
| | BLANKING PLATE FOR DAY TIME RUNNING LIG | 1 | \$ <i>Me</i> 69.00 | | | | ✓ |
| | REGULATOR <i>Ry</i> | 1 | \$ 130.00 | | | | ✓ |
| 18 | GO AHEAD Sticker <i>Me</i> | 1 | \$ 30.00 | | | | ✓ |
| 19 | Front Number Plate <i>Ry</i> | 1 | \$ 60.00 | 40 | | | 40 |
| 20 | M6X35 M1/B38 BIGHEAD BOLT <i>Me</i> | 1 | \$ 8.00 | | | | ✓ |
| 21 | M6 LUG NUT - ZINC NICKEL <i>Me</i> | 2 | \$ 10.40 | | | | ✓ |
| 22 | Bolt & Nut M6 X 40 <i>Me</i> | 8 | \$ 40.00 | | | | ✓ |
| 23 | Bolt & Nut M8 X 25 <i>Me</i> | 6 | \$ 30.00 | | | | ✓ |
| 24 | PLEXUS ADHESIVE <i>Me</i> | 1 | \$ 150.00 | | | | ✓ |
| 25 | | | | | | | |
| 26 | | | | | | | |
| 27 | | | | | | | |
| 28 | | | | | | | |
| 29 | | | | | | | |
| 30 | | | | | | | |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62815767

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 03 Sep 2019 | | 10 Sep 2019 18:30 Edit Adj Rpt | S\$6,735.26 Edit Estimates | S\$6,735.26 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | SIM PUAY GEK, ID: S8012323Z | | | | | | | | |
| Main Claimant: | GO AHEAD SINGAPORE PTE LTD, Co. Reg. No.: 201541900C | | | | | | | | |
| Vehicle Reg. No.: | SBS1Z | Date of Loss: | 02/09/2019 00:00 - :59 [48 Months and 20 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 604584 | Policy/Cover Note No.: | 80463843QMX (Comprehensive) Coverage: 28/11/2018 - 27/11/2019 | | | | | | |
| Vehicle Reg. No. (Insured): | SKQ4736P | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road, 579701 Toa Payoh - Tel: 63837168 /63837118 | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 10/10/2019] | | | | | | | | |
| Driver/Custodian (Insured): | SIM POH HUA (), NRIC: S8132917F, Tel: +6598755789 Email: | | | | | | | | |
| Adj Asg. Remarks: | on WP. Manual assigned to LKK via email on 09/09/19. (Manual Assign). Liab: NA. Contact: Mr Chan Foo Heng @ 9690 1177. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SBS1Z (604584)
[SKQ4736P]
TP
GO AHEAD SINGAPORE PTE LTD
Sep 2 2019 12:00AM
[SIM PUAY GEK]
ComfortDelGro Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

| Assessment Reports | | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|-----------|------------|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print | |
| 1 | 11/09/19 16:01 | Adjuster Immediate Advice | Load HTM | | |

| Photos/Images | | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|-----------|-------------------------------------|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print | |
| 1 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 2 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 3 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 4 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 5 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 6 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 7 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 8 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 9 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 10 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 11 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 12 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 13 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 14 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 15 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 16 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 17 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 18 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 19 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 20 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 21 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 22 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 23 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 24 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 25 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 26 | 04/10/19 17:48 | General View | Load JPG | <input checked="" type="checkbox"/> | |
| 27 | 04/10/19 17:50 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> | |
| 28 | 04/10/19 17:50 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> | |

| Documentation | | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|--|-----------|------------|-------------------------------------|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print | |
| 1 | 09/09/19 16:03 | TP SBS1Z GIA & POLICE REPORT | Load PDF | | |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) | Thumbnail | Print | |
| 1 | 10/09/19 18:27 | Survey Request - Manual Assigned | Load PDF | | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19015945/KTD3E2

Date: 11/10/2019

REFERENCE

| | |
|--|--|
| Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. | Policy No: 80463843QMX |
| Claimant | |
| Vehicle No : SBS1Z | Insured Vehicle No : SKQ4736P |
| Date of Loss: 02/09/2019 | Nature of Claim: TP Claim No: 604584 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--------------------------------------|-------------|-------------------|
| Reg No: | SBS1Z | Engine No: | D9194309 |
| Make & Model: | VOLVO B9TL, 9.4 D AUTO TURBO ABS (A) | Chassis No: | YV3S4P928FA172629 |
| Reg. Date: | 13/08/2015 (Man. Year: 2015) | Odometer: | 294593 km |
| Colour: | Green | | |
| Engine Capacity: | 9364 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------------|
| Front Tyre Size: | 275/70R22.5 | Rear Tyre Size: | 275/70R22.5(D/D) |
| Front Left Side: | Continental 4 mm | Rear Left Side: | Continental 8/8/8/8 mm |
| Front Right Side: | Continental 4 mm | Rear Right Side: | Continental 8/8/8/8 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts | 3,342.96 | 3,295.26 | 47.70 | 1.43 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,770.00 | 3,440.00 | 1,330.00 | 27.88 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 8,112.96 | 6,735.26 | 1,377.70 | 16.98 |
| + GST 7.00/7.00% (S\$) | 567.91 | 471.47 | 96.44 | 16.98 |
| Nett Amount (S\$) | 8,680.87 | 7,206.73 | 1,474.14 | 16.98 |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 10/09/2019 | |
| Date Inspected: | 10/09/2019 Inspected At: | ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701 |
| Estimated Period of Repair: | 7.0 days | |

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|----------------------|--|---|
| Reference | | |
| Part Source: | (Last Synchronised: 11 Oct 2019) | |
| Parts: | N/A | VOLVO B9TL 9.4 D AUTO TURBO ABS (A) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SBS1Z) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|-------------|-------------|--------------|
| 1 | 1 | | *M6X50-FLANGE SOCKET BUTTON SCREW S/S | Missing | 3.00 FL | *3.00 FL |
| 2 | 1 | | *FRT N/S CORNER DEFLECTOR COMP MOULD-C | Cracked | 196.00 FL | *196.00 FL |
| 3 | 1 | | *FRONT FIBRE GLASS CORNER FIX BRACKET N/S | Bent | 44.00 FL | *44.00 FL |
| 4 | 2 | | *STAINLESS STEEL HINGE-FRONT FRAME | Missing | 89.00 FL | *89.00 FL |
| 5 | 1 | | *FRONT BUMPER LOCK MECHANISM | Bent | 1,220.00 FL | *1,220.00 FL |
| 6 | 1 | | *N/S CRASH BRACKET | Bent | 35.00 FL | *35.00 FL |
| 7 | 2 | | *SPRING LOADED DOOR BOLT | Necessary | 58.00 FL | *58.00 FL |
| 8 | 1 | | *BUMPER ATTACHMENT BRACKET | Missing | 35.00 FL | *35.00 FL |
| 9 | 2 | | *BUMPER ATTACHMENT PLATE | Missing | 9.00 FL | *9.00 FL |
| 10 | 1 | | *BUMPER HINGE LOCATING BLOCK | Missing | 36.00 FL | *36.00 FL |
| 11 | 1 | | *BUMPER ATT BKT | Bent | 56.00 FL | *56.00 FL |
| 12 | 1 | | *FRT HANGING STRAP FRT FRAME | Serviceable | 33.00 FL | *- FL |
| 13 | 1 | | *DIPPED BEAM HEADLAMP | Mtg Cracked | 258.00 FL | *258.00 FL |
| 14 | 1 | | *BLANKING PLATE FOR DAY TIME RUNNING LIG | Necessary | 69.00 FL | *69.00 FL |
| 15 | 1 | | *REGULATOR | Bent | 130.00 FL | *130.00 FL |
| 16 | 1 | | *GO AHEAD STICKER | Necessary | 30.00 FL | *30.00 FL |
| 17 | 1 | | *M6X35 M1/B38 BIGHEAD BOLT | Necessary | 8.00 FL | *8.00 FL |
| 18 | 2 | | *M6 LUG NUT-ZINC NICKEL | Necessary | 10.40 FL | *10.40 FL |
| 19 | 8 | | *BOLT & NUT M6 X40 | Necessary | 40.00 FL | *40.00 FL |
| 20 | 1 | | *FRONT NUMBER PLATE | Bent | 60.00 FL | *40.00 FL |
| 21 | 1 | | *PLEXUS ADHESIVE | Necessary | 150.00 FL | *150.00 FL |
| 22 | 1 | | *N/S CORNER BUMPER-CLASS 2 | Cracked | 562.00 FL | *562.00 FL |
| 23 | 1 | | *FRONT MID BUMPER COMP MOULD-CLASS 2 | Broken | 553.00 FL | *553.00 FL |
| 24 | 6 | | *BOLT & NUT M8 X25 | Necessary | 30.00 FL | *30.00 FL |

F=Franchise part. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 3,714.40 | 3,661.40 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 371.44 | 366.14 |
| Total Parts (\$\$) | 3,342.96 | 3,295.26 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | REPLACE N/S CORNER BUMPER & BLANKING PLATE } | New | 560.00 | 1,440.00 |
| 2 | REPLACE N/S LIGHT BEZEL WITH BOLT & PLEXUS } | New | 360.00 | 0.00 |
| 3 | REPLACE N/S REFLECTOR PANEL,CLIPS & NUTS } | New | 240.00 | 0.00 |
| 4 | REPLACE MID BUMPER PANEL,LOCK MECHANISM,CRASH BRACKET,SPRING LOCK,BUMPER BRACKET,BOLTS & NUTS } | New | 760.00 | 0.00 |
| 5 | REPLACE N/S HEAD LAMP ASSY | New | 180.00 | 60.00 |
| 6 | REPAIR FRONT PILLAR BRACKET } | New | 240.00 | 720.00 |
| 7 | REPAIR FRONT CRASH FRAME SUPPORT & BRACKET } | New | 360.00 | 0.00 |
| 8 | REPAIR FRONT CHASSIS CROSS MEMBER STRUCTURE,BRACKET } | New | 360.00 | 0.00 |
| 9 | RESPRAY UNDERSEAL TUFF-COAT AT ACCIDENT AREA | New | 210.00 | 140.00 |
| 10 | SPRAY PAINTING ON MID BUMPER,LIGHT BEZEL,BUMPER CORNER,REFLECTOR PANEL & FRONT DOME | New | 1,500.00 | 1,080.00 |
| Gross Labour Cost (\$\$) | | | 4,770.00 | 3,440.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >