

ASS. REC. BY:

REF: CS/EQ1 19015985/ Rlyf3 Special Instruction:

Surveyor: Rasu

ASSIGNMENT (Office)

sharon@singanteecan

From (Person): Steve Lim of EQ Date/Time: 10/09/2019

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

①D / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YN 45243 Insured: \_\_\_\_\_at Workshop m/s Sng An Tee Motor & Panel Service Pte Ltd Tel: 6268 6183of Bik 3 Pioneer Road North #01-15Policy No: DMCPHA18-007218 Claim No: DM19H002512Sum Insured: \_\_\_\_\_ Excess: \$3750.00Make of Veh: \_\_\_\_\_ D.O.A. 07/09/2019  
(Client's Record)CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: \_\_\_\_\_Date/Time: 10/09/2019 @ 10:04 a.m Person Contacted: Samantha Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	YN 45243 - X
11/9/19	Sent Merimen to request Mandate Attach
11/9/19	Approval by Steven Lomp Lump Repair Limit \$7K
12/9/19	Sent E-Mail to Workshop authorise but workshop need to see first
20/9/19	Call Janil need to check owner for repair
25/9/19	Call today Jania said can repair by Lump Sum Limit \$7K already left Rasul.
19/10/19	Call Janice said can repair by Lump Sum or Total loss

Minor

photo O.K



## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Sep 2019 11:05 <a href="#">Sendback Est</a>	09 Sep 2019 14:33 <b>S\$12,056.40</b>	10 Sep 2019 09:27 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>HIAP SENG PILING CONSTRUCTION PTE LTD</b> , Co. Reg. No.: 199102037N								
Vehicle Reg. No.:	<b>YN4524J</b>	Date of Loss:	07/09/2019 07:00 - :59 [68 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>OD / DM19H002512</b>	Policy/Cover Note No.:	DMCPHQ18-007218 (Comprehensive)						
		Excess:	S\$3,750.00						
Repairer:	<b>Sng Ah Tee Motor &amp; Panel Service Pte Ltd (Pioneer)</b> Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183								
Handling Insurer:	<b>EQ Insurance Company Ltd (HQ)</b> - Tel: 6223 9433 ... [Handled by <b>Steve Lim</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Final Rpt due 19/09/2019]								
Driver/Custodian:	HASAN SAYED NAZMUL (30 / Male) , NRIC: G2081194W, Tel: +6591546093 Email: NOEMAIL								
Adj Asg. Remarks:	OD EXCESS \$750+3000								
<b>ASSOCIATED MAIL RECEIVED</b>									
There are no mail for this case.									
<a href="#">View All</a> <a href="#">Compose Case Mail</a>									
<b>ALL ASSOCIATED TASKS</b>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Yvonne Wong (LKK Auto)

---

**From:** Rasul (LKKAuto)  
**Sent:** Friday, November 01, 2019 4:43 PM  
**To:** Sharon Sng  
**Cc:** janice@sngahtee.com; Yvonne Wong (LKK Auto); sam@sngahtee.com; Yvonne Wong (LKK Auto)  
**Subject:** RE: YN4524J DOA: 07/09/2019 (finalise)

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

Hi Sharon,

Finalised amount confirmed \$6,600 / 7 days Lump sum before excess

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Sharon Sng [mailto:[sharon@sngahtee.com](mailto:sharon@sngahtee.com)]  
**Sent:** Wednesday, 30 October, 2019 4:20 PM  
**To:** Rasul (LKKAuto)  
**Cc:** janice@sngahtee.com; Yvonne Wong (LKK Auto); sam@sngahtee.com  
**Subject:** RE: YN4524J DOA: 07/09/2019 (finalise)

Hi Rasul

Please confirm. Thanks.

Best Regards

---

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457  
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



*-Please note that all offer/acceptance is made without prejudice.-*

**From:** Rasul (LKKAuto)  
**Sent:** Friday, October 25, 2019 10:41 AM  
**To:** [sharon@sngahtee.com](mailto:sharon@sngahtee.com)  
**Cc:** [janice@sngahtee.com](mailto:janice@sngahtee.com); Yvonne Wong (LKK Auto) <[yvonnewong@lkkauto.com](mailto:yvonnewong@lkkauto.com)>; [sam@sngahtee.com](mailto:sam@sngahtee.com)  
**Subject:** RE: YN4524J DOA: 07/09/2019

Hi Sharon,

Kindly forward the supplementary photos

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Yvonne Wong (LKK Auto)  
**Sent:** Friday, 11 October, 2019 5:12 PM  
**To:** [sam@sngahtee.com](mailto:sam@sngahtee.com)  
**Cc:** [sharon@sngahtee.com](mailto:sharon@sngahtee.com); [janice@sngahtee.com](mailto:janice@sngahtee.com); SUR; Rasul (LKKAuto)  
**Subject:** YN4524J DOA: 07/09/2019

Hi Sharon

Please send the damaged photo for supplementary item to us

Thank you.

Best Regards,

**Yvonne Wong (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [yvonnewong@lkkauto.com](mailto:yvonnewong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Yvonne Wong (LKK Auto)  
**Sent:** Thursday, September 12, 2019 12:11 PM  
**To:** [sam@sngahtee.com](mailto:sam@sngahtee.com)  
**Cc:** [sharon@sngahtee.com](mailto:sharon@sngahtee.com); [janice@sngahtee.com](mailto:janice@sngahtee.com); SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** YN4524J DOA: 07/09/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle YN4524J (excess \$3750/-).LIMIT REPAIR NOT EXCEEDING LUMP SUM \$7000/-

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Yvonne Wong (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [yvonnewong@lkkauto.com](mailto:yvonnewong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Yvonne Wong (LKK Auto)

---

**From:** Yvonne Wong (LKK Auto)  
**Sent:** Thursday, September 12, 2019 12:11 PM  
**To:** sam@sngahtee.com  
**Cc:** sharon@sngahtee.com; janice@sngahtee.com; SUR  
**Subject:** YN4524J DOA: 07/09/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle YN4524J (**excess \$3750/-**). **LIMIT REPAIR NOT EXCEEDING LUMP SUM \$7000/-**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Yvonne Wong (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [yvonnewong@lkkauto.com](mailto:yvonnewong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd  
5 Maxwell Road, #17-00 Tower Block  
MND Complex  
Singapore 069110

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Steve Lim

Date: 11 Sep 2019

**Preliminary Advice**

Vehicle No	: YN4524J	Accident Date	: 07/09/2019
Make	: MITSUBISHI CANTER	Policy No.	: DMCPHQ18-007218
Assignment Date	: 10/09/2019	Excess	: S\$3,750.00
Date of Inspection	: 10/09/2019	Est. Duration of Repair	: 7.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,056.40
Revised Amount	:S\$	6,375.40
Check Items (Estimated)	:S\$	3,648.00
Total	:S\$	10,023.40

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	31,000.00
COE / PARF Rebate	:S\$	23,681.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,319.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Pending for repair cost.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/09/2019 12:10
Date Of Accident	07/09/2019 07:40
Exact Location Of Accident	PIE TWDS CHANGI EXIT BT BATOK EAST AVE 3
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN4524J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HIAP SENG PILING CONSTRUCTION PTE LTD
Co Reg No	199102037N
Email Address	ADMIN@HIAPSENG.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64566093

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER-3.0 D FEB21ER3SDEB (M)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ18-007218
Cover Note Number	

### Driver

Name of Driver	HASAN SAYED NAZMUL
Passport No/FIN	G2081194W
Date Of Birth	01/01/1989
Occupation	OUTDOOR
Date Of Driving Pass	30/10/2017
Driving Experience	1 YEAR AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91546093
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : AMIR GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 07/09/2019 @ ABT 0740HRS. WHEN THE VEHICLE B WHICH IS IN FRONT OF ME SUDDENLY JAMMED BRAKE. AS FOLLOWER, I COULD NOT STOP IN TIME & KNOCKED ONTO THE SAID VEHICLE AT REAR. NO ONE WAS INJURED. THAT'S ALL.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB6554U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN BUCK HUAT
NRIC/Passport Number	S1656190H
Contact Number	82868027
Address	
Postcode	
Insurance Company Name	



Nature Of Damage  
No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

# Sketch Plan Pg. 2

## SKETCH PLAN

PLE turns Chong ext Rt Barbale East Ave 3



vehicle @: 4N4524J

vehicle @: GBB6554U

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 07/09/2019 @ 04:04hrs

Refer to circumstance of accident.

<input checked="" type="checkbox"/> Claim own policy
<input type="checkbox"/> Claim third party
<input type="checkbox"/> Claim OD / TP at other works hop
<input type="checkbox"/> For record purpose
Policy No. <u>DMCPHQ 18-007218</u>
Insurer <u>EQ (C)</u> Veh. No. <u>4N4524J</u>

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

*[Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	037N
<b>Vehicle Details</b>	
Vehicle No.:	YN4524J
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Sep 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER3SDEB
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	4P10B00897
Chassis No.:	FEB21EA00103
Maximum Power Output:	-
Open Market Value:	\$30,605.00
Original Registration Date:	12 Dec 2013
First Registration Date:	12 Dec 2013
Transfer Count:	1
Actual ARF Paid:	\$1,531.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	11 Dec 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$55,503.00
COE Rebate Amount:	\$23,644.00
<b>Total Rebate Amount:</b>	<b>\$23,644.00</b>

The information contained herein is correct as at 07 Sep 2019

OK

## Estimate Report

**Sng Ah Tee Motor & Panel Service Pte Ltd** (Co.Reg.No.200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

**INSURER: EQ Insurance Company Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCPHQ18-007218	Date of Loss:	07/09/2019
Vehicle Reg. No.:	YN4524J	Driveable?	
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HIAP SENG PILING CONSTRUCTION PTE LTD		
Driver:	HASAN SAYED NAZMUL		

Make/Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (M)	Vehicle Reg. Date:	12/12/2013
Vehicle Colour:	WHITE		
Engine No:	4P10B00897	Chassis No:	FEB21EA00103
Odometer:	5 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	9

Description of Accident/Loss: ON 07/09/2019 @ ABT 0740HRS. WHEN THE VEHICLE B WHICH IS IN FRONT OF ME SUDDENLY JAMMED BRAKE. AS FOLLOWER, I COULD NOT STOP IN TIME & KNOCKED ONTO THE SAID VEHICLE AT REAR. NO ONE WAS INJURED. THAT'S ALL.

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS		Amount
Parts		9,796.40
Miscellaneous Items		0.00
Labour		2,260.00
Paintwork Labour		0.00
Towing		0.00
Gross Total (S\$)		12,056.40
+ GST 7.00% (S\$)		843.95
Nett Amount (S\$)		12,900.35

This claim is handled by: JANICE CHANG SIEW YIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System



## Reference

Part Source: (Last Synchronised: 09 Sep 2019)

Parts: N/A MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YN4524J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE <i>cut</i> ✓	0	0.00	*20.00 FS
2	1		*FRT BUMPER <i>repair</i>	0.00	0.00	*550.00 F
3	2		*FRT BUMPER BRACKET <i>LH-X/LH-? (1pc)</i>	0.00	0.00	*220.00 F
4	2		*FRT BUMPER SIDE GARNISH <i>cut</i> ✓	0.00	0.00	*420.00 F
5	2		*FRT HEADLAMP <i>RH-X/LH-RH (1pc)</i>	0.00	0.00	*600.00 F
6	2		*FRT SIGNAL LAMP <i>RH-X/LH-RH</i>	0.00	0.00	*320.00 F
7	1		*FRT HEADLAMP SEAL(LH) <i>cut</i> ✓	0.00	0.00	*9.00 F
8	1		*FRT GRILLE WITH EMBLEM <i>re</i> ✓	0.00	0.00	*550.00 F
9	1		*FRT GRILLE CENTER RETAINER <i>bt</i> ✓	0.00	0.00	*17.00 F
10	10		*FRT GRILLE CLIP <i>re</i> ✓	0.00	0.00	*50.00 F
11	1		*FRT HORN <i>bt</i> ✓	0.00	0.00	*70.00 F
12	1		*FRT HORN COVER <i>bt</i> ✓	0.00	0.00	*70.00 F
13	1		*AIRCON HIGH PRESSURE PIPE <i>X</i>	0.00	0.00	*310.00 F
14	1		*AIRCON LOW PRESSURE PIPE <i>bt</i> ✓	0.00	0.00	*280.00 F
15	1		*FRT CABIN SUPPORT BEAM <i>?</i>	0.00	0.00	*280.00 F
16	1		*FRT CABIN SUPPORT BEAM BRACKET(LH) <i>?</i>	0.00	0.00	*500.00 F
17	1		*FRT CABIN SUPPORT BEAM BRACKET(RH) <i>?</i>	0.00	0.00	*450.00 F
18	2		*FRT CABIN SUPPORT BEAM MOUNTING BUSH <i>?</i>	0.00	0.00	*260.00 F
19	1		*FRT PANEL ASSY <i>bt</i> ✓	0.00	0.00	*1,200.00 F
20	1		*FRT PANEL FUSO LOGO <i>re</i> ✓	0.00	0.00	*70.00 F
21	1		*FRT WIPER GARNISH <i>re</i> ✓	0.00	0.00	*210.00 F
22	1		*FRT CORNER PANEL(LH) <i>re</i> ✓	0.00	0.00	*260.00 F
23	3		*FRT CORNER PANEL LH CLIPS <i>re</i> ✓	0.00	0.00	*18.00 F
24	1		*FRT SIDE MIRROR ROUND(LH) <i>cut</i> ✓	0.00	0.00	*35.00 F
25	1		*FRT WINDSCREEN RUBBER <i>re</i> ✓	0.00	0.00	*220.00 F
26	1		*ERP BRACKET <i>re</i> <i>?</i>	0	0.00	*26.00 FS
27	1		*HEATER BLOWER ASSY <i>?</i>	0.00	0.00	*1,100.00 F
28	1		*AIRCON INTAKE BOX <i>?</i>	0.00	0.00	*480.00 F
29	1		*FRT CORNER PANEL LH TOP COVER <i>MIS</i> ✓	0.00	0.00	*25.00 F
30	1		*FRT DOOR STEP GARNISH(LH) <i>re</i> ✓	0.00	0.00	*290.00 F

F=Franchise part, S=SpdNett.

Sub Total (S\$)	8,910.00
+ Margin on L,N Items 10.00% (S\$)	886.40
<b>Total Parts (S\$)</b>	<b>9,796.40</b>

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS



There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO KNOCK FLOOR PANEL, WELD, REMOVE & FIX ABOVE PARTS	New	700 <del>900.00</del>
2	TO SPRAY PAINTING ON FRT BUMPER, FRT PANEL, FRT GRILLE, FRT WIPER GARNISH, CORNER PANEL (LH), FLOOR PANEL & AFFECTED AREA	New	700 <del>900.00</del>
3	TO CHECK WIRING	New	30.00
4	TO REFILL AIRCON GAS	New	100.00
5	TO REMOVE & FIX FRT DASHBOARD	New	150? <del>180.00</del>
6	TO REMOVE & FIX FRT WINDSCREEN	New	120 <del>150.00</del>
Gross Labour Cost (S\$)			2,260.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Pune

Hp 90010068

7 days

P/P

10/09/19 @ 1450

Resurvey before paint

EXCESS : \$3750

REVERT

# Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **EQ Insurance Company Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCPHQ18-007218	Date of Loss:	07/09/2019
Vehicle Reg. No.:	YN4524J	Driveable?	
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HIAP SENG PILING CONSTRUCTION PTE LTD		
Driver:	HASAN SAYED NAZMUL		
Make/Model:	mitsubishi canter, 3.0 D FEB21ER3SDEB (M)	Vehicle Reg. Date:	12/12/2013
Vehicle Colour:	WHITE		
Engine No:	4P10B00897	Chassis No:	FEB21EA00103
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	9		
Description of Accident/Loss	ON 07/09/2019 @ ABT 0740HRS. WHEN THE VEHICLE B WHICH IS IN FRONT OF ME SUDDENLY JAMMED BRAKE. AS FOLLOWER, I COULD NOT STOP IN TIME & KNOCKED ONTO THE SAID VEHICLE AT REAR. NO ONE WAS INJURED. THAT'S ALL.		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

**COST OF CLAIMS**

	Amount
Parts	9,796.40
Miscellaneous Items	0.00
Labour	2,260.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>12,056.40</b>
<b>+ GST 7.00% (\$\$)</b>	<b>843.95</b>
<b>Nett Amount (\$\$)</b>	<b>12,900.35</b>

This claim is handled by: JANICE CHANG SIEW YIN

12666.40

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

## REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 09 Sep 2019)

Parts: N/A MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YN4524J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE <i>cut</i>	0	0.00	*20.00 FS
2	1		*FRT BUMPER <i>repair</i>	0.00	0.00	*550.00 F
3	2		*FRT BUMPER BRACKET <i>RH-X/LH-? (1pc)</i>	0.00	0.00	*220.00 F
4	2		*FRT BUMPER SIDE GARNISH <i>cut</i>	0.00	0.00	*420.00 F
5	2		*FRT HEADLAMP <i>RH-X/LH-Bro (1pc)</i>	0.00	0.00	*600.00 F <i>300%</i>
6	2		*FRT SIGNAL LAMP <i>RH-X/LH-Bro</i>	0.00	0.00	*320.00 F <i>160%</i>
7	1		*FRT HEADLAMP SEAL(LH) <i>cut</i>	0.00	0.00	*9.00 F
8	1		*FRT GRILLE WITH EMBLEM <i>re</i>	0.00	0.00	*550.00 F
9	1		*FRT GRILLE CENTER RETAINER <i>bt</i>	0.00	0.00	*17.00 F
10	10		*FRT GRILLE CLIP <i>re</i>	0.00	0.00	*50.00 F
11	1		*FRT HORN <i>bt</i>	0.00	0.00	*70.00 F
12	1		*FRT HORN COVER <i>bt</i>	0.00	0.00	*70.00 F
13	1		*AIRCON HIGH PRESSURE PIPE <i>xsu</i>	0.00	0.00	*310.00 F
14	1		*AIRCON LOW PRESSURE PIPE <i>bt</i>	0.00	0.00	*280.00 F
15	1		*FRT CABIN SUPPORT BEAM <i>xsu</i>	0.00	0.00	*280.00 F
16	1		*FRT CABIN SUPPORT BEAM BRACKET(LH) <i>? xsu</i>	0.00	0.00	*500.00 F
17	1		*FRT CABIN SUPPORT BEAM BRACKET(RH) <i>? xsu</i>	0.00	0.00	*450.00 F
18	2		*FRT CABIN SUPPORT BEAM MOUNTING BUSH <i>? xsu</i>	0.00	0.00	*260.00 F
19	1		*FRT PANEL ASSY <i>bt</i>	0.00	0.00	*1,200.00 F
20	1		*FRT PANEL FUSO LOGO <i>re</i>	0.00	0.00	*70.00 F
21	1		*FRT WIPER GARNISH <i>ca</i>	0.00	0.00	*210.00 F
22	1		*FRT CORNER PANEL(LH) <i>ca</i>	0.00	0.00	*260.00 F
23	3		*FRT CORNER PANEL LH CLIPS <i>re</i>	0.00	0.00	*18.00 F
24	1		*FRT SIDE MIRROR ROUND(LH) <i>cut</i>	0.00	0.00	*35.00 F
25	1		*FRT WINDSCREEN RUBBER <i>re</i>	0.00	0.00	*220.00 F
26	1		*ERP BRACKET <i>re</i>	0	0.00	*26.00 FS
27	1		*HEATER BLOWER ASSY <i>? ca</i>	0.00	0.00	*1,100.00 F
28	1		*AIRCON INTAKE BOX <i>? xsu</i>	0.00	0.00	*480.00 F
29	1		*FRT CORNER PANEL LH TOP COVER <i>MS</i>	0.00	0.00	*25.00 F
30	1		*FRT DOOR STEP GARNISH(LH) <i>ca</i>	0.00	0.00	*290.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	8,910.00
+ Margin on L,N Items 10.00% (S\$)	886.40
<b>Total Parts (S\$)</b>	<b>9,796.40</b>

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO KNOCK FLOOR PANEL, WELD, REMOVE & FIX ABOVE PARTS	New	700 <del>900.00</del>
2	TO SPRAY PAINTING ON FRT BUMPER, FRT PANEL, FRT GRILLE, FRT WIPER GARNISH, CORNER PANEL (LH), FLOOR PANEL & AFFECTED AREA	New	700 <del>900.00</del>
3	TO CHECK WIRING	New	30.00
4	TO REFILL AIRCON GAS	New	100.00
5	TO REMOVE & FIX FRT DASHBOARD	New	150 <del>180.00</del>
6	TO REMOVE & FIX FRT WINDSCREEN	New	120 <del>150.00</del>
Gross Labour Cost (S\$)			2,260.00

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

&lt; END OF ESTIMATES &gt;

Reue  
 Hp 90010068  
 7 days  
 P/P  
 10/09/19 @ 1450  
 Resny before paint  
 EXCESS : \$3750  
 Revert

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg;darren@sngahtee.com;janice@sngahtee.com

## (SUPPLEMENTARY)

INSURER: **EQ Insurance Company Ltd (HQ)**

### PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCPHQ18-007218	Date of Loss:	07/09/2019
Vehicle Reg. No.:	<b>YN4524J</b>	Driveable?	
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HIAP SENG PILING CONSTRUCTION PTE LTD		
Driver:	HASAN SAYED NAZMUL		

Make/Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (M)	Vehicle Reg. Date:	12/12/2013
Vehicle Colour:	WHITE		
Engine No:	4P10B00897	Chassis No:	FEB21EA00103
Odometer:	5 KM		

Paint Type:	
Total Loss?	<b>NO</b>
Est. Duration of Repair (day)	9

Description of Accident/Loss: ON 07/09/2019 @ ABT 0740HRS. WHEN THE VEHICLE B WHICH IS IN FRONT OF ME SUDDENLY JAMMED BRAKE. AS FOLLOWER, I COULD NOT STOP IN TIME & KNOCKED ONTO THE SAID VEHICLE AT REAR. NO ONE WAS INJURED. THAT'S ALL.

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

### COST OF CLAIMS

	Amount
Parts	550.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>550.00</b>
<b>+ GST 7.00% (\$\$)</b>	<b>38.50</b>
<b>Nett Amount (\$\$)</b>	<b>588.50</b>
<b>+ Previous Estimates (\$\$)</b>	<b>12,900.35</b>
<b>Claim Total (\$\$)</b>	<b>13,488.85</b>

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 04 Oct 2019)

**Parts:** N/A MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** Sng Ah Tee Motor & Panel Service Pte Ltd/YN4524J/04/10/2019 13:37

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR CON CONDENSER WITH COWLING ASSY <i>St ✓</i>	0.00	0.00	*500.00 F
F=Franchise part.						
Sub Total (S\$)						500.00
+ Margin on L,N Items 10.00% (S\$)						50.00
Total Parts (S\$)						550.00

Sng Ah Tee Motor & Panel Service Pte Ltd/YN4524J/04/10/2019 13:37. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

There are no labour items selected.

Sng Ah Tee Motor & Panel Service Pte Ltd/YN4524J/04/10/2019 13:37. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



## REPAIR DETAILS

Estimate Report

Panel 466

## Reference

Part Source: (Last Synchronised: 09 Sep 2019)  
 Parts: N/A MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M) (Model not available in database)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: (Unsubmitted, no print-code for YN4524J)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE <i>cut</i>	0	0.00	*20.00 F\$
2	1		*FRT BUMPER <i>repair</i>	0.00	0.00	*550.00 F\$
3	2		*FRT BUMPER BRACKET <i>LH-X/LH-? (1pc)</i>	0.00	0.00	*220.00 F\$
4	2		*FRT BUMPER SIDE GARNISH <i>cut</i>	0.00	0.00	*420.00 F\$
5	2		*FRT HEADLAMP <i>RH-X/LH-RH (1pc)</i>	0.00	0.00	*600.00 F\$
6	2		*FRT SIGNAL LAMP <i>RH-X/LH-RH</i>	0.00	0.00	*320.00 F\$
7	1		*FRT HEADLAMP SEAL(LH) <i>cut</i>	0.00	0.00	*9.00 F\$
8	1		*FRT GRILLE WITH EMBLEM <i>re</i>	0.00	0.00	*550.00 F\$
9	1		*FRT GRILLE CENTER RETAINER <i>bt</i>	0.00	0.00	*17.00 F\$
10	10		*FRT GRILLE CLIP <i>re</i>	0.00	0.00	*50.00 F\$
11	1		*FRT HORN <i>bt</i>	0.00	0.00	*70.00 F\$
12	1		*FRT HORN COVER <i>bt</i>	0.00	0.00	*70.00 F\$
13	1		*AIRCON HIGH PRESSURE PIPE <i>X</i>	0.00	0.00	*310.00 F\$
14	1		*AIRCON LOW PRESSURE PIPE <i>bt</i>	0.00	0.00	*280.00 F\$
15	1		*FRT CABIN SUPPORT BEAM	0.00	0.00	*280.00 F\$
16	1		*FRT CABIN SUPPORT BEAM BRACKET(LH) <i>?</i>	0.00	0.00	*500.00 F\$
17	1		*FRT CABIN SUPPORT BEAM BRACKET(RH) <i>?</i>	0.00	0.00	*450.00 F\$
18	2		*FRT CABIN SUPPORT BEAM MOUNTING BUSH <i>?</i>	0.00	0.00	*260.00 F\$
19	1		*FRT PANEL ASSY <i>bt</i>	0.00	0.00	*1,200.00 F\$
20	1		*FRT PANEL FUSO LOGO <i>re</i>	0.00	0.00	*70.00 F\$
21	1		*FRT WIPER GARNISH <i>re</i>	0.00	0.00	*210.00 F\$
22	1		*FRT CORNER PANEL(LH) <i>re</i>	0.00	0.00	*260.00 F\$
23	3		*FRT CORNER PANEL LH CLIPS <i>re</i>	0.00	0.00	*18.00 F\$
24	1		*FRT SIDE MIRROR ROUND(LH) <i>cut</i>	0.00	0.00	*35.00 F\$
25	1		*FRT WINDSCREEN RUBBER <i>re</i>	0.00	0.00	*220.00 F\$
26	1		*ERP BRACKET <i>re</i>	0	0.00	*26.00 F\$
27	1		*HEATER BLOWER ASSY <i>?</i>	0.00	0.00	*1,100.00 F\$
28	1		*AIRCON INTAKE BOX <i>?</i>	0.00	0.00	*480.00 F\$
29	1		*FRT CORNER PANEL LH TOP COVER <i>mis</i>	0.00	0.00	*25.00 F\$
30	1		*FRT DOOR STEP GARNISH(LH) <i>re</i>	0.00	0.00	*290.00 F\$

F=Franchise part, S=SpcNett.

Sub Total (SS) *\$5394.00* 8,910.00  
 + Margin on L,N Items 10.00% (SS) *add 10% = \$589.40* 886.40

Total Parts (SS) *Swat \$466* 9,796.40

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS

*\*A/C condenser -> \$500 / - set*  
*\*A/C Fan cowling -> \$500 / - set*



# Estimates on Miscellaneous Items

Estimate Report

There are no new miscellaneous items selected.

## Estimates on Labour

No Particulars

### Labour Items

	Lab.Type	Amount
1 TO KNOCK FLOOR PANEL, WELD, REMOVE & FIX ABOVE PARTS	New	700 <del>900.00</del>
2 TO SPRAY PAINTING ON FRT BUMPER, FRT PANEL, FRT GRILLE, FRT WIPER GARNISH, CORNER PANEL (LH), FLOOR PANEL & AFFECTED AREA	New	700 <del>900.00</del>
3 TO CHECK WIRING	New	30.00
4 TO REFILL AIRCON GAS	New	100.00
5 TO REMOVE & FIX FRT DASHBOARD	New	150.00
6 TO REMOVE & FIX FRT WINDSCREEN	New	120.00
Gross Labour Cost (\$\$)		(1800) 2,260.00

Report was unsubmitted during this print-out.  
Generated using Merlimen e-Claims IEAS

< END OF ESTIMATES >

total  
 \$8285.40  
 less 20%  
 = \$6628.32  
 ~\$6600  
 4%  
 before tax  
 \$3750  
 or?  
 shawl  
 20/10/2019  
 10/09/19 @ 1450  
 Revery before paint  
 9/p  
 7 days  
 Hp 90010068

## REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 04 Oct 2019)

Parts: N/A MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor &amp; Panel Service Pte Ltd/YN4524J/04/10/2019 13:37

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

*Supplementary*

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR CON CONDENSER WITH COWLING ASSY	0.00	0.00	*500.00 F
						Sub Total (S\$)
						500.00
						+ Margin on L,N Items 10.00% (S\$)
						50.00
						Total Parts (S\$)
						550.00

Sng Ah Tee Motor & Panel Service Pte Ltd/YN4524J/04/10/2019 13:37. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Sep 2019 11:05 <a href="#">Sendback Est</a>	09 Sep 2019 14:33 <b>\$S\$12,056.40</b>	10 Sep 2019 09:27 <a href="#">Edit Adj Rpt</a>	<b>\$S\$6,600.00</b> <a href="#">Edit Estimates</a>	<b>\$S\$6,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
Supp #1	04 Oct 2019 13:36	04 Oct 2019 13:37 <b>\$S\$550.00</b>	04 Oct 2019 13:37			(Combined)	<b>Combined with Main</b> <a href="#">Uncombine Suppl.</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	HIAP SENG PILING CONSTRUCTION PTE LTD, Co. Reg. No.: 199102037N		
Vehicle Reg. No.:	YN4524J	Date of Loss:	07/09/2019 07:00 - :59 [68 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DM19H002512	Policy/Cover Note No.:	DMCPHQ18-007218 (Comprehensive)
		Excess:	\$S\$3,750.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Steve Lim]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 19/09/2019]		
Driver/Custodian:	HASAN SAYED NAZMUL (30 / Male) , NRIC: G2081194W, Tel: +6591546093 Email: NOEMAIL		
Adj Asg. Remarks:	OD EXCESS \$750+3000		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- EQI\_HQ (11/09/2019): Alert - Adj Mandate Approved (\$S\$7000.00) - YN4524J - Claim Handler: Steve Lim
- EQI\_HQ (11/09/2019): Alert - Adj Mandate Approved (\$S\$10023.40) - YN4524J - Claim Handler: Steve Lim

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date   Priority   Type   Task Group   Subject   Handler   Assigned By   Completed On   Created On   Done?

No results.



## Claim Documents

YN4524J (DM19HO02512)

OD

Sep 7 2019 7:00AM

[HIAP SENG PILING CONSTRUCTION PTE LTD]

Sng Ah Tee Motor &amp; Panel Service Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#)
[View in Browser](#)

### Assessment Reports

1 per page















































No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	09/09/19 14:33	Repairer Estimates	1	Load HTM	
2	04/10/19 13:37	Repairer Estimates Suppl. #1	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/09/19 15:56	Adjuster Immediate Advice	1	Load HTM	

### Photos/Images

3 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/11/19 13:47	General View	1	Load JPG	✓
2	06/11/19 13:47	General View	1	Load JPG	✓
3	06/11/19 13:47	General View	1	Load JPG	✓
4	06/11/19 13:47	General View	1	Load JPG	✓
5	06/11/19 13:47	General View	1	Load JPG	✓
6	06/11/19 13:47	General View	1	Load JPG	✓
7	06/11/19 13:47	General View	1	Load JPG	✓
8	06/11/19 13:47	General View	1	Load JPG	✓
9	06/11/19 13:47	General View	1	Load JPG	✓
10	06/11/19 13:47	General View	1	Load JPG	✓
11	06/11/19 13:47	General View	1	Load JPG	✓
12	06/11/19 13:47	General View	1	Load JPG	✓
13	06/11/19 13:47	General View	1	Load JPG	✓
14	06/11/19 13:47	General View	1	Load JPG	✓
15	06/11/19 13:47	General View	1	Load JPG	✓
16	06/11/19 13:47	General View	1	Load JPG	✓
17	06/11/19 13:47	General View	1	Load JPG	✓
18	06/11/19 13:47	General View	1	Load JPG	✓
19	06/11/19 13:47	General View	1	Load JPG	✓
20	06/11/19 13:47	General View	1	Load JPG	✓
21	06/11/19 13:47	General View	1	Load JPG	✓
22	06/11/19 13:47	General View	1	Load JPG	✓
23	06/11/19 13:47	General View	1	Load JPG	✓
24	06/11/19 13:47	General View	1	Load JPG	✓
25	06/11/19 13:47	General View	1	Load JPG	✓
26	06/11/19 13:47	General View	1	Load JPG	✓
27	06/11/19 13:47	General View	1	Load JPG	✓
28	06/11/19 13:47	General View	1	Load JPG	✓
29	06/11/19 13:47	General View	1	Load JPG	✓
30	06/11/19 13:47	General View	1	Load JPG	✓
31	06/11/19 13:47	General View	1	Load JPG	✓
32	06/11/19 13:47	General View	1	Load JPG	✓
33	06/11/19 13:47	General View	1	Load JPG	✓
34	06/11/19 13:47	General View	1	Load JPG	✓
35	06/11/19 13:47	General View	1	Load JPG	✓
36	06/11/19 13:47	General View	1	Load JPG	✓

Assessment Reports			1 per page	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
37	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
38	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
39	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
40	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
41	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
43	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
44	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
45	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
46	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
47	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
48	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
49	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
50	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
51	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
52	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
53	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
54	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
55	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
56	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
57	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
58	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
59	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
60	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
61	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
62	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
63	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
64	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
65	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
66	06/11/19 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
67	06/11/19 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	06/11/19 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	06/11/19 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	06/11/19 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	06/11/19 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	06/11/19 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	06/11/19 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	06/11/19 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	06/11/19 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	06/11/19 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	09/09/19 14:34	E-filed GIA report	 Load PDF	
2	09/09/19 14:34	WP,DL,CI	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/19 15:33	ESTIMATE	 Load PDF	
2	15/11/19 14:25	SUPPLEMENTARY	 Load PDF	

## Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	07/09/19 13:49	Accident Statement	 Load HTM	

**Assessment Reports**

No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	1 per page ▼	✓
			Thumbnail	Print

**Photos/Images**

No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	3 per page ▼	✓
			Thumbnail	Print
1	07/09/19 13:48	Accident Photo	Load JPG	✓
2	07/09/19 13:48	Accident Photo	Load JPG	✓
3	07/09/19 13:48	Accident Photo	Load JPG	✓
4	07/09/19 13:48	Accident Photo	Load JPG	✓
5	07/09/19 13:48	Accident Photo	Load JPG	✓
6	07/09/19 13:48	Accident Photo	Load JPG	✓
7	07/09/19 13:48	Accident Photo	Load JPG	✓
8	07/09/19 13:48	Accident Photo	Load JPG	✓
9	07/09/19 13:48	Accident Photo	Load JPG	✓

**Documentation**

No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	1 per page ▼	✓
			Thumbnail	Print
1	07/09/19 13:47	Sketch Plan	Load TIF	

**Documents Checklist****DOCUMENTS CHECKLIST**

There are no document checklists configured.

[Reset](#)
[Save](#)
[Print](#)
**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**
**Show Remarks To:** ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd  
5 Maxwell Road, #17-00 Tower Block, MND Complex  
Singapore 069110

Our File No: CS/EQI19015985/R1YF3S2

Date: 15/11/2019

## REFERENCE

Insured/Claimant: HIAP SENG PILING CONSTRUCTION PTE LTD Policy No: DMCPHQ18-007218

Date of Loss: 07/09/2019

Nature of Claim: OD

Claim No: DM19HO02512

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>YN4524J</b>	Engine No:	4P10B00897
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (M)	Chassis No:	FEB21EA00103
Reg. Date:	12/12/2013 (Man. Year: 2013)	Odometer:	290031 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	S\$31,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	205/75 R16	Rear Tyre Size:	205/75 R16 (D)
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7/7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,346.40	6,485.40	3,861.00	37.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,800.00	460.00	20.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,606.40</b>	<b>8,285.40</b>	<b>4,321.00</b>	<b>34.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,600.00</b>		
<b>- Excess (S\$)</b>	0.00	3,750.00	-3,750.00	
<b>(S\$)</b>	12,606.40	2,850.00	9,756.40	77.39
<b>+ GST 7.00/7.00% (S\$)</b>	882.45	199.50	682.95	77.39
<b>Nett Amount (S\$)</b>	<b>13,488.85</b>	<b>3,049.50</b>	<b>10,439.35</b>	<b>77.39</b>

## INSPECTION

Date of Assignment:	10/09/2019 Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	10/09/2019 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Estimated Period of Repair:	7.0 days	Blk 3 Pioneer Road North, #01-18 Singapore 628457

Adjuster: MOHD RASUL

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 15 Nov 2019)	
<b>Parts:</b>	N/A	mitsubishi canter 3.0 D FEB21ER3SDEB (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YN4524J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Cut	20.00 FS	*20.00 FS
2	1		*FRT BUMPER (WCP)	Repair	550.00 F	*- F
3	2		*FRT BUMPER BRACKET (WCP)	Serviceable	220.00 F	*- F
4	2		*FRT BUMPER SIDE GARNISH (WCP)	Cut	420.00 F	*420.00 F
5	1		*FRT HEADLAMP (WCP)	N/s Broken	600.00 F	*300.00 F
6	1		*FRT SIGNAL LAMP (WCP)	N/s Broken	320.00 F	*160.00 F
7	1		*FRT HEADLAMP SEAL(LH) (WCP)	Cut	9.00 F	*9.00 F
8	1		*FRT GRILLE WITH EMBLEM (WCP)	Necessary	550.00 F	*550.00 F
9	1		*FRT GRILLE CENTER RETAINER (WCP)	Bent	17.00 F	*17.00 F
10	10		*FRT GRILLE CLIP (WCP)	Necessary	50.00 F	*50.00 F
11	1		*FRT HORN (WCP)	Bent	70.00 F	*70.00 F
12	1		*FRT HORN COVER (WCP)	Bent	70.00 F	*70.00 F
13	1		*AIRCON HIGH PRESSURE PIPE (WCP)	Serviceable	310.00 F	*- F
14	1		*AIRCON LOW PRESSURE PIPE (WCP)	Bent	280.00 F	*280.00 F
15	1		*FRT CABIN SUPPORT BEAM (WCP)	Serviceable	280.00 F	*- F
16	1		*FRT CABIN SUPPORT BEAM BRACKET(LH) (WCP)	Serviceable	500.00 F	*- F
17	1		*FRT CABIN SUPPORT BEAM BRACKET(RH) (WCP)	Serviceable	450.00 F	*- F
18	2		*FRT CABIN SUPPORT BEAM MOUNTING BUSH (WCP)	Serviceable	260.00 F	*- F
19	1		*FRT PANEL ASSY (WCP)	Bent	1,200.00 F	*1,200.00 F
20	1		*FRT PANEL FUSO LOGO (WCP)	Necessary	70.00 F	*70.00 F
21	1		*FRT WIPER GARNISH (WCP)	Cracked	210.00 F	*210.00 F
22	1		*FRT CORNER PANEL(LH) (WCP)	Cracked	260.00 F	*260.00 F
23	3		*FRT CORNER PANEL LH CLIPS (WCP)	Necessary	18.00 F	*18.00 F
24	1		*FRT SIDE MIRROR ROUND(LH) (WCP)	Cut	35.00 F	*35.00 F
25	1		*FRT WINDSCREEN RUBBER (WCP)	Necessary	220.00 F	*220.00 F
26	1		*ERP BRACKET	Necessary	26.00 FS	*26.00 FS
27	1		*HEATER BLOWER ASSY (WCP)	Cracked	1,100.00 F	*1,100.00 F
28	1		*AIRCON INTAKE BOX (WCP)	Serviceable	480.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
29	1		*FRT CORNER PANEL LH TOP COVER (WCP)	Missing	25.00 F	*25.00 F
30	1		*FRT DOOR STEP GARNISH(LH) (WCP)	Cracked	290.00 F	*290.00 F
<b>Supplementary #1</b>						
31	1		*AIR CON CONDENSER WITH COWLING ASSY (WCP)	Bent	500.00 F	*500.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$)	9,410.00	5,900.00
+ Margin on L,N Items 10.00/10.00% (\$)	936.40	585.40
Total Parts (\$)	10,346.40	6,485.40

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK FLOOR PANEL, WELD, REMOVE & FIX ABOVE PARTS	New	900.00	700.00
2	TO SPRAY PAINTING ON FRT BUMPER, FRT PANEL, FRT GRILLE, FRT WIPER GARNISH, CORNER PANEL (LH), FLOOR PANEL & AFFECTED AREA	New	900.00	700.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO REFILL AIRCON GAS	New	100.00	100.00
5	TO REMOVE & FIX FRT DASHBOARD	New	180.00	150.00
6	TO REMOVE & FIX FRT WINDSCREEN	New	150.00	120.00
<b>Gross Labour Cost (S\$)</b>			<b>2,260.00</b>	<b>1,800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >