

ASS. REC. BY:

Andrew Kenneth

REF:

CS/MSG19016002/K+4302

Special Instructions:

ASSIGNMENT (Office)

From (Person):

Crystal Lee

of

M811

Date/Time:

10/9/19 @ 10:17am

Estimated Cost:

Bill to:

On TP / WS / TP RES / OB RES / EVA / INV / MV / CS

To inspect Vehicle No:

GBF 8321R

Insured:

SJW 6722X

at Workshop m/s

Autowork Hunc

Tel:

6452 8211

of

176 Sn Miney Drive # 02-01

Policy No:

A29121333 70mx

Claim No:

603603

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

20/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:34am @ 10/9/19

Person Contacted:

Yulei

Vehicle

IN/OUT

Date/Time

Action/Instruction

10/9/19

SJW 6722X - X

GBF 8321R NA/INSTRUC 1910/19 02-01/2019

11/9-15

4- Report via maximen preli advice.

23/3

1/1 Rm 8 235d email & confirm (Ref: 3376.30)

ASS. REC. BY:

REF: MSG1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

05

days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

GBF 8321R

Yr Regn: _____

03, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toy Liteac GL

c.c

1495

Colour: _____

White

A/C: Insured / Std / NI / NA

Sp. Reading: _____

52356

T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: _____

S400m

00649P0

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: _____

165R13X8

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. _____

3

mm

Rear

R/Bal. _____

3

mm

L/Bal. _____

3

mm

L/Bal. _____

3

mm

D.O.A. _____

20/8/19

D.O.I. _____

10/9/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Area

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

Date/Time, File Pass to?

303 Typist

Date/Time, File Return to?



: Prel. Report



: Final Report

Days Of Repair: _____

5

Resurvey No. of Trip: _____

Add Fee: _____



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee: _____

Transportation: _____

S - RS. SI

Fees

Others

TOTAL

130

11

161

Report Format: _____

Lump Sum / I.B.I. (\$

2350

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 11 Sep 2019

Preliminary Advice

Insured Vehicle No : SJW6722X

TP Vehicle No : GBF8321R

Make : TOYOTA LITEACE

Date of Inspection : 10/09/2019

Inspection At : AUTOWORX HOUSE - SIN MING (HQ)
176 SIN MING DRIVE #02-01
SINGAPORE 575721

Accident Date : 20/08/2019

Assignment Date : 10/09/2019

Est. Duration of Repair : 5.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,736.30
Revised Amount	:S\$	3,142.58
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,142.58
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Tuesday, 10 September 2019 10:17 AM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui; Helene Phua
Subject: Survey Request - Manual Assigned
Attachments: 10092019100807-0001.pdf

PRE-REPAIR SURVEY REQUEST: Accident involving GBF8321R & SJW6722X on 20/08/2019

Manual Assigned

Dear LKK,

Refer to the attachment, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

AUTOWORX HOUSE

C/O, 176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64520715 FAX: 64529250

ESTIMATE

ADVENTURE WORLD
c/o 46 Lentor Plain
Singapore 786548

Not withain
12/9/19
11/By 82350h
Presman After Rainy
5 days
Date: 9/9/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: TOYOTA LITEACE / GBF 8321 R	
1 pc	rear bumper	Bul/cm 466.90 ✓
1 pc	rear bumper side retainer	cm 26.80 ✓
1 pc	rear end panel	n 478.90 X
1 pc	rear tail door 958.20	By 1,080.30 ✓
1 pc	rear tail door windscreen moulding	nn 116.70 X
1 pc	rear tail light R/H 287.90	Bn 378.40 —
1 pc	rear tail lamp apron panel	By 98.60 —
1 pc	rear tail lamp housing panel	n 456.20 X
1 pc	'logo" emblem	nn 78.60 ✓
1 pc	rear boot weatherstrip	nn 278.50 X
1 pc	'GL" sticker	nn 35.90 —
1 pc	'750kg" sticker	nn 32.60 —
	sub-total	3,528.40
	less 25%	882.10
	sub-total	2,646.30
2 pcs	reverse sensors	nn 440.00 X
1 pc	'5 Pax" Sticker	nn 25.00 121
1 pc	'70km/h" Sticker	nn 25.00 121
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	550f 1,000.00
	To check wiring system.	20f 40.00
	To apply rust proofing on affected areas.	30f 120.00
	To apply waterproof sealant on affected areas.	nn 120.00 X
	To apply putty and spray painting on affected areas.	700f 1,100.00
	To install reverse sensors.	50f 80.00
	To remove rear windscreen glass to enable repair.	120f 140.00
	Total	5,736.30

Link Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modifications is allowed
 • Small monetary fines must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Date: _____
 Name: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19016002/KTD3N2

Date: 01/04/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A291213337QMX

Claimant Vehicle No : GBF8321R

Insured Vehicle No : SJW6722X

Date of Loss: 20/08/2019

Nature of Claim: TP

Claim No: 603603

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF8321R

Make & Model: TOYOTA LITEACE, 1.5 (M)

Engine No: 3SZDGC1493

Reg. Date: 22/03/2017 (Man. Year: 2017)

Chassis No: S402M0064990

Colour: White

Odometer: 52356 km

Engine Capacity: 1495 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 165R13X8

Rear Tyre Size: 165R13X8

Front Left Side: Dunlop 3 mm

Rear Left Side: Dunlop 3 mm

Front Right Side: Dunlop 3 mm

Rear Right Side: Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,136.30	1,513.12	1,623.18	51.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,470.00	1,130.00	43.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,736.30	2,983.12	2,753.18	48.00
Approved Total (Overridden) (S\$)		2,350.00		
Nett Amount (S\$)	5,736.30	2,350.00	3,386.30	59.03

INSPECTION

Date of Assignment: 10/09/2019

Date Inspected: 10/09/2019 Inspected At:

Autoworx House - Sin Ming (HQ)

176 SIN MING DRIVE #02-01

Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Apr 2020)	
Parts:	N/A	TOYOTA LITEACE 1.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF8321R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Cracked	466.90 FL	*466.90 FL
2	1		*REAR BUMPER SIDE RETAINER	Cracked	26.80 FL	*26.80 FL
3	1		*REAR END PANEL	Repair	478.90 FL	*- FL
4	1		*REAR TAIL DOOR	Bent	1,080.30 FL	*958.20 FL
5	1		*REAR TAIL DOOR WINDSCREEN MOULDING	Not Necessary	116.70 FL	*- FL
6	1		*REAR TAIL LIGHT R/H	Broken	378.40 FL	*287.90 FL
7	1		*REAR TAIL LAMP APRON PANEL	Bent	98.60 FL	*98.60 FL
8	1		*REAR TAIL LAMP HOUSING PANEL	Repair	456.20 FL	*- FL
9	1		*LOGO EMBLEM	Necessary	78.60 FL	*78.60 FL
10	1		*REAR BOOT WEATHERSTRIP	Serviceable	278.50 FL	*- FL
11	1		*GL STICKER	Necessary	35.90 FL	*35.90 FL
12	1		*750KG STICKER	Necessary	32.60 FL	*32.60 FL
13	2		*REVERSE SENSORS	Serviceable	440.00 FS	*- FS
14	1		*5 PAX STICKER	Necessary	25.00 FS	*12.00 FS
15	1		*70KM/H STICKER	Necessary	25.00 FS	*12.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,018.40	2,009.50
- List Item Discount on L Items 25.00/25.00% (S\$)	882.10	496.38
Total Parts (S\$)	3,136.30	1,513.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	1,000.00	550.00
2	TO CHECK WIRING SYSTEM	New	40.00	20.00
3	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	120.00	30.00
4	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	120.00	0.00
5	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS	New	1,100.00	700.00
6	TO INSTALL REVERSE SENSORS	New	80.00	50.00
7	TO REMOVE REAR WINDSCREEN GLASS TO ENABLE REPAIR	New	140.00	120.00
Gross Labour Cost (S\$)			2,600.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >