

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19016009/AHA3Q2

**Date:** 27/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SLZ7201L **Insured Vehicle No :** SMN210H

Date of Loss: 02/09/2019 Nature of Claim: TP Claim No: 0289870313SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLZ7201L</b>		
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Engine No:	L13B1419201
Reg. Date:	16/05/2018 (Man. Year: 2018)	Chassis No:	GK31316503
Colour:	Brown	Odometer:	30881 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,302.96	1,109.68	193.28	14.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	630.00	800.00	55.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>2,732.96</b>	<b>1,739.68</b>	<b>993.28</b>	<b>36.34</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,400.00</b>		
<b>(\$\$)</b>	2,732.96	1,400.00	1,332.96	48.77
<b>+ GST 7.00/7.00% (\$\$)</b>	191.31	98.00	93.31	48.77
<b>Nett Amount (\$\$)</b>	<b>2,924.27</b>	<b>1,498.00</b>	<b>1,426.27</b>	<b>48.77</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 09/09/2019

Date Inspected: 09/09/2019 Inspected At:

Kang Car Repairers Pte Ltd (HQ)  
No 1 Kaki Bukit Ave 6, #02-06  
AutoBay@Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	781.60 FL	*540.00 FL
2	1		*FRT BUMPER RETAINER LH	Necessary	34.60 FL	*34.60 FL
3	1		*HEADLAMP LH	Cracked	762.50 FL	*762.50 FL
4	1		*SET FRT BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
					<b>Sub Total (\$)</b>	<b>1,618.70</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	<b>315.74</b>
					<b>Total Parts (\$)</b>	<b>1,302.96</b>
						<b>1,109.68</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	650.00	200.00
2	TO SPRAY PAINTING	New	650.00	400.00
3	TO SPRAY UNDERSEAL	New	80.00	0.00
4	TO CHECK WIRING	New	50.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>1,430.00</b>	<b>630.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**