

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19016015/BBA3Q2

**Date:** 11/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SKA7861A **Insured Vehicle No :** SKE9717A

**Date of Loss:** 30/08/2019 **Nature of Claim:** TP **Claim No:** 5700955837SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKA7861A</b>	Engine No:	27186030179585
Make & Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Chassis No:	WDD2120472A375402
Reg. Date:	14/03/2011 (Man. Year: 2010)	Odometer:	19379 km
Colour:	Black		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,923.91	4,225.71	10,698.20	71.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,430.00	970.00	40.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>17,323.91</b>	<b>5,655.71</b>	<b>11,668.20</b>	<b>67.35</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,500.00</b>		
<b>(\$\$)</b>	17,323.91	4,500.00	12,823.91	74.02
<b>+ GST 7.00/7.00% (\$\$)</b>	1,212.67	315.00	897.67	74.02
<b>Nett Amount (\$\$)</b>	<b>18,536.58</b>	<b>4,815.00</b>	<b>13,721.58</b>	<b>74.02</b>
<b>+ Loss of Use (6.0 x S\$120.00/day) (\$\$)</b>		720.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.49		
<b>Nett Liability (\$\$)</b>		<b>5,542.49</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>5,220.00</b>		

### INSPECTION

Date of Assignment: 09/09/2019

Date Inspected: 10/09/2019 Inspected At:

Teamwork Garage Pte Ltd (HQ)  
53 Ubi Ave 1 #01-24, Paya Ubi  
Industrial Park  
Singapore 408934

Estimated Period of Repair: 4.0 days

---

**Adjuster:** Lim Teow Guan**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	2,064.25 FL	*1,255.00 FL
2	1		*REAR BUMPER RETAINER	Necessary	75.90 FL	*65.00 FL
3	1		*REAR BUMPER INNER GUIDE	Broken	266.80 FL	*266.80 FL
4	1		*REAR BUMPER LOWER GARNISH	Dislodged	286.35 FL	*286.35 FL
5	1		*REAR BUMPER TOW COVER	Not Necessary	98.90 FL	*- FL
6	3		*REAR BUMPER CHROME PROTECTOR	Dislodged (2 PCS ONLY)	583.60 FL	*300.00 FL
7	1		*REAR BUMPER LOWER BRACKET	Not Necessary	75.90 FL	*- FL
8	1		*REAR BUMPER PDC SENSOR HARNESS	Not Necessary	152.95 FL	*- FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	999.35 FL	*666.00 FL
10	1		*END PANEL	Dented	1,554.80 FL	*656.00 FL
11	1		*END PANEL TOP GARNISH	Broken	158.70 FL	*78.00 FL
12	1		*BOOTLID	Repair	3,430.45 FL	*- FL
13	1		*BOOTLID HINGE	Not Necessary	370.30 FL	*- FL
14	1		*BOOTLID INSULATOR	Not Necessary	278.30 FL	*- FL
15	1		*BOOTLID LOCK	Not Necessary	361.10 FL	*- FL
16	1		*BOOTLID LOCK STRIKER	Not Necessary	75.75 FL	*- FL
17	1		*BOOTLID WEATHERSTRIP	Not Necessary	221.95 FL	*- FL
18	1		*BOOTLID EMBLEM -E250	Necessary	93.15 FL	*60.00 FL
19	1		*BOOTLID EMBLEM -CGI	Necessary	94.30 FL	*48.00 FL
20	1		*BOOTLID EMBLEM -LOGO	Necessary	58.65 FL	*48.00 FL
21	1		*BOOTLID OUTER CHROME GARNISH	Not Necessary	142.60 FL	*- FL
22	1		*REAR EXHAUST SILENCER	Not Necessary	2,448.35 FL	*- FL
23	2		*REAR EXHAUST MOUNTING	Not Necessary	42.00 FL	*- FL
24	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
25	1		*END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*30.00 FS
26	4		*REAR BUMPER PDC SENSOR	Dislodged (3 PCS ONLY)	800.00 FS	*225.00 FS
27	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
28	1		*JOINT SEALANT	Necessary	150.00 FS	*60.00 FS
29	1		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
30	1		*REAR LH TAILLAMP	Broken	1,225.50 FL	*582.75 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>16,439.90</b>	<b>4,656.90</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,515.99	431.19
<b>Total Parts (\$)</b>	<b>14,923.91</b>	<b>4,225.71</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE,REFIT REAR LINING ,TRIM AND GARNISH	New	150.00	80.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	60.00
4	REMOVE,REFIT REAR EXHAUST	New	150.00	0.00
5	TRANSFER PARTS ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	0.00
6	PANEL BEATING ON AFFECTED AREAS	New	800.00	600.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	600.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,400.00</b>	<b>1,430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >