

ASS. REC. BY:

REF:

MSG19016018/ Dfd322

Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Crystal Leeof MS19Date/Time: 10/9/19 @ 10:45am

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

3H 6061S

Insured: _____

SMN 8797D

at Workshop m/s _____

Chumi Motor

Tel: _____

6542519

of _____

Amk Autopoint #01-05/06

Policy No: _____

1000897086

Claim No: _____

231080

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. _____

6/9/2019

CA / REV / REP. / REV 24 HRS

rup

H.O.D. Endorsement: _____

Date/Time: _____

11:49am @ 10/9/19

Person Contacted: _____

dgmnVehicle IN / OUT

Date/Time	Action/Instruction	
	3h 6061S	
	3H 6061S-NBA / MSG19015991/F	DOA: 6/9/19
	SMN 8797D-NBA / MSG19015991/F	DOA: 6/9/2019
13/9/19 @ 2:27pm	revised to Christina Wong via messenger.	


REF:

ASSIGNMENT

COE 2023 March

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SM 60613 Yr Regn: 2015 March
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai I40 c.c. 1685
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 571667 T/Radio: Insured / Std / NI / NA
 Eng/No: D4PDPUE03339
 C/No: KMHLB41UMFU065901
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60R16
 R: — 11 —



(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 14 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or W, st lake
 Front Rear
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 06/09/2019 D.O.I. 11/09/2019
 Survey held at Chunni AMC
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MSIG SMN 8797D
	SV 41849.22 as at 6.9.2019
	LTA 32167.00 as at 13.09.2019
	MSV 9682.22
15/10/19	Summ 2/3 15000/- with 14 days & 12 (Red: 20538.02, 57%)

Date/Time, File Pass to? : Preli. Report Days Of Repair: 14
 : Final Report Resurvey No. of Trip: _____
 1) 16/10 Typist
 Date/Time, File Return to? _____
 2) _____
 Report Format : _____
 Lump Sum / I.B.I: (\$) _____

Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech. Invs (\$))
 : Weekend (\$))

Survey Fee: 290
 Transportation: _____
 Photos _____
 Others: 11
 TOTAL: 301

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Tuesday, 10 September 2019 10:45 AM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui; Helene Phua
Subject: Survey Request - Manual Assigned
Attachments: 09092019152905.pdf

Importance: High

Accident involving veh no: SH 6061S & SMN 8797D on 6.09.2019

Manual Assigned

Dear LKK,

Refer to the attachment, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,
Crystal Lee
Admin Officer, Claims Services (In-House Survey)
D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Motor Survey
Sent: Tuesday, 10 September, 2019 9:46 AM
To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Christina Wong <Christina_Wong@sg.msig-asia.com>; Iryani Amin <iryani_amin@sg.msig-asia.com>
Subject: FW: Accident involving veh no: SH 6061S & SMN 8797D on 6.09.2019

@Crystal, outsource to LKK
@ Christina, OIC to take note and check liability
@ Iryani, create TP folder

Have a nice day

Jason Sim
Manager, Claims Services (Motor)
D: +65 6643 1325 | F: +65 6225 7402 | jason_sim@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Chunni Motor [<mailto:chunnimotor@gmail.com>]
Sent: Monday, 9 September, 2019 3:41 PM
To: Motor Survey <motorsurvey@sg.msig-asia.com>
Cc: Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>
Subject: Accident involving veh no: SH 6061S & SMN 8797D on 6.09.2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor,#01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Please appoint your In house surveyors

Thank you for your kind assistance.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

ASSESSMENT OF DAMAGES: ~~\$30,000.00~~ \$15,000/-

BOOK VALUE AS AT 11.02.2019: ~~\$34,322.26~~ (est) 41,849.22

LTA REBATE AS AT 03.01.2019: ~~\$27,872.00~~ 32,167.00

NET BOOK VALUE: ~~\$6,440.26~~ 9682.22

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 13 Sep 2019

Preliminary Advice

Insured Vehicle No	: SMN8797D	Accident Date	: 06/09/2019
TP Vehicle No	: SH6061S	Assignment Date	: 10/09/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 10.00
Date of Inspection	: 11/09/2019		
Inspection At	: SOON HOCK MOTOR PTE LTD (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05/06 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,485.14
Revised Amount	:S\$	26,302.54
Check Items (Estimated)	:S\$	0.00
Total	:S\$	26,302.54

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SH6061S
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7L CRDI AT ABS AIRBAG 4DR
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	D4DFDU503339
Chassis No.:	KMHLB41UMFU065901
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$20,223.00
Original Registration Date:	26 Mar 2015
First Registration Date:	26 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$12,813.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Mar 2023
PARF Rebate Amount:	\$9,609.00
Intended COE Rebate Details	
COE Expiry Date:	25 Mar 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,092.00
COE Rebate Amount:	\$22,490.00
Total Rebate Amount:	\$32,099.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Sep 2019

Book value ≈ \$46,000

OK

MC0819118836 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 09/09/2019 07:32
 SUBMITTED BY: Catherine Por May Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/09/2019 07:32
Date Of Accident	06/09/2019 22:05
Exact Location Of Accident	ECP TWDS CITY NEAR 12.7KM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH6061S
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFTY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	TAN TOH SAN
NRIC No	S0379917D
Date Of Birth	31/07/1945
Occupation	OUTDOOR
Date Of Driving Pass	16/07/1964
Driving Experience	55 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96279852
Fax Number	
Contact Number	
EMail Address	NOEMAIL

4/ 6

Vehicle Category: PRIVATE CAR
Name of Driver: BALASUBRAMANIAM S/O THIRIVALLINGAM
NRIC/Passport Number: 90505877
Contact Number: 90505877
Address:
Postcode:
Insurance Company Name: FRT
Nature Of Damage: FRT
No. Of Passenger (including Driver):

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number: SL075150

Vehicle Make/Model/Colour:

Details Of Properties: PRIVATE CAR

Vehicle Category: PRIVATE CAR

Name of Driver:

NRIC/Passport Number:

Contact Number:

Address:

Postcode:

Insurance Company Name: FRT

Nature Of Damage: FRT

No. Of Passenger (including Driver):

DETAILS OF INJURED PERSON 1

Name: JAMILI SUFFIANS

Approximate Age: BACK

Injuries Sustain: SH6281S

Injured person in which vehicle? 7

Were seat belts worn? NO

Was this injured conveyed to hospital by ambulance? NO

Address:

Postcode:

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time: 7/9/2019


Driver's Signature
(If driver is not the policyholder)
Date & Time: 7/9/2019@11:15hrs

Lisa
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: -

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 6061 S

DATE : 7/09/2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

MSIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>bnc</i>			\$ 2,174.90
	Boot Lid Rubber <i>damaged</i>			\$ 96.50
	Boot Lid Hinge (LH/RH) <i>1st</i>	\$	142.30	\$ 284.60
	Boot Lid Lock Upper <i>D-m</i>			\$ 102.60
	Boot Lid Lock Lower <i>1st</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>nec</i>			\$ 28.70
	Boot Lid CRDI Plate <i>nec</i>			\$ 27.90
	Boot Lid Lamp (LH/RH) <i>crack</i>	\$	565.60	\$ 1,131.20
	Licence Lamp (LH/RH) <i>broken/damaged</i>	\$	33.95	\$ 67.90
	Boot Lid Absorber <i>HN</i>			\$ 65.65
	Boot Lid Trimboard <i>damaged/torn</i>			\$ 116.40
	Boot Lid Trimboard Clips (10pcs) <i>nec</i>			\$ 11.00
	Bootlid Moulding <i>broken</i>			\$ 85.00
	Bootlid i40 Emblem <i>nec</i>			\$ 27.90
	Bootlid Lower Garnish <i>broken</i>			\$ 227.90
	Rear Bumper <i>broken/damaged</i>			\$ 553.00
	Rear Bumper Reinforcement <i>broken</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>Dental</i>	\$	80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>nec</i>			\$ 22.00
	Rear Bumper Bracket <i>HN o/s N/S damaged/broken</i>	\$	35.60	\$ 71.20
	Rear Bumper Sponge <i>damaged/torn</i>			\$ 118.40
	Rear Bumper Under Cover <i>damaged</i>			\$ 228.00
	Rear Bumper Reflector Lamp (LH/RH) <i>damaged HN</i>	\$	30.60	\$ 61.20
	Rear Panel <i>bnc</i>			\$ 526.70
	Rear Panel Garnish <i>1st</i>			\$ 57.70
	Rear Panel Lower Panel <i>bnc</i>			\$ 495.50
	Spare Tyre Holder <i>1st</i>			\$ 223.10
	Tail Lamp Panel Top (LH/RH) <i>HN</i>	\$	545.90	\$ 1,091.80
	Tail Lamp Lower Panel (LH/RH) <i>N/S bnc o/s Dental</i>	\$	225.60	\$ 451.20
	Spare Tyre Panel <i>bnc</i>			\$ 852.80
	Spare Tyre Panel Cushion <i>1st/damaged</i>			\$ 209.05
	Rear Towing Hook <i>HN</i>			\$ 94.60
	Member Assy- Rear Floor Centre <i>HN</i>			\$ 570.40
	Panel Assy-Rear Floor Side (LH) <i>1st bnc</i>			\$ 90.10
	Rear Floor Chassis Member (LH) <i>1st bnc</i>			\$ 1818.10
	Exhaust Pipe Insulator <i>1st/crumpled</i>	\$	58.55	\$ 117.10
	Exhaust Silencer <i>N/S 1st o/s 1st</i>	\$	967.70	\$ 1,935.40
	Exhaust Pipe Hanger <i>HN</i>	\$	58.55	\$ 117.10
	Exhaust Pipe Centre <i>1st</i>			\$ 730.10
	Rear Fender With Housing (LH/RH) <i>o/s Dental n/s bnc</i>	\$	4,736.80	\$ 9,473.60
	Rear Fender Inner Lining (LH/RH) <i>HN without housing</i>	\$	169.30	\$ 338.60
	Rear Windscreen Moulding <i>nec</i>			\$ 28.30
	Rear Door Outer Moulding (LH) <i>HN</i>			\$ 35.80
	Rear Door 1/4 Glass Pillar (LH) <i>HN</i>			\$ 80.90
	Fuel Tank <i>HN</i>			\$ 962.90
	Fuel Tank Sub Hose <i>HN</i>			\$ 78.20
	Fuel Tank Upper Neck <i>HN</i>			\$ 221.10

Handwritten checkmarks and 'X' marks in the right margin of the table, indicating the status of each item.

6757.

SH 6061S

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Fuel Lid Cover <i>broken / distorted pl</i>			\$ 70.90 ✓
	Fuel Lid Outer Garnish <i>NH</i>			\$ 59.40 X
	Rear Tyre Rim (LH) <i>distorted</i>			\$ 325.30 ✓
	Rear Wheel Hup-Cap (LH) <i>cut</i>			\$ 107.10 ✓
	Rear Wheelbearing ING & Hub - LH <i>Distorted</i>			\$ 362.00 ✓
	Rear Trailing Arm (LH) <i>distorted</i>			\$ 192.00 ✓
	Rear Assist (LH) <i>distorted</i>			\$ 145.70 ✓
	Rear Shock Absorber (LH) <i>distorted</i>			\$ 276.30 ✓
	Rear Shock Absorber Mounting (LH) <i>NH</i>			\$ 81.30 X
	Rear Crossmember <i>BT</i>			\$ 1,021.50 ✓
	Stabilizer Bar <i>NH BT</i>			\$ 199.60 ✓
	Stabilizer Link <i>distorted NH</i>			\$ 85.90 X
	Rear Upper Arm (LH) <i>distorted</i>			\$ 335.75 ✓
	Rear Lower Arm (LH) <i>distorted</i>			\$ 353.80 ✓
	Rear Knuckle Arm (LH) <i>distorted</i>			\$ 545.60 ✓
	SUB TOTAL			\$ 32,703.05
	LESS 20%			\$ 6,540.61
	DISCOUNTED TOTAL			\$ 26,162.44
	Boot Lid Comfort Logo & Tel No. Sticker <i>Nec</i>			\$ 30.00 Nett ✓
	Rear No. Plate <i>broken</i>			\$ 25.00 Nett ✓
	Rear Bumper Reverse Sensor <i>distorted</i>			\$ 135.70 Nett ✓
	Rear Bumper Advertisement Logo <i>NH</i>			\$ 50.00 Nett X
	Rear Bumper Rubber Mat <i>NF</i>			\$ 50.00 Nett XXX X
	Rear Windscreen Sealant <i>Nec</i>			\$ 46.00 Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>Nec</i>			\$ 80.00 Nett ✓
	Rear Tyre (LH) <i>S/L</i>			\$ 216.00 Nett X
				\$ 632.70
	Labour Charge			
	Panel Beating			\$ 2,400.00 1200/-
	Spray Painting Charge			\$ 1,800.00 1000/-
	Wiring Charge			\$ 100.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Towing Fees			\$ 50.00 NH
	Rear Chassis Alignment Charge			\$ 400.00 ≈ 150/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Undercarriage (Rear)			\$ 200.00 ≈ 150/-
	Remove/Refix Fuel Tank			\$ 150.00 NH
	Remove/Refix Exhaust Pipe			\$ 300.00 60/-
	Rear Wheel Alignment			\$ 120.00 60/-
	Re-set Rear ABS System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 150/-
				\$ 6,690.00
	TOTAL LABOUR			\$ 6,690.00
	ESTIMATE TOTAL			\$ 33,485.14

24249.10

19399.28

366.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____

Handwritten signature and date: 16/9/19

3040.00

22805.98

1952.88

24758.86

R/S 15000/-

11/09/2019 @ 1400pm
N/A Invoice
2/1 same

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Handwritten notes at bottom: JKK Auto

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 6061S (Supplementary)

DATE : 17/09/2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door (LH) <i>Paint 1st</i>			\$ 2,201.10 ✓
	Rear Door Lock Assy <i>Done</i>			\$ 240.00 ✓
	SUB TOTAL			\$ 2,441.10
	LESS 20%			\$ 488.22
	DISCOUNTED TOTAL			\$ 1,952.88
			<i>2441.10</i>	
			<i>1952.88</i>	
	Rear Door Advertisement Logo (LH) <i>N/A, NF</i>			\$ 100.00 <i>Nett</i>
	ESTIMATE TOTAL			\$ 2,052.88
				<i>35538.02</i>

[Signature]
2 KK Ando
17/09/2019

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Sep 2019		10 Sep 2019 18:40 Edit Adj Rpt	S\$15,000.00 Edit Estimates	S\$15,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	Balasubramaniam s/o Tharmalinggam, ID: S7626099], Tel: +6590905877, Email: tbalahome@gmail.com								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SH6061S	Date of Loss: 06/09/2019 22:00 - :59 [53 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 231080	Policy/Cover Note No.: 1000897086 (Comprehensive) Coverage: 27/01/2019 - 26/01/2020							
Vehicle Reg. No. (Insured):	SMN8797D	Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer:	Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 10/10/2019]								
Driver/Custodian (Insured):	BALASUBRAMANIAN S/O THARMALINGGAM (43 / Male) , NRIC: S7626099], Tel: +6590905877 Email: TBALAHOME@GMAIL.COM								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 10/09/19. (Manual Assign). Liab: NA. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lynn or Ms Irene at 65425119 / 6542 7162								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SH6061S (231080)**
[SMN8797D]
TP
COMFORT TRANSPORTATION PTE LTD
Sep 6 2019 10:00PM
[Balasubramaniam s/o Tharmalingam]
Soon Hock Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>		
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print		
1	13/09/19 14:27	Adjuster Immediate Advice				Load HTM		
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print		
1	12/10/19 13:07	Rear View Right				Load JPG	<input checked="" type="checkbox"/>	
2	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
3	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
4	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
5	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
6	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
7	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
8	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
9	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
10	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
11	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
12	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
13	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
14	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
15	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
16	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
17	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
18	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
19	12/10/19 13:07	General View				Load JPG	<input checked="" type="checkbox"/>	
20	12/10/19 13:08	Rear View Left				Load JPG	<input checked="" type="checkbox"/>	
21	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
22	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
23	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
24	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
25	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
26	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
27	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
28	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
29	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
30	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
31	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
32	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
33	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
34	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
35	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
36	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
37	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
38	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
39	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	
40	12/10/19 13:10	General View				Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
54	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
55	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
56	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
57	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
58	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
59	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
60	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
61	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
62	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
63	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
64	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
65	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
66	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
67	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
68	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
69	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
70	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
71	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
72	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
73	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
74	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
75	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
76	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
77	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
78	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
79	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
80	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
81	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
82	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
83	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
84	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
85	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
86	12/10/19 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
87	12/10/19 13:10	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
88	12/10/19 13:10	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
89	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	12/10/19 13:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
152	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
153	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
154	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
155	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
156	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
157	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
158	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
159	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
160	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
161	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
162	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
163	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
164	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
165	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
166	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
167	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
168	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
169	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
170	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
171	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
172	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
173	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
174	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
175	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
176	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
177	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
178	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
179	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
180	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
181	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
182	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
183	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
184	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
185	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
186	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
187	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
188	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
189	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
190	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
191	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
192	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
193	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
194	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
195	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
196	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
197	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
198	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
199	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
200	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
201	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
202	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
203	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
204	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
205	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
206	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
207	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
208	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
209	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
210	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
211	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
212	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
213	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
214	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
215	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
216	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
217	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
218	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
219	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
220	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
221	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
222	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
223	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
224	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
225	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
226	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
227	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
228	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
229	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
230	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
231	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
232	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
233	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
234	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
235	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
236	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
237	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
238	12/10/19 13:12	Reinspection Photo		<input checked="" type="checkbox"/>
239	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
240	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
241	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
242	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
243	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
244	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
245	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
246	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
247	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
248	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
249	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
250	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
251	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
252	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
253	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
254	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
255	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
256	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
257	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>
258	12/10/19 13:13	After Repair Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/09/19 13:41	OI SMN8797D GIA REPORT		<input type="checkbox"/>
2	10/09/19 13:41	TPD SH6061S GIA REPORT		<input type="checkbox"/>
3	10/09/19 13:41	TPD SH6061S - ESTIMATE REPAIR		<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
4	10/09/19 13:41	TPD SH6061S - PRI		Load PDF
5	10/09/19 14:07	STATUS OF DRIVING LICENCE (OI)		Load PDF
6	10/09/19 14:54	Manual Assignment		Load PDF
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail Print
1	10/09/19 18:38	Survey Request - Manual Assigned		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	17/10/19 16:49	Supplementary		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19016018/DTD3E2

Date: 17/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1000897086
Claimant	Insured Vehicle No :	SMN8797D
Vehicle No : SH6061S		
Date of Loss: 06/09/2019	Nature of Claim:	TP Claim No: 231080

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH6061S	Engine No:	D4DFDU503339
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMFU065901
Reg. Date:	26/03/2015 (Man. Year: 2014)	Odometer:	571667 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,848.02	21,619.90	7,228.12	25.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,690.00	3,040.00	3,650.00	54.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,538.02	24,659.90	10,878.12	30.61
Approved Total (Overridden) (S\$)		15,000.00		
(S\$)	35,538.02	15,000.00	20,538.02	57.79
+ GST 7.00/7.00% (S\$)	2,487.66	1,050.00	1,437.66	57.79
Nett Amount (S\$)	38,025.68	16,050.00	21,975.68	57.79

INSPECTION

Date of Assignment:	10/09/2019	
Date Inspected:	11/09/2019 Inspected At:	Chunni Motor Work Pte Ltd Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint Singapore 568047
Estimated Period of Repair:	14.0 days	

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

ASSESSMENT OF DAMAGES: \$15,000.00

BOOK VALUE AS AT 06.09.2019 : \$41,849.22 (EST)

LTA REIMBURSEMENT VALUE AS AT:13.09.2019: \$32,167.00

NETT VALUE: \$9,682.22

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2019)
Parts: 143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SH6061S)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Buckled	2,174.90 FL	*2,174.90 FL
2	1		*BOOT LID RUBBER	Deformed	96.50 FL	*96.50 FL
3	2		*BOOT LID HINGE (LH/RH)	Bent	284.60 FL	*284.60 FL
4	1		*BOOT LID LOCK UPPER	Damaged	102.60 FL	*102.60 FL
5	1		*BOOT LID LOCK LOWER	Bent	31.70 FL	*31.70 FL
6	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
7	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
8	2		*BOOT LID LAMP (LH/RH)	Cracked	1,131.20 FL	*1,131.20 FL
9	2		*LICENCE LAMP (LH/RH)	Broken / Dislodged	67.90 FL	*67.90 FL
10	1		*BOOT LID ABSORBER	Not Necessary	65.65 FL	*- FL
11	1		*BOOT LID TRIMBOARD	Deformed / Torn	116.40 FL	*116.40 FL
12	10		*BOOT LID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
13	1		*BOOTLID MOULDING	Broken	85.00 FL	*85.00 FL
14	1		*BOOTLID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
15	1		*BOOTLID LOWER GARNISH	Broken	227.90 FL	*227.90 FL
16	1		*REAR BUMPER	Broken / Dislodged	553.00 FL	*553.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Broken	428.40 FL	*428.40 FL
18	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Dented	160.60 FL	*160.60 FL
19	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
20	1		*REAR BUMPER BRACKET (O/S NOT NECESSARY)	N/S Dislodged / Broken	71.20 FL	*35.60 FL
21	1		*REAR BUMPER SPONGE	Dislodged / Torn	118.40 FL	*118.40 FL
22	1		*REAR BUMPER UNDER COVER	Dislodged	228.00 FL	*228.00 FL
23	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Not Necessary	61.20 FL	*- FL
24	1		*REAR PANEL	Buckled	526.70 FL	*526.70 FL
25	1		*REAR PANEL GARNISH	Bent	57.70 FL	*57.70 FL
26	1		*REAR PANEL LOWER PANEL	Buckled	495.50 FL	*495.50 FL
27	1		*SPARE TYRE HOLDER	Bent	223.10 FL	*223.10 FL
28	2		*TAIL LAMP PANEL TOP (LH/RH)	Not Necessary	1,091.80 FL	*- FL
29	2		*TAIL LAMP PANEL (LH/RH)	N/S Buckled / O/S Dented	451.20 FL	*451.20 FL
30	1		*SPARE TYRE PANEL	Buckled	852.80 FL	*852.80 FL
31	1		*SPARE TYRE PANEL CUSHION	Bent / Deformed	209.05 FL	*209.05 FL
32	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
33	1		*MEMBER ASSY-REAR FLOOR CENTRE	Not Necessary	570.40 FL	*- FL
34	1		*PANEL ASSY-REAR FLOOR SIDE (LH)	Buckled	90.10 FL	*90.10 FL
35	1		*REAR FLOOR CHASSIS MEMBER (LH)	Buckled	3,636.20 FL	*1,818.10 FL
36	2		*EXHAUST PIPE INSULATOR	Bent / Crumpled	117.10 FL	*117.10 FL
37	2		*EXHAUST SILENCER	Bent	1,935.40 FL	*1,935.40 FL
38	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
39	1		*EXHAUST PIPE CENTRE	Bent	730.10 FL	*730.10 FL
40	2				9,473.60 FL	*6,757.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*REAR FENDER WITH HOUSING (LH/RH) (N/S BUCKLED)	O/S Dented without housing		
41	2		*REAR FENDER INNER LINING (LH/RH)	Not Necessary	338.60 FL	*- FL
42	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
43	1		*REAR DOOR OUTER MOULDING (LH)	Not Necessary	35.80 FL	*- FL
44	1		*REAR DOOR 1/4 GLASS PILLAR (LH)	Not Necessary	80.90 FL	*- FL
45	1		*FUEL TANK	Not Necessary	962.90 FL	*- FL
46	1		*FUEL TANK SUB HOSE	Not Necessary	78.20 FL	*- FL
47	1		*FUEL TANK UPPER NECK	Not Necessary	221.10 FL	*- FL
48	1		*FUEL LID COVER	Broken / Dislodged	70.90 FL	*70.90 FL
49	1		*FUEL LID OUTER GARNISH	Not Necessary	59.40 FL	*- FL
50	1		*REAR TYRE RIM (LH)	Distorted	325.30 FL	*325.30 FL
51	1		*REAR WHEEL HUP-CAP (LH)	Cut	107.10 FL	*107.10 FL
52	1		*REAR WHEELBEARING ING & HUB - LH	Damaged	362.00 FL	*362.00 FL
53	1		*REAR TRAILING ARM (LH)	Distorted	192.00 FL	*192.00 FL
54	1		*REAR ASSIST (LH)	Distorted	145.70 FL	*145.70 FL
55	1		*REAR SHOCK ABSORBER (LH)	Distorted	276.30 FL	*276.30 FL
56	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Not Necessary	81.30 FL	*- FL
57	1		*REAR CROSSMEMBER	Bent	1,021.50 FL	*1,021.50 FL
58	1		*STABILIZER BAR	Bent	199.60 FL	*199.60 FL
59	1		*STABILIZER LINK	Not Necessary	85.90 FL	*- FL
60	1		*REAR UPPER ARM (LH)	Distorted	335.75 FL	*335.75 FL
61	1		*REAR LOWER ARM (LH)	Distorted	353.80 FL	*353.80 FL
62	1		*REAR KNUCKLE ARM (LH)	Distorted	545.60 FL	*545.60 FL
63	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER	Necessary	30.00 FS	*30.00 FS
64	1		*REAR NO. PLATE	Broken	25.00 FS	*25.00 FS
65	1		*REAR BUMPER REVERSE SENSOR	Dislodged	135.70 FS	*135.70 FS
66	1		*REAR BUMPER ADVERTISEMENT LOGO	Not Necessary	50.00 FS	*- FS
67	1		*REAR BUMPER RUBBER MAT	Not fitted	50.00 FS	*- FS
68	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
69	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
70	1		*REAR TYRE (LH)	Serviceable	216.00 FS	*- FS
71	1		*REAR DOOR (LH)	Dented / Bent	2,201.10 FL	*2,201.10 FL
72	1		*REAR DOOR LOCK ASSY	Damaged	240.00 FL	*240.00 FL
73	1		*REAR DOOR ADVERTISEMENT LOGO (LH)	Not fitted	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **35,876.85** **26,945.70**
 - List Item Discount on L Items 20.00/20.00% (\$\$) 7,028.83 5,325.80

Total Parts (\$\$) 28,848.02 21,619.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,400.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,800.00	1,000.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING FEES	New	50.00	0.00
6	REAR CHASSIS ALIGNMENT CHARGE	New	400.00	150.00
7	REMOVE / REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
8	REMOVE / REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
9	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
10	REMOVE / REFIX UNDERCARRIAFE (REAR)	New	200.00	150.00
11	REMOVE / REFIX FUEL TANK	New	150.00	0.00
12	REMOVE / REFIX EXHAUST PIPE	New	300.00	60.00
13	REAR WHEEL ALIGNMENT	New	120.00	60.00
14	RE-SET REAR ABS SYSTEM }	New	200.00	150.00
15	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	0.00
Gross Labour Cost (S\$)			6,690.00	3,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >