

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19016023/KDS3Q2

Date: 12/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800085528

Claimant
Vehicle No : SDZ6779M **Insured Vehicle No :** SMC7119B

Date of Loss: 07/09/2019 Nature of Claim: TP Claim No: 5203593168SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDZ6779M		
Make & Model:	TOYOTA COROLLA AXIO, 1.5 X (M)	Engine No:	1NZE8217377
Reg. Date:	17/08/2017 (Man. Year: 2017)	Chassis No:	NZE1617124378
Colour:	Metallic Gold	Odometer:	67506 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,472.42	1,376.42	1,096.00	44.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,770.00	1,380.00	390.00	22.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,242.42	2,756.42	1,486.00	35.03
+ GST 7.00/7.00% (\$\$)	296.97	192.95	104.02	35.03
Nett Amount (\$\$)	4,539.39	2,949.37	1,590.02	35.03
+ Loss of Use (7.0 x S\$100.00/day) (\$\$)		700.00		
+ Doc/Search Fee (\$\$)		8.00		
Nett Liability (\$\$)		3,657.37		

INSPECTION

Date of Assignment: 09/09/2019

Date Inspected: 13/09/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	684.80 FL	*684.80 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Cracked	92.33 FL	*92.33 FL
3	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
4	1		*REAR BUMPER RH REFLECTOR	Cracked	56.90 FL	*56.90 FL
5	1		*RH TAILLAMP	Buckled	548.10 FL	*548.10 FL
6	1		*RH TAILLAMP PANEL	Repair	133.90 FL	*- FL
7	1		*RH TAILLAMP LOWER RETAINER	Cracked	89.90 FL	*89.90 FL
8	1		*REAR RH FENDER	Repair	989.20 FL	*- FL
9	1		*REAR RH FENDER INNER AIR SCROP GRILLE	Distorted	49.40 FL	*49.40 FL
10	1		*REAR RH FENDER INNER GARNISH	Deformed	292.80 FL	*292.80 FL
11	1		*REAR BOOT RUBBER	Serviceable	187.10 FL	*- FL
12	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	97.80 FL	*- FL
13	1		*REAR WINDSCREEN GLASS GUM	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,283.23	1,835.23
- List Item Discount on L Items 25.00/25.00% (\$)	810.81	458.81
Total Parts (\$)	2,472.42	1,376.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
2	REMOVE & REFIX REAR SEAT CARPET GARNISH TOP ROOF LININ ,ETC	New	120.00	50.00
3	REMOVE & REFIX REAR BUMPER ASSY ,RH TAILLAMP ,CUT,WELD & RENEW REAR RH FENDER ,RH TAILLAMP PANEL & REALIGN THE SAME	New	800.00	700.00
4	PUTTY & RESPRAY ON REAR RH FENDER ,RH TAILLAMP PANEL ,REAR BUMPER	New	700.00	600.00
5	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,770.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >