

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19016025/KGA3Q2

**Date:** 12/08/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SFV3249T	<b>Insured Vehicle No :</b>	SHB4492G
Date of Loss: 08/09/2019	Nature of Claim: TP	Claim No: MCT19090182

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFV3249T	Engine No:	FB20YE29947
Make & Model:	SUBARU FORESTER, 2.0 (A)	Chassis No:	JF1SJ5KC5JG111838
Reg. Date:	21/11/2018 (Man. Year: 2018)	Odometer:	12333 km
Colour:	Metallic Silver		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,243.36	1,235.68	1,007.68	44.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	1,160.00	370.00	24.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>3,773.36</b>	<b>2,395.68</b>	<b>1,377.68</b>	<b>36.51</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,900.00</b>		
<b>(\$\$)</b>	3,773.36	1,900.00	1,873.36	49.65
<b>+ GST 7.00/7.00% (\$\$)</b>	264.14	133.00	131.14	49.65
<b>Nett Amount (\$\$)</b>	<b>4,037.50</b>	<b>2,033.00</b>	<b>2,004.50</b>	<b>49.65</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment:	09/09/2019	
Date Inspected:	12/09/2019 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Aug 2020)
<b>Parts:</b>	M1-SUV	SUBARU FORESTER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFV3249T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Dented / Cut	600.30 FL	*600.30 FL
2	1	*REAR BUMPER LH SIDE RETAINER	Serviceable	29.80 FL	*- FL
3	6	*REAR BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
4	1	*REAR LH WHEEL ARP GARNISH	Cut	170.90 FL	*170.90 FL
5	1	*REAR LH DOOR	Repair	790.60 FL	*- FL
6	1	*REAR LH DOOR LOWER MOULDING	Serviceable	190.90 FL	*- FL
7	1	*REAR LH DOOR FRAME STICKER -FRT VERTICAL	Not Necessary	24.50 FL	*- FL
8	1	*REAR LH DOOR FRAME STICKER -REAR VERTICAL	Not Necessary	19.10 FL	*- FL
9	1	*REAR LH DOOR FRAME STICKER -TOP	Not Necessary	13.90 FL	*- FL
10	1	*FRONT LH DOOR LOWER MOULDING	Serviceable	190.80 FL	*- FL
11	1	*REAR LH SPORT RIM	Dented	750.00 FL	*750.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,804.20</b>	<b>1,544.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>560.84</b>	<b>308.92</b>
<b>Total Parts (S\$)</b>	<b>2,243.36</b>	<b>1,235.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REMOVE & REFIX REAR BUMPER ASSY ,REAR LH DOOR & ATTACHMENT ,KNOCK & REPAIR FRT LH DOOR & REALIGN THE SAME	New	600.00	480.00
2	PUTTY & RESPRAY ON REAR BUMPER ,FRT & REAR LH DOOR & ALL AFFECTED AREAS	New	800.00	600.00
3	TO CHECK REAR LH UNDERCARRIAGE & COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
4	REMOVE & REFIX REAR LH SPORT RIM	New	40.00	20.00
5	RUSTPROOFING	New	30.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,530.00</b>	<b>1,160.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**