





# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Spare Parts

Vehicle No. : SLU 7377 P  
 Make & Model : TOYOTA PRIUS  
 Chassis No : JTDKB3FU303564710

Submit By : SERENCE  
 Year Manufacture : 2017  
 Engine No. : \_\_\_\_\_

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	X
2	Rear bumper	1	\$497.50		X
3	Rear bumper clip	10	\$40.00		X
4	Rear bumper side retainer LH	1	\$112.70		X
5	Rear bumper side retainer RH	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		X
7	Rear bumper lower garnish centre	1	\$582.60		X
8	Rear bumper lower garnish LH	1	\$149.70		X
9	Rear bumper lower garnish RH	1	\$149.70		X
10	Rear bumper tow cover	1	\$31.70		X
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : SLU 7377 P Submit By : SERENCE  
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$800.00	1200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$800.00	2200
3	To tuff coat. <i>na</i>	\$50.00	X
4	TO Check wiring <i>na</i>	\$50.00	X
5	To remove & refit reverse sensor <i>na</i>	\$150.00	X
6	To conduct water leakage tests to ensure proper air and sealing <i>na</i>	\$120.00	X
7	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>na</i>	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.