

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19016034/AKA3Q2

Date: 28/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100449357

Claimant
Vehicle No : SJQ526S **Insured Vehicle No :** SKZ4413Z

Date of Loss: 05/09/2019 Nature of Claim: TP Claim No: 0432086098SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ526S	Engine No:	M16A1444363
Make & Model:	SUZUKI SX4, 1.6 NB (A)	Chassis No:	JSAGYC21S00202830
Reg. Date:	23/04/2009 (Man. Year: 2008)	Odometer:	111806 km
Colour:	Black		
Engine Capacity:	1586 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Gremax 6 mm	Rear Left Side:	Gremax 6 mm
Front Right Side:	Gremax 6 mm	Rear Right Side:	Gremax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,912.11	3,859.41	3,052.70	44.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,450.00	2,280.00	2,170.00	48.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,362.11	6,139.41	5,222.70	45.97
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	11,362.11	4,900.00	6,462.11	56.87
+ GST 7.00/7.00% (S\$)	795.35	343.00	452.35	56.87
Nett Amount (S\$)	12,157.46	5,243.00	6,914.46	56.87
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,610.45		
Global Sum Settlement (S\$)		5,610.00		

INSPECTION

Date of Assignment: 09/09/2019

Date Inspected: 09/09/2019 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B,
VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	688.30 FL	*688.30 FL
2	2		*FRONT BUMPER SIDE RETAINER	Necessary	124.80 FL	*64.00 FL
3	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	190.00 FL	*- FL
4	1		*CENTRE GRILLE	Cracked	420.00 FL	*196.00 FL
5	1		*CENTRE GRILLE LOGO	Necessary	80.00 FL	*45.00 FL
6	1		*HEADLAMP RH	Cracked	422.30 FL	*422.30 FL
7	1		*BOOTLID	Repair	850.00 FL	*- FL
8	1		*BOOTLID LOGO	Necessary	80.00 FL	*40.00 FL
9	1		*BOOTLID SX4	Necessary	60.00 FL	*42.00 FL
10	1		*REAR BUMPER	Deformed	530.00 FL	*530.00 FL
11	1		*REAR BUMPER SIDE RETAINER	Necessary	55.00 FL	*55.00 FL
12	1		*REAR BUMPER REFLECTOR	N/S Cracked	160.00 FL	*80.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	350.00 FL	*257.00 FL
14	1		*REAR END PANEL	Repair	366.20 FL	*- FL
15	1		*REAR END PANEL TOP GARNISH	Cracked	160.00 FL	*160.00 FL
16	1		*TAILLAMP	N/S Cracked	760.00 FL	*255.00 FL
17	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
18	1		*SET FRONT BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
19	1		*FRONT BUMPER LOWER LID	Cracked	850.00 FS	*600.00 FS
20	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
21	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
22	1		*REAR BUMPER LOWER LID	Deformed	1,050.00 FS	*600.00 FS
23	1		*REAR END PANEL SEALANT	Not Necessary	150.00 FS	*- FS
24	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
25	1		*REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,706.60	4,284.60
- List Item Discount on L Items 15.00/15.00% (\$\$)	794.49	425.19
Total Parts (\$\$)	6,912.11	3,859.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	New	2,000.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,200.00
3	TUFF COAT	New	250.00	0.00
4	WIRING AND BULB CHECK	New	80.00	30.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	50.00
Gross Labour Cost (\$\$)			4,450.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >