Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19016041/EBA3Q2

110415 km

Date: 16/07/2020

Odometer:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800130512

Claimant
Vehicle No: SG5802H Insured Vehicle No: SDG2121L

Date of Loss: 04/09/2019 Nature of Claim: TP Claim No: 6223719701SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SG5802H

 Make & Model:
 MAN A95, 10.5 D (A)
 Engine No:
 50344422604450

 Reg. Date:
 07/03/2017 (Man. Year: 2016)
 Chassis No:
 WMAA95ZZ9G7003444

Colour: Multi-colour Engine Capacity: 10518 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,512.90	211.50	1,301.40	86.02
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,927.00	1,241.00	686.00	35.60
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	3,439.90	1,452.50	1,987.40	57.77

+ Loss of Use (2.0 x S\$350.00/day) (S\$) 700.00

(\$\$) 2,152.50 Liable Amount (50.00%) (\$\$) 1,076.25 + Doc/Search Fee (\$\$) 7.00

Nett Liability (S\$) 1,083.25

Global Sum Settlement (S\$) 1,050.00

INSPECTION

Date of Assignment: 09/09/2019

Date Inspected: 09/09/2019 Inspected At: SMRT Automotive Services Pte Ltd

(Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster Report Page 2 of 4

Adjuster: CHEN TSUE YEE Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S FRP REAR LAMP COVER	Not Necessary	975.00 F	*- FL
2	1		*REVERSE LAMP BULB (A 95 MAN)	Broken	235.00 F	*235.00 FL
3	1		*REAR LAMP BULB (A95 MAN)	Not Necessary	245.00 F	*- FL
4	1		*REFLECTOR ASSY ,REFLEX, RH	Not Necessary	57.90 F	*- FL
F=Fra	ınchise	part. L=ListIte		Sub Total (S\$)	1,512.90 0.00	235.00 23.50
- List Item Discount on L Items 0.00/10.00% (S\$) Total Parts (S\$)					1,512.90	211.50
			Report was unsubmitted durin	g this print-out.		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,325.00	795.00		
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	602.00	446.00		
	Gross Labou	Gross Labour Cost (S\$)		1,241.00		
Report was unsubmitted during this print-out						

< END OF ESTIMATES >