

REF: EOI

ASSIGNMENT

From: Date: 12/09/2019

Veh No: SKH 51730 Yr Regn: 6106

Estimated Cost:

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or CA /

To Inspect Vehicle No: SKH 5173D

Make: Toyota corolla Altis c.c. 1.5-98

at Workshop m/s: HUP MOTOR TRADING

Colour: Grey A/C: Insured / Std / NI / NA

of: 81K 9004 Tampines St. 93 # 01-120

Sp. Reading: 283137 T/Radio: Insured / Std / NI / NA

Insured: X 17 9815K

Eng/No: C/No: MRO532EC107122838

Policy No:

Gen. Cond: Good / Fair / Poor / Burnt

Claims No:

Steering: In order / Jammed / Leaked / Burnt or

Sum Insured: Excess:

Brake: In order / Jammed / Leaked / Burnt or

(Client's Record)

Modi: Nil / SRim / STD A/Rim or

Make of Veh: 10:30am - 12pm

Tyre Size: F: 195/60R15 R:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Bal. or Market Value: 11K

TOYO / YOKO or

IDAC Accident Rport Consistent?: Yes or No

Front R/Bal. 6 mm Rear R/Bal. 6 mm

GLA / PR Seen Consistent?: Yes or No

L/Bal. 6 mm L/Bal. 6 mm

Est. Repairs: 4 days Res.: Yes or No

D.O.A. 10/9/19 D.O.I. 12/9/19

Lum Sum: 20 % 3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS (up)

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or Ref.

Date: Person Contacted: Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	31-5-2021 have video of folder 4747829
	45 \$1700/- (Red = \$1756.22 / 51%)

Date/Time, File Pass to? : Preli. Report : Final Report

Days Of Repair: Resurvey No. of Trip:

Survey Fee:
Transportation:
S + FS: \$
Photo:
Other:
TOTAL:

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Insp (\$) : Wheel and

Report Format: Lump Sum / I.P.R. /



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/EQI19016132/Uwb3

Date: 13.09.2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKH5173D


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12.09.2019 at the premises of M/s Hup Motor Trading & Service and have the following to report:-

Workshop Estimate Amount	: S\$	<u>3,456.22</u>
Revised Estimate Amount	: S\$	<u>1,994.30</u>
"Check" Items Amount	: S\$	<u>254.77</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:

The vehicle sustained damages at the Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2960/09/19

Your Ref: _____

Date: 11th SEP 2019

MDM LOO CHWEE KIM
BLK 106, #04-335
TAMPINES STREET 11
SINGAPORE 521106

*Not Authorized
like
1/50
12/9/19
Hdy.
Take photo. After*

Estimate cost of repair to TOYOTA COROLLA ALTIS 1.6 (A) Saloon - SKH 5173 D

1 pc front bumper	<i>o/s/oe</i>		\$ 374.40	
2 pcs front bumper o/s & n/s side retainer	<i>all</i>	@ \$ 41.70	83.40	<i>==</i>
8 pcs front bumper top clips	<i>all</i>	@ \$ 3.90	31.20	<i>---</i>
1 pc front bumper reinforcement			339.70	<i>?</i>
1 pc front bumper damper	<i>n/s</i>		65.00	<i>X</i>
6 pcs front bumper lower clips	<i>all</i>	@ \$ 3.80	22.80	<i>---</i>
1 pc front grille	<i>all</i>		269.70	<i>---</i>
5 pcs front grille clips	<i>all</i>	@ \$ 3.90	19.50	<i>X</i>
1 pc front grille logo emblem	<i>all</i>		39.20	<i>---</i>
2 pcs o/s & n/s head lamp assy	<i>n/s? also</i>	@ \$ 331.70	663.40	<i>1pc</i>
1 pc front number plate & frame	<i>all</i>		60.00	<i>405.00</i>

\$ 1,968.30
Less 25% \$ 492.08
\$ 1,476.22

To wiring check up & adjust headlight alignment. 40.00 *20*

To respray Tuff-Kote on all affected accident parts. *11* 90.00 *X*

To remove, refix & top up air cond gas for repair & knocking out front support panel & necessary parts. *11* 150.00 *X*

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front support panel, front o/s & n/s chassis frame member & necessary parts, to weld, renew & align above parts. 750.00 *400*

To putty & respray painting on all affected accident parts. 950.00 *600*

\$ 3,456.22
=====

Dollars : Three Thousand Four Hundred Fifty Six And Cents Twenty Two Only.

HUP MOTOR TRADING & SERVICE

[Signature]

[Faint stamp and text, mostly illegible]

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	478Z

Vehicle Details

Vehicle No.:	SKH5173D
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	3ZZ4578730
Chassis No.:	MR053ZEC107122836
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,950.00
Original Registration Date:	20 Jun 2006
First Registration Date:	20 Jun 2006
Transfer Count:	4
Actual ARF Paid:	\$17,545.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 May 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$22,789.00
COE Rebate Amount:	\$7,829.00
Total Rebate Amount:	\$7,829.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Sep 2019



ALL-NEW
Mercedes-Benz GLE450 AMG
Premium Plus

TEST DRIVE TODAY!

☎ 6250 6696 / 9637 5329

F1 AUTO CARS

altis Price Range Depreciation > 10 year(?) Vehicle Type

Advanced Search

Home » Used Cars » Boeki Auto Pte Ltd » Toyota Corolla Altis 1.6A (COE till 06/2021)

Toyota Corolla Altis 1.6A (COE till 06/2021)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



BOEKI AUTO PTE LTD



Price \$11,800

Depreciation \$6,580 /yr

Reg Date 29-Jun-2006
(1yr 9mths 16days COE left)

Mileage N.A.

Manufactured 2006

Road Tax \$965 /yr

Transmission Auto

Dereg Value \$8,336 as of today (change)

OMV \$15,950

COE \$23,227

ARF \$17,545

Engine Cap 1,598 cc

Power 81.0 kW (108 bhp)

Curb Weight 1,115 kg

No. of Owners 3

Type of Vehicle Mid-Sized Sedan

Features

View specs of the Toyota Corolla Altis (2000-2007)

Description

Trade In Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Category

COE Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Boeki Auto Pte Ltd

» Dealer's pricelist

» 72 vehs sold | 39 vehs available

Address

49 Sungei Kadut Loop

Search cars nearby this location

Office No

67555005

Contact Person(s)

Boeki

82180500

used cars
company profile

Posted on: 31-Aug-2019 | Last Updated on: 04-Sep-2019

Upfront Payment
Compare

» more Financial info

Shu Pei (LKKAuto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Thursday, 12 September 2019 1:56 PM
To: Shu Pei (LKKAuto)
Cc: Admin A; Vivian Lau (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving XD9855K (OI : EQI - DM19HO02532-JG) AND SKH5173D (TP : LKK REF - CC6/EQI19016132/wb3) on 10.09.2019
Attachments: XD9855K (10.09.2019).pdf

Dear Shu Pei

Attached our insured's accident report for your attention.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, September 11, 2019 4:04 PM
To: Joel Goh
Cc: Admin A; Vivian Lau (LKKAuto)
Subject: Direct Settlement - Accident Involving XD9855K (OI : EQI - TBA) AND SKH5173D (TP : LKK REF - CC6/EQI19016132/wb3) on 10.09.2019

WITHOUT PREJUDICE

Dear Joel,

We refer to the above matter.

We have received a new assignment from M/s Hup Motor Trading & Service and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:
- TP's EST & GIA report



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQI19016132/Ugb3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 21-10-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 9855K	Veh. Inspected	SKH 5173D
Policy No.	DMPCHQ18-007133	Coverage (\$)	0.00
Claim No.	DM19HO02532-JG	Excess (\$)	0.00
Assign From		Assign Date	12/09/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053ZEC107122836	Colour	GREY
Odometer	283137	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/09/2019	Inspection Date	12/09/2019
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 5173D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DENTED / DEFORMED	374.40	374.40
2	FRONT BUMPER O/S & N/S SIDE RETAINER @ \$41.70	NECESSARY	83.40	83.40
8	FRONT BUMPER TOP CLIPS @ \$3.90	NECESSARY	31.20	31.20
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	339.70	-
1	FRONT BUMPER DAMPER	NO SUCH PARTS	65.00	-
6	FRONT BUMPER LOWER CLIPS @ \$3.80	NECESSARY	22.80	22.80
1	FRONT GRILLE	CRACKED	269.70	269.70
5	FRONT GRILLE CLIPS @\$3.90	NOT NECESSARY	19.50	-
1	FRONT GRILLE LOGO EMBLEM	NECESSARY	39.20	39.20
2	O/S & N/S HEAD LAMP ASSY @ \$331.70	N/S NOT NECESSARY / O/S CRACKED	663.40	331.70
1	FRONT BRACE PANEL (ADDITIONAL)	BENT	151.00	151.00
	LESS 25% DISCOUNT		-514.83	-325.85
			1,544.47	977.55
1	FRONT NUMBER PLATE & FRAME (SN)	BENT	60.00	40.00
	LESS 25% DISCOUNT		-15.00	-
			45.00	40.00
LABOUR				
	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT.		40.00	30.00
	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS.	NOT NECESSARY	90.00	-
	TO REMOVE, REFIX & TOP UP AIR COND GAS FOR REPAIR & KNOCKING OUT FRONT SUPPORT PANEL & NECESSARY PARTS.	NOT NECESSARY	150.00	-
	LABOUR CHARGES TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT FRONT SUPPORT PANEL, FRONT O/S & N/S CHASSIS FRAME MEMBER & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS. INCLUSIVE OF THE		750.00	480.00

Report Ref No. CC6/EQ119016132/Ugb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.		950.00	600.00
			1,980.00	1,110.00
GRAND TOTAL			3,569.47	2,127.55
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CC6/EQ19016132/Ugb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.