

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19016141/KBA3Q2

**Date:** 16/07/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SGG1419A

**Insured Vehicle No :** GBF7957M

Date of Loss: 07/09/2019

Nature of Claim: TP

Claim No: 9618086945SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGG1419A**

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ2527113

Reg. Date: 03/05/2006 (Man. Year: 2006)

Chassis No: ZNE100304375

Colour: Metallic Silver

Odometer: 197984 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Nexen 9 mm

Rear Left Side: Nexen 9 mm

Front Right Side: Nexen 9 mm

Rear Right Side: Nexen 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,886.21	2,850.30	3,035.91	51.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	1,750.00	1,070.00	37.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,706.21</b>	<b>4,600.30</b>	<b>4,105.91</b>	<b>47.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,650.00</b>		
<b>(S\$)</b>	8,706.21	3,650.00	5,056.21	58.08
<b>+ GST 7.00/7.00% (S\$)</b>	609.43	255.50	353.93	58.08
<b>Nett Amount (S\$)</b>	<b>9,315.64</b>	<b>3,905.50</b>	<b>5,410.14</b>	<b>58.08</b>
<b>+ Loss of Use (7.0 x S\$80.00/day) (S\$)</b>		560.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>+ Other Costs (S\$)</b>		45.00		
<b>Nett Liability (S\$)</b>		<b>4,512.50</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,500.00</b>		

### INSPECTION

Date of Assignment: 11/09/2019

Date Inspected: 11/09/2019 Inspected At:

Accord Auto Services Pte Ltd (HQ)  
10 Ang Mo Kio Ind Park 2A #03-11,  
AMK Auto Point  
Singapore 568047

Estimated Period of Repair: 5.0 days

---

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Bent	1,589.70 FL	*1,210.40 FL
2	1		*REAR TAIL GATE LOCK	Dented	391.60 FL	*391.60 FL
3	1		*REAR TAIL GATE LOGO	Necessary	60.40 FL	*60.40 FL
4	1		*REAR TAIL GATE WISH CHROME PANEL	Serviceable	281.01 FL	*- FL
5	2		*REAR CAR PLATE LIGHT	Serviceable	284.50 FL	*- FL
6	1		*SET REAR TAIL GATE INNER COMPARTMENT CLIPS	Not Necessary	10.00 FL	*- FL
7	2		*REAR TAIL GATE HINGE	Repair	314.20 FL	*- FL
8	1		*REAR BUMPER	Bent	1,607.90 FL	*580.80 FL
9	2		*REAR BUMPER SIDE RETAINER	Serviceable	183.80 FL	*- FL
10	1		*REAR BUMPER REFLECTOR	Serviceable	117.20 FL	*- FL
11	1		*REAR BUMPER CLIPS	Necessary	11.60 FL	*11.60 FL
12	1		*REAR END PANEL	Bent	657.20 FL	*441.20 FL
13	1		*REAR END PANEL GARNISH WITH CLIPS	Dented	394.50 FL	*245.00 FL
14	1		*REAR WEATHERSTRIPE (50%)	Cut	298.50 FS	*164.55 FS
15	1		*REAR WINDSCREEN MOULDING (3 PCS)	Necessary	320.00 FL	*320.00 FL
16	1		*REAR SPARE TYRE PANEL (SWIMMING POOL)	Repair	680.00 FL	*- FL
17	1		*FRONT NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS
18	1		*REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
19	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,612.11</b>	<b>3,665.55</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,725.90	815.25
<b>Total Parts (\$\$)</b>	<b>5,886.21</b>	<b>2,850.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	1,000.00	800.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK ,JACK ,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	700.00
3	TO APPLY ANTI RUST TREATMENT	New	100.00	60.00
4	TO CHECK WIRING SYSTEM & LIGHT	New	100.00	20.00
5	TO REMOVE AND REFIX TAIL GATE ATTACHMENT	New	150.00	60.00
6	TO REMOVE AND REFIX REVERSE SENSOR	New	150.00	50.00
7	TO REMOVE AND REFIX REAR INNER COMPARTMENT TO FACILITATE REPAIR	New	200.00	60.00
8	TO REMOVE AND REFIX REAR TAILGATE WIPER ARM ,WIPER MOTOR & TOP SPOILER TO FACILITATE REPAIR	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,820.00</b>	<b>1,750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >