



Your Ref : D15007320MFSH/TPD/KT

Date: 02<sup>nd</sup> October 2019

Our Ref : CS3/FCI15014381/T1sd3s2-1

**M/s Ms First Capital Insurance Ltd**

36 Robinson Road

#16-01 City House

Singapore 068877

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FU 455P  
ACCIDENT ON 02/07/2015 INSURED VEHICLE SHD 3087P**

Instruction was received to inspect the vehicle Reg. No. FU 455P. The inspection was conducted on 12/09/2019 at the premises of DIRT Wheel Motor Trading, Blk 9004 #01-100 Tampines Street 93 Singapore 528838.

The following vehicle information was recorded:


Registration Number	: FU 455P
Make/Model	: K.T.M 390 Duke
Year of Registration	: 2014
Body Colour	: Black / Orange
Chassis Number	: VBKJGJ408DC215161
Engine Capacity	: 373 cc
Speedometer Reading	: Not Available


The chassis frame affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$	13,000.00(est)
Less: LTA Reimbursement Value (RV)	(S\$	3,500.00)
Nett Liability	S\$	9,500.00

Vehicle Inspected By:

  
MOHAMAD TAUFIKH  
M.MATAI, AMSAE-A  
Automotive Assessor

  
K.K.LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.