# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

3 Anson Road

51 Ubi Ave 1 #01-25 #16-00 Springleaf Tower Paya Ubi Industrial Park Singapore 079909 Singapore 408933

Attn: Ong Chin Kiat Date: 13 Sep 2019

# **Preliminary Advice**

Vehicle No : SLQ785L **Accident Date** : 02/09/2019

Make : TOYOTA LEXUS Policy No. : DMPCSN3077271800

**Assignment Date** : 11/09/2019 **Excess** : S\$2,000.00

Date of Inspection : 12/09/2019 Est. Duration of Repair : -

: Cheng Hoe Motor Pte Ltd (Yishun) Inspection At

Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident. The undercarriage, body structure affected due to collision

> Repairer's Estimate (Gross) 100.00 (TOWING) :S\$

**Revised Amount** :S\$

0.00 Check Items (Estimated) :S\$

Total :S\$

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 64,000.00 COE / PARF Rebate :S\$ 29,422.00

Salvage Value :S\$

Margin for Repair :S\$ 34,578.00

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage
		Kindly let us have your authorisation.

- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments: Vehicle recommended total loss due to uneconomical for repair.