

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG19016163/ASF3E2

**Date:** 18/06/2020

### REFERENCE

Insured/Claimant:	SITI ANIS	Policy No:	
Date of Loss:	07/09/2019	Nature of Claim:	OD Claim No: 3604340965SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT7955B	Engine No:	CVN041484
Make & Model:	AUDI A4, 1.4 (A)	Chassis No:	WAUZZZF44HA182509
Reg. Date:	13/11/2017 (Man. Year: 2017)	Odometer:	20090 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$110,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,521.00	6,240.24	3,280.76	34.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,632.00	10,657.00	5,975.00	35.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>26,153.00</b>	<b>16,897.24</b>	<b>9,255.76</b>	<b>35.39</b>
<b>- Excess (\$\$)</b>	600.00	600.00	0.00	0.00
<b>(\$\$)</b>	25,553.00	16,297.24	9,255.76	36.22
<b>+ GST 7.00/7.00% (\$\$)</b>	1,788.71	1,140.81	647.90	36.22
<b>Nett Amount (\$\$)</b>	<b>27,341.71</b>	<b>17,438.05</b>	<b>9,903.66</b>	<b>36.22</b>

### INSPECTION

Date of Assignment:	12/09/2019	
Date Inspected:	12/09/2019	Inspected At:
		Premium Automobiles Pte Ltd (UBI)
		55 Ubi Road 1
		Singapore 408699
Estimated Period of Repair:	13.0 days	

**Adjuster:** ADRIAN LING

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER SIDE PANEL-LH	Dented	2,443.00 FS	*1,954.40 FS
2	1		*REAR WINDSCREEN	Necessary	1,049.00 FS	*839.20 FS
3	1		*PRIMER	Necessary	19.00 FS	*14.88 FS
4	1		*SIDE WINDOW-LH	Necessary	561.00 FS	*448.40 FS
5	1		*REAR DOOR-LH	Dented	2,152.00 FS	*1,721.60 FS
6	1		*OUTER DOOR SEAL	Necessary	185.00 FS	*147.60 FS
7	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
8	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
9	1		*REAR DOOR SEALING STRIP	Not Necessary	15.00 FS	*- FS
10	1		*REAR DOOR CATCH	Not Necessary	109.00 FS	*- FS
11	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	515.00 FS	*- FS
12	1		*DOOR HANDLE TRIM PLATE-LH	Not Necessary	80.00 FS	*- FS
13	1		*DOOR HANDLE SENSOR-LH	Not Necessary	208.00 FS	*- FS
14	1		*REAR PERIPHERAL LIGHT-LH	Not Necessary	66.00 FS	*- FS
15	1		*EXTERIOR DOOR HANDLE-LH	Cut	35.00 FS	*27.52 FS
16	1		*REAR DOOR MOUNTING BAR-LH	Not Necessary	149.00 FS	*- FS
17	1		*REAR BUMPER GUIDE SECTION-LH	Not Necessary	40.00 FS	*- FS
18	1		*WHEEL HOUSING LINER-LH	Not Necessary	223.00 FS	*- FS
19	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	82.00 FS	*- FS
20	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
21	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
22	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
23	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
24	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
25	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
26	1		*SUNDRIES	Necessary	400.00 FS	*6.64 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)**      **9,521.00**      **6,240.24**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	600.00
3	TO INSTALL REAR WINDSCREEN SOLAR FILM	New	400.00	400.00
4	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	280.00	280.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
6	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS LUGGAGE COMPARTMENT TRIMS,DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
7	TO DISMANTLE REAR BUMPER,REAR LID AND LHS REAR DOOR.CUT OUT AND WELD LHS REAR FENDER.RENEW LHS REAR DOOR.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	6,300.00	3,500.00
8	TO RESPRAY REAR BUMPER,LHS REAR FENDER,LHS REAR DOOR,LHS SILL PANEL,DOOR ENTRANCES,ROOF CHANNEL,DOOR HANDLE,DRAIN PANEL AND END PANELLING.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	5,700.00	2,525.00
9	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>16,632.00</b>	<b>10,657.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >