



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL  
(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRE  
SINGAPORE 239924

INV No. AC2003730  
INV Date 08/05/2020  
Reference CS/AGI19016166/Eyf3n2  
Code AGI



### PROFESSIONAL SERVICE FEE

Vehicle No. SJK 824M  
Insured Veh. SLA 5245E  
Claim No. C10003975/KY  
Policy No.  
Accident Date 09/09/2019  
Inspection Date 12/09/2019

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI19016166/Eyf3n2		
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 08-05-2020		
Code : AGI				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLA 5245E	Veh. Inspected	SJK 824M	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10003975/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	12/09/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN SUNNY	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JN1CFAN16Z0114039	Colour	BLACK	
Odometer	187644	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	YOKOHAMA	5 mm	
L/H Front Tyre	185/65 R15	YOKOHAMA	5 mm	
R/H Rear Tyre	185/65 R15	YOKOHAMA	5 mm	
L/H Rear Tyre	185/65 R15	YOKOHAMA	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	09/09/2019	Inspection Date	12/09/2019	
Survey held at	160 SIN MING DRIVE #02-07			
Repairer	SIONG LEE MOTOR			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>10 Working Days</b>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 824M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DENTED	608.80	452.00
1	REAR BUMPER MOULDING	CUT	194.90	194.90
2	REAR BUMPER BRACKET	DENTED	190.80	190.80
1	REAR BUMPER SPONGE	CRUSHED	158.50	158.50
2	REAR BUMPER RETAINER	NECESSARY	70.40	70.40
1	SET REAR BUMPER CLIPS	NECESSARY	60.00	30.00
1	REAR BOOT LID	DENTED	754.90	655.00
2	REAR BOOT LID HINGE	TO REPAIR SEE LABOUR	180.00	-
1	REAR BOOT LID LOCK	DENTED	75.10	75.10
1	REAR BOOT LID LOCK CATCH	NOT NECESSARY	37.50	-
1	REAR BOOT LID BOTTOM MOULDING	CRUSHED	208.90	208.90
1	REAR BOOT LID TOP MOULDING	DENTED	369.10	369.10
1	REAR BOOT LID INSULATOR	NOT NECESSARY	188.30	-
1	REAR BOOT LID RUBBER	CUT	120.00	120.00
1	REAR END PANEL	DENTED	335.60	335.60
1	REAR END PANEL GARNISH	CRUSHED	120.00	120.00
1	REAR SPARE TYRE PANEL	DENTED	774.10	774.10
1	REAR SPARE TYRE NUT	NOT NECESSARY	35.10	-
2	REAR LAMP	BROKEN	720.40	720.40
3	REAR LAMP PANEL	DENTED (1 PC ONLY)	520.00	198.00
1	REAR SPARE TYRE COVER	TORN	203.40	203.40
1	REAR RIGHT HAND MUDGUARD	DENTED	776.30	776.30
1	REAR RIGHT HAND MUDGUARD HOUSING	NOT NECESSARY	441.10	-
1	REAR RIGHT HAND MUDGUARD INNER TRIM	CUT	280.30	280.30
1	REAR RIGHT HAND MUDGUARD COWLING	CUT	51.20	51.20
1	REAR EXHAUST BOX	BENT	504.00	504.00
1	REAR EXHAUST BOX INSULATOR	DENTED	144.80	144.80
1	REAR RIGHT HAND CHASSIS FRAME	TO REPAIR SEE LABOUR	682.70	-

Report Ref No. CS/AGI19016166/Eyf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RIGHT HAND DOOR	TO REPAIR SEE LABOUR	1,169.80	-
1	REAR RIGHT HAND DOOR LOCK	NOT NECESSARY	183.40	-
1	REAR WIND SCREEN MOULDING	NECESSARY	155.10	155.10
2	REAR SPARE TYRE PANEL INSULATOR	NECESSARY (1 PC ONLY)	420.00	100.00
1	REAR RIGHT HAND MUD FLAT	MISSING	87.80	87.80
2	REAR EXHAUST BOX MOUNTING	NOT NECESSARY	63.40	-
	LESS 10% DISCOUNT		-1,088.57	-697.57
			9,797.13	6,278.13
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	BROKEN	280.00	200.00
1	REAR NUMBER PLATE WITH COVER (SN)	NOT NECESSARY	30.00	-
1	SET REAR WIND SCREEN SEALAND (SN)	NECESSARY	60.00	40.00
			370.00	240.00
	<b><u>LABOUR</u></b>			
	LABOUR TO DISMANTLE REAR WIND SCREEN.		140.00	120.00
	LABOUR TO DISMANTLE CUSHION.		220.00	50.00
	LABOUR FOR RUST PROOFING.		200.00	30.00
	LABOUR TO SPRAY PAINT.		1,700.00	1,200.00
	LABOUR TO PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BOOT LID HINGE,REAR RIGHT HAND CHASSIS FRAME AND REAR RIGHT HAND DOOR.		1,900.00	1,200.00
			4,160.00	2,600.00
<b>GRAND TOTAL</b>			<b>14,327.13</b>	<b>9,118.13</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,800.00</b>

Report Ref No. CS/AGI19016166/Eyf3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.