

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19016171/EPA3Q2

**Date:** 08/10/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SG5869R	<b>Insured Vehicle No :</b>	SH8943J
Date of Loss: 09/09/2019	Nature of Claim: TP	Claim No: MCT19090193

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG5869R	Engine No:	50344832034486
Make & Model:	MAN A95, 10.5 D (A)	Chassis No:	WMAA95ZZXG7003548
Reg. Date:	18/12/2017 (Man. Year: 2016)	Odometer:	151552 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	275/50 R22.5	Rear Tyre Size:	275/50 R22.5
Front Left Side:	5 mm	Rear Left Side:	5 mm
Front Right Side:	5 mm	Rear Right Side:	5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,220.00	220.50	999.50	81.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,432.00	792.00	640.00	44.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>2,652.00</b>	<b>1,012.50</b>	<b>1,639.50</b>	<b>61.82</b>
<b>+ Loss of Use (2.5 x S\$300.00/day) (\$\$)</b>		750.00		
		<b>(S\$) 1,762.50</b>		
<b>Liabile Amount (50.00%) (\$\$)</b>		<b>881.25</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>880.00</b>		

### INSPECTION

Date of Assignment:	11/09/2019	
Date Inspected:	16/09/2019 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 08 Jul 2020)	
<b>Parts:</b>	N/A	MAN A95 10.5 D (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SG5869R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LAMP BULB (A95 MAN)	Cut	245.00 F	*245.00 FL
2	1		*O/S FRP REAR LAMP COVER	Repair	975.00 F	*- FL
					<b>Sub Total (\$\$)</b>	<b>1,220.00 245.00</b>
					<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00 24.50</b>
					<b>Total Parts (\$\$)</b>	<b>1,220.00 220.50</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,000.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	432.00	262.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,432.00</b>	<b>792.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >